

GENERAL INDEX

TO THE FOUR VOLUMES OF

Ore Dressing

 $\mathbf{B}\mathbf{Y}$

ROBERT H. RICHARDS, S.B., LL.D.

Professor of Mining Engineering and Metallurgy at the Massachusetts Institute & Technology, Boston, Mass., U. S. A.

FIRST EDITION
SECOND IMPRESSION

McGRAW-HILL BOOK COMPANY, INC 239 WEST 39TH STREET, NEW YORK

LONDON: HILL PUBLISHING CO., Ltd. 6 & 8 BOUVERIE St., E. C.

1909



INDEX.

A GENERAL GUIDE TO ALL FOUR VOLUMES.

Pages 1-643, Vol. I: 644-1197, Vol. II; 1199-1610, Vol. III; 1611-2052, Vol. IV.

A	Action of jaw and spindle breakers
	Rittinger table
Aachen, wash trommel at	rolls
Aaron, C. H., gold amalgamation	steam stamps
gravity stamps 226 leaching gold and silver xix losses in gold milling 1180 752	tronmels
leaching gold and silver XIX	Actions in cruebing
losses in gold milling	Actions in crushing
on amalgamated plates 752 leaching 1167	Adalbert Works, hand picking at
testing gold ores by chlorination	Adalbert Works, hand picking at
Abadie, E. R., gravity stamps	amalgam at the Owyhee silver mill 787
North Star gold stamp mill at Grass Valley,	dimension of Black Hill traps 773
California	end and side shake vanners
on mortars 100	form of riffle in mercury traps 772 gravity stamps
plates at the North Star mill . 787	gravity stamps
A Bartlett mill	impurities inmalgam
Abbé Engineering Company. Abbé spiral feed 1323	life of retorts
tube mill 1280, 1298 at Guanajuato, capacity of 1291	pointed boxes 477
	Slope of plates
	Adams W. L. amulgamated plates 730 748
mills 1291, 1626, 1677 Abbott, J. W., running a stamp mill . 229	ample amplian 787 1173
Absorption of amalgam by plates 765	amalgamation and gold mills
mercury by amalgamating plates 1514	
Accelerated pg 507, 510, 515, 519, 610	vanners
details of stroke 638	Adelaide mill
mechanism, air pressure and gravity . 537	Adhesion
cam and gravity in Stutz coal jig 537	
cam and spring 537	in dry concentration 826 of minerals, effect of 4 separation by 831
disc motion . 536	separation by 831
for jugs 533	Adjustment of Blake breakers
hammer and spring on Collom jigs 536	Separation by 8.33
motion Harz jigs at Mill 125 1701, 1702, 1703	classifier
on Willey table	Comet breaker 42
Accessory apparatus . 842, 1570 Accounting, mine . 1923	r rue vanner for testing
Accounting, mine	Gates breaker 39 gravity stamps 216 gyratory breakers 1218 Hooper air jig 822 822
Accounts and reports	gravity stamps
	Hooper air jig
Accuracy of machine sampling 1575 Acids, action of on mercury . 730	ings
for cleaning mercury . 786	machines . 1115
Acids used in settling tests 1147	Mechernich magnetic separators at Mill 135 1736
on amalgamated plates 751	throw on jigs 531, 594, 595
Acid water, cause of base bullion 783	travel, slope, and water on vanners 660
effect of 906	spindle breakers 47
in amalgamation 751	vanners 653, 663, 658, 659
on amalgamated plates 750	Wilfley table head motion 1460
jig tanks . 523	Advantages and disadvantages of various crushing
plates 749	machines 313 accelerated mechanism on jugs 538
screens 173	accelerated mechanism on jugs 538 accounts 1128
neutralized . 173 Acme concentrator, L. H. L. Huddart 2023	action of jaw breaker . 58
Acme concentrator. L. H L. Huddart 2023 E Walker 2023	action of spindle breaker . 58
guide for gravity stamps 154, 155	air versus water concentration 825
ore feeders at Mill 100 1624	arrastra 238
table	Collom jig 514
Across the San Juan Mountains. T. A Rickard 1923	concentration over smelting
Action of air jig 822	electric power . 1091
belt tables 698	Elmore oil process 832
breakers compared 55	filter pressing plants as against decantation
buddles 704	plants 1646, 1647 flat mill site 1086 gravity stamps
bumping belt tables 669	flat mill site
tables 682	
centrifugals force 827	hand breaking
classifiers 387	hand jigs
crusting machines	hand picking
	helicoid conveyor over older types
gravity stamps	large breakers

Pages 1-643, Vol. I.	ORE	DR	ESSING.	Pages 64	4-1197, Vol.
Advantages of large motors	1	1092	Albertite, specifi	c gravity of	
machine feeding		115	Albite, specific g	ravity of	• • • • • • • • • • • • • • • • • •
magnetic concentration	1	771	Alden brooker	ivania, mili at	
magnetic concentration mercury wells Muntz metal plates		750	Alexandria Coal	Co was hine plant	
Muntz metal plates		518	Alice mill	Co., washing plant.	
picking in the mine		481	Alignment of rol	Co., washing plant .	
pine and plug ng spigot .		527	Alkali to prevent	sickening of mercur	v
pipe and plug jig spigot removing dust before washing coal		817	Allard coal wash	ing methods	
riffle tables		679	Alleghany Iron (ls sickening of mercur ing methods	
rock breaker at mine	. 1	109			
rolls of large diameter	٠	83 108	Allan Balant M	nd Iron Company, A oll crusher at /est Australia metalli ng for friability g at	
sectional mills separate treatment of mine fines		111	Allevard calcini	rest Austrana metant	irgical practice
side hill site for mills		085	hend pickin	og for triatomity	
silver combination mills		040	magnetic se		
silver plated amalgamated plates	-	748	mill at		
skimming ugs		577	picking at		
chalang black may hans m		535	roasting for	friability at	
frames for gravity stamps	157,	158	magnetism	n at	
drica, milling at the Simmer & Jack,	, G ₹)••		sizes of ore	hand picked at	
frames for gravity stamps frica, milling at the Simmer & Jack, Swart	20	035 •	Allis, E. P., Co,	amalgamating pan	243, 244, 245,
stamp mur practice in, r. C. Koogres		V111	alas es assessina		247,
gassiz, 1 ggregation affecting separation		889	clean-up par	n . mult	•
of minerals, effect of		3	edge runner mechanical	batea	
gitation	892, 1		on design of		
after sizing or sorting		891	stamp tap	pets .	•
m kieves		726	natent cams		
ratio on vanuers		665	stamp mort.	u	
use made of in milk		890	stamp mort. Allis, E. P., on sl stamp bo	oe shanks .	
gitator for bottle tests		157	stamp bor stems rolls	sses .	
gitators for amalgamation for day		780 076	stems		
hun Colliery, Carr disintegrator at		284	rolls at Mill 1:	26	
ikinite, specific gravity of		188	speed		1737,
ir blast, continuous		816	Allis-Chalmers (ompany, an improve	d trommel
dry blanket		825	annulai ou	king table	AI HAMING
panning		825	Ayton thick	pulp extractor	
for emery	. 1	079	ball mills, r	egards work, cost, cte	
graphite		075	Challenge f	egards work, cost, etc eeder	
Hochstedt apparatus		816	գետութ եւ	n at Mill 100 rolls	
on horizontal belt		818	corrugated	rolls	
bubbles affecting separation effect of		890	costs of bro	aking ore	
on free settling		464	Mill 170	rs at Will 127	1711,
classifier at Engis		817	Gates ore h	restor.	
concentration, bibliography for		837	rock and	ore breakers	• • • • • •
by		815	tube and	ball mills	
concentrators, classification of		816	mill		
using centufugal force .		818	Hancock ju	S	1440,
continuous blast		816	improved W	olf Tongue classifier	
gaps, ampere turns required for hoists, Pilling		79 5 608	2.000000 000000	nane canngs samper	1074,
iors	640, 816,	290		hallow pocket hinder	
jigs Hooper Paddock Krom	040, 010,	820	rolls	1707, 1724, 175 66, 1867, 1877, 187 n stamp at Mill 182 ler steam stamp	1127
Krom		824	at mills	1707 1794 175	0 1751 1759 1
pressure and gravity ug mechanism		537	18	66, 1867, 1877, 187	8. 1885. 1898. 1
separator, Clarkson Stanfield x Mumford & Moodie	820,	828	simple stear	n stamp at Mill 182	,,,
Mumford & Moodie		818	single cyline	ler steam stamp	
Pape Henneberg	818,	828	stamps at A	Jill 100	
settling, use made of, in mills suction used in asbestos dressing		889 817	steam stam	P	. 8.
versus water for concentration		817	suspended f	rame va nner	
versus water for concentration itken, R. M., stamp mill construction		2048	lesting scree	.115	
kens & Evans slimer, the	1500, 2	2022	toothed roll vanners at	Mill 136	
kins & Evans concentrator	2	2023	Allis Corliss eng	ine	994, 997,
kins & Evans concentrator kron Chih mill	1	307	pump		994, 997, 1000, 1
table of sizes, capacities, speeds, weight	s, etc 1	308	relance roll		
table of sizes, capacities, speeds, weight ktien Company, new mill of labama graphite mills	!	924	steam stamp	114, 116 23, 124, 125, 126, 12	3, 118, 119, 120,
labama graphite mills hematite, cost of concentrating	!	075 135	122, 12	3, 124, 125, 126, 12	7, 128 131, 133,
ores roasted for magnetism		135 S14	vaive mou	ion	
fron ore concentration		176	Allison Rand mi	ne mine, hand picking_a	
magnetic concentration of	833, 835,		mill	nami picking a	9, 1107, 1109, 1
washing in	1	180	cost of sta	imping .	., 1107, 1109, 1
laska, cost of producing gold in 19	975, 1976, 1	977	steam stamp	×	
dredging in	. 1	009	Alma Emmons s	ludge mill	xxv,
stamp mill practice at Douglas Island Treadwell Gold Mining Co		039	Alpha Delaval ·	separator	
readwell Gold Mining Co	1	181	Alsing Company	, the LR driers	1597, 1
amalgam squeezer used by mill 1127, 113	33, 2037, 2	781	tube mills	•	
costs and output at the	10, 2037, 2	042 048	cylinder	.l	234,
descriptions of, R. A. Kinzie	2	033	bibliograf	ony of	1000
heavy stamps		220	tube mill	zes, power, etc.	1280,
heavy stamps H Watson		043	Altenberg classif	er, power, etc.	416, 475
mortar blocks		148	mine, wash	trommel at	
lbany compound for greasing guides		156	Saxony, cale	cining ore for friabili	tvat
grease		098	mill at		1086, 1

	Amalgamating pan dies
Alternate polarity in magnetic separation 798	Amalgamating pan dies
Alternating current in magnetic separation 835 Althans, E., Ball stamp 143 Blake, Marsden and Alden breakers 61	E P. Alli- Co 244, 245, 246, 247, 249
Althans, E., Ball stamp 143 Blake, Marsden and Alden breakers 61	for testing
	pan, frame, bottom, and central cone 241
Dingey mill 293	in I was mill 241, 249, 247, 249
German and California stamps 230	loss of mercury in 241, 243, 244, 240
Krom jig 839	method of working 248
Krom's rolls and coal rolls 112	power, wear, losses of iron and mercury 249
on breakers 61	Risdon Iron Works 244, 245, 246, 247, 249
Dingey mill	shafts and gears 248
Prientx and Shoil pneumatic stamps . 143	sides, flanges, ring, lining, covers 244
	shafts and gears sides, flanges, ring, lining, covers size of stuff treated by spider, driver, cap, lubrication, and grind-
atomic weight of	spider, driver, cap, lubrication, and grind-
plate screens	steam pipe and steam jacket
specific gravity of	tank and Boss systems 940
Alum used in settling kaolin	temperature of 949
tests	tank and Boss systems 248 temperature of 248 Union Iron Works 243, 244, 245, 246, 247, 249
Amador City, California, mill at 1032, 1037	emion from works 243, 244, 243, 240, 247, 249 • weight of spider and driving cone in wings, muller, shoes, and pulp current 245 tables, back deflectors for 1514 Krupp 788
County, California, mills in 1180	 wings, muller, shoes, and pulp current 245
cost of milling	tables, back deflectors for
County amorna, mins in 1180	
stamp mills	Shaking 1513 Amalgamation 730, 892, 1512
mill, stamps in . 228	Amalgamation 730, 892, 1512 agitators for 780
Managam absorbed by plates 765	an improved process for. A C. Beatty 2024
amount of bullion in	apparatus for 731
bullion contents of 783	at mills 1516, 1638, 1663
	bibliography for 787
distribution of, from plates	buttle amplicamation for testing 1986
meness of 764	combination process of 248 description of a new machine for 2025 effect of areas on 165
general discussion of, Leon de Mortillet 2025 gold	description of a new machine for
and silver in hard	2004
in 767	solutions of salts . 767
kettle	temperature on 766, 1516 J. J. Mac Dowell . 2024
nature of 208, 1512	C W Merrill 1520
plain copper plates coated with 747	followed by agitation 891
presses 1517, 1518, 1519	concentration 1616 1652
produced by fine gold, hard, A. L. Collins 2024	and lixiviation of concentrates 1616, 1620
	and tailings 1616, 1617
recovered by sweating plates 759 remedy for hard E Woakes 2024	of tailings
removal of impurities 251	lixiviation 1616, 1634 and concentration 1616, 1631
retorting . 781	in New Zealand 1. Park 2024
right consistency on plates . 756	the Southern Urals. C. T. Nissen 2024
scoop . 758	inside of batteries at Mill 112 1658
scoop . 758 silver . 731	the mortar C. DeKalb 2024
sodium 730	Lixiviation 1616, 1634 1617, 1631 16
specific gravity of 1188	
squeezer at the Alaska Treadwell, hydraulic . 2024	gold ores T. T. Read . 1520
squeezer at the Alaska Freadwell, hydraulic 2024 power 1519 squeezing of 781, 1517 strainer 781	new plates
strainer . 781	pan amalgamation 1517
treatment and retorting of 2024	plates, an article on. N. S. Keith 2024 of Muntz metal 2024
used on copper plates . 747	1514 preparation of pulp for 1514 principle of
Amaigams . 730	principle of 4, 2024
Amalgamated copper surface on Gilpin County tables 681	Reese River process of 248
Amalgamated plates . 731 1014, 1512 See also Plates	settlers for 777
object also Pates	side shake
absorption of mercury by 1514 amount of drop 743	sizing before 1514
at Mill 98 622	
at Mill 96, details of	tests 1156, 1167 J. R. Cooper 2024
clean up . 203	use made of, in mills 880 of copper plates for. E. Halse 2024 2025 oncentration in Gilpin County 1047
details of in the mills . 737	of copper plates for. E. Halse 2024
distributors and collectors used on . 743 dressing of. W. H. Kritzer 2024 for testing	versus concentration in Gilpin County 1047
dressing of. W. H. Kritzer 2024	Washoe process of 248
for testing 1156 heavily silver plated. F. W Cindel 2024 inside 179	Amalgamator, Bazin's 787
inside . 178	Eureka rubber 776
material for	Gowan's
Muntz metal for 1519	King gold 777
on writey table 1656	Lagarrigue Sutil . 2024
quanty of copper for 747	Lancaster gold I H Lancaster 1530
silver plated 1512	new type of 2024
slope of	new type of 2024 Pierce 1520, 1517 Amalgamators 775, 1517
speed of waves and thickness of films 746	Amalgamators
suggestion is made that pulp flow across. J. R. Sears _ 2024	amaigamating pans
Amalgamating device, a laboratory. H S. Guess 2024	American ball pulverizer 234 bibliography for 295
mills, bibliography for	
	Blower Company fans for furnishing air to pneumatic tables at Mill 151
pan 232, 239, 777	
bibliography for	magnetic separator 1541, 1508
Boss type 242, 244, 245, 246, 247	jig mechanism
circulation of pulp	New Century Blake breaker 1222
bibliography for 232, 239, 7/7 bibliography for 290 Boss type 242, 244, 245, 246, 247 circulation of pulp 250 cost of 250	J-62
5	

American Developing and Mining Company mill xxvii, 1028	Andrée, Th. Dressing of graphite in Austria and Ba-
American Developing and Mining Company mill xxvii, 1028 filter press at Mill 102 1630 gauge gold stamp mills improvements in ore dressing 1178 1178 Process Company driers 1597, 1609 was better to 159 1597, 1609	Andrée, Th. Dressing of graphite in Austria and Bavaria Andrews dredging pump 80 Angels, California stamps at 22 Camp. California, arrastra at. 1034, 1033, 1034, 1033 shoes and dies at 1024, 1033, 1034, 1033 shoes and dies at 22 Angle irons in launders 72 Angle irons in launders 73 of friction 124 in trommels 73 of nip, formula 93 gyratory breakers 121 how affected 94 of rolls 89, 109, 110, 122 affected by speed 93 slide of ore 93 Anglesite, specific gravity of 1188 Angleur, double discharge on jigs at 58 Anhydrite, specific gravity of 118 Anne mill 187
gold stamp mills	Angels, California stamps at 22
improvements in ore dressing	Camp, California, arrastra at 1034
Process Company driers 1597, 1609	mills at
rock breaker	stamps at
Smelters Securities Company, Tecolotes mill 1748	Angle irons in launders 87
steam stamp Steel Mfrs Association on screen gauges 173	of friction 124
Steel Mfrs Association on screen gauges 173	of nin formula
wire gauges . 227 Zinc Extraction Co., international separators at 1535	gyratory breakers 1219
Lead & Smelting Co, Huff electrostatic sepa	how affected 9
rator 1552	of rolls 89, 109, 110, 1220
Americus Zinc and Lead Mining Company, separa- tion of zinc blende and barytes . 1565	affected by speed
Amicus mill, milling cost at	Anglesite specific gravity of 1189
Ammelson heating ore for frishility	Angleur, double discharge on iigs at
Ammeberg, heating ore for friability 9 Heberh mills at 259 jig at 641	Anhydrite, specific gravity of
jig at	Animal oils 109
bed at 574 mill at . 911, 1086, 1121, 1176	Ankerite, specific gravity of
bed at 574 mill at 911, 1086, 1121, 1176 picking at 492	Anna mill
removal of stimes by classifier	stamp mill, spitzlutten at 42
screening at 373	Works, hand picking at 49:
separation of pyrite and blende at	Annealing copper plate . 74
sieve scale at 367 Utsch jig at , 520	
Ammonia used on amalgamated plates 753	Annular picking table
Amortization of capital 1128	Anis-Chainers type . 130c
Amount and temperature of water for gravity stamps 221	Krupp type 143.
of mercury fed to stamps 208	vortex classifier 400 Anodes used in electroplating copper plates 750
throw of jigs	Anorthite, specific gravity of 1180
Ampere turns for magnets	Anthony, W. A., Edison, Buchanan, and Wetherill
Ampere turns for magnets	separators 83
A. M. W. mill, Leadville, nulling at the. Λ. W.	Anthracite, angle of mp required to crush 9
Warwick . 2043 Amygdaloid ore, mills for . 990	hindered settling test on . 617, 62: settling velocity of . 466, 469
Amygdaloid ore, mills for 990 Anaconda classifier 395, 396, 476	specific gravity of
coal washer 2018	Antidote for mercury 73
concentration at M Schwerin 2037	Antimony amalgam 73
Concentrator D.E. Woodbridge 2040 Copper Mining Co 1836	atomic weight of 118 hindered settling test on 614, 61
	ore concentrated by Hooper air jig . 82
Huntington mill screens at 1317 in 1905 L. S. Austin 1922 mill xxvi, 984, 1181, 1182 plant of 2037	separated by oil . 83
mill xxvi, 984, 1181, 1182	settling velocity of . 466, 469
plant of 2037 11 O. Hofman 1922	Specific gravity of
rolls at mills 1822, 1824, 1828, 1829	Anvil blocks for Nordberg steam stamp 124
Analcite, specific gravity of 1188	Anzin Company, air blast for coal dust . 83
Analyses of Cammett table products . 678	using air blast 81
of canvas table products 701, 702 crude ore and concentrates at Mill 167 1858, 1859	Apatite, mill for 105 specific gravity of 118
Luhrig table products 679	used in making phosphate 81
Luhrig table products 670 mill products See individual mills in Chap-	Apophyllite, specific gravity of 118
ter AA	Apparatus, accessory 84
products at Mill 162 1847 of Auchor mill ore 815	used for amalgamation 73 Appendix 1187, 199 bibliography for 117 Appleby, C. J. 22 Appleby, C. J. 22
Ball Norton magnet . 798	bibliography for
Golden gate table 682	Appleby, C. J
Hallett table 676	Appliances for elevating ore and water 85
magnetic separation 802, 803, 804, 809, 810, 813 Parsons table 669	Application of magnets 19
Parsons table 669 pneumatic belt concentrator 818	Apron distributors
preumatic belt concentrator 818 Richards annular classifier 406	for feeding slime tables
roasting for magnetism 819	jígs 54
slime table . 1172	plates
roasted products 814 vanner products 650, 664	Arcadian mill 13
Wilfley table products	Archer breaker
Analysis by specific gravity tests	Archimedean screw for jig tailings
for minerals	Archimedes screw dredge
of Butte ore 135 Morison's curves of velocity of stamps 215	hobbs 110
products of disintegration and screening . 830	Area of amalgamated plates
of dry separation 820	discharge for stamps 20
Krom air jig . 824	steam stamps 12
magnetic separation 802	Sorting column 40
oil process 832 Paddock air jig 823 separated by decrepitation 829	Appliances for elevating ore and water Application of magnets 72 Application of magnets 79 rifles 77 Application of magnets 79 April Aproximation of 17 Aproximation of 18 Aragonite, specific gravity of 118 Arcadian mill 13 Archer breaker 57, 58, 6 Archimeelean screw for jig tailings 58 Archumeeles screw for jig tailings 10 Ara of amalgamated plates 10 Ara of amalgamated plates 74 discharge for stamps 20 steam stamps 12 sorting column 40 Argall, Philip. Capacity for rolls 22 cylindrical driers 59 driers 380 and drying of ore 180
separated by decrepitation 829	driers
See Assaving	
Anchor mill, roasting and magnetic tests on ore speed of jigs at 593	dry crushing 201
speed of jigs at	4000 400
Anderson's concentrating mill	four-tube drier at Bessie mill 160
Andesine, specific gravity of . 1188	
Andesite, weight of 1190	grinding pans versus tube mills

A 11 70 11 1 1 0 1 1 1 1 0010	
Argall, Philip, ideas on a modern fine crushing plant. 2018	Aspen, Colorado, rock house at
iournal pressure in solls 07	Asphaltum specific results of
jig 639 journal pressure in rolls 97 limit of economical sizing 3366 members receive and resident machiness 1378	Asphalt varnish used in electroplating 754
modern crushing and grinding machinery 1278	Assaying tests 1163
multi tubular drier at Mill 143 1770	Assay office
journal pressure it rous: Journal pressure it rous: Journal pressure it rous: Journal pressure it rous: Journal pressure it and it is a sing machinery in the form of the	for mill 1088
rules for sampling 648	ot tailings at Mill 48 Assays and sizing test of feed and products of Huntington mills 1317 of jig tailings 607 mill products Mill 142 1767 minerals 1162 products at Mill 129 1718 of Paddock air jig 823 stamp pulp 211 tailings 213 zine mill products 1169 See also Analyses
screens 385	ington mile 1217
ore dressing in British Columbia 2042	of jig tailings . 607
question of hole vs. mesh	mill products Mill 142 1767
rolls	minerals 1162
sampling and dry crushing in Colorado 9 1944	products at Mill 129
of ores and speeds, and cost of screening 1365 settlement of slimes 1410 stepting of rosted slimes 1410 stepting for rolls and speed curves 1224	stamp pulp 911
screens, kind, speeds, and cost of screening . 1365	tailings 213
settlement of slimes 1417	zinc mill products
settlement of slimes	See also Analyses
speed for rolls and speed curves	Atacama, Chih, mill at 1182 •nill, Taltal, Chili. S.H. Loram 2033
use of Vezin sampler 1572	Atacamite separated by screening 830
Argentite, specific gravity of 1188	specific gravity of 1188
Argon, atomic weight of 1188 367 Arithmetial, gatto for sieve scale 367 Arizona and Sonora. D. E. Woodbridge 1923 concentration at Humboldt A. H. Hamilton 10 10 10 10 10 10 10 1	
Arithmetical gatio for sieve scale	E. N. Fell 2034
Arizona and Sonora. D. E. Woodbridge 1923 concentration at Humboldt A. H. Hamilton 2038	Atkinson, A. S. Lake Superior milling practice 1419
in F. H. Probert . 2037	Atlantic mill 1175, 1180, 1183 cost of breaking at 51
of copper in F. H. Probert 2033, 2041	
concentrators in A Morison 2042	rusning and milling
Copper Company D. E Woodbridge 1923	steam stamping
	details of cylinders of steam stamps . 126
mill of A Morison . 2041 use of lime for slime settling . 1416	Evans classifier in 395 Launders 873
districts Cost of producing copper in 1953, 1954,	launders 873 screen for stamp 121 slime tables at 697 steam stamps 120, 135 Mining Co 1181 Atlas engine 902
1955	slime tables at 697
gasoline engines in	steam stamps 120, 135
milling at Mowry 2042 milling practice in. D. E. Woodbridge 2038	Mining Co
milling practice in. D. L. Woodbridge 2038 mills in 1005, 2043	Atlas engine
mills in 1005, 2043 sline treatment in 1411 stamp mill 1175	Atlin district, B. C., dredging in the
stamp mill . 1175	Atmosphere, weight of 1188 Atmospheric discharge for jigs
type of settling tanks at Morenci 1443 Arminius Chemical Company 1913	stamp 140
Arminius Chemical Company 1913	Atomic weights, table of 1188 Attaching jig screens 539
mill 1913 Armitage, H. E., adjustments of jigs 640	Attaching jig screens 539
Armitage, H. E., adjustments of jigs	Attachment of jig plunger to connecting rods 529 screens in trommels 355
on making bed material for jigs 574	Attendance required by American Process Company
spitalutte Hopper shaped unwaterer 476	driers 1599
Arrangement of holes in screens 168	Blake breaker at Mill 186 1917
tronmels 384	Gates breaker at Mill 159 1828
machinery in a modern mill A. Harvey . 2018 machines . 891	Pierce amalgamator at Mill 114 . 1663 rotary drier at Mill 186 1917
mills 1086, 1107	steam stamps at Mill 182 1912
mills	Wetherill magnetic separators 1525
screen notes . 369	Wiltley roasting furnace 1548
tronmels 364 Arrastra 232 237	Attraction of various substances by magnets . 796
Arrastra 232, 237 bibliography of 289	Attrition causing slimes 1121 Atwood amalgamator● , 775
description of the. A Lakes . 2013	Atwood amalgamator 775 Atwood, M Microscopic examination of pulp 228
discussion of construction. E. L. Ballou 2016	Augue, strength of 301
[元]	Aultman balanced shaking screen . 2018
value of the M.F. Leech . 2014	jaw breaker 2009
Arrastras, number used 231 Arsenic amalgam 730	Auriferous antimony ore, concentration of an . 2030
atomic weight of	Aurora mill, µgs at 641 pointed boxes at 477
in amalgam 767	Austin gyratory breaker 1210, 2009
Areson A	Austin, L. S., Anaconda Copper Company in 1905 1922
Arsenolite, specific gravity of	Deister concentrator at the Baltic mill 2023
Arsenopyrite, hindered settling test on 616, 617 roasted for porosity 829	Washoe Plant of the Anaconda Copper Com-
settling velocity of	Austin Manufacturing Company Cost of breaking
specific gravity of	ore . 1222
Artesian well for water 1105	Austin gyratory breakers 1222
covering for them with the control of the control o	The state of the s
sorting tot steam pipes 1091	Austin, W L amalgamating pan, Boss system 291
dressing 817 838 1070 1179 1199	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290
dressing 817, 838, 1079, 1178, 1182 in Quebec 1916	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290
dressing	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
methods of treating F R Wilson 2041	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
dressing 817, 838, 1079, 1178, 1182 in Quebec 91916 R Stokes 2046 methods of treating. E. B. Wilson 2041 milling of F. Cirkel 5168 10 8 Regglary 9938	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
dressing 817, 838, 1079, 1178, 1182 in Quebec 1916 R Stokes 2046 methods of treating. E. B. Wilson 2041 milling of F. Cirkel 1568 PS Ragelman 2036 in Canada. F. Cirkel 9934	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
milling of F. Cirkel 1568 158 Regelman 2036 in Canada. F. Cirkel 2034 Ascending current cones or cylinders 1402	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
milling of F. Cirkel 1568 12.5 Regelman 2038 12.5 Regelman 2034 2	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
milling of F. Cirkel 1568 P. S. Regelman 2036 in Canada. F. Cirkel 2034 Ascending current cones or cylinders 1402 Ashes used in preparing amalgamated plates 756 retorts 781	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
milling of F. Cirkel 1568 P. S. Regelman 2036 in Canada. F. Cirkel 2034 Ascending current cones or cylinders 1402 Ashes used in preparing amalgamated plates 756 retorts 781	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
milling of F. Cirkel 1568 P. S. Regelman 2036 in Canada. F. Cirkel 2034 Ascending current cones or cylinders 1402 Ashes used in preparing amalgamated plates 756 retorts 781	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 grizdles in the Harshaw mill 385
milling of F. Cirkel 1568 15 15 15 15 15 15 15 1	Austin, W. L. amalgamating pan, Boss system 291 at the Harshaw mill 290 Boss tubular classifier at Harshaw mill 478 gravity stamps 224 griz/les in the Harshaw mill 385

Australia, details of stamps 226 dredging in 1009 dry concentration in 837, 838 panning in 825 Hancock jig in 564 mercury wells and riflles in 769, 770 metallurgical practice in W. T. Saunders 2039 Western R. Stokes 2046 plates in 788 stamp mills in 1190 stamp in 226, 227, 229 treatment of lead zinc ores in V. F. S. Low 2034 low grade copper ore in J. J. Muir 2039 ore at the Lucknow gold field. A. Canning 2040 water used in stamp mills 222	Ball mills Ferraris caracities of 1300
dredging in	Ball mills. Ferraris, capacities of 1300 1300 table of sizes, power, weights, etc. 1300 2015 fine grinding for clays 2013 2015 Gates 1280, 1300 1280, 1300
panning in	for clays
Hancock jig in 504	Gates 1280, 1300 table of sizes, capacities, power, weights, etc general notes on 1301 Humboldt Engineering Works Company 1315 in Australia, capacity, speed of 2028 Krupp 1231 number used 340 operation of H Fischer 1302 szing test of ball mill pulp 1315 on 2017 using rollers E Poetgens 1830 versus rolls at Mill 159 1916 stampp as slume makers at Mill 185 1303 wear of steel balls in 2017
metallurgical practice in West R Allen 1323	table of sizes, capacities, power, weights,
mill practice in W T Saunders 2039	general notes on
plates in	in Australia, capacity, speed of 2028
stamp mills in 1180	Krupp
treatment of lead zinc ores in V F S Low 2034	number used
low grade copper ore in J. J. Muir 2039	sizing test of ball mill pulp 1315
Canning 2040	using rollers E Poetgens
Canning	versus rolls at Mill 159 1916
Metal Company's mill, Ullrich magnetic separ-	wear of steel balls in 2017
ators at practice, granding pans in 2283 Paractice, granding pans in 2283 Austra, chromate mill in 1073 graphite dressing in 1177 mills in 1075 Austrian graphite mill, kieves in 727	Stamps as stime makers at Mili 155 1303 wear of steel balls in 2017 wet 2016 with dust separator 2017 a fines separator 2028 Ball-Norton magnetic separators 797, 1527, 1508, 1527 1896 1897 1898 1897 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898 1898
Austria, chromite mill in 1073	a fines separator
graphite dressing in	Ball-Norton magnetic separators . 797, 1527, 1568, 1527
	belt type at Mill 158 1822, 1824, 1825, 1822
Author's tests on jigging mixed sizes	Ball-Norton magnetic separators 797, 1527, 1568, 1527 at Mill 158 1826 belt type at Mill 158 1822, 1824, 1825, 1822 drum type at Mill 158 1822, 1824, 1825, 1822 at 1926 drum type at Mill 158 1822, 1823, 1825, 1826 at 1926 drum type M' at Mill 158 1822, 1823, 1825, 1826 Ballou, E L Stamping and concentration on sulphide gold ore 1841's revolving knife buddle 328, 334 Ball steam stamps 114, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 130, 131, 132, 133, 134, 142, 143
Author's tests on jigging mixed sizes 630 suction 627 Automatic discharges on jigs 553, 576, 577, 583, 584 Kay Ixor 584 feeders853, 854, 855, 856 ore feeders853, 854, 855, 856 samplers Vezin type at Mill 1671857, 1858	type 'M' at Mill 1581822, 1823, 1825, 1826
stay box for	Ballou, E L Stamping and concentration on
ore feeders 1578	Ball's revolving knife buddle 328, 334
	Ball steam stamps 114, 118, 119, 120, 121, 122, 123 124 126 127 128 130 131 132 133 134 142
tripper at Mill 174	143
Avery automatic scales at vitil 105	valve motion
Avante specific gravity of	Cam 228
thick pulp extractor	W McDermott 2040
art Will 174 1873, 1874 tripper at Will 174 1883 Averv automatic scales at Will 105 1635 Avoirdupos weights, equivalents of 1187 Avante specific gravity of 1189 Ayton intermittent pulp thickener 2020 thick pulp extractor 1419 at El Bote mill 1408 Azurite, specific gravity of 1189	Baltic mill, Redridge, Michigan
	copper hand book
В	valve motion 143 Bally balanced cam 226 cam 228 Balte mill, Redridge, Michigan. E. D. McDermott 2040 W. McDermott 2040 W. McDermott 2040 Mining Company 1885 copper hand book 1225 Banking in stamp mortar 215 pervention 218 Banks on vanners 652, 656, 662 Bank, thickness of, in trommels 378, 880 Banner mine, concrete mortar block 148 Barber, G. M. Gruson ball mill at Atacama, Chili 1182 Bardwell, E. S. Free settling velocities 148 Barboun, T. J. Dredging in California 1182 Bardwell, E. S. Free settling velocities 1421 sorting tube for testing 1988 Barge with log washers 326 Barliet, angle of nip to crush 94 decrepitation of dressing at Long Island E. K. Judd 2027
Babbitting rolls 73 Babbitt metal for bearings 1098 effect on mercury 751 Babrock & Wilcox boiler 910, 1090 Back plates, disadvantages of 178 Bacon, Earl C viii rolls at Mill 152 1807 Bad Ems, Prussta, mill at 1177 Badouren A. Free settling in water 477	Banks on vanners 652, 656, 662
effect on mercury	Bank, thickness of, in trommels
Balcock & Wilcox boiler 910, 1090	Barber, G. M. Gruson ball mill at Atacama, Chili . 1182
Bacon, Earl C viii	Bardwell, E. S. Free-settling velocities
rolls at Mill 152 1807	sorting tube for testing 1988
Bad Ems. Prussta, mill at 1117 Badourcat, A Free settling in water 477 Badourcat, A Free settling in water 477 Baffle beard in mercury wells 768 settling tank 458 plates in distributors 857 driers 882 driers 882 bag to settle dust 1099 Bailev, G E Gold stamp mills 1183 Baiev, G E Gold stamp mills 1183 Baize for tables 703 Lables on dredges 1012 Baker, G, W. Blake breaker 58 Krom jig 838, 839 Krom's improvements on Cornish rolls 110	Barite, angle of nip to crush
settling tank 459	decrepitation of
plates in distributors	methods used in dressing E. Higgins, Jr 2026
to settle dust	washing
Bailey G. F. Gold stamp mills 1192	in Tennessee. E. K. Judd
Baize for tables	Barlor, J. C. Sampling of concentrating tables 2032
tables on dredges	Barnaby, G. A. Free-settling velocities
on breakers 58	Barnhart, G. A., on Griffin mill 284
Krom's improvements on Cornish rolls	Barrels for clean-up 234, 264 Barrels for shipping concentrates 1112 1113
on breakers 5.8 Krom jg 838, 839 Krom's improvements on Cornish rolls 110 Balancel rolls, Sturtevant 21232 Balancing of shaking screens 342 Balach magnetic separator 834 Ballod mill 1184 Ballarat, amalgamated plates at 745 plates at 788 single discharge at 200 stamps at 226 Victoria, mills at 1180 Ball, C. M. Ball Norton separator 833, 1175 Cummings mill 292 equations for concentration 1176	Barren Springs, Virginia, iron ore from 809
Balch magnetic separator	Bar riffes
Ballof mill 1184	Barry tube mill lining
plates at 788	Barth, C Krom's rolls vs. stamps 112
single discharge at	stamps and rolls 229 Barth K Bull Leavitt and Allie stamps 142
Victoria, mills at 1180	Blake and Krom breakers 60
Cummings mill 292	on breakers 60 Bartle pulverizer
equations for concentration 1176	bibliography for . 294
Ball mills	Barge with log washers 326
Allis-Chalmers	the C.O., drag or disc conveyors 1583
an article on the	Grill four-compartment driers ! 1007
as re-granding machines	fine crushing mill 1004, 1005 Bartlett F. J. Concentrating blands 1109
best size of feed for. H J. Brooke 1323	jerking table
continuous, dry, sieveless	Bartlett, F. L. Concentrating blende 1183 jerking table 492 milling 1181 Bartlett, J. C. Pneumatic concentration 837 ricking table 450
Ball, C. M. Ball Norton separator 833, 1175 Cummings mill 292 equations for concentration 1176 on power used for crushing 309 Ball mils 233, 260, 1285 Allis-Chalmers 1156 an article on the 2014 as re-granding machines 1322, 1332 at mills 1828, 1829, 1830, 1914 best size of feed for. H. J. Brooke 1323 bibliography for continuous, dry, sieveless 2017 discussion of feering 2015 Ferraris 1280, 1299, 1323	picking table 459 Simplex concentrator 1487
Ferraris	
•	,

	• ,
Bartlet, J. C., table 678, 680, 1153, 2022	Bellom, M
Bartlet, J. C., table	breakers
used as jigs at Mill 142	breakers
Rartola pan 1036	drum separator at Friedrichssegen 833
Bartola pan 1036 Bartsch breaker 61	finest size jigged
bumping circular table 691	hand and machine breaking Scheanz breaker 57
bumping circular table 691 rotary percussion tables at Mill 150 1800	jigs
	on number of sieves for jigs
rotary percussion table, the 1497 round table 2022	jigs
round table 2022 Barus, C. Settling in liquids 1186 settling of very fine particles in liquids 177, 479 tests on clay particles 474 Barytes and zinc blende, separation of by decrepitation 1565	
settling of very line particles in liquids . 171, 479	pneumatic machine at Himmelfurst mine . 837 pointed loxes at Friedrichssegen. Meinecke
tests on clay particles 4/4	hydraulic classifier, Meinecke spitzlutte 477
Baryles and zinc blende, separation of by decrepita-	
tion 1565 Basalt, strength of 301	Schranz breaker
Base metals, effect on mercury	Stein belt table and Linkenbach slime table . 728
in bullion 785	trommels. Schmidt spiral sieve 385
Risin Reduction Company 1848	value of hand rucking 402
washers for clay	
in bullton 785 Basin Reduction Company 1848 washers for clay 333, 335, 1076 Batea 1152	Bell, R. Concentration in British Columbia 2004
belt for vanners	dredging on the Snake River, Idaho 2036
mechanical	Grasshopper Creek
Bath for silver plating	Dell, Robert N Note on Triplex rolls 1244
Mexico Silver Mill at	Rolt and pulley for trammels 256
Battens for mills 1088	batea
Battery, Boss standard . 1267	Blasdel
cloth, brass and tron	canvas used in Mill 41 650
construction 2012	concentrator, air 818
frame, cantilever. I C. Boss 1278	
M. P Boss . 2012	at mills 1631, 1670, 1690, 1691, 1706, 1708,
description of a	at mills 1631, 1670, 1690, 1691, 1706, 1708, 1709, 1710, 1735, 1750, 1759, 1760, 1762, 1763, 1764, 1768, 1769, 1771, 1772, 1828, 1851, 1853,
screens at Mill 96 1618	1704, 1708, 1709, 1771, 1772, 1828, 1851, 1853,
Foote screen	1868, 1869, 1876, 1913 for dredges 1012
Foote screen	for dredges
	rubber 859
Baugh's mill of cone type 292	rubber 859 driven pumps 871 descriptor 862
Baum ite 519, 643	
coal jig 523	film tables
advantages of 519	Brunton table
air pressure and gravity 537 disadvantages 519	Ferraris table
disadvantages 519 discharge 581	Uren table
mechanism . 537	C47 GEE GE7
washing plant. Barnsley, Eng 2051	Loring
Herne coal washing itg 2021	percussion table 1496
Bauschinger, J Strength of stone 316	rope and plate conveyors for hand picking 489
Bauxite, specific gravity of 1189	screens 1358 Callow screen 1358 Dunlap perfect clay screen 1357
Bayaria, graphite dressing in 1177	Callow screen 1358 Dunlap perfect clay screen 1357
Baxter breaker Bayliss, R. T Amalgam on plates 56, 58, 60, 61	11
on Blanton cams 194	tables 009 bibliography for 724 travel on vanners 658, 660 Woodbury 197 Belted rolls 75
Bay State Mining Company mill xxvii, 1023	travel on vanners 658, 660
Bazin's amalgamator 787	Woodbury
Beach Glen iron ore concentrated by magnets 802, 803	Belted rolls
Beakers for settling tests 1146	Belling used on amalgamated plates
Bearings for cam shaft 190, 191	Belts 1176 and pulleys 197 188
rolls 72	and pulleys
Beason, L. H. Boston Con Mg. Co. mill, Garfield,	proper speed for belts in Wetherill magnetic
he mill of the Utah Copper Co. Garfield Utah 2045	separator 1523
Beatty A C An improved amalgamation process 2024	corrugated 647
Beaumont, W, on breakers . 59	corrugated versus plain 650
Cole's stone breaker . 99	cost of for vanners 663
Becker Foundry & Machine Co Becker, G. F. and S. F. Emmons. Amalgamating	Corrugated versus plain 647
Becker, G. F. and S. F. Emmons. Amalgamating	for gravity stamps
pans 291 amalgamation 789	
arrastra 290	for mills 1093 link 800 magnetic separators with 804 of vanners, details of 648 or tables for band nicking 1435
edge runners . 295	magnetic separators with 804
Becket Foundry & Machine Co., rolls . 76	of vanners, details of
Beckett and McDowell geared rolls at Mill 183 1913	or tables for hand picking
Bedding for jigs 1458	picking and sorting belts at Mill 137 1438
Harz jigs at Mill 183	rises of for sells 97
Bed of hand jig	of vanners, details of 648 or tables for hand picking 1435 picking and sorting belts at Mill 137 1438, 2021 sizes of, for rolls Spadone concentrator belt 1503
or jigs	take off in Wetherill magnetic separator, width
material for	thickness, and proper speed for 1524
size of grains for 575	thickness, and proper speed for 1524 Bendigo, amalgamated plates at
Becket Foundry & Machine Co., rolls 76 Becket Foundry & Machine Co., rolls 76 Becket Foundry & Machine Co., rolls 1913 Bedding for jigs 1458 Harz, jigs at Mill 183 1913 Bed of hand jig 8894 of jigs 495, 552 effect of 1463 material for 573 size of grains for 573 tests on 630 on boncen rators, depth of 660	Australia, mills at 1180 milling practice at. H. C. Boydell 2044 gold milling practice in. H. C. Boydell 2034 iron stamp frames in 160
	milling practice at. H. C. Boydell 2044
on vanners, thickness of	gord milling practice in. H. C. Boydell 2034
proper condition of, on jigs	plates in 788
70 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	shoes and dies at
Belgium, jigs in 641	stamps at
mills in	Benedict, W. de L. Log washer in South Carolina 1180
phosphate dressing in	stamps at 226 Benedict, W. de L. Log washer in South Carolina 1180 washing plant 335 on wash trommels 333
Beguein mine, Blake Dreaker at 1021	on wash trommels

Pages 1-043, Vol. 1.	n E	Dh	Lages OH-1101, Vol. 11.
Benson mines, magnetic separation at		798	Bilharz, O spitzlutte
Berdan's amalgamating pan Berenger and Stingls slime tank		291	test of jaw and Blake breakers 54 wash trommels 332
Berenger and Stingls slime tank		1407 301	Wash trommels
Berlin, tests on strength of stone at	٠.	2023	Bilharz circular iig
Bertha Zinc Co., mill Works		1180	Wenstrom, Lovett-Finney, Chase separators 832 Bilharr circular jig 518 sieve power jig 504
Works		1105	classiner 413
Berthelet inclined screen		$\frac{2018}{1189}$	improved Rittinger spitzlutte 478 oblong movable sieve power jig 503
Berthierite, specific gravity of Bertrand mill, rolls at	•	110	shitzlutte 477
Beryl, specific gravity of Bessemer steel for shoes and dies Bessie mill, Argall 4 tube drier at		1189	table
Bestemer steel for shoes and dies		185	Capacity of
Bessie mill, Argall 4 tube drier at		1600	at mills 1659, 1789, 1790, 1791 Billek, I Concentration on galena-blende pyrite at
Bethune Mining Co. France, surface equipment coal washing at the	101	2051	Billek, I Concentration on galena-blende pyrite at Maiern 1185
Bettel, W. Definition of slimes		1397	picking in mine and mill at Maiern, Austria 493
Beuthen, mill at 11		1186	separation plant at Maiern; Siemens and Halske
Upper Silesia, mill at		1087 1096	separators 836 Bin and feed chute for steam stamps 129
		839	Bingham, Utah, mill at 913
amalgamation	• :	839 787	milling the ores of W R Ingalls 2039
appendix		1173	*Binkley, George E. Settling system . 1409
breakers and hammers		57 839	Bins 842, 1027, 1570 at mills 1742, 1743, 1760, 1761, 1762, 1763, 1857
centrifugal separation classifiers and laws of classifying		475	concentrate drying 1570
decrepitation		839	discharge chute in 843
disintegrating and screening		839	drier, at Mill 100 1625
dust chambers and bag houses	• • •	885 884	tilter
elevators and conveyors feeders and distributors		884	for concentrates of the Wolverine mine, drawings of the ore 2032 sizes and capacities. See individual mills in
gravity stamps		223	
hand mcking		492	Chapter XX.
jigs and laws of jigging kieves		$\frac{639}{727}$	stamp . 128 with steam pipe for drying products at Mill 125 1705
Landers		885	Biotite separation from molybelenite by magnet 1568
laws of classifying by free settling in water	•	475	specific gravity of
crushing		315	Birkinbine, J., and T. A. Edison. Blake system 57
pigging		639	Buchanan, Wenstrom, Conkling, Monarch and Edison separators 833
magnetic concentration and roasting for mentism	лŖ-	832	Edison separators
mills and general milling		1173	concentrating iron 1175
pneumatic concentration		837	Conkling separator 833
preliminary crushing		$\frac{55}{334}$	cost of breaking at Atlantic mill 51 crushing at Atlantic mill 57
washers . pulverizers .	•	289	crushing at Atlantic mill 57 magnetic concentration . 1175
pumps		885	milling at Atlantic mill, Lake Superior 1175
rittles .		727	Lake Superior
roasting for friability		839 839	Birmingham gauge
roasting for porosity rolls		109	Iron foundry
Sampling		884	Bismuth amalgam 730
screening		384	atomic weight of
steam, pneumatic, and spring stamps		$\frac{142}{727}$	Bismuthinite, specific gravity of
vanners, tables, riffles, and kieves weathering		839	specific gravity of 1189
Bigelow patent breaker		2009	Bituminous coal, specific gravity of 1189
Bilharz cobbing magnet		1532	Blackhawk breaker of Dodge type 31
at Mill 126 O and E. W. Neubert. Dressing at Freibe	arct	1532	Colorado, mill at 1035, 1048 Black Hills, breakers at
Saxony	пд,	1174	cost of gold milling in 1132
Bilharz, ()		XIX	crushing in example solution in the C H Fulton 2033
Altenberg classifier and Rittinger spitalutic		$\frac{478}{142}$	district, South Dakota, cost of producing gold in 1977, 1978
Ball stamps		$\frac{142}{729}$	grizzlies in
hydraulic classmer, siphon separator, Altenb	erg		mercury trap 773
classifier, Billiarz spitzlutte		475	mills in . 1175, 1176, 1181, 1182
jig		641	plates in
movable sieve jigs table, Frue vanner, slime table, and buddle.	٠.	$\frac{643}{727}$	steam stamps in
versus Rittmer shitslutte		476	wet crushing cyanide mill in the. E B Sawyer 2044
Blake, Kley, Gates, and McCully breakers		55	Black Pine, Montana, mill at 1175
Carnali and Crickboom wash frommels		334 298	Black sands 1008, 1013, 1017 by U. S. G. S., investigation of 2042
Carr disintegrator Dingey mill .		293	Caribou riffle for treating 1509
edge runners		295	concentration by the U. S. G. S. K. Thomas 2046
general milling		1173	of 2038
gravity stamps		$\frac{223}{297}$	D. T. Day, R. H. Richards 2047 device for saving. W. Brazenall 2038
Griffin roller mill grizzhes, riddles, and trommels		384	Leighton separator for
Gruson ball mill		293	method of recovering gold from 1654
Heberh mill		292 639	problem of the. F Powell 1511 tests on at Dawson 2034
Heberwasche, Harz jig, Bilharz jig Himmelfahrt mill at Freiberg, Saxony 1	182	1185	treatment of
Huntington mill	,	296	I A Edman 2025
milling in Missouri		2034	California
Pape Henneberg separator and Krom jig		837 837	Blacksmith shop for mill
dry concentration . picking houses		492	Blaisdell aerators at Mill 109
Rittinger's principles		1175	Blades in centrifugal pumps 869 Blaisdell aerators at Mill 109 1650 centrifugal sand distributor 1602
Schwarzmann's rolls		109	Company. Billisded mechanical ore machinery 1009
			10

Pages 1199-1610, Vol. III.	INL	DEX.	Pages 1611-2052, Vol. IV.
Blaisdell distributor excavator excavator	1600	Blanding, L. Blandy, I. F.	Amalgamation 789 Ball stamp 142 c stamp 143
at mills	1868		
mechanical mixer	1670	for morta	ntrating tables at Mill 118 1677
sand distributor slime agitator system of mechanical ore handling Blake breakers 13, 55–61 at mils 1749, 1769, 1792, 1802, 1821, 1824, 1837, 1749, 1769, 1792, 1802, 1821, 1823, 1824, 1837, author's tests on samples crushed in	1602	tables .	ntrating tables at Mill 118 1877 1464 1507 1464 1507 1464 1507 1676
system of mechanical ore handling . 12 55_61	1600	tables on	dredges
at mills 1617, 1618, 1621, 1624, 1724, 1737,	1742,	used dry	for concentrating
1749, 1769, 1792, 1802, 1821, 1823, 1824, 1837,	1842,	in swea	ting plates 759
author's tests on samples crushed in	311	Blanton cams	ounts 193, 225, 228, 229
author's tests on samples crushed in Carterville Foundry & Machine Works . Case laboratory breaker of the Denver Fire Clay	1201	Blasdel vanne	r belt
Company Company	1204	Bleaching in the	e mine 9
comparative wear of metals in Jaws	48	Bleiberg, Ritti	nger tables at 668 Il tramway at mills 1719, 1769 way 937, 1016
compared with Dodge Gates	33 52	Bleichert aeria	d tramway at mills 1719, 1769
Denver Engineering Works Company	1203		
design of details of from the mills	1201	mine, mil	t at
Sizes Eli Whitney	$\frac{23}{16}$	Diende and py	isting and magnetism 814
	13	SCLUT	ation . 839. 900
Farrel Foundry and Machine Company for testing	$\frac{34}{1137}$	siderite crushed b	
for testing Gates Iron Works horse power required	34 17	jigs in Mi	ssouri, capacity of 602
Gates Iron Works horse power required Humboldt Engineering Company	17 1205	mill for	y rolls 62 850uri, capacity of 602 850uri, capacity of 602 907, 908 906 907 908 907 908
information on 18,	1223	test on	1168
	1202	weight	of 1190 by decrepitation 829 tote 829 7 720 7 1190 ole discharge on jigs at 3584 at 367 reens 175, 373 algamated plates 760
lead ore crushed in lever type	$\frac{274}{21}$	from 10	by decrepitation 829
life of wearing parts of at Mill 139	1221	quart	720
National Drill and Manufacturing Company's New Century Blake	1293 1203	separation	at Ammelærg
operation of	16	Bleyberg, doub	ole discharge on jigs at
Sturtevant roll-jaw toggles used for pounding blocks	1205 489	Sieve scale	at
Von Revit's tests	305	Blisters on am	algamated plates
wear of	25, 48 20, 59		
Blake-Denison continuous weighers	1603	Block 10 mine	selecting ore . 481 1713
Weigher Company Blake Demson Weighing		Blomcke, C	Advantages of the Wetherill separator 2030
machine at mills 1832,	1609 1860	apparatus ball mills	in German mills 1177 293
Blake double Jaw breaker at Mill 158 Blake, L. 1 Blake-Morscher separators	1824	Bartsch,	Schranz, Luhrig, and Lankenbach
Blake, L. 1 Blake-Morscher separators electrostatic separation	2027 1550	tables	728
magnetic separator .	833	Braun jig	nd Schranz jigs 641 and Harz eccentric jig 641
Blake Marsden fine breaker 5 breaker at Mill 185	6, 58	capacity o	f jigs 597
Blake-Morscher electrostatic separator. A H. Plomb	1915 2026	OI Tro Coarse and	mnicls 360 I fine crushing 2010
ore separator 1550	1611	complete o	liscussion of tube and ball mills . 2016
at Montana Zinc Company's mill separator, description of the L. I. Blake	$\frac{1551}{2027}$		ing at the Perm mine, Westphalia 1177 I lead 1177
separator W McA, Johnson	2026	Dörnberg	and Aurora concentrating plant at
at Mill 140 treatment of milling at Mill 131	1551 1551	Ramsbe	ck, Westphalia . 1177 nills 2034
Blake multiple 1/100 breaker	28	Groppel c	oncentrator 2023
pump Γ A, and S R Krom Improvements by Krom	1008 59	hand pick	ing at Ramsbeck, Westphalia. Cobb-
Blake breaker	57	ıng tabl Himmelfa	c 492 hrt ore dressing plant at Freiberg,
of Chateangay Ore and Iron Co.	59	Saxony	1177
multiple jaw breaker system	57 60	Saxony jigs at Lir in Auroi	
breakers 57, 5	9, 60	Káván-Ri	ttinger, vs. Luhrig, Stein vs. Bartsch
edge runners edge stone mills	$\frac{295}{269}$	tables	
edge runners edge stone mills Hade Gold mine, North Carolina, and Chateau-		magnetic s	separation
gay Ore and Iron Company, N. Y rock breaker	1175 20	in Hun	giry 2040
wearing parts for breakers	48	new jig sci	reen 834
W P. Amalgamation	789	ore dressir	ng at Bad-Ems 1177
Blake magnetic separator . breakers	833 57	Beuth Claus	en, Silesia 1177 thal
Howland's stamp battery stamp mills in Cali		Linto	rf 1177
fornia, Australia, and Brazil. German over- flow battery, Rittinger stay battery Huet & Geyler's settling cylinder, Hundt's sett-	229	Silber Pana-Ham	au, Laurenburg, and Clausthal 1177 neberg apparatus 839
Huet & Geyler's settling cylinder, Hundt's sett-			ator 837
ing tub and Kittinger's setzrad	4/8	pneumatic	concentration 837
jigs pivoting of jaw	640 57	riddles, tro	oxes in Dörnberg and Aurora mill 477 mmels, and spiral sieves for coal 385
reverberatory furnace designed by	829	Schmidt s	piral sieve
separating blende and pyrite separating pyrite	829 833	Schranz m	ill
separation processes silver milling at Butte, Montana	829	side plung	er eccentric jigs
	1175 143	slimes at t	he Himmelfurst-Fund mine at Przi-
two-stamp steam battery Wimmer's, Rittinger's, Harz, and Huet and		slime table	s
Geyler's jigs	643	Stein, Sch	ranz, and Rittinger tables 728
	11		

Blömeke, C Stroke of jigs 594	Boss, M. P., roller mill
trommels at Bad-Ems 385	shoe and die channels in amalgamating pan of. 247
use of wash frommels ,	stamp head 1271
Wetherill magnetic separator 834 Blower for Krom jig 824	standard battery
Blower for Krom jig 824 Blow of gravity stamps, effectiveness of 218	steel stamp battery frame
Blue Bell mine, British Columbia, proposed method	wedge-grip tappet for gravity stamps 1272 Boss or stamp head 185
of treatment at the 2042	pans
Bird mill, sizing test of stamped ore	steam jackets in 244
ground 1080	system
treated in South Africa	of pan amalgamation
weight of	tubular classifier
Blue, F. K. Experiments with launders 1594	Mining Company mill xxvi, 1841
Boards, covered with amalgam . 747	Boston Consolidated Copper Company 1850, 1852
for mill building 1088	and Mining Company mill Garfield Utah
to catch gold on dredges . 1012	L. H Beason
Bobtail mill, mortars 164, 165 rate of crushing in 165	Nissen stamps at
weight of stamps and mortars 164	Richardson Mining Company 1620 Bottle agitator 1157
Bodie, amalgamated plates at 766	Bottle agitator 1157 amalgamation
plates at 788	for testing 1996
stamps at 227, 228	Bottom bed in jigs, size of grains of
Bogardus eccentric mill 233, 259	thickness of
mill 232 bibliography for 292	material for
bibliography for 292 Boggs and Clark centrifugal pumps at Mill 141 1761	on Faust jig 548 jigs, defined 495
Bohemia, a mill in () Eypert 2047	for amalgamating pan 241
graphite dressing in 1177	ore bins 842
mill in 1075	Boulder County, Colorado, cost of mining and milling
Bohme Strength of stone . 316	tungsten ores . 1987
Boilers 1090 in mills – see Individual Mills in Chapter XX	dry separation in . 820
in mills—see Individual Mills in Chapter XX Boiler tubes for launders 873	Boulders in dredging
Boiling of pg beds 600	Bourdars disintegrators 899 Bournomte, specific gravity of 1189
point of mercury 730	Rouge's rolls 111
Bolivia, fin concentration in J. D. Minchin 2038	Bowie, A. J., Jr
dressing in 1084, 1183	Blake breaker at Father de Smet mill 57
M. Frochot 2033 W. McDermott 2040	Durcka runner and dags in the rather de Smet
W McDermott 2040	mill 787
Bolthoff rolls at Mill 166 1854 Bolton, R., on breakers 60	Father de Smet gold stamp mill 1174
Lancaster breaker 60	gravity stamps 224 grazzles in the Father de Smet Mill 385
Bolts for stamp mortars 148, 150	hydraulic giants 334
1 7	
removal of . 882	hydraulicking 1006
Bolzenmuhle 236	hydraulic mining xix 1173
Bolzenmuhle 236 bibliography for 299	hydraulic mining xix 1173 mortars 164, 165
Bolzenmuhle 236 bibliography for 299 Bonanza Co., use of hme for settling 459	hydraulic mining xix 1173 morture 164, 165 on grade of a sluice 723
Bolzemuhle 236 bibliography for 299 Bonanza Co , use of hme for settling 459 mill, details of stamps 221 Bonita Mning Company, Lane slow speed mill at 1309	hydraulic mining xix 1173 mortars 164, 165 on grade of a sluice 723 riffles 721
Bolzenmuhle	hydraulic mining xix 1173 mortary 164, 165 on grade of a sluice 723 riffle 721 timber riffle blocks 721
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164 165
Bolzenmuhle	hydraulic mining xi x 173 173 174 175 17
Bolzenmuhle 236	hydraulic mining xix 1173 mortary 164 165 no grade of a sluice 723 rifflec 721 timber riffle blocks 721 Box classifiers 432 surface current 433 whole current 443 distributors 857
Bolzenmuhle	hydraulic mining xix 1173 mortars 164, 165 on grade of a sluice 723 riffles 721 timber riffle blocks 721 Box classifiers 432 surface current 443 whole current 443 distributors 857 feel for Willey table 1468
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164 165 no grade of a sluice 723 riffles 721 timber riffle blocks 721 Box classifiers 432 surface current 443 whole current 443 distributors 857 feed for Willey table traps, Krupp type 1516
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164, 165 on grade of a sluice 723 riffles 721 timber riffle blocks 721 Box classifiers 432 surface current 443 whole current 443 distributors 857 feed for Willey table traps, Krupp type 1516 for mercury 773
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164, 165 no grade of a sluice 723 riffles 721 timber riffle blocks 721 Box classifiers 432 surface current 433 whole current 443, whole current 443, this right blocks 1468 traps, Krupp type 1516 for mercury 773 Boxes for jig concentrates 586 cam shafts 190
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164 165 no grade of a sluice 723 riffles 724 timber riffle blocks 721 timber riffle blocks 732 timber riffle blocks 742 timber riffle blocks 721 timber riffle blocks 721 timber riffle blocks 722 timber riffle blocks 723 timber riffle blocks 723 timber riffle blocks 724 ti
Bolzenmuhle 236	hydraulic mining xix 1173 mortary 164 165 no grade of a sluice 723 riffles 721 timber riffle blocks 721 Box classifiers 432 surface current 443 whole current 443 whole current 443 distributors 857 feed for Willey table 1468 traps, Krupp type 1516 for mercury 773 Boxes for jig concentrates 586 cam shafts 190 rolls 191 rolls 1875
Bolzenmuhle 236	hydraulic mining xi x 1172
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164 165
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164 165 no grade of a sluice 723 riffles 721 timber riffle blocks 721 further riffle blocks 721 mortars 432 mortars 433 mortars 433 mortars 443 mortars 443 mortars 445 mortars 457 mortars 457 mortars 156
Bolzenmuhle 236	hydraulic mining xix 1172 mortary 164 165 not grade of a sluice 723 riffles 724 timber riffle blocks 721 timber riffle blocks 722 timber riffle blocks 735
Bolzenmuhle 236	hydraulic mining
Bolzenmuhle 236	hydraulic mining xi x 1172 mortary 164 165 not grade of a sluice 723 riffles 724 timber riffle blocks 721 timber riffle blocks 732 timber riffle blocks 735 timber riffle turber 735 timber riffle turber riffle 735 timber riffle turber riffle 735 timber riffle 735 timber riffle 735 735 timber riffle
Bolzenmuhle 236	hydraulic mining xix 1173 mortars 164 165 mortars 164 mortars 16
Bolzenmuhle 236	hydraulic mining
Bolzenmuhle	hydraulic mining
Bolzenmuble 236	hydraulic mining
Bolzenmuhle 236	Nortauthe mining xx 1172 mortary 164 165 mortary 165 mortary 172 mortary 172 mortary 172 mortary 172 mortary 173 mortary 173 mortary 174 mortary 175
Bolzenmuhle 236	hydraulic mining
Bolzenmuhle 236	hwiraulic mining xx 1172 mortars 164, 165 on grade of a sluice 723 riffles 722 timber riffle blocks 721 timber riffle blo
Bolzenmuhle 236	hwiraulic mining xx 1172 mortars 164, 165 on grade of a sluice 723 riffles 722 timber riffle blocks 721 timber riffle blo
Bolzenmuhle 236	hydraulic mining
Bolzenmuhle 236	hwiraulic mining xx 1172 mortars 164, 165 on grade of a sluice 723 riffles 722 timber riffle blocks 721 timber riffle blocks 722 timber riffle blo
Bolzenmuhle 236	hwiraulic mining xx 1172 mortary 164, 165 on grade of a sluice 723 on grade of a sluice 723 timber riffle blocks 721 timber 164 traps (Krupp type type type 164 traps (Krupp type type type type type type type ty
Bolzenmuhle 236	hwiraulic mining xx 1172 mortars 164, 165 on grade of a sluice 723 riffles 722 timber riffle blocks 721 timber riffle blocks 722 timber riffle blo

	Pages 1611-2052, Vol. IV
Breakers, at Mill 144 1771	Breakers general consideration about
attendance in Ontario mili 57	Breakers, general consideration about 47 Giant Rock 22 Griffith type 55 Gyrutory, rapper of adjustment of 59
Austin gyratory breaker 1210 table of sizes, capacities, power speeds weights	Griffith type
table of sizes, capacities, power, speeds, weights, etc	
Bartsch type	Hathaway, C. L. Gyratory56, 57, 58
	Hall type Hathaway, C. L. Gyratory table of sizes, capacities, power, speeds, weights, etc.
bibliography for 55 Blake and Gates compared 52	77 1217
Blake and Gates compared	Houghand 22
chancinge type 20, 59	Hope type Humboldt Dades to 61
Kley, Gates, McCully 55	Hope type 61 Humboldt-Dodge type 1206 Engineering Company. Blake breakers 1205 in coal plant, requirements of
multiple i.w	in coal plant recommend. Blake breakers . 1205
type 57 Brennan and Young 21 Colorado Iron Works 23 dupley breaker 21	2(87)
Colorado Iron Works 23	Garner I
duplex breaker 21	Kennedy gyratory 1213 table of sizes, capacities, power, speeds, weights, etc. 1214
Friedrich Krupp Grusonwerk 23	weights, etc. 1214
Fulton Iron Works 22 Gates Iron Works 23	Krom, movement on in Mill 22
Criant Rock 99	Krupp garatana
Hercules rock breaker, Hendy Machine	table of sizes, capacities, power, speeds, weights, etc.
Works Krom's sectional breakers 22 21	
lever pattern 21	rock breaker 1202
Minnesota Iron mine aa	wearing parts for jaw 1221 Lancaster 50 60
Monarch breaker 20 Risdon Iron Works 22	large veryes small
Sectional cuspioned crusher on	
Union Iron Works breaker 21	and of wedfille barts of Farrel Rida at Mail 120 1001
Walburn and Swenson 23	McCully gratory breaker at Mill 139 1222 Lowry national 45
breaking point for 49	fitte
Brennan and Young 21, 59	MCCuity g ratory . 44, 1210
Drinje type Danie 1	manganese steel, self tightening months for 1219
Brown's 56 58, 59	
Buchanan type 59 61	table of sizes, capacities, power, speeds,
50	Marsdon from broad on
universal type 59 Camroux type 58, 61	tvine to the to the training t
Capacity of 51	
DOWERS, etc.	Monarch (Blake type) 20 Motte's type 20
Carterville Foundry & Machine Works Blake	movements of the
Case laboratory breaker of the Denver Fire Class	multiple jaw type National Drill and Manufacturing Company's Blake breaker
Company 1904	Blake breaker 1203
champion type 58 classification of preliminary 1200	New Century Blake
Codiman type 50 4.1	number used
Cole type 50 4.1	Phelps type 59 power, cost, Capacity, and weight 52
table of the decision of the d	
Comparison of 67	rustin from Works . 22
between different types of A.R. Paul 2019	Royal type · · · · · · · 13
compound 51	run by hydraulic power
cost of crushing by	Kutter 45
running	at Days Dalay 1202
Denver Engineering Works Company Blake 1203 Company Blake Table of sizes, capacities,	table of sizes, capacities, power, speeds, weights,
	Schranz .31, 57, 60
Douge type	sectional Krom's 31, 57, 60 section of Krom's standard 31 size and share of month
Dragon type	
dublex	Monarch Product 1218
Dycknoil type 57	speed, capacity, and power 53
effect of corrugations on 52 essentials of 49	spindle having largest movement on largest
excelsior type	
Parrel Blake Table of comments	or gyratory type
fine cru bing his	
Porster type 95 57 co	Olurie ani-1000 de type broukers toor
Endered 1 177 1 55	weights etc.
Carlie and Works 22	weights, etc
Gates 36	breaker 1205
action of 20	Taft type
cast-iron head center for gyratory 1220	Taylor hand
guillock angainese steel mantles for gyratory 1220 Gates Iron Works 23 style "K" 1207	tests of
style "K" 1207	I nion Iron Works
and, or sines, capacities, power, specis,	water used
table of details of 38	wearing parts for 48
with short head and concaves 1909	Western Wheelad Sanaran C
table of sizes and capacities 1209	Wolf's Scraper Company 25 Wolf's 56, 58
13	Won's
20	

,	,
Breaking before stamping in California 1619	Bromilow magnetic separator836, 2027
by hammers 9	Bromine, atomic weight of
cost of	Bromyrite, specific gravity of
at Mill 162 1222	
crushing, communiting . 8 details of cost 51	
for hand picking 1435	Brooke, feeding Ball mills
general considerations about . 47	Brooke, H. J. Best size of feed for ball mill 1323
hand and machine compared 12, 56 pieces for breakers 2009	Brookited Mining Co
Breast water wheels	Brooklyn Chrome Steel Works 183
Breccia, andesitic, crushed at Florence, Colorado Breckenridge, Colorado, ore crushed in Griffin mill . 284	Broom for amalgamated plates 758, 760 buddles 705, 707
Breinigerberg mill, jigs in 597	canyas tables 701, 702
mine, jig eccentrics at . 532	German sweeping table
Brennan and Young 1055 breaker	Brough, B. H. Concentration at Svarto, Sweden 1185 magnetic concentration plants in Sweden 1179
Blake type	Wenstrom separator and plant at Svarto, Sweden 834
Blake type 21 Brewer, W. M. Log washer plant in Alabama 1180	Broughton Ashestos Company magnet, the 1532
settling in liquids 1183 spray rule for frommel 385	Brown & Sharpe
Brewster, New York, mill at . 1180	
Briart bar screen 346, 384, 386	breaker 45
movable grizzly bars 380	
Brick and stone for mills 1088 Bridgman, H. L. Bridgman mechanical samplers 884	R G Details regarding Frenier sand pumps 1587
sampler 2032	Property of the Property of th
Bring, G. G. Action of sands in classifiers and jigs 2020	
study of jigs 1465	3 spindle breaker 56, 58, 59
Bringe's breaker . 58	Browne hydrometric conical sizer 409
Brink & Hubner disintegrator . 236, 284 bibliography for . 298	l sizing of products of 410 Brownell Frue vanner 2023
capacity of, at Mannheim 280	vanner helt 647
Brinsmade, & B. Concentration in Southwest Mis	Browning crane hoist at Mill 165 1852
Souri 2041 description of marble working machinery 2027	stamps at Providence mill Nevada City Cali-
pyrite milling in New York 2037	forma . 230
the Combination Mountain mill, Montana 204;	Prucite, specific gravity of 1189
mill of the North American Lead Company, Missouri 2042	Bruckner balt mill 233, 260 2 bibliography for 293
Union mill, Gratz, Kentucky 2038	8 Brunswick mill, wear of amalgamating pans 249
Briquetting iron concentrates 105	Brunton belt table 698
ore 1055 Britannia Beach Hancock ug at 144	1 revolving furnace 1082
Copper Company, B C, the mill of the,	Brunton, D. W. concentration by free settling 475
R Stokes 2040	
amalgamated plates in . 748	3 rock house 485 5 roll shims 74
amalgamation in 769	8 sampler 847, 1572, 2032
British Columbia, concentration at R Bell 203-	4 requisites to accuracy when using 1575 sampling 850, 884
concentration in the Kootenay district E R Workes 203	4 Brush for dressing amalgamated plates 756, 760
dredging in 1009	Brussels carpet in sluices 1008, 1012
history of mining in H M Lamb 2033 hydraulic minings in 2033	5 tor tables 703 3 on tables 750
jugging five minerals in 59	Bruyn shine separator 2020
nulling at Roseberry A W Dver 2033	5 Bryan mills at Mill 173 1879, 1928, 1929, 1930 4 bibliography for 295
mills 203- notes on L. Jordan 203	4 bibliography for
milling at the Slocan district S. S. Fowler 203-	I in Cananea for regrinding 2016
ore dressing in the Slocan district P Argall 204: British imperial wire gauge 1198	
British imperial wire gauge 1193 Brittain, D. Milling the sheet ore at Jophn 2039	product 1310
Brittleness of minerals, effect of	2 pulp from . 1317
under crushing force 161 use of made, in mills 89	
Brodie breiker 60	Huntington mill . 273
Broken Hill, Collom pg at 518	rolls F P Probert . 1323
at F. I. Greenway 2040) Bryan roller mill 234, 271
concentration of lead ore at V. F. S. Low 2037, 2039	s quartz mill, dimensions of 272
cost of producing lead and silver at 1964, 1965	5 Bryant, W. G. Discussion of design of Blake 2 breakers 1201
DeBayay flotation process at 1562 Hancock jig at 50-	Buchal, L. Pointed boxes at Przibram . 478
iigs at 64	3 rope driver for stamps at Przibram 229
metallurgy at 1560 milling practice G Delprat 2003	
R Stokes 204	6 at mills 1818, 1891, 1913
milling practice 2039, 204	7 table of movements of old . 23
mills at 1136, 118; ore dressing at G D Delprat 192;	2 C G Magnetic concentration1178 3 granulator59
Potter and Delprat flotation processes at . 156.	magnetic separator 803, 2028
Proprietary Company, report of the 2043	s rock breaker . 23
separation of galena sphalerite ores at 161	1 of Blake type
steam stamps at 14	2 rolls at mills
water used at 110	4 universal breaker b9
Broken ore, weight of	r marker. A. on Suvermanilly
	14

Pages 1199-1610, Vol. III.	L	NDEX.	Pages 1611-20	052, Vol.
Bucket conveyor dredge dredge elevators sample Buckets, elevator, materials for for elevators Buckey engine Bucking board King's samples Buckstaves for gravity stamps Buckstaves for gravity stamps Buckstaves for connected tyre	29	0 Butte Monto	na, ores, sizing tests on n Works	
elevators	1008, 101	1 Reduction	n Works	• • • • • • • • • • • • • • • • • • • •
sample	86	2 mills		
Buckets, elevator, materials for	86	Wililey	table at	AAVII,
Puckeya engine	86	distributors	table at Mem pulp distributor at Mill at Mill 106 (ugal pumps at miles 1671)	117
Bucking board	110, 920, 94	1 Butters centri	at Mill 106 fugal pumps at mills 1671, 1	000
King's	113	7 Butters, Chas	tugal pumps at mills 1671, 1 Coagulation, concentration ing of slimes ing at El Oro on sampling ling tests on sands	672, 1674,
samples .	1285, 132,	tli	ng of slimes	i, and set-
duckskin for squeezing amalgam	. 78	cyanidi tomore	ng at El Oro	1924,
Successives for gravity stamps	15	re-grin	on sampling ling tests on sands	
Buddle iig	1011, 1653	rules fo	r sampling c tube mill experiences in El s at Mill 101	
Buddle jig	1054		e tube mill experiences in Fl.	Oro
Buddles	685, 704	filter boxe	e tube mill experiences in El- is at Mill 101	
bilbiography for building	727	, part trim	ography or	
convex Cornish, at Mill 185	1464, 1507	Vacuum fi	lter boxes at Mill 100	
Dodd . rectangular	1916	Buttgenbach,	argamating pan lter boxes at Mill 102 P Glass jig ng jigs	!
rectangular round concave	1481 706	On testi	ng jigs	: : i
round concave	706	Buttgenbach's	Classifier	
convex tye	704	hydraulic	(Lissifiers	
uffalo Hump Mining Co mill	707	Schurator	(elimetross)	
Suffalo Hump Mining Co., mill Tiger and Poorman Branch mill	. 954	Byron Jackson	centrifugal pumps at Mill 10	3 1639 17
uffer for feeding gravity stamps	77/i 199			1662, 1
ing gold ore School laboratory work, a free	e mill		a	, -
ouffer for feeding gravity stamps ugbec, E. E. School laboratory work, a fre- ing gold ore uhrstone mill	2048		С	
Dibliography for	232, 252 291	Cabarceno, Sp.	in, mill at	•
tureus Caste	291 297			
uilding buddles . tables	1464, 1507	Cactus mill, No L A Cadmium amal	whouse, Utah	. 19
uildings, construction of	085, 704	Cadmium amai	ramer con	20
	1088	atomic wei	ght of	
alkley condenser	1086, 1087	atomic wei	vi'v of	. 11
				ii
allion Beck and Champion Mining Company	y mill xxvi.	districts	irt Treatment of gold ores	in dry
illion contents of amalgam	926	Caetam, G (omparison of stamps and I	. 14
uneness of	783 763, 785			lunting-
ill pgs at Mill 121	1685	definition o	f slime	. 13
imping ore feeder tables	051	Calamine mill	aher pg at Mill 120	14
amalgamated plate on 667.	1464, 1497	Specific gray	uts of	17
Bartsch	740	Calcining for fri	ability	11
compared	691 682	Ammel	erg, Sweden h Carolina	
depth of bed	1510	in North	h Carolina	•
details of in the mills end-bump tables	682	for magnetis	without quenching with water	er .
Hendy concentrator	680	Calcite, angle of	Bits record od to comb	. 15
Hendy concentrator principle of	683	· · · · · · · · · · · · · · · · · · ·	1 (1)	. 8
nker Hill and Sullivan mill 937, 1183, 1	1680 2041	Calcumate grav	ity of	118
rdon I A Brunt - I Depart of the Company n	nill xxvi	Calcium, atomic	weight of eavy solution for testing	118
gan classifier. The A. I.	728			199
Mining and Contentrating Company n Mining and Concentrating Company n glan classifier, The A. L. ke, Idaho, null at 4ap filter	1371	Calculation for p	pebble charge in tube mills, for P Scholl	81
lap filter	954 879	for G	P Scholl	201
for filtering dust	883	magnets	•	401, 42
tol merring dust tables on dredges lingame, E. E. figures on sampling rules for sampling nett and Newbegin coal washer t, E. delinition of shops	1012	middlings	into finished products	79
rules for sampling	852	settling tar	iks and S. H. Pearce	. 116
nett and Newbegin coal washer	848 2018	Caldecott, W 1	and S. H. Pearce	45- 129:
t, E, definition of slime	2018 1397	colloidall.	enciency of tube mills	132
milling at El Oro	2013	conoidal sihe	emolency of tube mills ic acid in slimes	1619
filter presses at Mill 118	2046	definition of	grinding	201
thiter presses at Mill 118 the, P. L. Gravity stamps	1678	discussion of	tine grinding	1398, 1399
silver milling in the United States	$\frac{224}{1176}$	lime in settln	ng slimes in South Africa	2014 1178
Variety Data	291	nse of loss	grinding in South Africa	
silver milling in the United States Varney pan patent Lubrig slimer slime table — E. Walker tables at Mill 185 and Boston Consolidated Mining Companies	1496	Caldwell, H. W.	stimong in South Africa I slime settling & Son Company Drag of	1410
tables at Mill 185	2022	conveyors	Cana Company Drag of	r disc 1583
e and Boston Consolidated Mining Companie mill, cost of the etc. at	1915 ps 1920	helicoid conv	vor	1583 1582
mill, cost of due etc. at	es 1836 121	SCIEW CONVEYO	ır	. 1582
	281	Caledonia mili		. 183
Mining Company, mill Reduction Works, test	xvi, 976	comparison	of Gates' and DI-1 . 1	783
Reduction Works, test on ore at concentration at. C W Good cost of milling at	674	details of se	of Gates' and Blake breaker reen in .	`n 54
rost of milling at	iaie 2035	dies used in		170 180
nammers used	1130			165
mprovement in concentration at. A H Wetl ig losses at aunders at nills at	hey 2036			. 785
aunders at	640	loss in melt mortar	ing at .	784
nills at . 976 078 000 007	875	mouth		228
re drossing at C 33 000, 302, 301, 1119, 11	75, 1176			167 164, 165
res, concentration of. C. W. Goodale crushed by rolls	1419 2042	rate of crus	hing in	165
crushed by rolls by steam stamps	110	running Losi	in	54
of steam stamps	:44	screen frame		177
	135	weight of as	amps and mortars	111

Pages 1-643, Vol. I.	ORE L	RESSING.	Pages 644-1197, Vol.
Calico, California, amalgamating pan at	290	"Camel Brand" ele	vator belting at Mill 175 1
California, chromite mill in concentration of auriferious sulphides in	1074	Cameron pump	872, 676, 680, 2022, 2
cost of gold milling in producing gold in	1131	Campoen coar wasn	ing table. C. R. Claghorn. 2
producing gold in	1977		
dredging in gold milling in Nevada county. H. F. I	. 1009 Brown 2043	Camp Bird mill Ouray, Colo T. H. Woo	E T C
gold mills in	7, 1178, 1181	T. H. Woo	S. L. Goodale
gold mills, modern practice in .	1619	Camroux breaker	
gravity stamps	138	Cams	
milling practice at Hedges mill, number and height of drops in	2044	Bally balanced	han 18 41-124-11-
mills in	1182	Boss cam key	her self-tightening
number of pulverizers in silver mill, Nevada	. 231	Canda came for	remaite etamou 1
silver mill, Nevada .	. 1174	de€gn of	
stamp mili	. 114, 2043 . 225, 230	decgn of for gravity stam friction and lub	ps rication of
m	226, 229		s and clearances
origin of	. 2012	lateral thrust of	
versus Colorado and steam stamps . Colorado stamp mills 2	134	right and left ha	ınd
suggestion for milling of gold ores N. H	15, 220, 1930 Storms 2034	self-tightening stamp mill cam	. 2
system	224, 227	table of details	of 2
of stamp milling .	1030	Canada, chromite m	ıll in . 1
diper, Snyder micrometer illon, J — Comparison of different crushing m	1362, 1366	Corundum Co,	mill 1078, 1
Engis machine and Krom jig	achines 315 837	Consolidated Co	on at D E Woodbridge 19
Engis, Thirion, and Dorr hydraulic cla	issiliers.	DOWER IES	ds at 1
Siphon separator	. 475	Sonora, I	Mexico, mill of the O-P. Finley 2 D-E Woodbridge 1 ker at Mill 151 1
gravity stamps hammers and breakers	223 55	ere dressing at	D E Woodbridge 1
jaw breaker	55 55	Carly dust separate	ker at Mill 151 12 r at Mill 151 13
lectures on mining	x1x	Canhy dust separato R C, separatio	n of mixed sulphides 1
mill schemes	1173	Sulton Steele	dielectric separators 2
movable sieve hand and machine jigs, Ha percussion tables, buddles, slime table	rzjigs 639	process . Canda cams	
kieves	727	at Mill 143	
rolls and stamps	109	stamb mill cam	2
sieve scale, trommels	. 384	steel jaw plates	for Blake breakers at Mill 139 Tob
value of hand picking illow cones	. 492 1402	at Mill II	ofi nnesota, washing iron ores in 1
at mills 163	2, 1660, 1687	Cannon ball malls n	uniter used
computation for	1404	Cañon, Arizona, gas-	oline engines at Billings at B
on Cœur d'Alenc galena slimes	1404	Cantilever crane at '	Mill 171 for removing tailings 13
test on Butte copper shines J. M. Callow traveling belt screen	. 1404 2018	Mahadda Iran	s on dredges 1
thoughout of mall many Callon may be	90.20	Canvas belt tables	Company, iron balls for jig beds 1
pulp thickening and setting tanks at Mil screens at mills 1661, 1662, 1684, 1685 1726, 1738, 1760, 178	1 114 1662	belts	10
screens at mills 1661, 1662, 1684, 1685	7, 1689 1725,	conveyor belt, L elevator belt at	eyiathan 1
Capacity of to various meshes	1360 (1833) 1360	elevator belt at	Mill 125
water in feed to	1360	plant 1017, 10	nalgam 021, 1029, 1035, 1037, 1038, 1101, 1
	9, 1711, 1712	at Garnet, Me	ontana P S Mussigbrod 20
slime and water cones	1367 2, 1687, 1689	cost of	1
sloughing off tanks at mills 1662 system of ore concentration J M Call	a, 1057, 1059 ou 2045	failure of results at Mill	. 101
tanks	1420, 2020	test	1
at mills 1683, 1684, 1846, 1848, 1851	, 1852, 1867,	shield for stamp	5 .
saying effected at Mill 163	1898	surface for slime	tables
traveling belt screen	1358	sweeps for budd tables	
traveling belt screen J. M. Callow	2015	at mills	1696, 1755, 1
alumet and Hecla, jigs at. (See also Mi	ll 177)	bibliography f	
mill 1	1440, 1446 42, 990, 1184	details of, in r	nills 1
Huntington mill in	. 281	new Dimmick	patent slime table
Krause stamp	. 141	on dredges .	1
mortar Lousing lining for stamp	120	vanner belt	\ \
Steam Stamps Mining Company	120 141, 1891	Capacities and smad	r vanner belts s of picking tables and belts 1
copper handbook	1925	of Abbé tube m	ills at Mill 1011
mill	. xvvii . 259	air classifiers	
sizing tests in sand wheel	. 259	Akron Chili r	nills, table of 1 s rolls at Mill 179 1
tero Chib mills at Mill 177	1893, 1894	Aurs-Chaimer suspended i	rame vanners
classifier at Mill 166	391	toothed and	corrugated rolls, table of 13
at Mill 166	1855	Alsing cylinde	rs
Michigan, mill at mill	. 990 1892	amalgamating	pans cess Company's driers
or Richards-Coggin classifier	. 1367	Anerican 170	cess Company's driers
or Richards-Coggin classifier tables at Mill 177	1894	aliasuas	
am and gravity for jig mechanism	506, 537	Atwood amalg	zamators
in Stutz jigs and spring jig mechanism	507 527	Austin gyrato	ry breakers, table of 1
shaft for gravity stamps	507, 537 190	ball mills at Mill 159	
Krupp	1272	Ball-Norton 1	elt type separator at Mill 158 . 1
Krupp spring and bumping post for tables	680	magnetic sc	parators 1
mechanism stick	. 667	magnets Bartlett picki	
		eimpler cor	ng tables 1
template			

,	24800 1011 2002, 101. 11.
Capacities of Bartsch rotary percussion table 1497 belt conveyors at mills 1667, 1670, 1681, 1690, 1691, 1707, 1708, 1709, 1771, 1772, 1828	Capacities of Edison driers
1691, 1707, 1708, 1709, 1771, 1772, 1828 percussion table	elevator at mills 1661, 1663, 1667, 1685, 1690,
Bilharz jigs 504, 518	1707, 1727, 1728, 1729, 1749, 1750, 1752, 1753, 1755, 1771, 1772, 1774, 1829, 1842, 1843, 1844,
tables 504 Blake breaker at mills 1618, 1621, 1742, 1749,	magnetic separators 813 elevator at mills 1661, 1663, 1667, 1685, 1690, 1707, 1727, 1728, 1729, 1749, 1750, 1752, 1753, 1755, 1771, 1772, 1774, 1829, 1842, 1843, 1844, 1845, 1846, 1847, 1853, 1854, 1877, 1850, 1898 Ellenbecker bumping tables 681
Blake breaker at mills 1618, 1621, 1742, 1749, 1769, 1792, 1802, 1853 breakers	Elmore vacuum oil process 1558
Diake-Morscher electrical ore separator 1991	Eureka rubbers
blende jigs of Southwest Missouri 602	Evans classifiers 395 slime tables at Mill 177 1893 Farrel Blake breakers, table of 1200 Farrel Blake breakers, table of 1200
Bogardus mills. 260 Boggs and Clark centrifugal pump at Mill 141-1761	Faust jigs 548 Ferraris ball mill 1300
boilers 1091	belt tables . 698
box classifiers	classifiers 401 patent tables, table of 1490
at Mill 144	fixed screens 341
Brink and Hubner disintegrators 286	flotation vats at Mill 129 1718 Forsgen's electromagnetic separator 1539
Browne hydrometric conical sizers 410 Browning crane hoist at Mill 165 1852 Bryan mills 272, 273	Forster breakers 28 Frayer centrifugal pump at Mill 159 1829
Bryan mills 272, 273 at Mill 173 1879	Frayer centrifugal pump at Mill 159 1829 Fremer spiral sand pump 871 Frisbee Lucop mills 267
Buchanten magnetic separators 803	Frue vanners at mills 1662, 1694, 1695, 1711, 1712.
bucket conveyors	furnaces roasting for magnetism . 1755, 1880 Code and M. Colle languages . 814, 815
Bucyrus dredge . 1654 buhrstone mills . 253	furnaces roasting for magnetism 814, 815 Gates and McCully breakers 45 ball mills, table of 1301
Butters' centrifugal pump at mills 1671, 1672,	Gates breaker on "choke crushing" 48
Buttgenbach's separator	breakers 38, 46 at mill, 1635, 1661, 1706, 1710, 1727, 1728, 1853
Byron Jackson centrifugal pumps at mills 1662, 1673	breaker with short head and concaves, table of 1209 style "K" breaker, table of 1208
calcining furnace at Friedrichssegen . 1546 Callow conical tanks at Mill 122 . 1687	Georgiaer Suizer centritugai pumps at 3141 118 1678
screens at mills 1661, 1662, 1687, 1795	German sweeping tables 703 Geyer slime settlers 460 G. G. Gates classifier 418
to various sizes 1360 sloughing-off tanks at Mill 122 1687	G. G. Gates classifier 418 Gilpin county bumping tables 681
Calumet and Hecla type Chili mills at Mill 177 1893 classifiers 401	Golden Gate tables 681
	Gould centrifugal pump at Mill 139 1757 gravity stamps 148
tables	Griffin centrifugal stamp mills 269 mills at Mill 105 1636
Carr disintegrators 285 Castchiau belt tables 700	roller mill 284
centrifugal pumps 869 at mills 1688, 1694, 1695, 1696, 1721, 1880,	Grill four compartment driers 1596 grinding pans at Mill 105 1638
1890, 1904, 1905	Groudd magnetic separators 1537 Hadfield gyratory breakers at Mill 130 1719
Challenge feeders at Mill 174 1883 Chile mills 269, 270	Hallett table 676
at Mill 179 1898	at Mill 127 1710
chip screens at Mill 173 1879 clarifying reservoirs 460 tanks at Mill 138 1743, 1744	on Montana copper ores 1442 hand jigs 499
Clarkson Stanfield centrifugal separators 820	Hardinge tube mills 1296 Harz jigs at mills 1772, 1773, 1774, 1775, 1877,
Carsiners 400, 400, 402	1878, 1879
clay washers 1076	Hathaway gyratogy breakers, table of 1217 Heberli magnetic separators 799
Cleveland Knowles magnetic separators 1542 cobbing magnets at Mill 164	mills 257, 259 wet magnetic separators . 810
Cobbing magnets at Mill 164	Heberwasche
cone mills . 256	Hochstedt apparatus 817 Hodge and Cleaves sand pumps at Mill 182 1910.
control trommels at Mill 180 1902 Conkling jigs 503	Hodge and Cleaves sand pumps at Mill 182 1910, 1911
convex buddles . 705	jigs at Mill 180
conveying belts at various mills 1585	Vanning ngs 505
crushing machinery 2010 Cummings granulating mills 255	Huntington mills 280, 281 at mills 1669, 1686, 1687, 1694, 1701, 1711, 1753, 1869, 1897
Cyclone beaters at Mill 186 1917, 1918 Cyclone dust settlers at Mill 105 1637	with various screens 1753, 1869, 1897
pulverizers 289	Husband pneumatic stamps 141
decrepitating furnaces 829 Dellvik-Grondal magnetic separators 804 Denver Engineering Works Company's Blake	Imperial screens, table of 1350 International magnetic separator 1535
Denver Engineering Works Company's Blake breakers, table of 1204	James slimer 1492 Jeffreg swing hammer pulverizers, table of 1322
dewatering wheel at mills 1772 1773 1878 1879	jigs 507, 596, 597, 599
at Mill 140 1759	at mills 1685, 1686, 1692, 1693, 1694, 1707, 1708,
	1909 Johnston vanners
Dodge breakers 30 pulverizers 262	at Mill 117
double cone classifiers . 427	Kent roller mills 1304
drag or disc conveyors	King screens 1357 Knowles duplex vacuum pumps at Mill 117 1673
driers 880, 882 drying floors versus mechanical driers 1596	New Century magnetic separators, table of 1542 triplex pump at Mill 114 1674

,	, , , , , , , , , , , , , , , , , , , ,
ities of Krause pneumatic stamps 141	Capacities of Scoby sampler at Mill 173 1880
Krom air jugs 824 Krupp gyratory breakers, table of 1215 Laboratory Willity tables 1991 Lake Superior bog trough classifiers 300	scraping conveyor at Mill 114 1662 screw conveyors, table of 1583
Krupp gyrafory breakers, table of 1215	screw conveyors, table of
Lake Superior hog trough classifiers	settlers 778 settling tanks 455 shaking feeders at Mill 124 1690 grzz/y at Mill 124 1690 s.reens 342, 345 Sherman re grinders at Mill 132 1728, 1729 Siemens and Halske magnetic separators 790
Langley's dry crushers	shaking feeders at Mill 124 1691
La Point flour gold separators, table of, 1510	grizzly at Mill 124 1690
La Point flour gold separators, table of 1510 Latta and Martin pumps at Mill 144 1779	screens 342, 345
Launders . 875, 878	Sherman re grinders at Mill 132 . 1728, 1729
Linkenoach pointed toxes 412, 441	Siemens and Halske magnetic separators . 799
\(\text{hox classifiers} \\ \text{log washers} \\ \text{321} \\ \text{324} \\ \text{324} \\ \text{324} \\ \text{324} \end{array}	
og washers 321, 324 Jacquisten tubes . 1565	simple steam stamps at Mill 182
agnetic separators at Monteponi	slime tables 697
Przibram . 812	Shitzkasten at Mill 173 1878 1879
fathey roasting furnaces at Mill 148 1793	Spitzkasten at Mill 173 1878, 1879 stamps
day Brothers' jigs at mills 1714, 1720	at mills 1620, 1621, 1624, 1632, 1640, 1661, 1668,
AcCully breakers	1677, 1769, 1915
at Mul 139 . 1749	1077, 1769, 1915 in California
roug stand long from table of	increasing the 2012
gyratory breakers, table of 1212 leipecke spitzlutten 425	on different size of feed 2012 steam hammer 12
deinceke spitzlutten	
spalling	on ore of Mill 48, table of 130
nill bins 842	
ills . xxv, 1100	Stein, Bilharz, and Luhrig tables 670
in reserve . 1109	Stroug mus, tables of 1320, 1321
See Individual Mills in Chapter XX.	Sturtevant, Dodge type, breakers, table of emery null at Mill 186 1918
Jonadnock Chili mills at Mill 144 . 1775 Jorris centrifugal pump at Mill 139 . 1757	emery mill at Mill 186 1918 fan at Mill 105 . 1637
Iorris centrifugal pump at Mill 139 1757 Iumford & Moodie dry separators 818	fan at Mill 105 . 1637 mills . 288
iarod pulverizers 282	roll jaw breakers
ewaygo separators with various sizes of	rotary breakers at Mill 186 1917
screens 1351	Sutton, Steele & Steele dry table 1555
ew Humboldt concentrator . 1494	pneumatic separators at Mili 151 1803
ew Standard concentrator	Tamarack classifiers 397, 398
hssen stamps at Mill 165 1264 lordberg stamp at Mill 179 1897	Traylor centrifugal pumps . 1588 at Mill 114 1662
steam stamps 997	jigs at Mill 169 1864
steeple compound steam stamp at mills 1894,	Trego roasting furnace . 1548
1895, 1901	Tremain steam stamp 138
verstrom tables at mills 1711, 1730	tronmels 359, 377
Oxland furnace at Mill 137 1549	at mills 1681, 1682, 1690, 1694, 1692, 1693, 1742,
pe Henneberg dry separators 820	1743, 1749, 1750, 1751, 1752, 1771, 1772, 1773,
tarsons & Fisher jigs . 518 tables . 669	1774, 1876, 1877
vne magnetic separators 800	trough washers 319 tube mills 1291
erserverance furnaces at Mill 105 1637	at mills 1632, 1770, 1922
icenty atmospheric stamps	Tustin's mill 262
serce amalgamator . 1517	Tustin's mill 262 Ulliub magnetic separator 1535 vanners 648, 658, 659, 662, 1110 and slime tables compared 691
lling air hoists, table of . 1609	vanners 648, 658, 659, 662, 1110
dp thickeners at Mill 173 1880	
dvenzers 232, 326 imps 872	at mills 1687, 1778 washing pans 333
ctangular buddles 707	washing pars wash frommels 330, 332
volving kmfe buddles 329	Wengler & Lowe's classitier 413
iblet aerial tramway at Mill 124 . 1696	Wenstrom magnetic separator 801, 802
ichards' annular classifiers 406	Wetherill magnetic separators 805, 807, 808, 1522.
at Mill 127 1710	1592
-Coggin classifiers 392, 393 at Mill 173 1878, 1879	-Roward magnetic separators at Mill 141 . 1763 Whelpley & Storer pulverizer . 289
at Mill 173 hydraulic classifier at Mill 159 1878, 1879 1829	Whelpley & Storer pulverizer
pulsator classifier table of 1300	Wilder mills, table of 1304 Wildey roasting furnace 1548
jug, table of 1455	at Mill 140 , , , 1759
vortex classifiers at mills 1692, 1693, 1694, 1774,	slimer 1505, 1506
1776 1778	
	at mills 1633, 1661, 1662, 1669, 1687, 1694, 1699, 1715, 1729, 1744, 1745, 1776, 1777, 1829, 1830, 1880, 1894, 1904, 1908 Woodburk Benedict jigs at Mill 177 1892, 1893
gd rolls at Mill 181 1906	1695, 1715, 1729, 1744, 1745, 1776, 1777,
tringer Spiiskasien 440	1829, 1830, 1880, 1894, 1904, 1908
tables 668 astroy furnace at Mill 138 1747	Woodbury for compared with that of Collec-
asting furnace at Mill 138 obins belt conveyors at mills 1636, 1750, 1876	Woodbury jig compared with that of Collom and Evans jigs 1448
conveying and picking belts at Mill 132 1727	tables 676, 1496
ck emery mills 255	at Mill 117 1669
11	Worthington centrifugal pump at Mill 138 1745
lls 64, 100, 1226	pump at Mill 175 1890
at mills 1667, 1686, 1714, 1727, 1743 1749, 1750,	
at mills 1667, 1686, 1714, 1727, 1743-1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854,	on the Rand, by addition of tube mills, increase of 2015
at mills 1667, 1686, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879	on the Rand, by addition of tube mills, increase of 2015
at mills 1667, 1686, 1714, 1727, 1743, 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879 diagram of 1228	on the Rand, by addition of tube mills, increase of 2015 large increase of 2013
at milk 1667, 1680, 1714, 1727, 1713 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879 diagram of 1228 tary driers at Mill 186 1917	on the Rand, by addition of tube mills, increase of 2015 large increase of 2013
at milk 1607, 1680, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, diagram of tarv driers at Mill 186 1917, and tables at mils 1904, 1905, 1908	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process . 1560, 1561. See also each machine
at mills 1667, 1686, 1714, 1727, 1743, 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1875, 1879, 187	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process . 1560, 1561. See also each machine
at mills 1607, 1686, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879 1879 1879 1879 1879 1879 1879 1879	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process 1560, 1561 See also each machine Capacity, effect on cost Care Colomy, tin mining in. H. D. Griffiths 2035
at mills 1607, 1686, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process 1500, 1561 See also each machine Capacity, effect on cost Cape Colony, un mining in. H. D. Griffiths 2035 Capel mine 905
at mills 1607, 1686, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879 diagram of 1228 tary driers at Mill 186 1914, 1905, 1908 und tables at mills 1904, 1905, 1908 unson breakers, table of mills 1904, 1905, 1908, at mills 1908, 1668, 1669, 1894 formula for 1586	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process aration process. 1560, 1561 See also each machine Capacity, effect on cost. 1127 Cape Colomy, in mining in. L. D. Griffiths 2035 Capel mine. 905 Capelton, Canada, mill at 267 Capital Mining and Tunnel Company, mill of 1659 Capital Mining and Tunnel Company, mill of 1659
at mills 1667, 1686, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879 diagram of 1228 stary driers at Mill 186 1917 und tables at mills 1904, 1905, 1908 und tables at mills 1904, 1905, 1908 und wheels 865, 866 at mills 1668, 1669, 1894 formula for futter magnetic separators 788	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process . 1560, 1561 See also each machine Capacity, effect on cost . 1127 Cape Colomy, in mining in. H. D. Griffiths . 2035 Capel mine . 905 Capelton, Canada, mill at . 2034 Capital Mining and Tunnel Company, mill of . 1659
at mills 1667, 1686, 1714, 1727, 1743 1749, 1750, 1751, 1771, 1773, 1774, 1792, 1793, 1829, 1854, 1877, 1879 diagram of 1228 totary driers at mills 186 1904, 1905, 1908 amon breakers, table of at mills 1904, 1905, 1908 at mills 1904, 1905, 1908, 1904 wheels 1906, 1806,	on the Rand, by addition of tube mills, increase of 2015 large increase of treated by Catermole process, or minerals separation process 1560, 1561 See also each machine Capacity, effect on cost Cape Colony, un mining in. H. D. Griffiths 2035 Capel mine 905 Capelton, Canada, mill at 905 Capital Mining and Tunnel Company, mill of 1659

Pages 1199-1610, Vol. III.	INL	DEX.	Pages 1611-2052,	Vol. IV.
Carbon added to roast at Mill 137	. 1549	Cement surf	ace on Linkenbach slime table	690
atomic weight ofeffect of, in roasting for magnetism	. 1188	Center disch	arge for jigs	582
effect of, in roasting for magnetism	. 1544	Centimeter,	equivalents of	1187
Carbonate mine, Paddock jig at Carcanagues. Cornish buddles, frames, and kieve	822	Central City	arge for jigs equivalents of , screens amalgamating pans ompany mill North Star Mines Company to Packer Argelles	172
Carcanagues. Cornish buddles, frames, and kieve	5 728	cone of	amalgamating pans	241
tin dressing in Cornwall	1176	Lead C	ompany mill	. xxv, 917
Card concentrator 148	1, 2023 632	MIII OI	North Star Mines Company	1617
of pg work	657			
Nanners Tables at mills Care of belts journals mercury mills	7. 1830	Centrifugal	concentrator, Peck	1719, 1735
Care of belts	1093	dust col	lector	883
iournals .	1097	SCDAL	itor	000
mercury .	785	force	m magnets separation adv concentrator nutrigiton mill ood pulverizer if wheels nucls attential to the separation of the separation tion by ade of in mills tractor for oil process, for separating oil from concentrat	1611
mills Carey mill, bibliography for pulverizing mill	1114	ın drı	im magnets	798, 799
Carey mill, bibliography for	292	dry	separation .	. 818
pulverizing mill	232	He	ndy concentrator .	683
Caribou rifle	1509	liju	ntington mill .	278
for black sands. F. Powell Caramban, mill in Carkeek classifier James, classifier hydraulic classifier jig beds slope of launders Carlisle stamp mill	2027	Na	rod pulverizer	. 282
Carlonia, min in	. 1100	San	ii wheels	866
Limos disenter	416	ton.	nners 34,	7, 350, 373
hadranha dissifier 416 4	76 477	acpara	ide of in mills	. 827
not beds	595	hydro-e	etractor for oil process	. 890
slope of Lunders 87	4 875	machine	for separating oil from concentrat	in
Carlisle stamp mill	1180	Elmo	e vacuum oil process	1558
Carnall wash trommel	334	pumps		868
Carn Dochan mill, dry concentration at	838	at mi	ls 1688, 1694, 1695, 1696, 1711, 1	1712 1721
	820	175	6, 1757, 1856, 1880, 1881, 1890, 1	899. 1904
Carpenter shop for mill	1087			1905
Carpet tables 703, 750, 1035, 146	4, 1507	for hy	draulicking	1006
Carr disintegrator . 23	36, 284	san	d and water, used for elevating mill	pulp 870
bibliography for	298	rolls		74
Carpenter shop for mill Carpet tables Card staticgator Dibliographs for table to details of Carr, M., Carr dismitegrator F., Carr dismitegrator Carreds, J. T. Carreds, J. Carreds,	285	Sturte	vant	1237
Carr, V., Carr distinguator for flour	908	Trayl	or tribution	. 1588
Correl 1 T	1178	pump		1602
Carrier for conveyor belt, self-oiling	1585	Separatio		1588 839
Carroll, Montana, mill at	984	Separato		827
Carrying conveyors	1585	a dry	T Henrotte	2025
current in jigs	494		son Stantield	820
power of water current	477	theory	of separation on the L Kleritz	2020
Cars	843		lunger pumps	868
for concentrates	1112	Centripact so	reens	1360
weighing of	1160	at Mil	1 169	1865
Carter auto-magnetic separator	2029 789	Traylo		1352
1 L amalgam in the Transvaal Carterville Foundry & Machine Works, The Blak	103		concentration of	1016
breaker	1201	Cerium, aton	gravity of	1189 1188
life of wearing parts	1223		co, Chih mill at	295
Casapalca, Peru, mill at	1180	Prieto n	ill, Sonora, Mexico	2042
Case laboratory breaker	1223	Cerrusite, sp	cific gravity of	1189
of the Denver Fire Clay Company	1204	Chabazite, si	sectic gravity of	1189
Cisings for elevators, etc	1099	Chain and sp	rocket	1096
Cassiles Mine, Australia, milling at the, F. B		magnetic	separator	811
Stephens	2041	Chainman m	ill, Ely, Nevada	2036
	5, 617	Chain plate of	onveyor, picking on	489
settling velocity of 4	66, 469	scraper	or removal of jig tailings	588
Settling velocity of 4 Specific gravity of . Castelnau table	1189 698	Charcoche, h	indered settling test on ".	617
Cast gears	. 1096		relocity of gravity of	466, 469
Cast iron head center for Gates gyratory breakers	1220	Chalcopyete	crushing by rolls	1189 62
morar blocks	148	free sottl	ing velocity	471
specific gravity of	1189	Separatu	on from quartz	720
Castor oil	1097	sizing te		99
Cataract sand pump	868	specific a	gravity of	1189
Catermole flotation process	1555	Chalk used i	n retorts	781
the minerals separation process	1560	Challenge fee	d clutch .	657
Catherine (Australia) mill, wear of shoes and die	s	feeder		853, 1578
ın	183		t Mill 174	1883
Caucasus Copper Company Limited	1860	rock bro	iker	20

specific gravity of Chalk used in retorts Challenge feed clutch feeder feeders at Mill 174 1189 781 657 1578 1883 20 1499 1695 in Caucasus Copper Company, Limited 183 Caucasus Copper Company, Limited mill polarsh, use of on amalgamating plates in California soda for settling slimes Cave springs, Georgia, manganese ore from Cazan, F., advantages of water over air Cazan, Signature of theory of settling theory of settling Cazan's circular jig 641, 645 rock breaker
Chalmers and Wilhams Frue vanners
at Mill 124
Huntington mills at Mill 171 1860 1860 1694, Huntington mills at Mill 171
Kennetly gyratory breaker
1213,
power amalgams squeezer
rolls at Mill 171
Chalmers, estimate of cost of hand picking on the
Rand
J A and F. H. Hatch, gold stamp mills in So.
Africa
Chalon, P. F., crushing machines
stamps
Chamber mill
Chambers for dust
Chamos leather used on amalgamated plates
skin for dressing plates
skin for dressing plates
skin for dressing plates
skin for dressing plates
Skin for heaker
Champton breaker
Copper Company. Copper handbook 1619 1869 1148 809 838 641 640 1213, 1223 1519 1687 476 487 640 Celestic, specific gravity of Cement for surface of slime tables Gravel Drift Mining Company 641, 642, 643 1173 1189 689 211 1017 211 316 227 294 883 752 759 781 58 gravel mill stimped grinders grinding 2016 2017 screening of surface for slime tables 345 69**5** 1925

Champion rolls mill 190	O Chill million and a second
stamp mill 189	7 etc., of Akron Chile mills
spiked rolls for coal 11	
Change house	2 West 1011S for Clay 2010
of magnetism by heat porosity by heat	4 Chilled cast-iron for toothed rolls 2017
	4 Cost of for Brane will bedding at Mill 183 1913
Channels in amalgamating pans 245, 24 Channing, J. Patke, graded crushing at Lake Supe-	cost of, for Bryan mills 272 6 for amalgamating pan dies 245
100	8 well shall 1243
Charcon for mening 78	4 Short and dies too too too
Charge for amalgamating pan 24	
Charleston, Arizona, feeding gravity stamps 20	
Stantes on min	
Charleton, A. G., accounts and reports 117	9 Chism R. F. arrates at S. 760
amargantation 78	9 Chlorin diam 1311 at San Dillias, Mexico 290
breakers 7. 25	0 cost of 1020
breakers versus hand breaking . 6	0 rolls for . 1622
tost sheet forms	
	5 Choctay Coal & Rubers Co. 1188
tin ore at Altenberg, Saxony 1177 gold stamp mills 1186	Choice of trushing machines 912
Huntington mill 99	process . 1161
Libyrinth pointed boxes 470 methods of accounts 1180	Choke crushing by breakers
milling for gold ores at Postarons, Tests and	rolls
amaigamation at Franciort 1182	1000
revolving tables roasting for friability 56	
rolls versus Sturtevant mill and stamps 111	Christensen concentrator
stamps in various parts of the world 220) (brothe fron ore in Analysis
Sturievant null 906	
tin xii	
Charleton classifier 478	Siect for breaker jaws 2010
ore concentrator (classifier) 428 Chase, H. S., cost of milling 1138	roll shells at Mill 158 1822
Cranberry magnetic ores	
magnetite in North Carolina 1176	Patent cams 68
Chase magnetic separator 832, 833, 835 Chetard, F. M. 1149 and Cabell Whitehead, settling of slimes at Re- public gold mine. Wishington	Chromite concentrated by free settling
and Cabell Whitehead, settling of slines at Re-	mill, in Newfoundland
on settling slimes	Newfoundland, sizing tests on 90
Chateaugay from ore concentrated by magnets 202	Chromosom and 1189
59	atomic weight of
ore separated by magnets 700	Chrysolary Letter of 1189
Chaumers and Simonnet, American gold stamp mill- ing	
Uncese scoop sampler	Chuquicamata, Chile, separation by screening of
Chemicals for slime settling, relative values of use of 1414	Church, J. A., amalgamating pans 291 pans at Tombstone 290
in amaigamating pan 249	amalgamation of sold
used on amalgamated plates 756 Chester, Massachusetts mill at 1078, 1079	mill at Tombstone 1788 Paddock's pneumatic jig 837 Stamp, and tomestate jig 837
Chester Springs, Pennsylvania, graphite mill at 1075	Paddock's pneumatic jig
Chester, Massachusetts mill at Chester, Massachusetts mill at Chester Springs, Penuselvania, graphite mill at Chicago & Aurora Smelling Co , speed of rolls and angle of mp cost of mill at 1 126 1126 1126	stamp and concentration mill at Tombstone, Arizona 1180
cost of milk at	ora lune (17 lune 189
Fron Works rolls Chihuahua, Mexico, concentration in. W.S. Hutchinson	in the mills
3030	Cimabar in Cantornia, concentration of . 2044
	ore dressing plant 1919 specific gravity of 1189
milling practice at T. H. Oxnam 2039	Circular iins
mining in western W.S. Hutchinson 1923	movable sieve power jig 518 shime tables, operation of 692
triple deck 2015	Circulating evanues solution, advantages of Cirkel, F., asbestos milling in Canada 2034, 2048
underdriven, an 2017	Cirkel, F., asbestos milling in Canada 2034, 2048
with two sets of rollers 2017	milling of asbestos 1569
Akron 1280, 1307	City & Suburban mill details to 2025
as a re-grinder 1332, 1333 at mills 1767, 1775, 1833, 1859, 1865, 1873, 1886,	
1803 1804 1900	Clam shell deedes . 1093
Day of D	Clarifying reservoirs
different methods of attaching rollers to 2014	tanks
Tame along 1 280, 1305	Van Ryn gold mines estates 1642, 1743, 1744
Mantey offset for	
push feeder for	Morrill cylindrical almifaire 1 1409
	1406

-			,
Clarifying tanks. Scobey system as used in Ariz	ona	1411	Classifiers, Charleton ore concentrator 428
Clarifying tanks, Scobey system as used in Ariz Tays' clarifying tank with skimming lat	ınder	1410	
Clark, A. J., plate amaigam		788	Colorado Iron Works Company slime tanks . 1407
silver plating copper plates at the Home	stake	-	computation of 429
mill		789	Richards' pocket vortex classifier 1374
Clark, D. K, manual for Mech. Eng		XIX	cone 410
for Mech. Eng		1173	constant head of water for
strength of stone		315	Dalton 398
Clark, D., Potter and Delprat processes vs. mag separation	gneuc	1568	deep double trough
Clark, Ellis, Jr . Blake breaker at Przibram .		57	deep pocket classifier 1371 free settling classifiers 1371
dressing works at Przibram		1174	free settling classitiers
gravity stamps		224	definition 387
hand picking and picking tables at the	Anna		of sorting column
and Adalbert works, Przibram		492	of sorting column 387 De Kalb's perforated board classifier 1402
Harz jigs at Przibram .		640	design of 1432
magnetic separator at Przibram		833	Dimmick 1417, 1420
on length and number of strokes in jigs		594	distributing tanks 449
on power in jigs Przibram pointed boxes and Rittinger spitzluite at	D= .:	603	Dodge siring box 416 Dorr J V N. Dorr 1344
bram	LANI-	476	Dorr J V N. Dorr . 1344
Rittinger and Salzburg tables at Przibrai	m	$\frac{476}{728}$	mechanical 1343 double cone 426
rousting for magnetism		815	Dow 475 476 477
rousting for magnetism stroke of jigs		594	Dow 475, 476, 477 Engis 475, 477
trommels at Przibram, Bohemia		385	Evans 393, 1367
table 🔸		689	extent of classification 1433
tube mill	2014,	2016	feed for 389
Clarkson sampler Thomas, Clarkson sampler		884	sole for 434
Thomas, Clarkson sampler		884	Ferraris 400
Clarkson Stanfield centrifugal separator	820,	828	for coal . 476, 479
dry separator Classification by free settling	390,	891	jig tailings 587
of breakers .		475 13	steam stamp 1003
classifiers		1370	testing 1144 Fraser & Chalmers 416
conveyors .		1582	gates and dams 406
crushing machines		316	G G Gates segregator 418
driers		1595	gooseneck spigot . 388
feed for slune tables		720	gooseneck spigot 388 hoberwasche 421
finely crushed ores J M Callow		1420	helical current in 401
fine sand and slime concentrators		1464	hog-trough 1367
grinders		1279	hopper bottom 412, 413, 414, 415, 416
jigs .	500	551	hopper-shaped shallow pocket 400 Huet & Geylers 478
magnetic separators , preliminary breakers	796,	1521	Huet & Geylers 478
washers		1200 1341	Hundt's 478
pulp thickeners .		1401	hydraulic 387 Burgan, A. L. 1371
pulverizers		231	Burgan, A. L. 1371 deep-pocket hindered settling 1387
revolving screens .		1353	difficulties attending classification 1368
riddies		1346	direct pulsator classifier 1391
rolls		62	double-cone hydraulic classifier 1381
screens		1345	15vans 1369
slime table feed		693	Ferraris 1369
stamps	113,	1246	Fraser and Chalmers 416
tube mills vanners	0.45	1285	Gates classifier 1369
Wiltley table group	645,	1498	hindered-settling, improved Wolf-Tongue 1387
Wilfley table group Classified feed for Wilfley table		1465 1473	history of 1367 Krupp Spitzlutten 1382
products, proper treatment of	•	1478	
products, proper treatment of used for film sizing tests		1478 707	limitations of 1368 Longdale, at Mill 155 1369
versus sized feeds for the Wilfley table	•	1478	Longdale, at Mill 155 1369 means for overcoming adverse tendencies 1369
Classifier jigs		1447	Merrill small cone classifiers 1371
new laboratory H S. Munroe	1447,	1452	New Standard 1369, 1373
new Laboratory H S. Munroe		2020	principle of action of 387
Spigots diameter of		388	Richards' annular vortex classifier 1382
Classitiers	207	404	pocket vortex classifier . 1373
adjustment of	o61,	1367 430	pulsator classifier 1388 shallow-pocket hindered-settling classifier 1384
Altenberg	416,	475	shallow-pocket hindered-settling classifier 1384 undercurrent 1386
Anaconda .	305	1367	vortex, at Mill 124 . 1692, 1693, 1694
hydraulic, details of in mills	000,	396	single-spigot vortex classifier 1377
article on		2020	rigue of food to 900
ascending-current cones or cylinders		1402	sorting column in . 387
at Ammeberg		1121	spigots in 388
Engis using air	1000	817	Swain classifier 1371
mills . 1878, 1879, 1880,	1902,	1903	table of sizes, capacities, etc., of Richards'
Vaucron mill . before vanners		416	pulsator classifier 1390
Berenger and Stingls slime tank		658 1407	tank vortex classifier 1379 trough or shallow-pocket 389
bibliography for		475	trough or shallow-pocket 389 tubular free settling classifiers 1381
Bilharz		475	Wengler classifier 1367
s pitzlutte		423	Wengler classifier 1367 Wolf-Tongue classifier 1369
Boss cone		425	imperfections of deep-pocket form . 409
inox		432	inclined one current . 1146
Browne hydrometric conical		409	in stamp mills 658
Buttgenbach's separator		447	investigation of currents
Calculation of		401	James Carkeek 416
Callow cone		1402	kinds of 387
slime and water cones		1367	labyrinths and runs 4447 Lake Superior hog-trough 390
or Richards-Coggin		391	Lake Superior hog-trough 390
		1367	products of in Mill 45 391

ages 1-643, Vol. I.	ORE	DRI	ESSING.	Pages 644-1197, Vol. II
lassifiers, Lake Superior, hog trough, product Mill 46	s of in	391	Clausthal, power	at 108 es used at 476, 47 slimes by classifiers at 37 slimes by classifiers at 37 at 36 hand picked at 48 sieves at 25 sq at 38 at 31 steve at 58 washing, capacity of Stedman disin-
launders for		440	removal of s	slimes by classifiers at 373
Linkenbach pointed boxes	412,	416 421	rolls at	
V box Lockhart's automatic gem separator		430	screening at	26
tubular		476	sizes of ore	hand picked at
Meinecke .		430	slope of jig	sieves at
puzlutte		425	Stamps at .	
Merrill cylindrical clarifying tank hydraulic classifiers	. 1	406	stroke of jig	rs at
		406	tronners at	at 110
at Mill 106		640	unwatering	sieve at
small cone at Mill 106	1	641	Clay and kaolin	washing, capacity of Stedman disin-
New Standard		419 437	e tegrator f	or
perforated board in pointed box, in the mills		442	crucibles for	r melting
position of	1	108	crushing ma	chine for
principles of action	387,	1368		
products, sizing tests on	1141, 1		enect on me	
purpose and essentials of purposes of	٠,	389 1367		OI
quality of work of		461	moved by w	dge runner mills
Ramsey sludge tank		446	preparation	of G Benfey 202
results of Richards' annular vortex		405	quartz, wen	ght of
Richards' annular vortex		406 391	removal of	impurities from F. Lehm. n 202
Coggin or Calumet pulsator		1419	settling of	
shallow pocket		401	used in reto	orts 333, 1075, 1173, 1178, 1183, 1185, 1186, 202; 203
tubular		428	washing	333, 1075, 1173, 1178, 1183, 1185, 1186
Rittinger pointed boxes		411	C F Bin	ns
Robinson coal washer		478 476	Dummler	2030
Schone tubular screen for	433,		H Kies	202 hamberger 203 A M Fish 2020 119
settling tanks	100,	450	in Ohio	A M Fish 2020
Sherman system of settling tanks		1404	weight of	
sizing tests on		406	Clavey ores on v	tanners 660
slope of sides		440 433		
spigots for spitalutte		421	Cleaned ore plan	ne . 1468 dill 148
strainer for		388	Cleaning amalga	dill 148
suited for testing		1989	amalgamati	ng plates . 756, 75
surface current box	433,		at Mill 10 Mill 10	00 162
in the mills		441 1420	Mill 10)1 162
Swain Tamarack		397	in Califor jıg	nia 1619
testing of		1170	jig concentra	89
Thirion		475	screens at	
trough or shallow-pocket		389	sieve	
tubular	,	421 1371	machines fo	or concentrates 320
classifier, vpuzlutte for hindered settling tests		611	of conver of	or concentrates
investigating free settling		469	plane, defin	ition of 146
unwatering boxes		450	on vanne	15 64
used for mercury trap		774	up diedge j	1015
use of hydraulic water		433 424	mercury 1	trans
U shaped iron pipe V-box design		419	Clean-up appara	m roller mills H S Kenney . 2013
		442	barrel	234. 26
versus screens		368	barrel at Mill 1	11 1650
vortex		403	bibliograj	ohy for 29-
water See Water Wengler & Lowe's		413	for testing details of, in	g
whole current box	443,		doman	1516
Wunderlich coal washer	,	477	of gravity s	tamps 201
Yeatman		399	mercury 1	traps
issifying by free settling in water, bibliogra-	phy for	475	riffles	mechanical batea
laws of flaws of flaw		461	stamps in	mis
udet. A. C		1182	pans .	
		1182	and barro	ds , ,
austhal, Germany, breaker at		57	bibliograj	ohy for
central ore dressing plant at	,7.,	2039		
classitiers at	476,	1795	trolley for a	vold mill
details of stamps at		223	See Individ	nal Gold Mills in Chapter XX.
details of stamps at finest size jigged at		606	Clearance in ste	am stamp cylinder 12
hand picking at	,	492	of gravity s	am stamp cylinder
improvements at		1924 582	jig plung	er
jig discharge at feeder at		582 549	concentrators	oper rime cleans for partient simplex
mechanism at		530	concentrators copper riffle	cleats for concentrating tables . 148
spigot at	• • • • • • • • • • • • • • • • • • • •	528	for De	ister concentrators
iigs at	640,	643	Over	rstrom tables 148
versus tables at		606	height of ru	ttle cleats for Williey table . 146
life of screens at mill at 965, 1086, 1102, 1116, 1121, 117	4 1177	354	rittle for W	on" versus "grosving" 140
sieve scale at	4, 11/7,	367	Cleavage effect	ister concentrators . 148 strom tables 148 fifte clears for Wilfley table 146 inlihey tables 146 on "cersus "grooving" 149 of in minerals 113 ry of stamps 22
picking at		487	Clemens Iones	ry of stamps
plunger rods of jigs at				ry of stamps

Pages 1199-1010, Vol. 111.	21122	1 ages 1011-2002, Vol. 1V.
Clerc, G., methods of jigging	641	Coal washing, discussion of. H. L. Siordet 2051
Clerc, G., methods of jigging	1177	
at Mili 148	1790	in a Belgium colliery 2050 Alabama E Ramsay, C. E Bowron 2050
Chinord, Fl. E.	A 116	W. B. Phillips 2049, 2050 W. R. Crane 2051
Clinochlore, specific gravity of	1159	Improvements in 2050
Clinton fossil ores treated on Wetherill magnetic sep	808	Belgium. E. Discry
arator Chitters mines, treatment at the 1924,	2041	bituminous 2051
Clogging of screens	373 606	England M. Baldauf 2052
Close sizing for jigging Cloth for dust prevention	1099	
cereens	170 171	Indiana. G H Ashley 2051
compared with punched plate details of from the mills	170	machines, control of P. Charvet 2052 plant, at the St. Louis Exposition J. D. Wick 2052
Clunes, amalgamation at double discharge at	788 209	plant, at the St. Louis Exposition J. D. Wick 2052 description of a D. F. Cameron 2051
mercury wells at	768	preliminary investigation of L. A. Harding 2051
shoes and dies at stamps at	183 226	principles of 2050 results of 2050
Victoria, mills at	1180	 some references to . 2051
Clutches for gravity stamps	198 1606	Coarse concentrates on jigs, defined . 494 removal of in jigs . 576
Congulation of fine shmes	1147	concentration without sizing S. W. Taylor . 2043
Coahula coal washer Coal See also Fuel	2051	limit of screening
as fuel in Wilfley roasting furnace breaker, a new W.S. Avres at Alden, Pennsylvania M. S. Hochita	1548	Convent city traited by uge 605
breaker, a new W. S. Avres	2049 2051	Coates tubes at Mill 149
Bankhead, Moerta L Stockett and B. K.		
Warden Stockett, Montana – L. Stockett	$2050 \\ 2049$	Cobaft amangam
briquetting system	2050	specific gravity of
burned in mills – See Individual Mills in Chap- ter XX		Cobline, spect-a gravity of
roasting for magnetism	815	Cobbing
capacity for, of Stedman disintegrator centrifugal machine for	$\frac{286}{820}$	devices
classifier	479	hammers
combined disintegrator and screen for M. A. Sattiaux	2018	at Mill 186 . 1917 houses 492
consumed in roasting for magnetism	814	magnets . 1531
crushing of	, 882 284	at Mill 138 1742, 1806, 1807, 1818 Bilharz 1532
dressing, changes in anthracite jugs R. A. Henry dust, air blast for	2052	Broughton Asbestos Company magnet . 1532
dust, air blast for	2051 839	Cranberry 1530 Eastwood 1532
removal of	2050 837	Manhattan Asbestos Company magnet (Wethey) at Mill 164 1849, 1850
removed by air blast from	817	plant at Vill 158 . 1821
handling machinery for C. Piez	$\frac{2051}{2052}$	Cocheño, settling tank it
in Pennsylvania, breaking of anthracite jigs 520, 523, 548, 549, 574, 588, 639, 640, 641 magnetic treatment of. E. Post	2051	Cochiti, New Mexico, gold mining at, W. C. Wynkoop 2036
jigs 520, 523, 548, 549, 574, 588, 639, 640, 641	2052	Cocoa matting for tables on dredges 722, 1007, 1008, 1012
method of separating dust from	2000	tables at Mill 111 . 1655
method of separating dust from mine to develop electric power mining in India, cheap. II M. Cadell	1092 2050	efficiency of 1657 Codman breaker 58, 61
picking in Cainsdorf	2051	Cœur d'Alene districtaldaho, concentration in the.
preparation machinery R. V. Morris Ramsey shidge tank for	2050 446	A Locke 2041 cost of producing lead and silver in 1960, 1961, 1962,
Ransev sludge tank for equired per horse-power hour at Mill 172	1874	1963, 1964
screening and washing of. T. H. Aldrich .	$\frac{365}{2052}$	hammers used
by the by pass system	2050	milling at 2045
of	$\frac{345}{2050}$	milling practice in the J. R. Finlay 2037 mining J. R. Finlay 1922
papers on	2018	Coffee mill
plant of the Clifton colliery, a new 3000 tons capacity	$2051 \\ 2052$	Coggin, F. G., Ball and Leavitt stamps
screens for	$\frac{342}{2051}$	on area of discharge of steam stamps . 129
separation of dust from, A. Wiedl , slate pickers for , 489, 492	493	power for steam stamps . 131
slate pickers for	1993 815	slime tables 697 steam stamps 142
used in roasting for magnetism washeries, anthracite. G. W Harris 2049,	2050	Cohesion of mercury, effect of temperature 767
different Pennsylvania, bituminous W G Wilkins .	2050 2051	Cohn'e ball mill 203
washery at St. Beram, M. Benotte	2050	M F, California stamp battery 225
	, 1178 2050	Coke breaker, a new. G. Kroupa 2010
advances made in an article on. S Diescher, Sr	2051	used in roasting for magnetism
	2049 2050	Cole. David, power tests by
the Baum colliery Cadeby colliery	2000	Cole's breaker
		Collar for cam shafts 190 grit 1098
Reynolds culm bank. A. D. W. Smith . bibliography. S. S. Wyer . bituminous. G. R. Delamater	2049	Collectors for amalgamated plates 748
oituminous. G. K. Delamater	· ²⁰⁵¹ 2:	Collett, water softening 1419

,	- ,
Collins, A. L., amalgam	Combination of principles of separation 891, 1611
Collins, A. L., amalgam	pan 239
H. F., Clarkson sampler 884	process of amalgamation 248
metallurgy of lead and silver xix	silver mills
I H . definition of slimes	Comet breaker 41, 57-60, 2009
Colloids, effect of heat on Collom, Evans, and Woodbury jigs, capacities com-	adjustment for wear 43
Collom, Evans, and Woodbury jigs, capacities com-	amount of throw 43
pared 1448	table of details of 41
jig 510, 1440, 1446 advantages of 514	dimensions of
construction of 524, 525	buddles, percussion tables, vanners, slime
height of tailboard . 551	tables 729
hydraulic water in	capacity of jigs . 597
life of . 604	Clarkson Stanfield, Mumford & Moodie, Pape-
mechanism on grizzly 345	Henneberg separator 838
modifications of 515	grazies, riddles, and trommels 385
size of sieve and plunger 529	hand picking and picking tables 492
slope of sieves in . 548	jigs 643 Richards-Coggin classifier, Buttgenbach's
speed of 593 sampler 847	Richards-Coggin classifier, Buttgenbach's pointed boxes, Bilharz, Rittinger, spitalutte
sampler 847	Octor row cubon courter mad at Macher-
Colombia, S America, milling in Juan de la C.	Osterspey siphon separator used at Mecher- nich 478
Posada 2039	Schranz breaker 60
quartz milling in F. F. Sharpless 2038 Colorado, concentration of zinc ores in 2043	separation 1182
Colorado, concentration of zinc ores in 2043	separators 835
concentrator, cost of crushing by rolls 104	slope of jig sieves . 548
cost of milling in 1129 1133	stroke of jigs . 594
producing gold in 1974, 1975	Commercial limit of concentration 1118
lead and silver in 1909	Commonwealth mill, Pearce, Arizona, milling at the 2044
tungsten mining and milling in 1987 dredging in	Mining and Milling Co., b. 11 - 211
	Mining and Milling Co., ball mill 261 Compañía de Huanchaca de Bolivia, stamp frames 160
general milling practice in Gilpin County . 2045 Iron Works 1407	Minera del Tiro General 1802
Akens and Evans slimer	Comparative sizing test of tailings and concentrates
Blake breaker	Comparative sizing test of tailings and concentrates from stamps and Lane Chili mill 1309
breakers at Mill 144 1771	tests of spindle and jaw-breakers 53
Challenge type feeder 1580	table of 45
continuous grinding pans 1323	wear of metals for jaw plates of Blake breakers 48
Dodge breaker	work of gravity stamps and Huntington mills 1262
double cone hydraulic classifier 1381	Comparison between single-cylinder and compound
grinding pan, continuous 1282	Steam Stamps 1204
Humphrey rolls . 1244 impact screen . 1351	of Blake and Dodge type of breakers 33 California and Colorado systems of stamp
impact screen 1351 at Mill 151	milling 1030
octagonal trommel 1360	canvas and rubber vanner belts 650
on rolls	capacities of Woodbury, Evans, and Collom
Perfect ore feeder 1609	jigs 1448
power for rolls 97	concentration and amalgamation 1047
rolls	convex and concave buddles 706
at mills 1690, 1691, 1749	slime tables 692
roll speeds	crushing machines 313 flat and sloping null sites 1085 Gates and McCully breakers 45
	flat and sloping mill sites 1085
single cone classifier of	Gates and McCully breakers 45 geared and belted rolls 83
and classifiers ,	Harz and Collom jigs 515
vanner 652	jaw and spindle breakers 51
jig connecting rod in 530	jaw and spandle breakers 51 jigs and tables 606 large and small breakers 49
mill in 1120	large and small breakers . 49
milling in 1177	materials for hig screens 545
mill, number and height of drop of stamps . 214	wearing parts for breakers 48
practice in different camps 2043 present milling practice in H C. Parmalee 2035 Smelting and Mining Company 1836	methods of running jigs 571, 572 mine and mill work 1123
present milling practice in H. C. Parmalee . 2035 Smelting and Mining Company 1836	mine and mill work 1123
mill xxvi, 978	picking tables .4. 491 plain copper and silver plated plates .748
Huntington mill in	pulverizers 231
stamps versus California and steam . 134	punched plate and wire cloth
system of stamp milling 224, 227	riffe tables 679
versus California stamp milis 213, 224, 1030	Rittinger and Wilfley tables 679
Zinc Company* 1758	rolls and Sturtevant mills
Color affecting separation 889	round hole and slotted screens
and luster of minerals, effect of	sampling methods . 848
of minerals in artificial light	screens 175, 345, 369 side-hump and end-hump tables 682
Columbia mill, Browne hydrometric sizer in 410 vanners in 658	side-bump and end-bump tables . 682 side-shake and end-shake vanners 655
Columbian mines, amalgamated plates at 749	single and double discharge for stamps . 209
pulsating screen 343	smooth and corrugated vanner belts . 650
separator, Jeffrey 2018	spindle breakers 46
Columbite, specific gravity of 1189	steam and gravity stamps . 134
Columbium, atomic weight of 1188	trommels 362, 377, 378, 379
Combination cone and horizontal ball mill 2017	and riddles 365
crushing, amalgamating, and cyanide machine. M. Dekeyser 2033	Utah Copper and Boston Consolidated mills . 2012 vanners with convex slime tables . 691
mill, Goldfield, Nevada, treatment at the. F.	water used by Evans and Hancock jigs a 1442
L Bosqui 2045	water used by Evans and Hancock jigs 4. 1442 wire and plate screens 171
M R Lamb 2038	Compensating weights for gravity stamp at mills 1645,
Granite County, Montana. R. B. Brins-	1651, 1668
made 2042	Complex jigging mills at Lake Superior
of the Goldfield Consolidated Mines Com-	in Colorado and Utah 925
pany 1626 mills 1039, 1046, 1060, 1101	Idaho and Europe 936
· · · · · · · · · · · · · · · · · · ·	Montana 973
2^{i}	4
-	

Complex jigging mills in southeastern Misso for blende or pyrite			Pages 1611-2052, Vol.
	uri	16 Concentrators, Feri	romin dull-
Compound and single cylinder steam stam	DS COM-	06 fine sand and	and slimes, belt film-tables
parison between	. 12	254 for one sands	and slimes, belt film-tables
breaker		57 tilm-sizi	nor tables
parison between breaker edgestone mill bibliography for	2	menunt	tent surface tables
engines		AICYCS	
engines steam stamp at Mill 181	19		
ompressed an ior pumps	11	06 Gilpin County	nts on rectilinear tables 1
jig ompressive strength of stone	5		
Computation of Callow cone		00 Hendγ	
classitier	. 14 401, 4	04 Hooper pneum 29 James slimer	atic
grain sizes for free-settling tests		65 table	
Richards' annular vortex classifier, fo	or coarse	Johnston	i
fine grains	13 13		ble
fine grains pocket vortex classifiers	13	Kuhrig slimer	
single-spigot vortex classifier	. 13	74 magnetic separa 77 McLeod	ators 1
tank vortex classifier	13	80 New Humboldt	1
work for crushing omputed horse-power for trommels	3	80 New Humboldt 12 New Standard	· · · · · · · · 1
	11	Norbom	
omstock, amalgamating pans at .	2	61 Pinder 91 pneumatic belt	10 10 10 10 10 10 10 10 10 10 10 10 10 1
lode, Nerada, mills on	1175, 11	84 Shmers	** **
omputing tests omstock, amalgamating pans at kode, Norada, mills on mills, wear of amalgamating pans stamp mills oware hyddle	2	19 Triumph	
oncaye buddle	2	30 Tulloch	•••
slime tables	. 6	06 vanners	. 12
versus convex slime tables	(1)	12 table	· 16
oncaves and short head, Gates breaker with for spindle breakers	h 120	08 Woodbury table	. 19
oncentrate drying bins	17.	Concentric conical to	rommels at mills 1010 10
at milk	1570, 160	Cymarical from	mels at mills 1655, 17
oncentrated, list of ores that can be	204	9 grinders 9 trommels	3
	84	3 at Mill 154	30.5
cleaned by trunking machine cleaning of	32	1 Conchusiu	1815, 18 16
coarse, definition of	32	Concrete bins at mil Concrete bins at mil foundation for r mine, stamping	ls 1756, 1834, 18
drying of	49 88	14 Ioundation for r	nills . 10
moisture in	116	0 mine, stamping 7 mortar blocks	of ore from . 2
of pigs, removal of	58	6 C D Kard	ling 1
percentage of, affecting capacity of jigs purity affecting extraction	- 60	1 settling tanks at	Mill 171 18
	111 84	e Stamp mill found	dations C P Schall 60
sizes of, in mills . storing and shipping	111		
storing and shipping	111	2 Conductors for electr	rostatic separation, list of good
tank for vanners ncentrating plane on vanners	64		
slope of in vanners ncentration See also Milling and Ore Di advances in the art of. F. Cirkel	64 65		410 498 4
ncentration See also Milling and Ore Di	ressing	9 for amalgamatın mill	g pan 2.
advances in the art of. F Cirkel amount of	204	S bibliography fo	232, 255, 20
by free settling	111	pulleys for Bradi	or ford jig 50
followed by hxiviation	47.) 11gs	5
followed by hxiviation	1616, 166		84
history of. A. W. Warwick limit of	2049	settlers at Mill 1 Cones, pyramids and	Drivme 188
magnetic	1111	Conglomerate ore, mi	prisms 36
mill	790, 152	weight of	119
molybdenite dressing of copper ore. F. H. Probert galena ore F. H. Mason pucumatic	1117 156	Coniagas mill, Cobalt	, Ontario. R. Stokes 204
or copper ore. F. H. Probert	1997	Conval trompule	167
galena ore F H Mason pneumatic	2046	at mills 1714.	, 1783, 1784, 1785, 1815, 1854, 189
progress in. V. Horel	817		
progress in V. Horel of	2049 2049		100
ratio of See Individual Mills in Chapter	: XX.	Coning and quartering sampling by	g in sampling 157
ratio of See Individual Mills in Chapter relation of physical properties of minerals separation by crushing and screening decremitation, and screening	to 2	Conkling dry magneti	c separator
	1566	318	· to
tondanas is	1565 2048	movable sieve jig	
versus amalgamation	1047	Conrecting rosts for ji	gs 53
resus amalgamation wet C Taylor works at Monteponi, Sardinia Centrature, air winter	. 2043	Consistency of pulp for	gs 64 53 Co. 203 or Wilfley table work and van-
	1066		
	air 816 818	vanner feed at	
amalgam traps for Bartlett Simplex	. 1516	Wilfley table fe Consolidated Main Re Stanley mill, Com	ed at Mill 173
Dartiett Simplex	1487	Stanlew mill. Com	ret, sand wheel at . 158'
Bartsch rotary percussion table belt percussion table Card	1497	Stanley mill, Cam Virginia mill, cros	s sills in
	1496 1481		
Charleton ore	. 427	Constant speed for ma	Chines 1000
[height	1484	Aitken	auon or stamp milis. R. M
D	1400	expenses	204
D	1488	CADCHSCS	
D	644, 1510	method at Mill 17	
D	644, 1510 . 2022	method at Mill 17	74 112
Deister depth of bed in	644, 1510 . 2022	method at Mill 17	74 112

Construction of stamp mills. J. J. Deming 2	2049	Conveyors, Robins belt
J. Roskelly 20	2048	rubber belt 859
trommels	300	scraping
	049	screw . 861, 1582
Consumption of cast from per ton rock crushed at	000	Cook, R. A., magnetic plant at Dannemora, Sweden 1175 Wenstrom separator at Dannemora mine, Sweden 833
Mill 180 . 19	902	Wenstrom separator at Dannemora mine, Sweden 833
coal in American Process Company's driers . 15 Argall drier . 16	600	Cooley, G. T., dressing zinc ore in Missouri 1180
Edison diter . 16		jig
per horse power in gas system at Mill 172 . 18	874	shafts for
fuel in Williev roasting furnace 15	54X	tank 522
oil in Elmore vacuum oil process 15	560	width of sieve
pebbles by Abbé tube mills at Mill 101 16	626	jigs for blende 643
Krupp tube mills at Mill 118 . 16	$677 \\ 632$	Cooling ore from galena roaster 1548
	032	Cooperficult lamp 1931
steel by Bryan mills at Mill 173 18 rolls at Mill 173 18	879 877	Cooper, J. R., on amalgamated plates
in shoes and dies at Mill 117	668	Coppée coal washer 2018
sulphuric acid by flotation process at Mill 130 17	722	Copper, action of gravity stamps on 314
sulphuric acid by flotation process at Mill 130 17 trommel screen steel at Mill 173 1876, 18	877	amalgam 730
water at mills 1413, 1640, 1648, 1664, 1730, 17	731	amalgamated plates 747
the Rand 14	410 411	amalgamating plates, difficulties in use of 1515 and silver plated plates 764
	490	and silver plated plates . 764 atomic weight of 1188
	441	haves for air products 586
working on Montana copper ores 14	442	breaking in Mine 44
Tohnston vanners 15	502	clean up of in stamp mills 134
suspended frame vanners . 15	503	breaking in Mine 44 54 clean up of in stamp mills comparison of breaking by hand and by machine 13
Wilfley shimer 15	506	concentrated by free settling 475
Continuity of running, effect on costs	282	cost of producing 1948 crushed by Calumet & Hecla Company in Mill
turns	282	44 259
kieve . 7	727	for jig screens 545
movable sieve power jigs . 4	499	rittle cleats on concentrating tables . 1481, 1486
or Boss system of working amalgamating pairs .	248	screens 354
	506 686	handbook, Lake Superior copper mines 1925
	689	hindered settling tests on 611, 617 in tailings of Mill 48 130
	692	Lake Superior, adaptability of steam stamps for
versus intermittent action on breakers .	55	crushing 314
Convex and concave rolls	111	mils 114, 475
	704	masses cleaned by steam hammer 12
Cornish buddles at Mill 185 19 slime tables 6	916 686	native, specific gravity of . 1189 ore hand picked . 482
	691	leaching 1167
versus concave slime tables (692	method for treating low grade N S Keith 2039 mill for 893, 904, 905, 915, 958, 961, 965, 973, 984.
Conveying and draining belt at Mill 130 17 picking belt at Mill 139 17	720	mill for 893, 904, 905, 915, 958, 961, 965, 973, 984,
picking belt at Mill 139	749 585	990, 1005, 1022 separated by oil . 831
belts 15 at mills 1585 1631 1667 1670 1681 1706 170	'08	separated by oil . 831 screening . 830
1709, 1771, 1772, 1805, 1806, 1807, 1808, 180	i09,	size of grizzly used for 340
at mills 1585, 1631, 1667, 1670, 1681, 1706, 171 1709, 1771, 1772, 1805, 1806, 1807, 1808, 1886, 1810, 1811, 1812, 1813, 1819, 1831, 1859, 181 1861, 1862, 1863, 1882, 18	60,	stamps suited for 134
1861, 1862, 1863, 1882, 18	883	treated at Moonta mines, Australia 505
New Kieinfoniein Company plant 13	585 804	by Collom jigs 515 in Mills 44, 46, 47, 48 486 percentage of in tailings of Mill 46 131
	031	percentage of in tailings of Mill 46
belts, layer of coarse ore to protect belt at Mill		picking of . 894
158	826	plate, annealing of 747
	807	preparation of . 747
	585 031	screens 174 plates 179
method of cleaning 20 of Wetherill magnetic separator, proper speeds	001	plates 179 absorption of amalgam by 765
for 15	523	preparation of 752
portable at Mill 167 18	857	stains on 751
self orling carrier for 15	585	precipitated by scrap iron 1082
tripper at Mill 124	691	pure, specific gravity of
for discharging 15 use of with Blaisdell excavator at Mill 117 , 16	586 670	pure, specific gravity of Range Consolidated Company, Champion stamp mill 1897, 1900
notes on a 75-foot 20	031	Mrg to rock houses, Michigan 2040
Conveyors 859, 15	582	removal of 251
See Individual Mills in Chapter XX		results of tubular classifier tests on
	735 884	riffle cleats for Deister concentrators 1488 rock, cost of crushing at Atlantic mill 51
	860	rock, cost of crushing at Atlantic mill
Caldwell helicoid conveyor 15	582	stamped at Phenix Mine . 140
carrying conveyors 15	585	settling velocity of
classification of	582	
different types of W R Ingalls 10	609	ores tested by Collom jigs in Mill 42 515
different types of W.R. Ingalls Judisc, at Mill 124 16 drag or disc 11	695 583	specific gravity of 3 versus silver-plated plates 748
push . 18	582	wire cloth for itg sieves at mills 1707, 1708, 1809
Edison distributing 8	861	Cordier, E. Vapart disintegrator 299
endless belt 8	861	Core for magnets 4 . 794
	588 881	Cores of rolls 65
	581 582	Corliss engines 906, 958, 973, 982, 986, 987, 1057, 1091 Cornacchino Mine, Tuscany, mill at 1074
Kreiss jerking	884	Corning, Frederick G., Corning belt concentrator 729
pan or plate	860	table 609
	489 80.1	Cornish convex buddles at Mill 185 1916 • feeder
push	584	• feeder 856

	704	at the second second
Cornish frames	704 Cost o 506	of direct smelting
jigs	994	dredges
rolls 10	9, 112	dredging 1654
at mills 1/14.	. 1868 2012	drying
stamp mill for tin ores	230	dust chamber and fans
tin concentration works, roasting for porosity at	829	electroplating 755
dressing E Walker	2038	erecting a complete decantation slime plant in South Africa . 1940
mills ore, crushed by Husband stamps	1119 141	large Montana copper sulphide mill 1939
practice	1915	roasting and magnetic separation plant 20 stamp mill. F. C. Roberts 2049
works · · ·	704	20 stamp mill. F. C Roberts . 2049
vanning shovel Cornwall, England, Acme table for treating tin slimes	1152	zinc-lead concentrator 1940 mills 1124 1618 1731 1770 1875 1939 1940
cost of crushing by rolls in	104	mills 1124, 1618, 1731, 1770, 1875, 1939, 1940 filter pressing plant, Mill 108 1647 fine grinding W. A. Caldecott 2015
Elmore vacuum oil process in	1559	fine grinding W. A. Caldecott 2015 freight 1126
jigging in	609 1077	freight 1126 fuel for rotary drier at Mill 186 1917
kaohn washing in kieves in	727	gold dredging 1009, 1013
labyrinths in	448	milling in Venezuela 1127
milling in	1173	grinding at Vill 130 1724 by arrastra 238
mills in . 1176, 1180, rolls in	111	tube mills 1291
runs in, on tin ore	478	hand jigging 1129
runs in, on tin ore stamps in	228	jigs 499
system of tin dressing. C. M. Myrick tin dressing in	2044 1081	picking 487, 489, 492, 1438 galena 488
E. Skewes	2037	handling material by conveyor belts 1585
F. Skewes F. Walker	2038	ores by Blaisdell system 1603
use of rag frames in	1507 5, 547	Heberli mill wear 258 jaw and spindle breakers 52
c/ reens	354	plate on Blake breaker 48
Corrugated belts for vanners 64	7, 650	jigging 'n Missouri 609
Frue vanners at mills 1703, 1868	, 1870	ngs 604 ng screens 547
Johnston vanners at Mill 167 1858.	1859 650	jig screens 547 labor and supplies 1941
iron for mill buildings	1088	at Mill 174 1887
rolls 106, 110, 111	, 2010	for breakers 51 Huntington mill 281
at Mill 152 description of Allis Chalmers type	1806 1242	Huntington mill 281 pan amalgamation 250
table of	107	stamps 206
sizes, capacities, and power	1243	in mills 1100
stamp screens	226	power, supplies, board, etc. See Individ- ual Mills in Chapter XX
Corundum, broken by heating and quenching dressing 1176, 1181, 1183, 2029	. 2030	lumber 1126
Hill, North Carolina	57	machines 1125
mill at 1078, 1079, 1176	, 1184 2025	magnetic separation 810 of iron ore 802
milling H E T Haultain in Canada D. G Kerr	2025	McDougall roasting furnaces 1546
ore, mill for . 1078,	1184	mercury for stamps 206
specific gravity of	1189 333	milling at mills 1619, 1639, 1640, 1643, 1645, 1731, 1793, 1905, 1906, 1916, 1919
washing pan for	335	in Colorado 1129
Cost accounts	1122	Masonri 1129
and extraction	1939	Nova Scotia W. L. Labbey 2049 South Africa 2049
bibliography for details of for breaking	1173 50	1 H Pitchford 2048
of blanket tables .	703	various mills 1126
blowing dust from coal	817	on the Rand J R Williams 2049 mining 1126, 1940, 2048
board at mills • breaking	1100 51, 57	mining 1126, 1940, 2048 and treatment at Cripple Creek, Colorado 1616
ore 1222	, 1223	effect of attitude of orebody on 1942
in Gates breakers	1222	economy and speed on 1948
buckets for conveyor calcining at Mill 137	861 1549	external factors on 1941 internal factors on 1942
changing heads and concaves, Comet breaker	47	size of orebody on . 1942
chemicals for pan amalgamation	250	stamping, dressing, etc., at Mail 180 1905
coal	1092 1917	mortar lining 166 oil for separation 831
cobbing at Mill 186 concentrating lead zinc ores A Bordeaux	2049	operating 1940
concentration	2	all sliming filter press system 1648
at Butte C W Goodale	2048 1881	Argall four tube drier 1600 at Mill 186 1919
copper refining at Mill 173 crushing 60,	1222	flotation processes 1562
at mills . 1222	, 1883	Minerals Separation Company, flotation
by breakers	49	process . 1561
Huntington mills 281	, 1318 50	Trego reasting furnace 1548
jaw breakers, table of Minnesota Iron Co.	51	with Cleveland-Knowles magnetic separators 1542
rolls	104	pan amalgamation 250 plant for electroplating 755
spindle breakers, table of	50 205	plant for electroplating . 755 power at Mill 105 . 1639
stakips for interest, taxes, insurance and depre		by gasoline engines . 1041
ciation .	205	for stamps 205
steam stamps	134 51	producing copper at mills 1894, 1956, 1957 general considerations with regard to 1958,
road material cyaniding	51 1028	1939, 1900
at Mill 106	1642	in Arizona districts 1953, 1954, 1955
decantation slimes plant, Mill 108	• 1647	Bisbee or Warren district 1954, 1955

27

Cost of producing copper in Clifton-Morenci dis-	Cotton cloth for filtering dust
trict . 1953, 1954 Globe district . 1963, 1963 Loke Superior district . 1948, 1949, 1959	Cottonseed oil 1007
Lake Superior district 1948, 1949, 1950	Coupling of machines 1110
Globe district 1953 Lake Superior district 1948, 1949, 1950 Montana district 1950, 1951, 1952, 1953 Mount Lyell, Tasmania 1957, 1958	Cover for amalgamating pan 244
Mount Lyell, Tasmania 1957, 1958	for oil holes
Utah district 1955, 1956 various districts 1958	work of stamps, cleaning up 320
diamonds at Mill 188 1922	Covers for mortars
gold 1974	Cowenhoven Tunnel Co., rock house 485
at Douglas Island, Alaska 1975, 1976, 1977 in Black Hills district, South Dakota 1977, 1978	Coxe automatic slate picker
Cripple Creek district, Colorado 1974, 1975	gyrating screen 345 Coxe, Eckley B., corrugated rolls for coal 110
El Oro district, Mexico 1980, 1981	Coxe's finger bar grizzly and gyrating screen . 385
Grass Valley district California 1977	gyrating screen 345 Coxe, Eckley B., corrugated rolls for coal 110 Coxe's finger bar grazdy and gyrating screen 385 Lulwig coal jig at Drifton, Pa 640 Coxe's screen 2018
Kolar district, India 1981, 1982, 1983 San Juan district, Colorado 1978, 1979, 1980 Witwatersrand, South Africa 1983, 1984,	
Witwaters and South Africa 1983 1984	Coxheath ore crushed by rolls, sizing test 99 Cox, William J, manager of Mill 100 1275
1985, 1986	Crab for gravity stamps . 200
iron ore concentrates in eastern United	"Crack-proof" vanner belt, the
States 1986, 1987	Cradle
lead and silver in Broken Hill district 1964, 1965 Cocur d'Alene district 1960, 1961, 1962,	washing machine. W. Scott 2031
1900, 1904	washing machine. W. Scott 2039 Cranberry coal breaker . 2051
Colorado district 1965	magnet 1530
Utah district 1966, 1967, 1968 lead and zinc 1968	at Mill 156 • 1531, 1818 magnetite ore, cost of concentrating 1135
in Missouri district 1968, 1969, 1970, 1971,	mill for . 1180
in Missouri district 1968, 1969, 1970, 1971, 1972, 1973, 1974	tests on 1176
lead, general considerations regarding 1974	mill
in Flat River district 1971	ore, magnetic separation of . 835 separated by magnets 835
tungsten ore concentrates in Boulder County, Colorado 1987	separated by magnets 833 Crane at Mill 171 for removing tailings 1870
zinc in Toplin district 1972	log washer at Mill 95 . 1617
pumping at Mill 180 1906	Crank arm mechanism for jigs 535
with Latta & Martin pump 1590 quarrying 51	Crawford mill 234 bibliography of 295
quarrying 51 refining at Mill 106 1643	Cream separator 827
repairs on rolls 104	bibliography of 299 Cream separator 827 Creede, Colorado, milling at 1925
vanners 663	milling at A Lakes 2041
Wetherill magnetic separators 1525 retreatment at Mill 130 1724	Unite l Mines, Humphrey mill 1766 Cremer, R, Baum and Sheppard jigs for coal . 648
	Carr disintegrator for coal 299
roll shells 66, 68, 69	tom streeting . oo.
running breakers . 54 log washer . 324	Hochstedt apparatus 838 Cresson, George V., breaker of Blake type 23
log washer . 324 screening 360	Cresson, George V., breaker of Blake type Co., rolls Crickboom log washer at Mill 147 1787
screens . 169, 170, 174	Crickboom log washer at Mill 147 1787
for Bryan mills 273	wash trommel 330, 334
jigs 547 shoes and dies 182, 183, 184	Cripple Creek, Colorado, concentration at
slime table	producing gold in 1974, 1975
smelting versus chlorination 1020	mill at
stamping 221	milling practice at 1925
stamp cams - 192 miling - 2048	rock house
screens 173	Crocker's natent stamps 990
stem 187	Crocotte, specific gravity of
tappets 189	Crookes, Sir Wm , diamonds 1185 the washing pan 2020
steam power 1134 transming at Mill 133 1731	the washing pan
treatment at mills 1649, 1920	mill, Colorado, gold and silver in amalgam in 702 hydraulic classifier in 774
trommel screens 352, 361	
tube mill lining in New Zealand 2016 vanner 691	mercury trap at
belts . 650	wells in
water at Mill 179 1899	ratio of gold to silver on plates in . 763
for stamps	mine, Blake breaker at
wearing parts for stamps 206 of Blake breakers 26	mine, Blake breaker at 1621 sills for gravity stamps 155 Crossley pebble mill 2014 Croton from mines, cost at 1135
of Blake breakers	Croton iron mines, cost at 1135
Forster breaker . 28	niii at 1179, 1160
spindle breakers 46, 47	ore concentrated by magnets 798, 803
wear of stamps and Bryan mill	Sturtevant mill at
Costs. See also each machine.	ore sizer 2019
at Mill 97 . 1621	gold dry concentrating plant, Tintic, Utah . 2044
effect of altitude on . 1941	mill, Georgia H. V. Maxwell 2036
climate on	Point, mill at 901 mines 1174
losses on 1944	Reef Gold Mining Company, use of milk of lime
marketing the products on 1942	for slime settling at
population on . 1941	mill, details of stamps 221
temperature on 1942 transportation on 1942	tailings, treatment of 2048 Crucible for melting 784
underground conditions on 1941	Crusher in a stamp mill, description of a fine 2014
general principles governing 1940	stamp mill, fine
high grade versus low-grade mines	Martic 200
Cosumnes River, California, mill at	McLanahan and Stone single-roll. 1241 sectional cushioned

2 1 60001-0-0-1	22	Current water wheels
Crusher, Sturtevant	1137	wheel dredges
	8	Curtis, A. H., ball mills
Crushing and jigging department at Mill 146	1783	Blake, Gates, Comet, Dodge, Marsden breakers 59
screening, separation by	1566 1568	Bryan mill
article on L. H. Sturtevant	2009	crushing machines
at Black Hills, S. Dakota. C. H. Fulton	2033 2018	Cyclone pulverizer 299 Cyclops mill 294
the Sammer and Jack mine	2010	Harvey's stamp, Hope's compound battery 227
Dibliography for laws of	315 54	Howland pulverizer 297
choice of breaker for	98	Husband pneumatic stamps . 143
by breakers	48	Krom's rolls 111
comparisons between wet and dry. F Merrick concentrates	1113	
cost of · · · ·	49 1222	Morel and Hall's mill
at Mill 162 by breakers	49	Niagara crusher 294 on breakers . 59
gravity stamps	205	• pneumatic pulverizer . 299
Huntington mills	1318 50	stamp mills. Krom rolls. Huntington mills . 1182
rolls	104	Curve of cams 196
spindle breakers, table of steam stamps	50 134	Curves of film sizing tests 708 jig work 632
a ali malom	65	settling velocities 467, 473
department at mills 1690, 1709, dry P. Argall .	2010	sizing tests 1139, 1144 stamp velocities 216
rolls for	1224	Cushman and Hubbard Prevost, decomposition of
extent desired	303 62	feldspars 1418 A S, decomposition of the feldspars 1400
for cyamde, comparison between wet and dry	2017	effect of water on rock powders 1418
free graded by rolls	98 103	Custom millin 482 mills 915, 978, 1029, 1035, 1157
in sampling	849	bins for
laws of 300,	1325 2018	plates in 748 sampler of Mill 102 1629
machines, advance in	313	Cut govers 1008
discussion of fine. R Allen	2014	Cutten, W. H., gold dredging in New Zealand 1179, 1184 Cutter, G. A., tests on strength of granite 302 H. C., testing plant at the University of Minnesota 1179
for cement	2014 8	H. C., testing plant at the University of Minnesota 1179
sizing tests of	315	Cutting down in sampling 849 Cuyahoga steam stamp 114, 118, 119, 121, 122, 123, 126,
means of computing efficiency. Pearce & Cal- decott	2017	Cuyanoga steam stamp 114, 116, 119, 121, 122, 125, 120, 127, 128, 133
mechanics of. C. De Kalb	1340	Cyanide, amount used on plates 757
methods of null, description of a wet	8 2017	effect of on plates
of Lake Superior iron ore. R. C. Newhouse	2009	preparing amalgamating plates 752
middlings	1119 2035	machinery 1600 of silver used for electroplating 755
plant at Kalgoorlie, dry H. J. Brooke mills 1748, 1828, 1831, 1871,	1882	plant for gold mill tailings 1017,1028, 1114
	2018 1340	Robinson rifle in
power for E. A. Hersam preliminary	9	the Windsor in the West Rand
principle of roll crushing quality of, by rolls	1224 50	process, rolls for
relative ments of wet and dry crushing		slimes plant, Mill 106 1642
P Danckwardt ribbons	2018 101	-treatment at Mill 117 1671 tests
rolls	62	used on amalgamating plates . 751, 760 1619
Fules for power used	309 103	Used on amalgamating plates 751, 760 1619 Cyaniding at El Oro, Mexico, C Butters 1942 Goldried, Actada M. R. Lamb 1942 the Homestake, C. W. Merrill 1943 1143
tests of Gates and McCully breakers tabulated results of J. B. Porter	45	Goldfield, Nevada M. R. Lamb 1922
tabulated results of J. B. Porter . theory of E. A. Hersam .	2017 2018	the Homestake. C. W. Merrill
with stamps, coarse	2015	in New Zealand. 1 Park . 2024
work required for	304 1189	of gold and silver ores Julian and Smart . 1323 with and without concentration 2047
	890	Cyanite, specific gravity of
effect on mill scheme	1120 188	Cyanite, specific gravity of
of stamp stems Cubic foot of broken ore, weight of 1160,	1190	
measures, equivalents of	1187	dust collector at mills 1637, 1803, 1863
Culm banks, methods of washing. B. T. Berthelot classifiers at Mill 134	1733	bibliography for
Cumberland Ely Copper Company 1805	, 1800	table of details of
Cummer drier Cummings mill, bibliography for	880 292	bibliography for
ore granulating mili	255	Cylinder, Alsing
mill Cumulative direct plot	232 1140	steam 122
Cumulative direct plot	1140	
plot of sizing tests	, 1144 232	Cylindrical driers
bibliography for	293	Argall 1599
Cuprite, specific gravity of	1189 434	roasting furnaces at Mill 148 1793
settling tanks	451	trommels 348
velocity of in settling tanks	* 454 20	wash trommel

D	Dayton, Nevada, amalgamating pan	20 2-
Daggett, E, on Invivation 1167 Russell leaching process 1175	mill at	115
Russell leaching process		35
Danionega district fight stamps	Dead plate on trommels sea water, weight of	116
	Deadwood, Terra mill, amalgam in order of drop	78
Daily amalgam, gold and silver in 769	De River flot itton process 1555 1559 1559 9020	21
Dalhousie University, the ore dressing apparatus at	De Bayay flotation process 1555, 1562, 1568, 2030 at Broken Hill	156
the r. n sexion	De Beers Co., diamond dressing	83
Dalton classifier . 398	Consolidated mines	108
hydraulic classifier . 398	Lid	192
Daly Judge mill 1724 Park City, Utah 1923, 2038	Minning Company	192
P. A. Gow, A. M. Hobart, G. S. Kruger, F. H.	Debris, control by government of Deck cover linguism for	204
1405015		146 150
mine and mill 2042	table	146
Daly-West mill W. I Spencer . 2035	of New Standard concentrator, linoleum for	147
Park City, Utah	round tables, material for, at Mill 162	184
slime plant. Park City Drah 9849	Decomposition of feldspars, A. S. Cushman and Pre- vost Hubbard	
Dam, Belgium, Kittinger tables at 668	DeCourteney, H W.	141 22
Dams for classifiers 406	gravity stamps	22
Dana, E.S	Decrepitation	161
mineralogy . xix minerals . 1173	and screening	83
minerals 1173 system of mineralogy 1188	at Mill 137 heating for	174
table of hardness 2	of minerals	82
Dana's tube mill 2017 Daniels, C. H., on settling kaohn 1149		156
	use made of, in mills	89
Dannemora, Sweden, magnetic concentration at 833 separation of iron ore 801	Deep double trough classifiers	41
separation of iron ore 801 mill at 1475	pocket hydraulic classifiers	40
Darlington, J., on breakers . 60	free settling classifiers	137
rolls . 111	hindered settling Classifier Deetken, G. F., Atwood amalgamator, Eureka rubber	1383 789
tronmels 385	concentration in California stamp mills	118
Darrow, W. E., testing of gold mill tailings 2049 Dash pot for steam stamps 127	kieve	729
of Northern stein stems 1975	stamp battery	229
Data from the mills concerning settling tanks 458	Definition of free settling and hindered settling of lundered settling	46
or rous, danc or 64	Definitions for jigs	48-
Datolite, specific gravity of 1189	Deflection of wire rope	109
Davey, Paxman and Company 282	Deflectors for spitzkasten	440
Davidsen, formula for calculating amount of pebbles for charging tube mill 1288	in settling tanks	45
power required by tube mills 1289	with plates De Course a and Sum of Mathet Hack trade on	74:
speed of revolution of tube mills 1337	De Gournay and Suisse, Mathet, Hochstrate appara- tus	837
10D2 mill 1980 1967	Deister concentrator .	2023
Cost of grinding by 1292 Davies, D. C., Blake breaker 56	at the Baltic mill. L S Austin	202: 202:
Davies, D. C., Blake breaker 56 free settling velocities 476	concentrators	1488
grauti stamas gog	at mills 1489, 1680, 1896, 4 De Kalb, Courtenay, adjustment of the stamp mill 2	1900
Husband and Sholl pneumatic stamps, Patter-	amalgamation inside the mortar	$\frac{2011}{2024}$
son spring stamp 143	definition of slimes 1	1398
hydraulic mining 1173 Marsden breaker 56	De Kalb classifier 2	2020
metalliferous numerals and manine	discussion of conditions under which crushing	
movable sieve and Harz nos (20		1326
is it, amagamation 787		1340 1340
Blake Marsden, Dodge, Gates breakers 56	on settling tank .	459
breakers 56	slimes	$^{1419}_{257}$
buddles, slime tables, vanners, kieves, Hendy concentrator 727	sizing test on sample grinder	257
Clarkson Stanfield process 837		2048 2019
Crickboom wash trommel 334	tests on corundum	2019 1184
Tree-settling velocities, hydraulic classitier		
pointed boxes 476 gravity stamps 223		14113
gravity stamps 223	De Limar, J. R., on Gulfin mill	$\frac{1402}{284}$
grizzhes and fromniels 90 (De Limar, J. R., on Gulfin mill	284 1134
grizzhes and trommels 384 Gruson ball mill 2993	De Lamar, J. K., on Griffin mill mill Delameter coal testing device	284 1134 1993
Huntington mill 296	De Lamar, J. R., on Griffin mill mill Delameter coal testing device De Laval centrifugal pumps at Mill 124 1	284 1134 1993 1695
Huntington mill 296 jig bed 574	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction	284 134 1993 1695 827
Huntington mill 296 ig bed 574 Krom's rolls 109	De Lamar, J. K., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 1 separator Delesse on magnetic attraction Delvik Grondal magnetic separator	284 1134 1993 1695 827 796 804
293 Huntington mill 296 jig bed 574 Krom's rolls 109 Lion mill 294	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar. A. advantages of stamps 2	284 1134 1993 1695 827 796 804 2013
203 204 205 206	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Lavial centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar, A., advantages of stamps discussion of plate amalgamation 2	284 1134 1993 1695 827 796 804 2013
123 124 125	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik-Grondal magnetic separator Del Mar. A. advantages of stamps discussion of plate amalgamation dredging, cost of	284 1134 1993 1695 796 804 2013 2024
123 124 125	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik-Grondal magnetic separator Del Mar. A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences million in Chiforni 2 2	284 1134 1993 1695 796 804 2013 2024 2036 2049
Huntington mill 233 236	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik-Grondal magnetic separator Del Mar. A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences million in Chiforni 2 2	284 1134 1993 1695 827 796 804 2013 2024 2036 2049 2045
Huntington mill 293 jig bed 574 Krom's rolls 109 Lion mill 294 machinery for metalliferous mines xix material of bottom bed 574 mill schemes 1173 Monarch magnetic separator 832 movable steve, Harz, Bilbarz jugs 639 on limit of sizes jügged 605, 666 roll streek 1666 roll stree	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik-Grondal magnetic separator Del Mar. A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences million in Chiforni 2 2	284 1134 1993 1695 827 796 804 2013 2024 2036 2049
Huntington mill 293 jug bed 574 Krom's rolls 109 Lion mill 294 machinery for metalliferous mines xis material of bottom bed 574 mill schemes 1173 Monarch magnetic separator 832 movable steve, Harz, Bilharz jugs 639 on limit of stees jügged 605, 666 son limit of stees jügged 605, 666 Son limit of stees jügged 87 Davis Colly shaft furnate for roasting 814	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik-Grondal magnetic separator Del Mar. A. advantages of stamps discussion of plate amalgamation 2 dredging, cost of stamp mill experiences milling in California Deloro, Ontario, milling at, an auriferous mispickel at P. Kirkegaard Delprat, G. D., Broken Hill milling practice 2	284 1134 1993 1695 827 796 804 2013 2024 2036 2049 2038
Huntington mill 293 jug bed 574 Krom's rolls 109 Lion mill 294 machinery for metalliferous mines xis material of bottom bed 574 mill schemes 1173 Monarch magnetic separator 832 movable steve, Harz, Bilharz jugs 639 on limit of stees jügged 605, 666 son limit of stees jügged 605, 666 Son limit of stees jügged 87 Davis Colly shaft furnate for roasting 814	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 1 Separator Delesse on magnetic attraction Dellvik-Grondal magnetic separator Del Mar. A. advantages of stamps 2 discussion of plate amalgamation dredging, cost of stamp mill experiences milling in California Deloro, Ontario, milling at, an auriferous mispickel at P. Kirkegaard Delprat, G. D., Broken Hill milling practice concentration at Broken Hill 2	284 1134 1993 1695 827 796 804 2013 2024 2036 2049 2038 568
Huntington mill 293 jug bed 574 Krom's rolls 109 Lion mill 294 machinery for metalliferous mines xix material of bottom bed 574 mill schemes 1173 Monarch magnetic separator 832 movable steve, Harz, Bilharz jugs 639 on limit of stees jugged 605, 606 roll speech 870 Davis Colby shaft furnate for roasting 814 ditter press at Mill 102 dats, F. M. I from Works Co , Ferraris ball mill 1823	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 1 Separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar, A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences milling in California 1 Deloro. Ontario, milling at, an auriferous mispickel at P. Kirkegaard Delprat, G. D., Broken Hill milling practice concentration at Broken Hill flotation process 1555, 1	284 1134 1993 1695 827 796 804 2013 2024 2036 2049 2038 568 568
Huntington mill 233 236	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 1 Separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar, A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences milling in California Deloro. Ontario, milling at, an auriferous mispickel at P. Kirkegaard Delprat, G. D., Broken Hill milling practice concentration at Broken Hill flotation process at Mill 129 15561, 1 testing for	284 1134 1993 1695 827 796 804 8013 8024 2036 2038 568 561 718 1993
Huntington mill 293 jug bed 574 Krom's rolls 109 Lion mill 294 machinery for metalliferous mimes xix material of bottom bed 574 mill schemes 1173 Monarch magnetic separator 832 movable sever, Harz, Bilbarz jugs 639 on limit of sizes jugged 605, 606 roll speeds 87 Davis Collow shaft furnace for roasting 814 other press at Mill 102 1630 Davis, F. M., Iron Works Co., Ferraris ball mill 1323 patent cames 194 roll speeds 87 87	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar, A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences milling in California Deloro, Ontario, milling at, an auriferous mispickel at P. Kirkegaard Delprat, G. D., Broken Hill milling practice concentration at Broken Hill floation pracess at Mill 129 1556, 1 testing for 1 1 1561, 1 1561, 1 1 1561, 1 1 1561, 1 1 1561, 1 1 1561, 1 1 1561, 1 1 1561, 1 1 1561, 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	284 1134 1993 1695 827 796 804 2013 2024 2036 2038 568 568 5718 1993 1923
Huntington mill 2936 293	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar, A., advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences milling in California at P. Kirkegaard Deloro, Ontario, milling at, an auriferous mispickel at P. Kirkegaard Delprat, G. D., Broken Hill milling practice concentration at Broken Hill flotation process at Mill 129 testing for ore dressing at Broken Hill process of flotation D. Clark	284 1134 1993 1695 827 796 804 2013 2024 2036 2038 568 561 718 1993 1923
Huntington mill 236 jug bed 574 Krom's rolls 109 Lion mill 294 machinery for metalliferous mines xix material of bottom bed 574 mill schemes 1173 Monarch magnetic separator 832 movable steve, Harz, Bilharz jugs 605 606 701 peeds 605 606 roll speeds 87 Davis Colby shaft furnace for roesting 814 filter press at Mill 102 Davis, F. M., Iron Works Co., Ferraris ball mill in 1823 jatent cams 194 roll speeds 87 M. C., on Tremain stamp 139	De Lamar, J. R., on Griffin mill mill Delameter coal testing device 1 De Laval centrifugal pumps at Mill 124 1 Separator Delesse on magnetic attraction Dellvik Grondal magnetic separator Del Mar, A. advantages of stamps discussion of plate amalgamation dredging, cost of stamp mill experiences milling in California Deloro, Ontario, milling at, an auriferous mispickel at P. Kirksgaard Delprat, G. D., Broken Hill milling practice concentration at Broken Hill flotation process at Mill 129 1561, 1 1661, 100 or dressing at Broken Hill proces of flotation D. Clark 1 1	284 1134 1993 1695 827 796 804 2013 2024 2036 2038 568 568 5718 1993 1923

Pages 1199-1610, Vol. III.		DEX.	Pages 1611-2052	, Vol. IV.
Demaret, L., Husband pneumatic stamp mechanical versus hand crushing	143	Details of screens		168, 170
Nicholas pulverizer	$\frac{61}{292}$	for stamps, table	of	121
stamps and other pulverizers	316	spindle breakers in stamp bosses	the mills	186
tin ores in Cornwall Tregoning pulverizer	118 5 297	cams		192
Demond, C. D.	viii	shaft, table of stem		128
on electrolytic dissociation of slimes	1414	tappets		187
Denny, G. A., and H. S. Rand metallurgical prac- tice.	1923	Staves from mills, to	ıble of	123
Rand mill equipment	2041	steam stamps Sturtevant roll jaw	hreaker .	126
design and working of gold mill equipment equipment of stamp mills	126 1 2012	trommels	DATURCI	. 33
hydraulic stamp	1257	valve action whole current box of	1	347 127
mill of the Van Dun gold mine estate	2041	Detroit Copper Mining (Company of Arizona	444, 446 1874
on hand picking sectional guide blocks	2021 1269	Detroit Copper Mining (of the	2041
n. 5., discussion of grading analysis	2048			. 1310
sizing tests on slimes and sands slime treatment on the Rand	2019	Development, effect on a Devices for safety on ste	am stamps	. 1128 . 127
Density of liquids affecting concentration effect on free settling	1419 3			689
effect on free settling	465	Devonshire, kaolin washi Dewaterers at Mill 138	ing in .	1077 1745
pulp for slime tables . Denton, F W , crushing plant at Minnesota Iron mine	$\frac{695}{57}$	Dewaterer, shovel		2032
plant at Minnesota Iron mine	57	Dewatering device at Mi screens	li 141	1760
rolls versus steam stamps at Mill 179	1900	at mills	••	1591 1858, 1867
Denver, cost of mill at Engineering Works Company, Blake breaker	$\frac{1126}{1203}$	Fitzgerald Rogers' dewaterin		2032
gravity stamps	1278	shaking launder at 2	g sercen	. 1591
grinding machinery .	1323	wheels	MIII 112	1872 1590
revolving grizzly Richards' pulsator classifier	1353 1388	at mills	1591, 1725, 1772, 1773	. 1878. 1879
jig -Shepard <i>spitskasien</i>	1459	Fleming Dewey, C. E., Plake bre	1590	, 1609, 2031
-Shepard spitskasten	1401	on breaker	aker would Dodge	57 57
and Richards' pulsating classifier rigid rolls	$\frac{1419}{1235}$	Sizing tests of right	products	6.00
at Mill 181	1906	Diagram of sizing tests of and stamps	of products of Tustin	mill
scoop feed for tube mills .	1287	Dial cocks		300 858
tube mill 1280, at Mill 143	1770	for classifiers		387, 388
Fire Clay Company, Case Liboratory breaker 1204	1223	gravity stamps on jigs		199
Depreciation expenses	1123	Diamagnetic substances Diameter of classifier spir		538 796
Depth of bank in trommels bed on concentrators	380 1510	Diameter of classifier spir	gots	404
Harz jigs at mills 1750, 1751, 1877, 1878, 1	879,	iron papa rolls		405 83
	1929	shafts in jigs	•	533
Hodge jigs at Mill 180 1902, 1903, 1904, Derrick, W. H., tin ore in the Malay Peninsula	1182	slime tables trommels		696
	viti	effect of		349 379
Derry, W., Husband stamp Description of Blake breaker	143	wire for screens		371
Desert mill, Fonapalt, Nevada, A. R. Parsons Power and Mill Company	13 2045	Diameters and velocities of	of quartz grains	2003, 2004,
	1666	areas of circles	2000, 2001,	2005, 2006 2002, 2003
hte of shoes and dies at Designation of holes in stamp screens	1277 172	of stamp shoes and die		
Design of Blake breakers	1201	Diametral ratio between e settling		dered 1460
Classifiers	196	Diamond dressing in S. A.	Mrica A F Wilham	> 2040
electro magnets	1422 790	neids of South Africa	i, washing pans used i	n 333
machines	1096	pans specific gravity of		335 1189
	2049	washing at Mill 188	839, 1080, 1178,	1179, 1185
	1126 2048	at Mill 188		1921
A C McCallum	2048	W H Mungal	ll	2046 2034
rolls settling tanks	78	in Africa - R. Stok W. H. Mungal Brazil - H. W. I	Furniss	2038
sulplude mill, 150 ton A Harvey 5	454 2041	South Africa G. F. William	3.3.3 20.3.3	2040, 2042
two small miles S. I. Hallett	2043	tube mills for	•	2043 2014
Trestoke, J. M., Blake breakers	57	Diamondiferous earth, was	shing pan for	335
1175 1	175	Diamonds recovered by go separated by weather	reased plate	831
disposal of concentrates in	57	Diaspore, specific gravity	of	. 830 1189
De Soto mine ore Krom air iir on	587 824	Diepenlinchen, jigging fou Luhrig tables at	ir minerals at	590
A von temperature of water for amal	024	mill, jigs in		670 597
	789	Die rings and roller shells	in Huntington mills	280
Details of Blake type of breakers from the mills cams, table of	23 192	for Huntington mill	1	280
Clean-up of gravity etampe	202	and shoes for grinding	g pans, wear of	174 1289
Comet breaker cost of crushing by breakers	41	and shoes for grinding at Mill 117		1668
crushing by rolls	49 104	for amalgamating pan	15	245
steam stamps	135	gravity stamps, life steam stamp	oı	1277 120
	180	weight, life, etc.	•	. 122
diessing and Cleaning plates	30 757	life of table of details of		184
	178	Diescher coal jig		180 520, 640
McCully gyratory breeker	540	connecting rod for	1	530
rings from mills, table of	4 4 122	Differential-motion jig, Ho New Century jig .	xige jig	1444
	21	remaining .		1220

TO 100 - 11 1 - 1 - 11 - 11 - 11 - 11 - 1	
Differential motion, Woodbury jig	Dissemination of mineral affecting crushing limit 304
Difficulties in concentration 892	Distances between rolls for various angles, in author's tests
of dredging 1009	tests 311 Distillation of mercury 782
screening 372	Distilled water, effect of in settling
Dillon concentrator	Distl-Susky screw grate screen 386
Dillon concentrator 2022, 2023 Iron Works, Perfection ore feeder 1578, 1609 Dillsboro, North Carolina, kaolin washing at 1149	Distributing conveyor 861
Dillsboro, North Carolina, kaolin washing at	at Mill 143
Dimensions of Abbé tube mills at Mill 101 1626	devices
Comet breaker 44	tanks 449, 1115
Ding's magnetic separators	Distribution of amalgam from plates . 764
jig sieves 591	gold recovered in mill
Linkenbach pointed boxes 441	•pulp in settling tanks
Richards' pulsator jig, table of 1455 shoes and dies 181	Distributors
stamp dies	bibliography for . 884
mortars 165	Blasdell 1600
Sturtevant balanced rolls, table of 1234	centrifugal sand distributor . 1602
tappets	Butters & Mein at Mill 106
tule mills at Mill 103 tule mills at Mill 103 tule of 1532	for amalgamated plates
Wetherill magnetic separators, table of 1522 Dimmick classifier 1417, 1420, 2020	buddles 704, 706 canvas tables . 700, 701
J O, on classification 2020	canvas tables 700, 701 feed on Roberts' slime tables 691
sizing before amalgamation 1514, 1520	slime table feed and water 4 688
& Son, distributing launder 1417	stamp mills 772
patent slime table 1507	vanners 646
Ding Electromagnetic Separator Company, the Ding	machine . 857
separator 1540, 1568, 2029 at mills 1541, 1663, 1737, 1739, 1759	mill 857 revolving distributor or divider 1418
description of the 2027	Ditches for water 1105
table of weights, dimensions, and power for . 1541	Dives-Pelican Mine, Samson breaker at . 1203
roasting furnace . 1548	Robert, advantages of hand picking 493
at Tripoh mine	Dividend gold saver
Dingey mill 233 bibliography for 293	Driston of concentrating 318 mills for different ores 1111 Dodd buddle G Attwood 2022 buddle at Mill 96 1481 disc water wheel 1022
Diorite, strength of 301	mills for different ores 1111 Dodd buddle G Attwood 2022
Dipper diedge	buddle at Mill 96 1481
sample . 845	disc water wheel 1022
Direction of rotation for tube mills	table 675
Direct pumps 871	tables at Mill 96 1618
smelting, cost of 1 Dirt . 900	water wheels 1024, 1089, 1090 W G
Disadvantages of gravity stamps as compared with	W G viii on amaignmating pan 248
rolls and grinders . 222	Dodge breaker
Krom jig 825	at Mill 183 1913
springs on jigs 517	compared with Blake 33
Disc conveyors 1583 at mills 1583 1695	Humboldt type 1206
	improvements on in Mill 26 35 movements on, made by Gates Iron Works 34
motion for accelerated µgs 536 Discharge, bell, for µg concentrates 506	Parke and Lacy Company . 34
for jig 510, 518, 553, 576, 577	Parke and Lacy Company . 34 perspective of . 29
concentrates 500	section of 30
m Krupp Harz ng 1446	sizes of 30
New Century jig . 1445 Woodbury jig . 1448	Sturtevant Dodge type breaker 1205
Woodbury pg . 1448 Leavitt steam stamp 993	table of details . 30 used in stamp mills . 1014
steam stamps 129, 1003	wear of 31
Krause mortar and mortar ug 1256	M B
tube mills	jaw breaker . 28
into the hutch in jigs 586	mill, bibliography for . 294
of belt conveyors 860 elevators 862	pulverizers . 231, 233, 262
jig concentrates by rakes 502	number used 231 sizing box
ore bins 842	Dolbear, Clinton E, electrostatic separation 1550
products on Hooper air pg 821	Dolcoath mill 1082
settling tanks . 458	Cornwall, concentration at the. R. A.
stamps, area of 209	Thomas
height of 212 roll for vanner concentrates 647	strips
with unwatering sieves 586	tin mill 1183 Dolgelly, Wales, mill at 1072
Discussion of design of Blake breakers, by W. G.	Dolomite, with disseminated galena, crushed in Mill
Bryant . 1201	25 47, 98
sorting tube results . 467	ore, weight of
Disintegrating and screening 839	specific gravity of
Disintegration and screening for graphite ore 500 to 1074 followed by screening 500 sc	Domeykite, specific gravity of 1189
settling • 830	ore, weight or
Disintegrators	Dornberg and Aurora mill
and pulverizers 1319	classifiers at 477
bibliography for	sieve scale at . 367
Bourdais	and Aurora works, sizes of ore hand a cked at. 487
Brink and Hubner 284 Carr	mill, jigs at . 641
Stedman . 284	Dorotheer mill
Vapart's	of Lundberg, Dorr, and Wilson, Black
Dispersion of magnetic lines . 791	of Lundberg, Dorr, and Wilson, Black Hills, South Dakota
Displacement pumps 1589 Disposal of concentrates 586	Dorr, John V. N., Dorr mechanical classifier 475, 476.
4.0	477, 1343 Double-cone classifiers
tanings	Double-cone classifiers

14600 1100 0000,		rages 1011-2052, Vol.	IV.
Double-cone classifiers at Mill 117	, 1669	Dredging gold, how tomake it pay A. W. Robinson saving tables used in. C. W. Purington. ground, testing of, R. M. Downe in Alaska. O. Halla gold C. A. Tupper Bornes, gold Br. 2018 C. S. W. Bolt. Br. 2018 C. S. W. Bolt.	2035
hydraulic classifier	1381	saving tables used in. C. W. Purington.	2041
tubular classifiers	476	in Alaska, O. Halla	2043
Double crimped wire screens	370	gold C. A. Tupper	2041
Double-cone classifiers at Mail 117. 1608 hydrafulic classifier table of sizes tubular classifiers Double crimped wire screens screens discharge for jigs mortar, Traylor on stamps eccentrics for jigs iron frame for jig sieves issue in stamps	583	Borneo, gold Brazil F. C. Nicholas	2036
mortar, Traylor	1266	British C. U. Nicholas British C. L. Watson	2046 2041
on stamps	209 531		2042
iron frame for jig sieves	540	A. G. Hillen L. E. Aubury	2046 1924
issue in stamps -Rittinger sieve scale	167 1361		
trough classifiers		details of, G. P. Grimsley	2036 2044
Douglas Island, Alaska, cost of producing gold in 1976	1975,	Colorado, cost of, W. E. Thorne F. I.	2044
	1133	Moore Europe L St. Rainier	2045
mortar blocks on	148	Grasshopper Creek, R W Bell	2047 2041
Douglas, James Blake, Dodge, Forster, Comet, and Gates breakers	57	Grasshopper Creek. R W Bell Guiana, S America O Rehwagen	2039
breakers	55	riungary and Transylvania	2040 2036
gravity stamps Harz jigs	224	New South Wales	2034
ore dressing	$\frac{640}{1175}$	ranure of gold. D K Blair	2034
principles and operations of crushing and		unsuccessful	$2034 \\ 2034$
grinding machinery J. Jr., Ball stamps	$\frac{2017}{142}$	New Zealand	2043
on cost of crushing by steam stamps	134	F. W. Payne	2043 2039
Drag conveyors 1582, Dragon breaker .	1583	D B. Sellars	2043
Descritore mill	$\frac{58}{237}$	gold	2036
Drained ore, moisture in	1107	1900, gold 1 Littenins	$\frac{2041}{2038}$
Drake, F. M., gold stamp mill of Wentworth Com- nary at Lucknow New South Wales	1181	Oregon	2043
Drained ore, moisture in Drake, F. M., gold stamp mill of Wentworth Com- pany at Lucknow, New South Wales plates in Wentworth mill, Lucknow, Australia	788	Siberia C W Purington and J. R Land-	2043
shoes and dies Wentworth Goldfields, Proprietary Co , stamps	181	nea. n	2035
at. New South Wales	227		2039 2040
W F, amalgamation on temperature of amalgamation	789	Venezuela F Owen	2036
Draper's dry concentrator in Australia	767 2029	modern gold H G Clark	2046
Dredge .	898	Klondike J P Hutchins	2043 2038
at Ruby, Montana bucket in New Zealand	$\frac{2043}{2037}$	Saskatchewan 1 Cowie	2034
current motor	2044	operation, returns from	2036 2046
for phosphate limit for Stewart River district, Alaska A. W.	897	plants	1006
Kobinson	2037	power plants for	2044 2036
New Zealand gold J. P. Smith	2046	prospecting and operation R H Postlewaite	2040
yild of a California Dredges and equipment, cost of	2037 1654	river C C Longridge	2036
at Ruby, Montana, electrical	2045	spuices and riffles in D. H. Stovall	2045 2045
Bucyrus comparison of American and European F. C	1654	tin tables for	2040
Perkins .	2042		703 2636
old and modern style	2044 2034	Dressing of belts	1093
construction and operation of. D. K. Blair detailed comparison of R. L. Montague different types of B. Cunningham	2034	of plates	756 166 3
different types of B Cunningham	2035	tin ore	1081
electrical equipment of gold. C W Whitney history of J P Hutchins	2041 2037	Driers 879, 880, 1595, American Process Company driers	1609 1597
nvaraunc power for	2036	and drying of ore P. Argall Argall cylindrical driers	1609
improvements in gold G E. Walsh revolving versus shaking screen in	$\frac{2037}{1653}$	Argall cylindrical driers at mills 1762, 1807, 1813, 1822, 1860.	1599
rilles for	722	capacity of drying floors versus mechanical driers	1917 1596
Risdon Dredging	$\frac{1654}{1652}$	Classification of	1595
Dredging P. G. Morgan	2036	cylindrical driers drying floors	1596 1596
amalgamated plates and riffles in gold. J. M. Sweenev	2041	Edison tower drier	1600
	2041	Grill four-compartment direct heat driers	1596 1597
at Italia Talaka	2043	ore C O. Bartlett	2031
Golden, Colorado K Thomas Nome, Alaska, J P Hutchins gold, G P Grimsley Oroville, California N B Rose	2046 2039	revolving, at Mill 138 cylindrical drier at Mill 135	1746 173 5
gold, G. P. Grimsley	2036	shaft, at Mill 151	1803
Oroville, California 2037, N. B. Knox	2044 2040	Drifting tool for stamp cams	193
Ruby, Montana, gold. J. P. Hutchins	2039	rolls at •	640 110
by the Oroville Dredging Co , California	2044 2046	Drill points in mills	1115
cost data on. Alex. Del Mar	2046 2036	Driver in amalgamating pan Driving mechanism for cam shafts	247 197
CARL CO	1654	ciucnes	198
discussion on. L. I. Hahl	2046 2037		198
for gold 1007, 1181, tables for	1182	gravity stamps	197 75
rold	703 2046	tightener	198
A. W. Robinson 2035,	2041	table of	356 76
T. F. Van Wagenen W. S. Russell	2043 2041	Drop between jig sieves 524,	549
W. S. Russell	3	plates	743
	9	o e e e e e e e e e e e e e e e e e e e	

Drop hammers	Dust chambers
limits of speed and height of, due to mortar 218	difficulty of concentrating 820
maintaining height of in gravity stamps 200	fans and chambers
on amalgamated plates	prevention 1099
maintaining height of in gravity stamps 200 of gravity stamps, order of 1274 on amalgamated plates 737 order of C S. Réthardson 1278 for stamps 214 Drops in amalgamated plates 733 number of in gravity stamps 214 of stamps 114 of stamps 114 of stamps 115 of stamps	prevention
Drops in amalgamated plates	
number of in gravity stamps 214	at Mill 151 1803
number of in gravity stamps 214	settler at Mill 135 1736 settling apparatus. T White 2032
Drumlummon mine ore 1027, 1040	device 2032
Drum magnetic separators	system at Mill 141
blowing in prospecting for gold ores 2029	Duty or capacity of trommels 359
concentration	Dyckhoff breaker 57 Dynamo for lighting 1100
Roseberry 2047	
Round Mt, Nevada. G. A. Packard 2038	E
bibliography for 837 in Australia	Eagle Foundry Co , rolls
Austrana, comparison of 2030	West Va., Stedman disintegrator at 285
on the Cammett table 2022 crusher, Langlev's improved 274	Eames, W. H
crushing and evaniding at the Luipardsvlei mine.	dredge, tables on 703
F White, G H Furnee 2047 by Edison process 2010	Earth in bank, weight of
stamps 226	extraction 1117
in Colorado 1244	number of pg sieves 589
rolls for 1224 house for men 1102	Eastern United States, cost of producing iron ore concentrates in 1986, 1987
magnetic separator, Conkling 809	Eastman, G. W., analysis of work on free settling
ore sizer, Keedy	velocities 1423 Eastwood improved lifting magnet 1532
panning and blowing 825	at Mill 164 1532
placer machine 838, 839	Frantisc for us
screening <i>versus</i> wet 1139 separation 890, 891	gears for steam stamp valve motion 123 grinders
separator used in Germany 2029	ng, the Bradford 400
silver mill 1039	mill James Bogardus . 259
stamping 221	Eckart rolls
at Ontario mill	Economy of hand picking 487
table, Sutton, Steele & Steele . 1554 vanner . 838	large engines
Dryers See Driers	Eddies in rifles . 721
Drying bin at mills 1625, 1669, 1705, 1912 for concentrates 1570	Electric Mfg Co , dynamos 437 Electric Mfg Co , dynamos 1062
floors 880, 1596	Edge runners 234, 269, 1305
at Mill 143 . 1770 in kilns . 899	bibliography for 295 Bryan roller quartz 271
iron ore 1054	Bryan roller quartz 271 compound 296
kaolin . 1077	Lingley's recognized denomation 974
necessary for air concentration . 826 of clay . 1077	Edgestone mills
of ores W R Ingalls 1610	Edison concentrating plant 834
slimes at Mill 129 1717 use of hot lines for drying coarse ore at Mill 158 1826	corrugated rolls 106 at Mill 152
Dubuat, M., Hydraulique et Pyrosiynamique xix	distributing conveyor 861
launders 885 on transporting power of water 878	distributor 858 dry gold separation process. C M Chapman 2027
Duck for canvas tables 700, 701	dryng kiln 861, 1600
	dusting chambers
Dudley, A. P., spring for Collom jig 517 W. L., amalgams 787	giant rolls 105 magnetic concentration mill 1056
Dufferin mill 1099	concentrating plant, New Jersey and Pennsyl-
Duffield, P. W	vania Concentrating Company mill xxix mill
	plant 1179
hand jig 1182	plant . 1179 separator for fine materials . 810 method of preventing blinding of screens . 373
testing igs 1151	New Jersey, mill at 1056
Dummler, K., crushing and washing clays 1173	on life of belts 864
Dump at Mine La Motte, Missouri, treating the old 2045	opinion on shape of hole in screens 369 process of crushing 2010
for tailings 1113	screens 341
of the Bellevue Colhery, method of working G. W. Harris 2041 Dunham's spring stamp 141, 143	separator 812 smooth rolls at Mill 152
Dunham's spring stamp 141, 143	special forms of rolls . 110, 111
Dunlap Manufacturing Company, perfect clay screen 1357 Dunnellon, Florida, mill at 899 Dunnellon, Florida, mill at 899	sprocket drive . 860
Phosphite Co, mill xxv, 899	siationary screens 341 three-high rolls 107, 2010
Duplex breaker 60	T A, on belts 1094
of Blake type 21 Callow screens at Mill 123 1689 1672	T A, on belts and J Birkinbine, Blake system Buchanan, Wenstrom, Conkling, Monarch and Edison separators 833
vacuum pumps at Mill 117 1673	arch and Edison separators . 833
Dupont () and Ch. Quélynt, dressing lead and	on blinding of screens 373
zine in Belgium 1185 Durango, sectional iron stamp frame for 161	breakers . 57 lubrication
Dust blown from coal 817	magnetic concentration 1058

ages 1-643, Vol. I. O.	KE L	RESSING. Pages 644-1197, Vol.
many all assess in Commell M. Boldani	2047	Family all all and the same
more, oil process in Cornwall. M. Baldauf Ore Concentrating Company	. 1993	Engis, air classifier at
plant, London, England	2035	English standard gauge
process	1158	English standard gauge
at Dolcoath E Walker .	2039	
the Tywarnhaile copper mine, Cornwa	dl.	Enterprise mill. Plattesville, Wisconsin
England	2038	E. P. Allis Company 72 76 111 181 187 180
C. M. Rolker	202	197 228 243
E Walker	1569	batea made by
failure of	2029	
for Slocan ores	202	edge runner made by
in diamond washing Rossland, failure of	2020	inside plates
Rossland, failure of	. 202	muller and shoes made by
saves 93 percent of values statement on the F/H Claudet	202	power for 5-foot pans estimated by
statement on the F H Claudet	202	shoe and die channels in amalgamating pans
testing for	199	bv .
tests on, at Glasdir mine, Wales	83	
results of	204	Epidote, hindered settling test on 617,
vacuum flotation process, description of the A S Elmore E Walker	he.	settling velocity of . 466,
A S Elmore 15	69, 202	specific gravity of
E Walker	202	Equipment of gold mills. G. A. Denny Equivalents of weights and measures Erbum, atomic weight of
oil process 1556, 20	26, 203	Equivalents of weights and measures
at Cornwall, England	155	Erbium, atomic weight of
Mill 141	. 176	Erecting mills, costs of
consumption of oil	156 202	
description of the F. H. Prentiss in Sweden	202 156	Ernst, C. von, separator at Monteponi
Oro cast iron ribbed liners for tube mills at M	190	Errors of small tests
Oro east from rioned liners for tube mills at A.	167	Erythrite, specific gravity of Eschka, A , separation at Przibram
district, Mexico, cost of producing gold		Espiritu Santo mill at Cana, Darien E R Woakes 2
10	80, 198	plates in
lining for tube mills .	1340	Essential qualities of classifiers
Mining and Railway Company	1670	Essential qualities of classifiers Essentials of a good breaker
Mining and Railway Company tube mill hining 2014, 20		
Paso Foundry rolls at Mill 151	180	Estimates on cost of hand picking
smelter, sampling at	88	Eureka Hill mill xxviii, 228, 1041, 1
smelter, sampling at Potrerito mill	1663	Eureka Hill mill xxviii, 228, 1041, 1 W McDermott . xxviii, 228, 1041, 1
Silencio mill, fineness of amalgam in	763	stimic
spass mili 12	80, 132	wear of amalgamating pans
utriation 8	30, 161	rubber 770,
for emery	107) Utah, mill at 926, 1
use made of, in mills	889	
nbrev vanner	65	milling in
testing	117	
nerv mill at Mill 186	191	Eustis, Canada, hammers used
ore, mili for	107	mill at
separated by magnets	79	
washing	70 121	mill . xxv,
wheel for truing roll shells	70, 124; 117,	W E C. and H M Howe, magnetic process for
nmons, S. F., gold stamp mills in Maryland and G. F. Becker, amalgamating pans	. 29	
and G r becker, amaigamating pans amalgamation	789	Evans classifier 393, at mills 1838, 1839, 1844, 1
	29	Collom, and Woodbury jigs, capacities com-
edge runners .	29.	
pire mill xx	vii, 1020	pared I G. H., hydraulicking
Plattesville, Wisconsin	203	hydraulic mining xix, I
stamp mill	118	
Zine Company	175	ideas on jigging 2
mill	90	7 ing - 517.
15	110	2 at mills 1837, 1843, 1844, 1
Linkenbach V box classifier at	42	size of sieve and plunger
mill at 10	87, 113	water used by compared with that used by
number of sieves on jigs at	59	I Hancock jig .
sieve scale at	36	round tables at Mill 162
argite, specific gravity of	118	short stroke pg at Great Falls . 2
d-bump group of tables	149	slime tables at Mill 177 .
tables , 667, 6	80, 146	table
comparison with side bump	68	
Ellenbecker table	68	Waddell Chili mills at Mill 160
Gilpin County concentrator	68 68	W. J., slope of launder in mill of Atlantic Copper Mining Company
Golden Gate concentrator	68 68	Mining Company
Imlay	109	Evrard, M., rod pgs
dless belt	. 85	mechanical discharge for jig tailings
conveyors chain conveyor .	. 86	
d-shake vanners 652, 11	6 5 , 150	jig
Akens and Evans slimer	150	Excavating expenses .
Embrey concentrator	65	
for testing	115	B Excelsior breaker
Triumph concentrator	65	Exhaust fans 1
versus side shake	65	steam for heating
vibration in	65	Expanded metal rifles 703, 722, 1067, 1008, 1
Woodbury	65	
ergy of gravity stamps	21	Expense accounts
steam stamps	13	
steam stamps igelmann, H, air versus water jigging, Utsch si	ide	study
plunger rig	. 64	Experiments on film sizing
igines used in mills. See Individual Mills	111	
plunger jig igines used in mills. See Individual Mills Chapter XX. in mills	109	Overstrom's

Eatent of crushing desired 302	_	_		
Extraction at Meyer & Charlon mill, Soluta Arrica and Sime tables compared to surprise the strains of strains and sime tables compared [91, 602] in mills [1018, 1022, 1026, 1039, 1048, 1049, 1057, 1059, 1060, 1075, 1078, 1059, 1060, 1075, 1078, 1078, 1078, 1079,	Extent of crushing desired	303	Feed for stamps, quarter inch 2	012
Average Secretage made in various districts 1911 1912 1918 1912 1914 1916 1971 1972 1973 1978 1	Extraction at Meyer & Charlton mill, South Afric	a . 1647		
1837, 1891, 1897, 1898, 1900, 1907, 1907, 1908 1901, 190	average, percentage made in various distri	cts,	vanners	658
1837, 1891, 1897, 1898, 1900, 1907, 1907, 1908 1901, 190	table of	1012	and slime tables compared 691,	692
1837, 1891, 1897, 1898, 1900, 1907, 1907, 1908 1901, 190	in mills 1018, 1022, 1020, 1009, 1048, 10	719 1791	proper consistency of	
1837, 1891, 1897, 1898, 1900, 1907, 1907, 1908 1901, 190	1792 1794 1796 1730 1745 1767 17	71 1780	free and chake foul for rolls are rolls	
1837, 1891, 1897, 1898, 1900, 1907, 1907, 1908 1901, 190	1782 1791 1815 1816 1817 1820 18	326 1827	maximum size for Wetherill magnetic separator 1	595
Extraction and costs 136	1830, 1834, 1849, 1856, 1865, 1870, 18	371, 1881,	natural, on Wilfley table	
Extraction and costs 136	1887, 1891, 1897, 1899, 1900, 1906, 19	907, 1908,	opening in mortars	
Extraction and costs 136	1900, 1912, 1914, 1916, 1	920, 1922	openings for tube mills	287
Extraction and costs 136	of metals and minerals by Elmore process	:559	sized, for Wilfley table	473
Extraction and costs 136	percentage of. See Individual Mills in Cha	pter XX.	versus classified feed for Wilfley table . 1-	
State Stat	percentage of	1115	size of feed to Ball Norton magnetic separators 1	528
Section Chibuahua 1932 1933	Extractions and costs	2014	in gravity stamps	207
Second	III 5 Allica increment by time grinding .		For the magnetic countries	
Faber du Faure furnaces at Mill 176 E. washing of graphite for lead pencils 1776 E. washing of graphite for lead pencils 1776 Face of rolls 1776 Face of rolls 1877	numerican of in various mile		sole for chaerfore	
Faller du Faure furnaces at Mill 117	percentage of in various sums	1002	shizlute	
Faller du Faure furnaces at Mill 117	F		suited for Wiltley slimer 1	505
Factor foll Marcy Company, Elspass mill Falten bentoms Factor foll Marcy Company, Elspass mill Falten bentoms for stamps Farbe bottoms for stamps Farbe bottoms for stamps Farbe bottoms for stamps Farbe for farbe following the following stamps at the following s			to Polls	63
Factor foll Marcy Company, Elspass mill Falten bentoms Factor foll Marcy Company, Elspass mill Falten bentoms for stamps Farbe bottoms for stamps Farbe bottoms for stamps Farbe bottoms for stamps Farbe for farbe following the following stamps at the following s	Faber du Faure furnaces at Mill 117	. 1674	Wilfley table	674
Factor foll Marcy Company, Elspass mill Falten bentoms Factor foll Marcy Company, Elspass mill Falten bentoms for stamps Farbe bottoms for stamps Farbe bottoms for stamps Farbe bottoms for stamps Farbe for farbe following the following stamps at the following s	E, washing of graphite for lead pencils	1176	water for New Standard concentrator 1	
Fashe intofamilia at 136, 177 False intofamilia at 136, 177 Samps at 225 Samps at 225 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 171 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 1	Face of rolls		reeders See Individual Mills in Chapter XX.	
Fashe intofamilia at 136, 177 False intofamilia at 136, 177 Samps at 225 Samps at 225 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 171 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Chalenge feeder 187 Samps at 180 Chalenge feeder 187 Samps at 1	Fairbanks, Morse Company, Elspass mill	1323	reeders . 853, 1	578
Total part 180	Nissen stamps .		at Mill 120 [100
Falm, Sweden, mill at Samps at Samps at Samps at Samps at 225 Fan for air blast start 225 Fan for air blast 816 Fan at Mill 186 1917, 187 1976 1977 1978 1978 1979 19	raise pottonis		Challenge forder	
stamps at Samps at Samps at Samps at Samps at Samps at Samps at Sam for art blast for distributing share of the stamps and stamps are stamps as the stamps are and stamps and stamps are stamps and stamps are stamps and stamps are st	Isalan Sweden mill at		type 1	580
Fan for air blast 846	etamps at	225	for Argall driers	600
Farlake, Netan, comparison between Wetherill septartator and wet pgs.	U f non bloot	816	clavey ore	71
Farlake, Netan, comparison between Wetherill septartator and wet pgs.	shaped apron for distributing .		gravity stamps	199
Farlake, Netan, comparison between Wetherill septartator and wet pgs.	Fans at Mill 186	917, 1918	Huntington milt	278
Arator and wed piges Sale 2009 Samual steams 134 1287	for dust	883	movable sic' e jigs	500
Farrol Baton breaker at mills 1221, 1690, 1749, 1769, 1868 1864 breaker at mills 1221, 1690, 1749, 1769, 1868 1864 breaker at mills 1221, 1690, 1749, 1769, 1868 1864 breaker at mills 1221, 1690, 1749, 1769, 1868 1864 breaker at mills 1221 1869, 1749, 1769, 1868 1864 breaker 14, 21 1864 breaker 14, 21 1864 breaker 18	Farbaky, Stefan, comparison between Wetherill	sep-	rolls	.71
Barcel Baron breaker at Mill 175 1888 1889 1886 1816	arator and wet jigs	836, 2030	small steam stamps	137
Hos of wearing parts at Mill 139 1221 Hos ur ore 2383 2384 2	l argo guide for gravity stamps	104, 100	tune mills 1	287
Hos of wearing parts at Mill 139 1221 Hos ur ore 2383 2384 2	Plate breaker at mile 1991 1600 1740 1	760 1868	Woodbury vanners	
Foundry and Machine Company 52, 59 Blake breaker 14, 21 Jay movements 34 Jay movements 35 Jay movements 35 Jay movements 36 Jay mo	life of nearing parts at Mill 130	1991	Hoseur ore 9	
Blake breaker 14, 21 Musterschutz 884	duplex breaker, table of sizes of	21	improved swing ore P. I. Johnson 2	
Blake breaker 14, 21 Musterschutz 884	Foundry and Machine Company	52, 59	in the mills	856
breakers 559	Blake breaker .	14, 21	Musterschutz	884
breaker 59	jaw movements		Pepler ore D. J. Pepler 2	2032
information on Blake breakers roll speeds Fastening plates to table III III III III III III III III III I	breakers		Perfection ore 1578, 1	609
Fastering plates to table	cost of breaking ore	1223	Perfect ore . 1	1609
Fastering plates to table	information on Blake breakers .	1223	push feeder at Mill 113	1861
Father dis Smet gold stamp mill 110s 1	For toping plate, to table		Shaking, at Mili 124	
mill breaker in 57	Externing plates to table			
Eureka rubber in face bottoms in mortar 180	mill	1174	arrangements of stamps	
Eureka rubber in face bottoms in mortar 180	breaker in	57		115
grazhes in mortars 164, 165	Eureka rubber in		gravity stamps	
mortar liners 166	false bottoms in mortar	180	Huntington mills . 1	1314
mortars	grizzlies in	385	jigs	548
plates in shoes in 181 1				
Shoes in 181 orc bins 182 228 184 228 184 228 184 228	mortars	164, 165	of slime tables . 684,	089
Stamps recens 169		187		849
Stamps in 224 Feldshars, decomposition of A. S. Cusliman and warr of shoes and dies in 183 184 1		160	tule mills	1288
Faults and features of rolls 1229	stamps in		Feldspars decomposition of A. S. Cushman and	
Faults and features of rolls 1229	wear of shoes and dies in .	183	P. Hubbard 1	1418
Fearm S. milling at M. Bischof, Tasmania 2037 1008, in Cornwall 111 118	Faults and features of rolls	1229	for heds on coal jigs	574
Fearm S. milling at M. Bischof, Tasmania 2037 1008, in Cornwall 111 118	Faast, H , on jig capacity		Feldtmann, W., definition of slimes 1	1398
Fearm S. milling at M. Bischof, Tasmania 2037 1008, in Cornwall 111 118	ng, slope of sieves on	548	Fenner, C. M., on gol I and silver in amalgam	763
Fearm S. milling at M. Bischof, Tasmania 2037 1008, in Cornwall 111 118	width of sieve	591	Ferguson, H. T., Dingey mill	293
Stating and Smelting (or plany) 1687 1684 1	Fawcett, W., testing of black sands	2048	riusiana pneumatic stamps	
Stating and Smelting (or plany) 1687 1684 1	Father River California declare on 1	008 1184	runs in Cornwall for tin	
Stating and Smelting (or plany) 1687 1684 1	Federal Lead Company	1690	tin dressing in Cornwall	
Morning mill 1687	Mining and Smelting Company		Ferrand, P., amalgamating pans at Ouro Preto, Bra-	
1173 178	Morning mill		zil	
Feed arrangements on slime tables 688 box for jus 549	shaking screen at Mill 124	1694	amalgamation at Ouro Preto, Brazil 1	173
Brazil 227 Brazil 228 Brazil 228 Brazil 228 Exception 229 Brazil 229 Brazil 229 Exception	Feed arrangements on alimo tables		California versus Brazilian stamps at Ouro Freto,	
1224 Cassing to Willey Labe 1224 Capacity of jugs 1224 Capacity of jugs 1225 Capacity of jugs 1226 Cap	box for jigs	549	Brazil	
1224 Cassing to Willey Labe 1224 Capacity of jugs 1224 Capacity of jugs 1225 Capacity of jugs 1226 Cap	Wilfley table	673, 1468	gold mill at Ouro Preto, Brazil	IIXZ
Ferraris adjustable eccentric for jigs 532	Cassilled, for willey table	1473	L'Or à Minas Geraes	X1X
Classifiers 389, 442, 444 ball mill 1280, 1299, 1323 1320 1321 1320 1321 1320 1321 1320 1321 1320 1321 1320 1321 1320 1321 13	cone for trommels	358		539
Freid dry-process separator 1554 at Mill 137 1300 Ghpir County bumpang table gravity stamps 681 capacities of table of sizes, power, weights, etc 1300 Huff electrostatic separators jigs 1552 1553 W. R. Ingalls 2014 kieves 726 classifier 400, 478, 1369 riffle tables 679 E, calamine plant at Monteponi 2044 rolls 1224 capacity of jigs 597 slime tables 720 concentration at Monteponi 1185 stamps 1224 dressing zinc ores at Monteponi 1185	on canvas tables	442 434	bull mill 1280 1299 1	1323
Colpit County bumpans table 681 capacities of 1300	Freid dry process separator		at Mill 137	1300
Huff electrostatic separators 1552, 1553 W K. Ingail 2014	Gilbir County humping table		capacities of	1300
Huff electrostatic separators 1552, 1553 W K. Ingail 2014	gravity stamps		table of sizes, power, weights, etc 1	1300
jigs 552 belt table 698 kieves 726 classifier 400, 478, 1369 rifile tables 679 E, calamine plant at Monteponi 2040 rolls 1224 capacity of jigs 597 slime tables 720 concentration at Monteponi 1185 stamps 1224 dressing zinc ores at Monteponi 1185	Huff electrostatic separators	1552, 1553	W R. Ingalis	2014
kieves 726 classifier 400, 478, 1309 riffle tables 679 E. calamine plant at Monteponi 2040 rolls 1224 capacity of jugs 597 slime tables 720 concentration at Monteponi 1185 stamps 1224 dressing zinc ores at Monteponi 1185	jigs	552	belt table	698
rolls 1224 capacity of jigs 597 slime tables 720 concentration at Monteponi 1185 stamps 1224 dressing zinc ores at Monteponi 1185	kieves	. 726	classifier 400, 478, 1	1309
stamps	rittle tables .	. 679	E., calamine plant at Montepont .	
stamps		7224	capacity of jigs	1185
	stime tables	120	dressing zinc ores at Montenoni	
	оширь	1227	•	

1450 1 010, 10111	
Ferraris, E., Ferraris adjustable eccentric 643	Fine sand and slime concentrators, riffles 720
belt tables . 729	concentrators, Wilfley table 1465
classitier 478	slimes, effect of 892
magnetic separator at Monteponi 836 shaking screen 386	Fineness of bullion
shaking screen . 386 Harz jigs at Monteponi . 643	crushing desired
magnetic separation at Monteponi 2046	retort residue
mechanical preparation of ore in Sardinia 1568	Fines for miners 1115
riddle 385	in product from Wilfley roasting furnace sink
separation at Monteponi 1185 separator at Monteponi 836 velocity of particles falling in water 477	in water 1547
separator at Monteponi 836 velocity of particles falling in water 477	Finest size jigged 606 to which middlings are re-crushed in the mills 1119
hand screen 1360	Finger bars for gravity stamps . 199
intermediate jig 539, 540, 584	lever operated, for gravity stamps 1273
ing 522	geared rolls 77, 78
magnetic separator 799, 4525 at mills 1525, 1741	Finish angles in film sizing tests 715
	Linishing machines . 318
description of the . 2027 drum type . 1528	Finland, magnetic separation in 804 Finlay, J. R., milling in the Cœur d'Alene . 2033, 2037
drum type 1528 method of removing tailings 587	mining in Cocui d'Alene, Idaho 1922
shaking screen 342, 386, 1347	on costs 1927
at Mill 137 1347	Fire and water for breaking rock . 9
stay box for jig discharges 585	assay of gold ore . 1166
tables 1154, 1490	tube boilers 1090 water for 1106
at mills 1659, 1740, 1741, 1782, 1785, 1786, 1914 tables of sizes, capacities, speeds, power,	Fischer, formula for speed of revolution of tube
weights and water consumption 1490	mills . 1337
versus ugs M. Lenicque 2021	George K., Robinson rittle . 729
waving screen C W Wright 2019 at Mill 137 1739, 1740, 1741	Herman, operations of tube and ball mills 1340
at Mill 137 1739, 1740, 1741	Fisher's steam stamp 142
wet ball mill at Mill 137 1740 Ferreira mill, details of stamps 221	Fitzgerald shaking screen-launders at Mill 142 1767 Fixed circular convex slime tables 689
mine, saving by hand picking 487	Linkenbach fixed conical table
weight of ore at 1160, 1191	Roberts table . 691
Ferro aluminum for roll shells 68	sieve hand ngs . 519
shoes and dies 184 Ferrous sulphate used in dressing plates 757	jigs 494, 507, 1444
Ferrous sulphate used in dressing plates 757 Fiber asbestos 1080	classifier jigs
Fiberizer at Mill 186 1917 Film gauge 1159	Krupp Harz jig 1446 New Century . 1444
on a circular slune table, thickness of 695	Richards' pulsator jig 1453
sizers 1464	Woodbury pg 1447
sizing, results of tests 719	Flange, Brownell 647
tables 685, 1506 Acme table 1506	for analgamating pan 244 Flanged rolls 110
bibliography for 727	at Mill 130 . 1720
buddles 704	Flash point of oils . 1098
building tables 704	Flat grains, action of 892
continuous surface tables 686	on slime tables 694
depth of bed 1510	in middlings 1121 River district, cost of producing lead in 1971
intermittent surface tables 700 investigation of 707	River district, cost of producing lead in 1971 Lead Company, disc conveyor at Mill 1 of 1583
principle of . 644	null xxvi, 920
revolving circular convex slime tables 686	Missouri, mill at 917, 920, 1089
surface tables 685	site for mills 1085
use made of, in mills 889	Fleming dewatering wheel 1609
thickness of on amalgamated plates 746 on slime tables 695, 697	at mills 1590, 1725
on slime tables 695, 697 Films on canvas tables, thickness of 702	J. D., Fleming dewatering wheel 1590 Flim pebbles for grinding 267
Filter 879	Flints for tube mills 1288
bins	Floors for draming concentrates 1112
at Mill 171 1870	drying . 880, 882
boxes for pg concentrates . 586 in cyanide plants . 1107	hand picking 485, 486 mills 1088
press at mills 1628, 1630, 1641, 1642, 1678	receiving ore
Filtering mercury 786	sampling 844
slimes 1160	steam stamps . 128
Filters in settling tanks 458	weathering 830
Final conclusions on crushing 62	diamond ground 1080
hindered settling and suction 631 separators 480	slope of 1089 Florence, Colo., rolls at
Financial standing 1124	Florida, phosphate mills in
Findley, O P 1408	Flotation at Golconda, Nevada, water W. A. Root 2046
mill of the Canane (Con Copper Co., Mex-	of clay 1075
Fine contents definition of	process 1555
Fine concentrates, definition of definition of objections to 1053	at Broken Hills 2038 acid 2035
concentration test	acid 2035 F. H. Jackson 2045
crushing by breakers 54	Mill 130 1719, 1721
department at Mill 152 1806	data on C. Blomeke 2030
gravity stamps used for 314	De Bavay . 1555, 1562, 1568
mills 1004	Delprat 1558, 1561, 1568
grains investigation on rate of settling 473 grinding A W Warwick 1340	at Mill 129 1718 description of different 2026
importance of F C Brown 1323	economic side of the W. G. Swart 2029
in the tube mill. A. W. Warwick 2015	Elmore
limit of screening 369	E Walker 1569
sand and slime concentrators 644, 700	vacuum-oii process
classification of 1464 kieves	history of the C. Gopner 2028 list of minerals floated by 1555
	11st of initiating acted by 1000

Flotation process, Macquisten 1555	
Magnin tan's Contac tubes Ergo	Foster, C. Le N., Jordan's centrifugal grinder Krom jig, Clarkson Stanfield, Pape-Henne- berg mat hines
Macquisten's Coates tubes	Arom jig, Clarkson Stanfield, Pape-Henne-
Minerals Separation Company 1560	limite of miles
or Catermole 1555	pointed boxes, cone classifier, Lockhart's
Potter 1555, 1561, 1568	classifier, siphon separator 476
principle of	settling tube 621
theory of the	Sturtevant mill 298
G Hoagiand . 2027	text-book, ore and stone mining xix Vapart disintegrator 299
used at broken run, acid 2037	washing pits, pans, and trommels 334 Foster Coolidge automatic sampler 2032
Van Meter testing apparatus 1992 vats at mills 1718, 1722	Foster Coolidge automatic sampler 2032
vats at mills 1718, 1722 versus magnetic process for zinc ores. E. Laugh-	, on concentrating in ore 288
tr∰n = 20.90	Foundation for arrastra 238
"Flouring" of mercury 751	gravity stamps 145 Linkenbach shime table 690
Flow in launders 876	mills
of sand and water in launders 1592, 1593, 1594, 1595 water in launders 884	Wilfley table 1088
Flues in boilers . 1091	frame for amalgamating pan 241 Foundations and mortar beds for stamps, table of 118
Flume for water . 1105	Grass Valley, mortar 2012
Huorine, atomic weight of	for fruntingion mills 1313
Fluorite, specific gravity of 1189 Fluorspar, decrepatation of 829	1125
separated by Hooper air jig 822	Nordberg steam stamp 1247 stamp batteries 2011
Fluxes for melting 784	mills, concrete 2019
F. M. Davis Iron Works Company Folsom dredge of 140,000 cubic yards capacity 2044	steam stamps . 114
Folsom dredge of 140,000 cubic yards capacity Fonseca on impurities in amalgam 2044 251	tube mills . 1286
Fonseca on impurities in amalgam 251 Foot, equivalents of 1187	in stamp mill, masonry 2012 mortar W. H. Washburn 2013
A. D., battery screen 1270	2012
North Star mill 2045	
Mines Company 1925	Four mineral separation on jigs 590 Fowle, J. C. Buchanan and Wenstrom separators at
Foote, A. E., glass classifier 1146 Foot pounds, equivalents of 1188	Fowle, J. C., Buchanan and Wenstrom separators at
Lorce required on rolls 74	22tkt (1tperio) 933
Lorces, table of value of, acting at different angles in	magnetic plant at Michigamme mine, Lake Su- perior 1175
rolls . 94	Practional selection for sampling 944
Foreign mills, sites of 1086	Fracture affecting separation 889
Forge I steel roll shells at Mill 141 1760, 1761, 1762 Forms of frames for gravity stamps 156	effect of in dressing ores 3 Frachkel, A. 476
Runders 876	Frame, Boss cantilever frame for gravity stamps 1272
rittles 721	for slime table 687
Formula for centrifugal force 827	Steam Stamps 119
free setting 374	Willey table tilting frame 1467
free settling 471, 473 magnetic lines of force 793	Prantes 1464, 1507
magnets 794	for amalgamated plates 733
path of particle in trommel 375	Frue vanner 645
settling tanks 455	
Formula Blue's formula for the of and and	gravity stamps 152, 156
Formulæ, Blue's formulæ for flow of sand and water	jigs 507, 522
Formulæ, Blue's formulæ for flow of sand and water in launders	screens 176
Formulae, Blue's formulae for flow of sand and water in launders. Torsition electromagnetic separator 1538, 1815, 2038. Forster breaker 57, 60	screens 176 tm ores 1083 vanners 653
Formula, Blue's formula for flow of sand and water in launders. 1594 For green electromagnetic separator of paw type 1538, 1815, 2038 For the properties of paw type 57, 60	screens 17/6 tin ores 1083 vanners 653 Willley tables 671
Formule, Blue's formule for flow of sand and water in launders in launders and the state of the	176
Formule, Blue's formule for flow of sand and water in launders. Forsgren electromagnetic separator 1538, 1815, 2038. Forsgren electromagnetic separator 57, 60 of paw type 25 plan of 28 Table of wear, in Mill 67 28 For Scott Foundry & Machine Co., rolls 76	176
Formula, Blue's formulae for flow of sand and water 1594 In launders 1538, 1815, 2038 Forsgren electromagnetic separator 1538, 1815, 2038 Forster breaker 27, 60 of paw type 28 plan of 28 Fort Scott Foundry & Machine Co., rolls 76 Matchine Works, rolls 111	176
Formula, Blue's formula for flow of sand and water in launders 1594 Forsgren electromagnetic separator 1538, 1815, 2038 Forsgren electromagnetic separator 57, 60 of pay type 25 plan of 28 table of wear, in Mill 67 28 Fort Scott Foundry & Machine Co., rolls 76 Machine Works, rolls 76 Fortura mill, unalgamated plates in 745, 762	176
Formula, Blue's formula for flow of sand and water 1594 Forsgren electromagnetic separator 1538, 1815, 2038 Forsgren electromagnetic separator 1538, 1815 Forsgren electromagnetic sep	176
Formula, Blue's formula for flow of sand and water 1594	176
Formular, Blue's formular for flow of sand and water 1594	176
Formular, Blue's formulae for flow of sand and water 1594	176
Formular, Blue's formulae for flow of sand and water 1594	176
Formular, Blue's formulae for flow of sand and water in launders and in launders 1594	176
Formule, Blue's formule for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgren electromagnetic separator 2 57, 60 of low type 2 52 pala of 4 52 pala of 4 52 pala of 5 52 pala of 5 52 pala of 5 52 pala of 5 52 pala of 6 52 pala of 6 52 pala of 6 52 pala of 7 52	176
Formulae, Blue's formulae for flow of sand and water in launders I haunders I haunders Forsgren electromagnetic separator I orster breaker of paw type plan of table of wear, in Mill 67 Lable of wear, in Mill 67 Lable of wear, in Mill 67 Fort Scott Founder & Machine Co., rolls Machine Works, rols Fortun mill, umalgamated plates in breakage of stamp stems Order of drop wear of shoes and dies in weight of stamps in Foss, rolbrumble Lable Comsh frames, buddles, percussion tables, kreve Blake, Baxter, Marsden, Hall, Lester, Dodge 727	176
Formulae, Blue's formulae for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgren electromagnetic separator 2 57, 60 of low type 2 28 table of wear, in Mill 67 28 and 18 and 1	176
Formular, Blue's formulae for flow of sand and water 1594	176
Formulae, Blue's formulae for flow of sand and water in launders and annual for in launders for in launders. Forsgen electromagnetic separator of paw type plan of paw type plan of paw type plan of paw type plan of paw type. Fort Scott Foundry & Machine Co., rolls Machine Works, rolls. Fortuna mill, unadgamated plates in product of drop wear of shoes and dies in weight of stamps in 190 kers, rolls and the sin 191 kers, rolls. Forts of the Co., rolls for the stamps of the control of the paw to the control of the paw to the control of the paw to the control of the cont	176
Formule, Blue's formule for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 1538, 1815, 2038. Forsgen electromagnetic separator 3 1538, 1815, 2038. Forsgen electromagnetic separator 4 1538, 1815, 2038. Lable of wear, in Mill 67 2 28 28 28 28 29 29 29 29 29 29 29 29 29 29 29 29 29	176 176
Formulae, Blue's formulae for flow of sand and water in launders agreed agre	176
Formule, Blue's formule for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 1538, 1815, 2038. Forsgen electromagnetic separator 3 1538, 1815, 2038. Forsgen electromagnetic separator 4 1538, 1815, 2038. For Scott Founders & Mackine Co., rolls 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	176 176
Formulae, Blue's formulae for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 1538, 1815, 2038. Forsgen electromagnetic separator 3 1538, 1815, 2038. Forsgen electromagnetic separator 4 1538, 1815, 2038. Forsgen electromagnetic separator 5 1538, 1815, 2038. Forsgen electromagnetic separator 5 258, 288, 288, 288, 288, 288, 288, 28	176 176
Formulae, Blue's formulae for flow of sand and water in launders and anterest land in launders and launders a	176
Formule, Blue's formule for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 1538, 1815, 2038. Forsgen electromagnetic separator 3 1538, 1815, 2038. Forsgen electromagnetic separator 4 1538, 1815, 2038. Forsgen electromagnetic separator 5 1538, 1815, 2038. Forsgen electromagnetic separator 5 258, 258, 258, 258, 258, 258, 258, 25	176
Formule, Blue's formule for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 1538, 1815, 2038. Forsgen electromagnetic separator 3 1538, 1815, 2038. Forsgen electromagnetic separator 4 258. Lable of wear, in Mill 67 258. Lable of wear, in Mill 67 258. Matchine Works, rolls 1 171 Fortuna mill, unalgamated plates in 745, 768. Forsgen of stamp stems 1888. Order of drop 215. Forsgen electromagnetic stamps 1888. Forsgen electromagnetic separator stamps 1888. Forsgen electromagnetic separator stamps 1882. Forsgen electromagnetic separator stamps 1882. Forsgen electromagnetic separator stamps 1888. Forsgen electromagnetic separator stamps 18	176
Formulae, Blue's formulae for flow of sand and water in launders are in launders and in launde	176
Formulae, Blue's formulae for flow of sand and water 1594	176
Formulae, Blue's formulae for flow of sand and water in launders and and water in launders and an experimental problems of part launders and problems of part launders and problems of part launders and part laun	176
Formule, Blue's formule for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 1538, 1815, 2038. Forsgen electromagnetic separator 3 1538, 1815, 2038. Forsgen electromagnetic separator 4 258. Lower of Jave type 2 28. Lower of Jave type 2 28. For I Scott Founders & Machine Co., rolls 3 76. Machine Works, rolls 1 71. Fortuna mill, unalgamated plates in 5 76. Machine Works, rolls 1 71. Fortuna mill, unalgamated plates in 5 18. Weard of stomp stems 215. Weard of stomp stems 215. Weard of stomp stems 18. Fors, rollemulatic 2 293. Fors, rollemulatic 2 293. Forst, rollemulatic 2 293. Forst, rollemulatic 2 293. Forst, rollemulatic 2 293. Hall & Leavitt stamps 2 298. Lowett-Finney, Ball-Norton, Buchanan, Friedrichssegen, King's, Wenstrom magnetic separators 2 298. Cornish rolls, Krom rolls 2 298. Cornish rolls, Krom rolls 2 298. Gales breaker 5 56. For breaking 11. And Dreaking and picking picking tables 56.	176
Formulae, Blue's formulae for flow of sand and water in launders agnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 1538, 1815, 2038. Lorster breaker 28	176
Formulae, Blue's formulae for flow of sand and water in launders magnetic separator 1538, 1815, 2038. Forsgen electromagnetic separator 2 57, 60 of low type plan of table of wear, in Mill 67 28 28 table of wear, in Mill 67 28 28 28 table of wear, in Mill 67 28 29 table of wear of shore and die in weight of stamps in 190 20 20 20 20 20 20 20 20 20 20 20 20 20	176

Fraser and Chalmers on amalgamators 780	Friability, use made of, in mills
attaching screens to trommels 356 capacity of rolls 102	Friction
capacity of rolls	angle in trommels
design of cams	tor gravity stamps
mortar bolts	the H. W. Caldwell and Son Company friction
power for jigs	clutch
stamps	in jigs 602 launders 876
punched screens	roll journals
screen gauge 173	rolls, how reduced 96
shoe shanks . 181 stamp bosses . 187	losses
clearance	of breakers
stems . 187	gravity stamps . 219
tappets 189	process of concentration (). Witt 2030
thickness of screen plate 372 vanner adjustments 659	ore dressing
vanner adjustments 659 vanners 655, 662, 663	Friedeberg mill
we tring parts of breakers 48	Friedensville, jigs at 642 movable sieve jig at 506 Pennsylvania, mill at 903, 1178
power for rolls	Pennsylvania, mill at 903, 1178
settlers . 779	Zinc Co., mili . xxv, 903
trominels 357	Friedrich Krupp Grusonwerk 260 amalgam press 1518
at Mill 136 1737, 1738	amalgamating tables
Mill 175 1890	box traps 1516
roll speeds 87 sample grinder 257	ball mill 260
sample grinder 257 sand wheel 1587	breaker jaws 23 Erikssons' electromagnetic separator
settlers 777	Forsøren magnetic separator 1539
spindle breaker wearing parts 47	Krupp Harz jig 1446
stamp frames 153 standard rolls 2010	high speed rolls 1244
standard rous 2010 cam 197	mill for five mineral separation 591 picking tables
steam stamp 114 116 118 119 120 121 122	spitzlutten
123, 126, 127, 128, 131, 133	wash trommel . 1341
two stamp mill 203 weights of spider and driving cone made by 247	Friedrichssegen, calcining furnace at 1546
weights of spider and driving cone made by 247 Fraver centrifugal water-line l pump at Mill 159 182)	classifiers at
Frecheville, R. J., Cornish tin dressing . 1183	Heberli magnetic separator 799
Free and choke feed for rolls, comparison of 1229	magnetic separator at 799, 833, 834
crushing 98, 313 milling test 1166	mines, Sautter magnet at 798 picking at 481, 487
settling affected by natural properties of min-	picking at 481, 487 roasting for magnetism at 815
erals 461	sieve scale at 367
and hindered settling defined 464	Frisher Lucon mill 234 267
classification by 474 classifiers, tubular 1381	mill, bibliography for 294 Frisco mill, Utah, Paddock jigs at 822
concentration by 475	Mining Company 1737
deep pocket Classifiers 1376	Utah, mill at 1015
defined 461, 1421	Paddock ng at 839
formula 471, 473 general principles 464	Fritsch rolls . 2010 Frobel's grinding mill . 232
investigated by tubular classifier 469	mill, bibliography for . 291
ratio free to hindered settling 1430	Fröding separator 2028
ratios 469, 471, 1426	in Sweden, data on 2030
of quartz and galena 1426 table of 4426	Frontzheim's spring stamp 143 Frongoch mine, double cone classifier at 427
sorting by G 489	Frue vanners See also Vanners
tube investigation 465	
use made of, in mills 889 velocities 476	vanners at mills 1625, 1627, 1662, 1689, 1694, 1695, 1703, 1704 1711, 1712, 1755, 1844, 1865, 1863, 1870, 1880, 1881, 1884, 1929, 1930
velocities 476 of mineral particles 1421	1880 1881 1884 1929 1930
versus hindered settling 1431	capacity of . 002
Freezing of stone, effect on strength . 301	description of . 645
point of mercury 730 Freiberg, Bilbarz jig at 503	for testing 1153 in Cornwall R. A. Thomas 2022
oblong movable sieve power jig used at 503	modification of 651
classifier at 413	testing . 1171
hand picking at 486, 492	vibrations of 658 water used in 659
mill at 1087, 1099, 1102, 1135 bibliography for 297	water used in 659 without previous classification, use of 2023
Saxony, mill at 958, 1174, 1177, 1179, 1183	Fuel See also Wood and Coal.
screens at 364, 365	burned in driers
sieve scale at 367	consumption by Wilfley roasting furnace . 1548 required by roasting furnace at Mill 138 1747
skimming jigs at 576 Stein, Bilharz and Luhrig tables at 670	required by roasting furnace at Mill 138 1747 rotary drier at Mill 186 1917
water used on humping tables at 670	Fuller mines, gasoline engines at . 1091
Freid Engineering Company, gravity dry process sep-	Full teeter velocities of quartz and galena, table of 1430, 1431
arator 1553, 1554, 2027 size of feed for	Fulton, C. H., cyaniding in the Black Hills 2033
Freight, cost of 1126	the history of the Homestake mills 2041
French Rand Mining Company mill T Dupont 2039	Engineering Works, clean up barrel 234 From Works, breaker of Blake type 22
Fremer, J. H., & Son, spiral sand pump . 870 sand pumps . 1588	Iron Works, breaker of Blake type 22 distributor at Mill 126 1707
at mills 1630, 1708, 1755, 1756, 1761, 1769 1779	mechanical batea . 633
at mills 1630, 1708, 1755, 1756, 1761, 1769, 1779, 1811, 1812, 1830, 1885, 1886	rolls 76
Friability of minerals, affected by calcining 9	Furman, H van F., amalgam
separation by 830 under a blow	amalgamated plates
4	and an
70	<u>v</u>

Furman, H. van F., amalgamation and concentrator gold and silver	ation 1173	Galena-sphalerite ores at Broken Hill, separation of 1611
and S. R. Krom, pneumatic concentration	n 838	with limestone, crushed by rolls 69 Galland coal breaker 2009
arrastra	290	Gallium, atomic weight of 1188
Blake, Dodge, Comet, Schranz breakers	. 58 58	Gallon 1187 equivalents of 1187
breakers	295	equivalents of 1187 of water 1187
capacity of jigs	597	Galvanic couple used on amalgamated plates 752
clean-up pan	291	Galvanized iron classifiers 1144
Crawford mill	295 1167	Gandy belting for elevators 862 canvas belts 1094
cyaniding	. 294	canvas belts 1094 elevator belt at Mill 114 1663
	295	Gangue minerals in mills See Individual Mills in
gold amalgamation	▶ 1179 225	Chapter XX
gfavity stamps Graffin roller mill	297	Gantry clam shells for loading concentrates at Mill 167 . 1858
Huntington mill	297	Garde, A. G., New Century magnetic separator . 1542 Gardiner breaker 57
jigs	642	Gardiner breaker 57
material for jig screens Morning mill, Mullan, Idaho, and Hecla	545 mill	Garneld Chili mill . 1305 at Mill 167 . 1305, 1858
Giendale, Montana	1179	• screen analysis of product 1307
Paddock jig at Frisco, Utah .	839	Smelting Company, Silver Lake mill . 1771
practical assaying . Roger's rolls	110	Garland wire-rope disc conveyor at Mill 124 1695 Garnet rock, weathering of 831
sample grinder	292	Garnet rock, weathering of 831 separated by magnets 790
spitzkasten, Frazer & Chalmers deep pe	ocket	specific gravity of . 1189
classifier, cone classifier, made by Colo Iron Works, Carkeek classifier	rado	treated on Hooper air jig 505, 824
testing of gold ores	477 2048	Garn, M. 297
Furnace for drying	880	Gartrell, H. W., effect of varying speed on percent of undersize in crushing 2017
heating for decrepitation	829	Gas engines 1091
melting	784	power plant at Mill 172 1874
roasting at mills for magnetism	1747, 1862 814, 815	Gasoline engines Gassaway, A. D. plates, rittles, and sluice plates at
Furnaces, roasting Future of ore dressing	1545	the Magalia drift mine 789
Future of ore dressing .	. 1119	Gate and dam discharges, center discharges 582
G		for jigs 577
G		height of dam 579 gate 578
Gaetzschmann, M. F., amalgamating pans	290	on iigs 553
amalgamators arrastra	787 289	ratio of height of gate to size of feed 578
Aufbereitung	XIX	side discharge 580 tail discharges 581
Ball and Wilson stamps	142	Gates 138 139
ball mills	293	all iron frame revolving screen 1353
Bogardus mill Carr disintegrator	292 298	ball mill 1280, 1300, 2014, 2017 table of sizes, capacities, power, weights, etc. 1301 breakers 55-60
classifiers .	476	breakers 55-60
cone mill	292	action of 39
crushing machines	315 295	at mills 1635, 1661, 1706, 1710, 1713, 1716, 1727, 1768, 1817, 1818, 1821, 1828, 1853, 1857
edge runners fixed and movable sieve jigs	$\tilde{639}$	compared with McCully 45
general milling	1173	description 36
gravity stamps grist mill or buhrstone mill	223 291	details of 38
hammers, breakers, roasting for friability	56	on "choke crushing" 48 with short head and concaves 1208
for breaking	11	at Mill 165 . 1851
hand picking	492	canvas plant 1017, 1184
Hughes pneumatic stamp Nicholas pulverizer	$\frac{143}{292}$	of the Kenned Mining and Milling Com- pany mill xxvin, 1037
pneumatic concentration	837	cast iron head center for gyrating breakers 1220
Addles and trommels	384	Classitier 1369
roll-speeds schleudermuhle	87 299	economic rolls 81 feeder . 136, 854
sledging, spalling, and cobbing hammers	56	for rolls 71
sledging, spalling, and cobbing hammers slime tables, bumping tables, buddles	727	for classifiers 406
trough washers and wash trommels	334	ore bins 843
various obsolete breakers Whelpley & Storer pulverizer	56 299	G. G . • 1369 classifier . • 418
Gagnon ore, sizing test on jig tailings	607	end Shake vanner 653
Gabrite, specific gravity of	1189	patent vanner belt 650
Galena and quartz, jig tests on	62 0 707	gunlock manganese steel mantles for gyratory
used for film sizing tests blende ore, Missouri sizing tests on	303	breakers 1220 hydraulic classifier 477
treated at Diepenlinchen	670	Iron Works, beyeled rolls 71
crushed by rolls	62	Blake breaker 23
cost of hand picking of extraction plant at Mill 130	488 1720	breaker 23 jaw movements 34
free-settling velocity	1720 471	jaw movements 34 capacity of jigs 597
hindered settling tests on		comparative tests of jaw and spindle
	612, 617	comparative tests or law and shindle
in dolomite, crushed in Mill 25	612, 617 47, 98	breakers 53
in dolomite, crushed in Mill 25 in Missouri, treatment of O M Bilharz Iron Works Blake breaker at Mill 148	612, 617 47, 98 2034	breakers 53 estimate of cost of crushing 51
in dolomite, crushed in Mill 25 in Musouri, treatment of O M Bilharz Iron Works, Blake breaker at Mill 148 Kansas, mill at 901,	612, 617 47, 98 2034 1792 902, 1179	breakers 53 estimate of cost of crushing 51 Lowry National breaker 45 on design of cams 196
in dolomite, crushed in Mill 25 in Masouri, treatment of O M Bilharz Iron Works Blake breaker at Mill 148 Kansas, mill at 901,	612, 617 47, 98 2034 1792 902, 1179 1190	breakers 53
in dolomite, crushed in Mill 25 in Masouri, treatment of O M Bilharz Iron Works Blake breaker at Mill 148 Kansas, mill at 901,	612, 617 47, 98 2034 1792 902, 1179 1190 624	breakers 53
in dolomite, crushed in Mill 25 in Misouri, treatment of O M Bilharz Iron Works, Blake breaker at Mill 148 Kansas, mill at 901, ore, weight of pulsion jig test on rossting furnace	612, 617 47, 98 2034 1792 902, 1179 1190 624	breakers 53 estimate of cost of crushing 51 Lowry National breaker 45 on design of tame 196 friction in rolls 97 wearing parts of breakers 48 power for jugs 603 rolls 73
in dolomite, crushed in Mill 25 in Masouri, treatment of O M Bilharz Iron Works Blake breaker at Mill 148 Kansas, mill at 901,	612, 617 47, 98 2034 1792 902, 1179 1190	breakers 53

Pages 1-643, Vol. I.	OKE DR	ESSING.	Pages 644-1197, Vol.
ates Iron Works, Tremain steam stamp	136	Gilpin County sh	oes and dies
vanner in mercury traps	651 . 773	stamp mi	l
wells on Tremain stamp	/08	stamps	
on Tremain stamp	139	in	
P W. rolls	. viii 109, 111	Girard water tur	bine .
.t milk	. 1707, 1710	Groux Consolid	iberg steam stamp ated Mines Company evada. W. R. Ingalls
rule for power used in crushing tube mill vanner	309	mill, Ely, N	evada. W. R. Ingalls
tube mill	1280, 1296	Gladolinium, ate	
vanner .	658	Glasdir mine, W	ales, mill at 1072,
lauges 22 for brass and iron wire	3, 1097, 1174 1999	Glass classifier	ess at
	. 171, 172	iie .	623
water films	1159	Lander lini	ngs at Mill 166
wire and blate	1194	table for filr	n sizing tests .
layet, argentiferous galena at Villefort, Fran Castelnau belt table	ce . 1178 728	Clandula war at	
Geared rolls .	. '75	Glendale, jigs at Montana, n	ull at
at Mill 183 .	. 1913	Glenn, Wm., sat Glidden, J. T., Globe battery st	nipling
learing .	€ 096	Glidden, J. T.,	Woodbury jig .
for gravity stamps lears for amalgamating pans	198 248	Globe battery st	em guide
trommels	356	guides for s iron stamp	tamps mide
a . n.l. urbank	94.5	Glucinum atom	ac weight of
Gebruder Sulzer centrifugal pump at Mill 11	8 1678	Glycerine for re-	spirators
said wices behrider Sulzer centrifugal pump at Mill 11 feddes & Bertrand mill, sizing test on crust ferssler's sampler	red ore 100	Gmehling, A, I.	spirators ohnert's ball-mill Janfield, Wood machines
ierssler's sampler ieldenhuis Deep mine, saving by hand picki	2031, 2033 ng 487	Complete or	Sanheld, Wood machines
mill, details of stamps	ng 487 221	Gmelinite, speci Gneiss, weight of	of
iem mill	940, 941, 942	Gneiss, weight of Goddard, S. H.	-
of the Milwankee Mining Company	XXVI	Edison's	concentrating plant
separator, Lockhart's automatic	eaking 47	rons	
Jeneral considerations about breakers and bi of jigs	522	Croiconda, Neva	da, Macquisten flotation process at 1565,
regarding costs of producing lead	. 1974	Gold, action of	gravity stamps on
construction of rolls .	63	amalgam	. 730,
(*XJX*NS(*S	1123	used in p	reparing copper plates
ideas on milling milling ideas, bibliography for	1085 1173	amaigamate	ed plates used in milling
practice in the Witwatersrand, South	Mrica 1643	and Siver i	n amalgam, proportions of tions of, caught on plates
principles	1	retaine	d by amalgamated plates
governing costs	1940	apparatus t	d by amalgamated plates ised for amalgamation
of ore dressing	1199	assay for in	Mill 55
pulsion suction	1450 1461	Mill	Mill 55 68 dit of g Company, plant of
remarks upon jaw breakers	33	Rluff Minir	or Company plant of
table of foll data from the mills	64	Coins Mine	s Co
ienesee Vanderbill mili	xxv, 893	combination	ı millə
Gentle Annie mill	xxviii, 1035 367	concentratio	on of fine N J Fleck
Geometrical ratio for sieve scale Georgetown, Colorado, Krom jigs at	838	condition o cost of prod	l n. ma
Locardo V. Crosson Compuny	23, 72	dredges, me	tal rifles used on
Georgia stamp mill, an old time W S Yat gold milling in H V Croll Germannum, atomic weight of	tes 2036	dredging	tal rifles used on
gold milling in H V Croll	2043	in genera	1
Termanium, atomic weight of Terman mills - C. Blomeke	$\frac{1188}{2034}$	plant tables for	
mils C. Biomeke .	1177	fineness in	bullion :
arrangement of 4.	1107	hydraulicki	ng and dredging
cost of milling	1135	in amalgar	١ .
labor in	1102	sluices, d	istribution of
overflow battery	229 230	Snake	River, Idaho, recovery of tine R. Ne
stamps sweeping table	703	Bell strained i	mercury
tests on strength of stone	301	tailings	rtrad to save coarse P. L. Johnson
Pernet, A. von, definition of slimes	1398	King amale	amator dstone, Colorado G. P. Scholl
lersdorflite, specific gravity of	1189	mill, Gla	dstone, Colorado G P. Scholl
leyer, R , concentrating lead and silver at S roll		love of	ted mercury
	. 477, 478 460	by use	of cyanide. B. C. Wilson .
setting apparatus setting G. G. Gates' hydraulic classifier faunt rock breaker rolls, Edison's libbonstille, Idaho, mill at stamus at	460	milling W	of cyanide. B. C. Wilson 7 R. Ingalls
G Gates' hydraulic classifier	418	books on	
ralle Februar's	105	cost of	n modern G. P Scholl go H. C. Bogdell
libbonsville, Idaho, mill at	1028, 1181	in Bendu	go 11. C. Bogdell
stamps at	227	Mexico	cheap. H. L. Collins .
labbsite, specific gravity of	1189	1908	Λ. James
Tibs for stamp tappets Tilchrist, J., Carr disintegrator Peter S., test of American Process Compa	. 188	notes on	modern
Peter S. test of American Process Common	298 ny's drier 1500	mill test	an stamps used for .
Gillon, A , Cyclone pulverizer	299	mull with gr	avity stamp and canvas table and no vanners
Gillon, A., Cyclone pulverizer on breakers	61	nl stoe	and no vanners
Gilbin County bumping table	680, 682	mills, desig	n and equipment of. G A. Denny
with screens attached	342 1030		
Colorado, milling system mills in	1180, 1181	using pla table	ites, vanners, and canvas or blanket
milling in	1047	with grav	vity stamps .
mills, acid water	173	no um	and the state of t
screens used in	169	plates	and vanners
mortars of wood and iron	164		

vel screens	339	Gravity stamps mouth	or feed openings in .	
stamp mill for cement	2012	mud sills		
washing	1000	Newton mortar	·	
ves, F. L., dredge	1013	Nissen stamp	í	1
vity mulier, Stanwood	1285	North Star mii mortar	l	101
vity muller, Stanwood -screen at Mill 138 specific, effect of	3	number and he	ght of drop	161,
stamps	144, 1246	used	agm or drop	
adjustments of .	206	Oldham morta	r	
advantages of for fine crushing analysis of Morison's curves of the veloc	. 314	old wooden typ	xe	
analysis of Morison's curves of the veloc	city of 215	order of drop i	or	. 214, 1
area of discharge	. 209	overflow batter	у .	
belt tightener bibliography	. 198 . 223	Pachuca		1
blankets and rubber sheets for mortar b	locks 148	perts of placing screen	in	
blow, efficiency of	219	platforms		
Boss cam key for	1273	J×:615		
cantilever frame for .	1272	power		. 204, 1
head for	. 1271	principle and p	ourpose of	113, 1
latch finger	1273	principles of a	tion	100
or head wedge-grip tappet for	. 485 1272	proportions be	ween weights of parts	189, 1
buckstaves	154	pulley for belt pulp, weight of	transmission	1
California versus Colorado practice	215	putting on new		
cam shaft	190	ratio of power	required to overcome gi	ravity .
cums	191	right and left l	and cams	
for	1272	round and slot	ted hole screens .	
Canda cams for chuck blocks	. 1273 177	running of		
clean up	201	screen area frames	•	
clearance	195, 196	openings	•	
clutches	198	screens		
collars and bearings	190	designation	of	
comparative work of stamps and Hunt	ington	material and	cost	
mills	1262	sectional guide	s for	400
compared with Huntington mill compensating weights for	278	mortar		163,
cost of crushing	1645, 1651 205	setting up shield and spla	ich laurel	
cost of crushing Crocker's patent	229	shoe	ish board	
cross sills	153	and dues sig	e, life, cost, etc	182, 183,
details 2	23, 224, 225	fastened to	head	I, I,
of screens	169, 170	single and dou	ble discharge mortars	
dies	179	size of feed		
disadvantages of	222 197	screen hol	(%	
driving mechanism	1276	sizing tests		
economic range of effect of variation in ore	207	sockets in boss South African	prutice	
efficiency of, compared with steam	134	splash boards	in	
false bottoms	180	zersus swast	 I	
feeders	199	stamp stem		
finger bar, cam sticks, and crab	199	staves for shoc	shanks	
Foote screen for	1270	stay battery		
foundation	145	stem		
frames gauges for screens	152 172	table of weight	s or parts	
gearing	198		two stamp mills	
gils and keys for tappets	188	types of frame	v owny mna	
Gilpin County	152	used in Califor	nu	
guide blocks for	1267	velocity cards		
timbers	155	versus rolls an	d grinders	
guides	154, 155 227	steam stanij	<u>.</u>	٠. (
Harvey's patent heavy stamps at Mill 107	. 1645	Walker's pater	п	
height of discharge	. 1045 212	water pipes required	•	
drop	200	wear of shoes	and dies	
Horade nutont	227	weight and blo	ow of	
Howland's patent	225	drop, capaci	tv, etc.	
Huntington tatent	227	power, etc of mortars		
in South African practice	1643	of mortars		
iron stamp frames	158	wire screens		
Krupp cam shaft for life of shoes and dies 1	1272 84, 185, 1277	Cray corres and but	ngement of	itation .
limits of drop	216	I W New Zeal	and gold dredges	
ho apron	178	rock ore, sizing	est on ug tailings	·-
location of main shaft Luckling's mortar	197	Grease, effect on mer	ngement of ate separated by decrep and gold dredges est on jig tailings cury	
Luckling's mortar	227	Greased plate		
made by the Denver Engineering Works	Com-	user marie (2),	in mills	
pany	, 1278	surface action		
maintaining height of drop in	200	for diamonds	v	•
materials for wearing parts of a mercury required	1277 208	tables at Mill 18 for diamonds	o	
method of feeding	208	Greases	•	
setting up	200	Greasiness of minera	ls. '	٠
mortar blocks	145	Greasy flotation		1121,
lxilts	148, 150	use made of, i	n mills .	
covers	167	Great Boulder Perse	erance mine .	
dimensions	165	plant R	Mien .	
feed opening	166	Falls, Montana,		

Habermann, J., ore dressing at Raibl 1177	Hammond cylinder feeder for gravity stamps 199
pistons 641 power for jigs 603	dredge at Nome Beach 2036 Mfg. Co., two-stamp mill 209, 210
	Mtg. Co., two-stamp mill
proposed concentration mill at Przibram 1177 crushing plant at Przibram 1176	rouer reeger 854
rolls and grinders 110	Hancock, H. R., inventor of Hancock jigs 1440 jigs 504, 643, 1440, 1459, 2021
at Przibram 110	jigs 504, 643, 1440, 1459, 2021 at mills 1710, 1711, 1846, 1847, 1869, 1870, 1871
Schwarzmann's rolls, Neuerberg's rolls,	Mine La Motte 2021
for crushing coal 110 for graded crushing 110	for dredges 2043
for graded crushing 110 in a lead mill 110	punchings as bed for 1459
shells in two sections 110	versus Evans jigs at Mill 162 1846
versus stamps 110	water used by compared with that used by Evans jigs 1442
Salzburg table 728, 1185	Mighigan, mill at . 993, 998
Schranz mill 296 Separator at Przibram 836	Hanctin's mill 235
Separator at Przibram 836 stamps at Przibram 229	hibitography for 90c
Stefan mill at Przibram 1177	Hand breaker for testing 1137 breaking 56, 57
trommels and jigs at the Anna mill, Przibram 1177	breaking 56, 57 advantages of 12
screens 385	and picking . 409
zinc ores at Raibl 1285	electromagnet 812
Habets, A., Baum jig for coal	feeding 223, 1115
plates 57	for gravity stamps 199 jig mills 892
on breakers 57, 59, 60	
ordinary versus manganese steel for jaw plates 60	cost of 1126
Blake breaker at Mill 134 1733 breaker 2009	for testing 1150
gyratory breakers at Mill 130 2009 1719	operation of 497, 894
rigid rolls 2010	skimming of 497
rolls at Mill 134	Speed, labor, and capacity 499 pan 1152
Haile gold mine, Chili, mill at 269, 295	with flange 1184
North Carolina, mili at 1175	picking See also Picking
plates at 735, 787 purifying mercury at 785	picking 480, 492, 889, 1435, 1611, 2021
Mining Company 1621	advantages of 480, 2021 after breaking by hammers 9
Halk breaker 2009	after breaking by hammers 9 an equation for 2021
Hall breaker 56, 57, 58	assisted by layers on belt conveyor at Mill 145 1781
	trommels and belt conveyor at Mill 145 1781
stamp mill in Dahlonega district 150 Hallett, S. I viii	at Chusinai aas
Hallett's hand ng 1180	Cripple Creek, Colo 2021 Mill 176 1891
on extent of crushing desired 304	Mill 176 1891 belt, rope and plate conveyors for 489
fine crushing 1004	bibliography for 492
form of launders 873	breaking for 1435
power used for crushing 309 roll speeds 88	combined with screening on grizzlies 340
screens in concentrating 1114	comparison of picking tables 491 cost of 487 1438
screen versus hydraulic sizing 2020	cost of 487, 1438 delimition of 480
testing jigs 1151	general considerations on 481
table 675, 680, 1153, 1172, 2022 three nuneral separation in Mill 49 676	in mills . 485
Hallett's hand testing up 1180	use made of 889
Hallidie's corrugated stamp screens 226	mine 481 rock house 482
Taise, r., amargamated plates 749 765	South Mrica 482, 2021 S Milican gold mines. A. C. Key 9021
copper plates cersus silver plates for amalga mation 2024	
	light for 481
tests on loss of gold with plain copper plates 749, 750	limits of 486
Hambou classifier 2020	mathematical discussion of 2021 of low grade ore at Leadville, Colo 2021
Hammer and spring mechanism for jigs 536	nugget copper in Mine 44 54
drop for cleaning mass copper 12	on steam stamps * 129
for breaking 9 cobbing 11, 480	Dicking chutes 480
at Mill 186 1917	revolving circular tables
kieves 726	speed of revolving table used in 491
scaling plates 760	stationary tables 488
sledging * 10 and spalling 480	tables for 488
and spalling 480 spalling, and cobbing 56	tests
spalling 11	sampler for slime table 1172 sampling 844, 1570
and cohburg 55	sampling 844, 1570 dipper or bucket sample 845
steam for cleaning copper rock 12 used in hand picking 1435	grab sample 845
used in hand picking 1435 Hammerswasche mill 1177	moisture samples 846
1025 at 597 641	pipe sampler 845 screens 1137
stroke of jigs in 594	
Hammond, J. H. 286	sledges 10 kinds 10
amalgamated plates 735, 757	sorting tests at Mill 162 1842
cost of gold milling 1134 plating copper plates 755	washers for placer work
gold stamp milling . 1178	washing 319 Handles for hammers 11
gravity stamps 995 996	Handles for hammers
mercury used in stamping 206 milling in the Transvaal 2033	Hanna, M & M Company mill, Capitol City, Colo-
milling in the Transvaal 2033	
plates and traps 788 riffles 721	Hansell, N. V., study of water jigs 1463
steam stamp 166	Hanson, P., on Tremain stamp
tables for supporting plates 735	rard amagam
breaker, descriptions of the new 2051	on plates

ard amalgam, proportions of gold and silver in 762	Haussner, A., curves for lifting cams
banks in jig beds ardinge, H. W., Hardinge conical tube mill 1280, 1296,	Haverstraw sandstone, compressive strength of Hayden, Ralph, free-settling velocities
2014, 2016	Head center, Gates cast iron, for gyratory breakers 1
conical tube mill, capacity	for gravity stamps
power required by 1296 ardman, J. E. viii, 196, 1184	spindle breakers 46.
absorption of amalgam by copper plates . 765	turbane water wheels 1 motion of Card concentrator 1 New Standard concentrator 1
absorption of amalgam by copper plates 765 amalgamated plates 735, 748, 751, 752, 762, 765	New Standard concentrator 1
amaiganation	Overstrom table
blow of stamps	Wittley slimer 1 table 1
false bottoms in mortar 180	table 1.
Forster breaker 60	plunger jig Heard, John, Jr
foundation for gravity stamps 145	concentrating antimony on Paddock jig
gravity stamps 225 keeping accounts 1178	Krom jig and Paddock jigs
keeping accounts 1178 keys for stamp cams 192	and Paddock µgs Paddock air µg
mortars 165	Sturtevant mill
Oldham and Wayerley mills 228	Heat and quenching for breaking rock
gold stamp mill . 1184 plates and traps in the Oldham mill . 789	e∎ect of on amaigamation 750,
stamp stems . 187	settling slimy water 1
redness of minerals	strength of stone
ard rock phosphate 895	to change potosity
and rock phosphate 895 airbuck, F. W. Baum ng 642 airmotome, specific gravity of 1189 airney Peak tin mines, mill 1180	used for settling line slimes 1
armotome, specific gravity of	in straining amalgam Heating for decrepitation
arriciving min, amaigamated plates in (49, 748)	Heating for decrepitation friability
mortar and screens 226	in magnets .
shoes and dies at . 183	the mill 1
arrington and King, clear punched slotted screens 169 material for screens 355	to change magnetism
screens, table of dimensions 168	Heavy solutions 1
stamp screens 168, 169	testing by 1156, 1
standard plate screens 369, 370	Heberle, b., Heberli mill
trommel at Mill 144 arris atmospheric discharge for jigs	none or screening
Corliss engine 925	ore dressing at Falun, Sweden 1 discharge for jigs
airon, Rickard, and McCone, the new improved	stamps at Falun, Sweden
Huntington mill 1313	Heberle O. magnetic separation at 1 riedrichssegen
arshaw mill 1174 amalgamating pans at 290	Heberh and Grondal mills compared 2 magnetic separator
amalgamating pans at 290 amalgam in 783	magnetic separator mills 141, 232,
Boss classifier at 478	bibliography for
cone classifier at 425	compared with Schranz mills
fuel for retorting amalgam 782	power required for
grizzlies in 385 high stamp capacity 207	tests on work required by versus rolls
settlers in 787	system of trommels
stamps 224	wet magnetic separator
wear of amalgamating pan 249	Heberwasche 421, 478, 520,
artman mine, power jig used at 506 movable sieve jig at 506	used at Mechernich Hecla mill 1179, 1
artzell Concentrating Company mill 3313 1055	igs in
arvev's slamp 227	Mining Company 1
arz, bull jigs at Mill 162 1843	Hecion breaker 2
jigs 507	Hector mill I Mining Company radii xxvii, 1
1728 1729 1743 1744 1750 1751 1752 1753	Hedburg, E., hand jigs and Cooley jigs in southwest
at milb. 1692, 1693, 1694, 1701, 1702, 1703, 1725, 1735, 1726, 1729, 1743, 1744, 1750, 1751, 1752, 1753, 1767, 1772, 1773, 1774, 1775, 1829, 1837, 1843, 1854, 1855, 1869, 1877, 1878, 1879, 1888, 1930, construction of 524, 525, 527	Missouri
 1854, 1855, 1869, 1877, 1878, 1879, 1898, 1913 	iig
construction of 524, 525, 527	magnetic separator R T Clegg Height of chuck blocks
iron balls for bedding 1458 Krupp pg 1446	discharge in stamps
tailboard in 551	of steam stamps
using one shaft and eccentric for plungers 530	stamps at mills 1621, 1624, 1632, 1640, 1
versus Collom jigs 515	. 1008, 1
mills in the 1176 round rotating cement buddles at Mill 150 1800, 1801	in California drop of stamps 200,
slime tables in 697	in mills 1618, 1620, 1621, 1624, 1626, 1
use of Linkenbach pointed boxes in 441	1640, 1658, 1661, 1668, 1677, 1769, 1
askell's log washer 327 assell Iron Works Company, King's bucking board 1323	gate and dam in jigs
assen iron Works Company, King's bucking board 1323	riffle cleats for Wiltley table Pinder concentrator
Stanwood gravity muller or King's bucking board 1285	taillyand affecting iig canacity
atch & Chalmers cost of hand picking 487	Gon jiss Heinstein ill mill Helena & Frisco mill Gen, Idaho, tree of the Mining Company
hand picking on the Rand 492 F. H. and J. A Chalmers, gold mines of the	Heinstein's hall mill
P. H. and J. A Chalmers, gold mines of the	Heiena & Frisco mill Com. Idaho tree of the W. M. Eduards 9
Rand xix gold stamp mills in S Africa 1173	Mining Company
gold stamp mills in S Africa 1173 athaway C L. Hathaway gyratory mill 1281, 1310,	mill . xxvi,
gyratory breaker 1215, 1223	Helical current in classifiers
Rock Crusher Company, 1223 Lucr. Lyon Blanton cam 229	Helicoid conveyor Helium, atomic weight of
auer, i von Blanion cam 229	Hell upon Earth mill xxv,
Pape-Hennelverg Machine 828	
Pape-Henneberg Machine 838 auraki Peninsula, New Zealand, cyanide mills	Helmhacker, K
Lucr, J. von, Blanton cam 229 Pape-Hennelverg Machine 838 Luraki Peninsula, New Zealand, cyanide mills in 181 aurez, P., Carr disintegrator for coal 298	Helmhacker, R hand picking of quicksilver at Idria, Austria. quicksilver concentrator at Idria, Austria.

Pages 1-643, Vol. I.	ORE DI	RESSING.	Pages 644-1197, Vol. 1
Iematite, See also Iron.		High-speed rolls, a	dvantage of
concentration of	1054	Humbold	t
crushed by Minnesota Iron Company method of washing at Iron Mountain,	31		
mill for	897	Hill, R. T., Mexic	an placers 20
ores, magnetic separation of	809	Hille, F., Bilharz	yan mills 1 an placers 20 spitzlutte 4
weight of preparation for paint	1190 839	concentratir gravity stan	ng galena and zinc blende1178, 11
separated by magnets	790	Krupp ama	ips lgamating table and Laszlo amal-
specific gravity of treated by jig at Iron Mountain, Miss	1189	gamaior	
Vermillion, action of Monarch breaker	ouri . 500 r on 21	nosses in goi	ld stamp mills
lemp ropes	1095	material for Himmelfahrt Fund	mine, classifier at
lendrick Manufacturing Company's scree	n at Mill	mill #936, 9	58, 1087, 1099, 1102, 1116, 1127, 11
157	1820 58 1822, 1824	sieve scale i	1177, 11 n
steel plates for tower screens at Mill 1 lendrie & Bolthoff, double cone classifier	. 1322, 1324	Himmelfurst Fund	''' mill
portable stamp mill Mig and Supply Company, King so lendryx cyanide method at Nelson, Briti	226	mine, air conc	entrator at
Mig and Supply Company, King so	reen 1360	dry concents Hindered settling	rator at
bia	c 2035	and suction	, final conclusions on
lendy and Meyer, rolls	76	classifiers, d	leep-pocket 13
Challenge feeder used in Huntington i	mill 278	Shallow p	ocket l
feeder concentrator	853 683	defined	docities of quartz and galena 14
feeder	136	general prin	locities of quartz and galena 14 coples
for gravity stamps	. 199	in kieves	7
rolls	71	pin conce	entrator (
gold hand pan Machine Works, Blake breaker	1184 22	on jigs	etical value of 4
mechanical batea	683	free to hi	ndered settling 14
on design of cams	196	ratios	617, 6
two stamp mill	209, 229 xxv, 895	results of tu	ibular classifier tests on
lenninger's hmonite washer lenneh, C., blende dressing at Webb City lenry, A., breakers	. Missouri 1175	tests in pulsion	. 610, 14 v jig 6
lenry, A , breakers	. 57	use made of	f, in mulls &
capacity of jigs	597	versus free	settling 1
dressing lead and zinc in Belgiun Rhenish provinces	and the	washer Hinged hammer pr	ulverizer, leffrey
destate of energy	994	Williams	15
hand breaking and jaw breakers in	Belgium 57	Stone break	er
hand breaking and jaw breakers in Hard eccentric jigs at Przibram	641	History of hydraul	ic classifiers 18
ngging in ocigium	114.0	Hoagland, M., Sor breaker	
labyrinths, pointed boxes, Engis tre- itiers, Dor classifier, and siphon	separator	rolls at Mill 1	57 18
mod at Machaenich	477	Hobson, J. B., and	I E A Wiltsee, arrastra at Smarts-
magnetic separation at Przibram ore dressing at Przibram Ritinger s <i>pitslutte</i> at Przibram	833 1176	Ville and Vlooney	y Flat
Rittinger Aptislatic at Przibram	477	gravity stam Hochstedt air blast	Capparatus 816, 8
tane	477 728	Hochstrate air blas	st apparatus 8
rolls	110 594	dust appara	tus
stroke of jigs wash trommel	335	tubular classit	paratus at Rheinpreussen colliery 8 ser for coal 4
lenry Faust jigs, slope of sieves in width of sieves in	548	Hodge, C J , Coll disc motion	om jig
width of sieves in	591	disc motion	for jigs
Faust mill Nourse Gold Mining Co., sand wheel	xxv, 901 865	jigs and Clauses	517, 5 and pumps at Mill 182 1910, 19
tailings wheel at	884	classifier	anti pumpo at 41th 162 1910, 18
enshire great screening tower .	2018	jigs	1440, 14
ercules mill, Burke, Idaho S Turner	2045	at mills 18	896, 1898, 1902, 1903, 1904, 1905, 19
ercules mill, Burke, Idaho S Turner rock breaker of Blake type ering, R and J C Trautwine, Jr., form	ula for the	differential	1910, 19 motion for . 9 1
uniform now of water	XIX. 577	Hodges, A. D., an	algamating pans
launders	กกอ	Hodges, A. D., an Comstock le	ode
C, tables of equivalents errang, Sweden, Grondal magnetic separ.	xix, 1187 ators at 1537	hand sam	
erreshoff roasters at Mill 168	1862	silver mill	ies in amalgam ling on Comstock lode
erreshoff roasters at Mill 168 ersam, E. A. power required for crushin power in crushing	g 1334	Hoe conveyors	
power in crushing	1340 2019	at Mill 141	
size of opening in screens sources of lost power in crushing	. 1325	for skimming Hoffman	jıgs
theory of crusning	2018	magnetic sepa	rator . 832, 8
essite, specific gravity of	1189	mill	17
eusschen furnace for decrepitation ewitt's amalgamator	829, 839 788	()	
exagonal trommels	362	W H., concer	ntration at the Croton mines
at Mill 183	1913	cost of milli	ng 11
ibernia magnetic concentrating plant	1125 1122	magnetic co	oncentration at the Croton iron
mill magnetic separation at	1135, 1183 803	mines Sturtevant t	nill 11
New Jersey, mill at	1058		
lick revolving grizzly bars	385	Hofman H ()	11
licks, L. slimes in dressing tin	1183	Anaconda (Opper Company Gates breakers in the Black Hills ups in the Black Hills
tin ores in Cornwall . lidden Treasure mill .	1180 xxviii, 1035	Blake and (Gates breakers in the Black Hills
moreon allabult iiiii .	AA111, 1000	gravity stan	the Black Hills
acid water	1/3	grizziies in i	
acid water mortar	173 165	hand sample	ing and various samplers 8
acid water	173 165 788 805	Homestake	and Various samplers 8 and Caledonia mortars 2 Bartlett bag process 8

Tages 1100 2010, Toll 2111	rages 1011-2052, Vol. IV.
Hofman, H O., mortars 164, 165	Home power and f 1 1
most re injure 166	Horse-power, rule for breakers
plates and traps in the Black Hills 787	
roasting a piende-marcastic concentrate for	Hoscur ore feeder 9022
magnetism 2025	Hot air heating
Hog trough classifier 390, 476, 1367	sand for sweating plates
Hoists . 1008	water for sweating plates 759 Hotop, oscillating ram for roles 112
for gravity stamps 200 Pilling's picumatic 1608, 1610	Hotop, oscillating ram for roles 112
Pilling's pncumatic 1608, 1610 Holes, arrangements of in screens 168	washing of clays 1185
Holes, arrangements of in screens 168 in screens relation of thickness of plates and	Houghton County, Michigan, mill in . 994, 1000
	, 802, 1099
size of, in sieves Holhaugh J R, hand jigs in Missouri Jint ore in Missouri Holloway, G F, disadvantage of the mesh designa	
Hohbaugh, J. R., hand jigs in Missouri 9643	trommels 358 Howe, H. M. 188
zinc ore in Missouri 1181	Howe, H. M. 188 and W. E. C. Eustis, magnetic process for
Holloway, G. T., disadvantage of the mesh designa	
110h	Howell L and M. B. Jamieson, Collom 1975 at Real on
Holman Brothers' Ltd Acme table 1506	riii . 643
Holman Brothers Ltd Acme dole 1500 Holmes & Blanchard, buhrstone mill 252 Holtoff, H. C viii	concentrating silver ores at Broken
Holtoff, H. C. viii Homberg, Hochstedt apparatus at 816	Hill, New South Wales Stamps at Broken Hill, New South Wales 227
Homberg, Hochstein apparatus at 1264	Stamps at Broken Hill, New South
Home Run mill, Prescott, Arizona, Nissen stamps at 1264 Homestake mill, cam shafts 190	Wales 227 steam stamps at Broken Hill, New
cyanding at F L Bosqui 1925	South Wales 142
dies used in 163	Howell-White roasting furnace 1545
dimensions of tappets in 189	Howell-White roasting furnace 1545 furnaces at Mill 148 1792, 1793
fineness of amalgam 764	Howland mill No. 4 235
guides in 155	No. 2 232
history of the C H Fulton 2041	bibliography for 290
life of cam shafts in 190 shoes and dies 184	patent stamp battery 229
	pulverizer No. 1, bibliography for 297
mortar mouth 166 mortars 164, 165	rifiles 722 rotary stamp mill 225
plates in 789	Huanchaca Mining Co., size of stamp feed 207
rate of crushing in . 165	Hubbard, Prevost, decomposition of the feldspars 1400
screen frame 177	and Cushman, A.S., decomposition of feld-
screens used in 175	SIMIS 1418
shoes in 181	Hubner, Bartsch and Linkenbach tables 729 testing shines at Tairowitz 1186
stamps 224	testing slimes at Tairowitz 1186
tappets 188	Huet & Gevier's µg 641, 643
treatment at the, C W Merrill 2044	settling cylinder 478 Huff, Charles II., electrostatic separation 1551
Mining Company 1133	Huff, Charles II , electrostatic separation 1551
mill yvin, 1025, 1181, 1639	electrostatic separator 1551, 1611
mortar 160, 228 at Mill 106 1640	principle of action of 1552 sizes treated by 1552, 1553
1 1007	Hughes Day of electrom agreet \$19
ore, metallurgy of C W Merrill 1419	penumatic stamp 143
slime plant M Ehle, Ir 1925	Hude gold mill A Lakes 2041
modern 1200	penumatic stamp 143 Hule gold mill A Lakes 2041 Hull, Florida, mill at 897
Hood, O.P., test of Nordberg stamp at Mill 181 1250	Humbold coal breaking machine M J Julin 2050
	crushing rolls 1244
Hooper, E. H., suspension of solids in a horizontal cur	Engineering Works Company 1493
rent of water 477	ball mill 1301
air jig 820 Hooper's vanning jig 505	Bartsch rotary percussion table 1497 belt percussion table 1496
Hoover, C. H., economy and speed of operating mine 1948	belt percussion table 1496 Blake breakers 1205
	Dodge type breakers . 1206
Норк's stamp 227 Норкиs, Т. С., washing kaolin 1183 Норк. О., action of jigs	high speed rolls 1241
Hopkins, T. C., washing kaolin . 1183	Humboldt crushing rolls 1244
Hoppe, O , action of jigs 499	magnetic separators 1530
jig bed 641 settling in water 1186	picking table 1437
settling in water 1186	sand wheels 1586
Suction in a jig bed 643	tables at Mill 150 1800, 1801 high speed rolls - C. Blomeke 2016
	high speed rolls C. Blomeke 2016 "Perfect Table" 2023
Water separation 1186 Hopper bottomed classifiers 412, 413, 414, 415, 416	riffle concentrator C Blomeke 2023
shaped shallow pocket classifiers 400	Humphrey, R K, roll crushing 2010
unwaterer 476	mill 1766
Hoppers for rolls 83	Creede, Colorado 2044
Hoppers for rolls 83 Horel, V., progress in concentration 2049	new rolls 2010
Horizontal log washer 328	quartz mill 2015
mils 255	rolls 1234, 1244
plunger for jigs 517	table of sizes, power, speeds, weights, etc 1235
shifts of amalgamating pans 248	Hundt's setting tub Hungarian mercury wells 770
washers for day 1076 Horn amalgamating pan 291	Hungarian mercury wells . 770 mill 787
Horn rotary slime concentrator, the 1499	riffes . 725, 770
Horn rotary slime concentrator, the 1499 Hornsilver Mining Co 1181	Hungary, starto mills in 1 Bauer 2034
mili xxvii. 1015	U shaped classifier 424
Horn stroop 1153	Hunt, R, arrastra 290
Horse power. See Power also under each machine	Ball's revolving knife buddle
equivalents of	breakers 56
of blake breakers . 17, 21, 24	British mining xix
Comet breaker 41, 46	buddle jig
Dodge breaker 30 Forster breaker 28	buhrstone mill
Forster breaker 28 Gates and McCully breakers 45	Carr disintegrator 298 cost of crushing by rolls 104
breaker 38, 46	Cunnack's pulverizer 293
McCully breaker	edge runners 295
rolls	English, German, and French types of rolls 109
	-

Hunt R general milling ideas 117	3 Hutchinson, W. S., standardization of screens 2019
Hunt, R., general milling ideas	3 Huxley, E. C., breakers 57
gravity stamps 22 grist mill or buhr-tone mill 20 Harz, Argalls, Collom, circular slime jigs 63 Husband and Sholl pneumatic stamps, Patter-	Hoagland breaker
Husband and Sholl pneumatic stamps, Patter-	Hydraulic classifier. See Classifiers.
son spring stamb	13 Clissifier 387
Jordan's pulverizer	
Michell and Tregoning pulverizer 29	deep double trough
Nicholas pulverizer 29 pointed boxes, cone classitier, Hodge's class-	02 pocket
ther 47	6 extent of classification
Wilson's small stamp 14	2 Ferraris
Huntington amalgamating pan . 29 centrifugal roller null 23	Fraser and Chalmers
mills i 10, 228, 276, 1182, 131	1 hopper-shaped shallow pocket 400
as regrinding machines 1332–133	measures of a four-spigot, with sorting columns
mills 1625, 1668, 1684, 1686, 1687, 1689, 169	4 of a 3 inch pipe 403 4, purpose and essential qualities of 389
as regranding machines 1332-133 at Butte, Montana 201 mills 1625, 1668, 1684, 1686, 1687, 1689, 169 1701, 1711, 1738, 1753, 1839, 1845, 1867, 186 bibliography for 1870, 1871, 18	4, purpose and essential qualines of . 389 9, Richards' shallow-pocket
1870, 1871, 189 hibliography for 29	97 sizes of feed to
Boss, M. P 12	81 Yeatman . 399
roller mill 13	13 discharge for steam stamp at Mill 179 1897
capacities of 21 with various screens 13	
centrifugal force in 2	78 Monitor 333
comparative work of stamps and Huntington mills 12	gold mining G H Evans . 2041 62 jigs, compared with air jigs . 825
cost of crushing by 281, 13	
costs, life of, wearing parts in the C. E. Parsons 20	methods, discussion of R. H. Grider 2026
die rings and roller shells 2	mining. See under Placer 80 at British Guiana F. W. Luick 2033
dimensions and weights 2	80 by clevator C. W. Wright 2044
feeding 13 foundations for 13	14 cost of W. H. Radford 2033 113 in British Columbia 2033
Fraser and Chalmers figures on 2	50 Canorna 2001
Harron, Rickard & McCone 12 improved 13	81 W. H. Radford 2033 11 Colorado W. E. Thorne 2033
in Australia A. G. Charleton 20	14 K Thomas 2046
El Oro, cost of running 20	14 riffles for 721, 770
general 13 southern Rhodesia C Parsons 13	
life of screens 13	17 separators at Kalgoorlie mili 2034
wearing parts . 13 new improved . 13	17 stamp 1257 13 the Denny 1257
number used 2	31 tables 1187
	81 water for jigs 537 80 quantity . 598
quality of work done by 13	17 table of 596, 597
screens for 281, 13	14 in classifiers 387
screen sizing test of feed and product of Hun- tington mill 13	Hydraulicking 897, 1006 16 bibliography for . 1173
Sherman 1281, 13	13 in Oregon A P Dittmar , 2045
sizing test of pulp from 13 table of sizes, power, speeds, and weights of	17 of low-grade gravels P Bouery 2044 plants 1006
improved 13	12 under artificial pressure T. A. Yeatman 2044
used in California , 2 Mill 21 4	31 See also Placer
near Fremnitz Hungary 2	13 Hydrochloric acid in settling tests . 1147 82 used on plates . 752
valuable paper on C. E. Parsons 20	16 Hydrogen, atomic weight of
stamps	73 amalgamator 787 28 Hyposulphite leaching
oscillating stamp 2	27
patent stamp mill 2: theory of flotation processes 15:	29 I 56
Huntoon, L. D., separation by crushing and screen-	Ice, specific gravity of
ing 150 Hurdy Gurdy water wheels 1023, 108	
Hurst, George H., methods of washing	73 milling in 1134
Hurst, George H., methods of washing painters' colors, oils, and varmshes Hurter, C. S., wave action on amalgamating plates Husband and Sholl penumatic stamp 11 11 11 11 11 11 11 11 11 11 11 11 1	xx dredging in
Husband and Sholl penumatic stamp 14	43 mine, Alabama, mill at . 1174
pneumanc stamps 141, 100	82 amalgamation at . 787
Hutch, discharges into the for jigs, slope of 55	86 Springs, Colorado, Cammett table at 677 mills at 915, 1029, 1047
product, definition of . 49	95 pan concentrator
on jigs, defined 49 Hutches for jigs 55	95 shaking screens at . 342 23 Idlers for belts . 1094
Hutchins, J.P., dredging in Montana 203	39 Idlewild Gold Mining Co., mill
the Klondike 20 gold dredging in 1906 . 20	38 Idria, Austria, hand picking at
history of dredging 200	37 picking of waste at
Hutchinson W S	iii quicksilver dressing at
plant at Grass Valley 118	29 I Know mill
milling in Chihuahua, Mexico 20	oo imidy table
mining in western Chihuahua	
standardization of laboratory screens 130	
	50

Imperfections of deep-pocket classifiers	Iron atomic weight of
Imperial magnetic separator 2209	Iron, atomic weight of 1188 balls for jig beds at Mill 183 1458 City mill, effect of slow drop stamps. 220 cloth screens
	City mill, effect of slow drop stamps 220
table of sizes and capacities of the 1350 Improved Huntington mill 1311	cloth screens 173 concentrates, disadvantage of 1053
table of sizes, power, speeds, and weights 1312	
Impulse water wheels	crushing 60 for jig screens 545 mill buildings 1088
Inch, equivalents of 1187	surface of Gilbin County table 681
included grains	frames for jigs
action of 892 Indian metallic red paint mine 839	
Indicator bell on steam stamps . 129	Gate, Virginia, iron ore from
cards of steam stamps 130, 131, 132, 433	J ¹ 6
vanners 657 diagrams of Nordberg single-cyclinder steam	life of 604
stamp 1250, 1251	tanks 522 lining for ore bins 842 lost in page market market
steeple-compound stamp 1254	lost in pan amalgamation . 249
for iig	
Individual mortar	magulacture in Alaska. W B. Phillips 2025 Mountain, Bradford jig at 500
mortars at Mill 165 1852 Merrill's mortar . 1264	Mountain, Bradford jig at 500 hydraulic nozzle at 334
M. P. Boss mortar 1265	mil at 895, 897, 1185
Nissen mortar 1263	mill at 895, 897, 1185 plate screens in 173
Rapid Economy 1266 Induction motor, increased use of in milling 1927	sampling at 845
Ingalls, W. R., conveyors 1609	sizing tests of trommel products at
Ferraris ball mill 1323, 2014	concentrated by magnets 798
Groux mill, Ely, Nevada 2039 gold dredging in the United States 1183	concentration of 2018
milling 2040	bibliography for 1173 Lake Superior. L. H. Hardenburgh 2036
Macquisten process 1569	R. Nordensten
mill of the Steptoe Valley S & M. Co., Ely,	cost of milling 1135
Nevada 2039 milling the ore of Bingham, Utah 2039	producing concentrates in eastern United States 1986 1987
ore drying , 1610	in Quebec, milling of chrome W H Ed
power required for screw conveyors . 1583	wards 2043
Inman, A. L., multiple jaw breaker plant 57 on breakers 57	jig for 518
on breakers 57 Inscribing circles for cams . 196	magnetized by heat 799, 800 mills for 895, 1053, 1065, 1066
gravity stamus 216	of Colerane, Minn 1924
Inside amalgamated plates 178	separated by magnets 790
amalgamation 223 Inspection of jig bed 1171	treated by hydraulic nozzle . 334 in log washer 324
Instilment plan of mills 1118	by wash trommel 330
Institution of mining and metallurgy on sieve scales 1362	in log washer 324 by wash trommel 330 washing W Kellett 2018
Instructions for mounting Blake breaker 18 Interest and depreciation on breakers 49	ores in Birmingham, Alabama, washing soft. W R Crane 2041
Intermediate bins 571 Intermediate bins 843	magnetic separation of. H Wedding 2030
Intermediate bins 843	roasted for magnetism 814
Intermittent automatic discharge for jigs 584 bumping tables 682	to magnetic oxides 813 washing of Mesabi 2040
movable sieve power jigs 506	washing of Mesabi 2040 permeability of . 792
or tank system of working amalgamating pan . 248	pipe 1106
surface tables	SIZCS 405
blanket tables . 703 carpet tables . 703	punchings for jig bed riffles 722
cocoa matting 702	riffle tables on dredge. 1008
Cornish "frames" 704	sieve frames for jigs 539
Cornish "frames" 704 German sweeping tables 703 International committee of atomic weights 1188	specific gravity of 1189 cast 1189
Emery & Corundum Co , mill . 1078, 1079	wrought 1189
	stamp frames . 158
magnetic separator 1533 separators at mills 1535, 1746, 1747, 1748 Phosphate Company, McLanahan and Stone sin	strip for fastening amalgamated plates [35]
gle roll crusher at 1241	table for amalgamated plates 735 wear and loss of, in amalgamating pans 249
Interstitial currents, tests on	Irons on launders • 872
lactor on jugs 575	Irregularity of feeding 1115 Isbells improved hydraulic sizer 2020
ratios on jigs 627, 630, 631 Investigation of box classifiers	Isbells improved hydraulic sizer 2020 Isel Corundum Co , mill 1183
feed, slope, and water for film sizing tables 707	Ivanhoe mill 1731
pulsion and suction in mill jigs 632	÷
settling of fine grains	J
classified feed . 1473	Jack 900
conclusions 1477	Jacket shaft for gravity stamps 199
discussion of results . 1474 natural feed . 1471	steam for amalgamating pan 243 Jackling conveyor belts at Mill 167 1859
practical applications of results 1477	Jackson, California, mill at 1031, 1034, 1037
sized feed 1473	
lodide of mothyl 1156 potassium and mercury 1156	vanner at 653 concentrator, Idaho Springs, Colorado. C M. Rath and R. L. Grider 2042 J. W., rolls 111
potassium and mercury 1156 Iodine, atomic weight of	I. W. rolls 111
Indexite specific gravity of 1189	rolls
Iridium, atomic weight of	roll speeds
	discussions of the tube mill 2015
Irish Creek, tin ore at 288	milling practice on the Rand
ion-adminum, alloy for fig beds 5/5	tube mill installation
Iron amaigam	automatic ore feeder 2032

James Bogardus eccentric mill 259	Jig bed inspection
Carkeek classifier	box 495
slimer . 1491	concentrates, removal of 586
Jamieson, M. B. and J. Howell, Collom jigs at Broken	department at Mill 161
Hill 643	discharges 510
concentrating silver ores at Broken Hill, New South Wales 1182	at Milt 137 1458 Krupp Harz 1446
stamps at Broken Hill, New South Wales steam stamps at Broken Hill, New South	New Century jig 1445
steam stamps at Broken Hill, New South	Woodbury 1447
Wales . 142	frames 507, 522
Janin, L. Jr . viii adjustments of a stamp battery 227	Hancock 1459
amalgamated plates 743, 748, 750	hutches
amalgamating pans 291	linings
arrastra 290	mechanism 519
impurities in amalgam 251	mechanisms See the Individual Jigs.
plates and traps 789 purifying mercury 785	New Century 1459
purifying mercury 785 rolls for examde process 111	Richards' pulsating
straining amalgam 781	cost of 547
Taquet, I. B., hydraulicking in New South Wales 1178	cross bars on 504, 574
Jar, affecting settling of slimes 1149	details of 540
effect of, on plates 735, 761	length of 592
Jars for settling tests 1146 Jarvis, R. P., determination of the hindered settling	materials for 545 percentage of opening 546
ratio between quartz and galena 1460	percentage of opening 546 slope of 548
ratio between quartz and galena 1460 investigation on jigging 1463	supports for 539
suction in jigging 1462	spigots 527
Jaw breakers 55-57	tadings, definition of 494
action of 36 apacity of 52	removal of 587
capacity of 52 classified 13	tanks, materials for 522 testing 1161
compared with spindle breakers 51, 53	Jigging, an investigation on R P Jarvis 1463
cost of 52	comparison of English and continental system of.
distribution of crushing in mill 54	H S Munroe 1463
fine crushing in 54	effect of suction 628
friction 54	English system of 1463
general remarks 33 having equal motion on coarse and fine lumps 25	general principles of pulsion in 1460 suction in 1461
greatest movement on largest lump 28, 1205	laws of 610
smallest lump 13, 1200	lever on hand jigs 496
intermittent action of 55	mills 1101, 1103
Krupp's wearing parts for 1221	power used in 602
necessity for simplicity of action in 36 number used 51	using hand jigs 802
number used 51 of Dodge type 28	new developments in 2022 pulsion velocity in 1460
Western Wheeled Scraper Co 25	Sizing before 1463
power of 52	suction and pulsion in . 1460
principle of action . 52	tank . 495
running cost 54	tests . 1165
size and shape of mouth 54	on mixed sizes 630
sizing tests of product 53 table of cost of crushing of 50	theory of 631 suction in jigging 1462
taper 52	without sizing . 609
tests on work required for 307	Jigs 494, 1150
weight of 52	See also An Jigs, Hand Jigs, Harz Jigs
breaker plates, comparative wear of metals for, in Blake breakers 48	accelerated 507, 510, 515, 519
in Blake breakers 48 movements on breakers 34	mechanisms for . 533 action of . 494
Jeffrey belt conveyor 859	adjustments of 6 595
conveyors at Mill 183 1913	pulsion and suction 598
Century conveyor belt 2032	throw 531
coke crusher . 2013	air 640, 820
Columbian separator 2019 double beaded flight conveyor at Mill 126 1706	bibliography for 837 versus water 826
Manufactering Co., bucket elevators 864	and vanners versus oil concentration 832
Columbian pulsating screen 343	results compared with Elmore process . 832
drag or disc conveyors 1583	Argall's 630
friction clutches 1607	at mills 1448, 1449, 1685, 1686, 1692, 1692, 1694, 1694, 1702, 1703, 1707, 1708, 1714, 1708, 1714, 1708, 1714, 1720, 1725, 1728, 1729, 1737, 1738, 1743, 1744, 1750, 1751, 1752, 1753, 1767, 1777, 1773, 1774, 1775, 1788, 1789, 1792, 1793, 1796, 1797, 1798, 1799, 1800, 1801, 1812, 1829,
pulverizer and shredder 1321, 1323 table of sizes, capacitics, power, etc 1322	1701, 1702, 1703, 1707, 1708, 1714, 1720, 1725,
steel link chain scraper conveyor at Mill 126 1709	1753 1767 1779 1773 1774 1775 1788 1780 1703
swing hammer crusher 1281	1793, 1796, 1797, 1798, 1799, 1800, 1801, 1812, 1829
capacity of 2015	1832, 1833, 1837, 1843, 1844, 1845, 1849, 1854, 1855, 1858, 1864, 1867, 1869, 1877, 1878, 1879, 1885, 1892, 1893, 1902, 1903, 1904, 1905, 1913, 1928, 1929, 1930
trippers at Mill 183 1913	1858, 1864, 1867, 1869, 1877, 1878, 1879, 1885, 1892,
Tentsch ball mill 233, 261	1893, 1902, 1903, 1904, 1905, 1913, 1928, 1929, 1930
Jenkins, C. V., keeping accounts 1184 Jenks, C. V., dressing corundum 1183	automatic discharges for 576, 577
washing pan for corundum 335	100
Jerking dioles 667	Bilharz circular 504, 518
Bartlett 492	oblong movable sieve . 503
for testing 1153, 1171	bottom bed of, products of 495
principle of 644 trough conveyors 861	Bradford 500
Jets on slime tables 688 689	Braun 641
let washer 334	buddle 518 cam and gravity in Stutz coal jigs 537 spring mechanism for 507
J H Frenier and Son, spiral sand pump made by 870	spring mechanism for
Jig and table departments at mills 1691, 1811	Capacity of
bedding 1458	power and water
52	2

Cazin's 640, 641, 642, 643 center discharge in changes in the Harz 582 changes in the Harz 2022	Jigs, McLanahan's
circular 518	hutch and tailings
classes of	material of bottom bed
classification of 551	materials for tanks
classifier	May's
at Mill 120	mechanism for
cleaning sieves of . 576	method of running
clearance of plunger . 529, 530	methods of feeding
coarse concentrates of . 494	movable sieve hand
Collom	testing
compartments in 507	New Century
compressed air	drop motion
Conkling 503	number of compartments
connecting rods for	strokes
construction of 524, 527	operation of
continuous movable sieve power 400	
Cooley . 522, 643	Osterspey Parsons & Fisher
Cooley 522, 643 cost of 604, 1126	turn die barro in
cover 537	pipe discharge in Pl a mb circular
dead box on 510	plunger
depth of longitudinal partition 524	
details of 552	attachment to connecting rods
Diescher coal 520	plungers for 510
difference in specific gravity of minerals for 609	Oil .
different types of 2021	position of
differential-motion viriable exists much made	power used by
differential-motion, variable-crank mechanism of 1457	principle and advantages of
	purpose, and definitions products of
disc motion in	products of
discharges into the hutch 586 with unwatering sieves 586	pulsion 518,
with unwatering sieves 586	and suction investigated
disposal of concentrates in 585 double discharge in 583	tvjx
double discharge in . 583	purpose and adjustments range of sizes fed to
with one shaft 530	range of sizes fed to
drop between sieves 549	relation of sieve to plunger
eccentric for 510, 531	removal of coarse concentrates
enter or redding 1463	tailings in
slimy water 599	repairs on
elliptical gear in . 536	Downath
Evans 517	Richards' pulsator ng
Evrard's 642, 643	table of sizes, capacities, and dimensions
Evrard's experimental data on. G. C Bring 642, 643 2022	Richards' pulsator jig table of sizes, capacities, and dimensions Rittinger's
feed aprons for 549	Robinson
box for 549	Rogers
Ferraris intermediate 539, 540, 584	Schranz 503
fine concentrates of . 495	Schranz 503, screen saying device for
fixed sieve 507, 1444	screen saving device for shaft and pulleys for
for testing 1150, 1174, 1989	Sheppard 538
three mineral separation 590	side discharge in
two mineral separation 589	plunger
four mineral separation on 590	sieve wires and prices
Francou 519 643	sieves
gate and dam discharges . 577	size of grains of bottom bed
general considerations . 522	size of grains of bottom bed sieve hole
Green's movable sieve 639	sieve note
Hancock . 504, 643, 1440	sizing before jigging
	skimming of .
	slime
practice in the mills	slope of hutches in •
Harz compared with Collom 515 -cycentric bedded sand jig at Mill 125 1703 type 507	sieves
eccentric bedded sand pg at Mill 125 . 1703 type	slow return speed of
hard plunger form	speed of
head plunger form 518	Spilsbury
richerwasche 520	spring and bell crank mechanism for
height of gate and dam 578	Stapff 642,
tailboard 550	stay box for
hinged connecting rod for	boxes for discharges .
	steam driven
Hooper's vanning 505	Stroh's
Huet & Geyler's . 641, 643	study of water N. V. Hansell
hutch spigot 507	G. G. Bring
irenaunc water quantity in 537, 598	Stutz
indicator cards of 632	coal .
intermittent automatic discharge 584	tailboards for
movable sieve 506	testing of
interstitial factor . 575	tests on suction in
iron 510	thickness of bottom bed
balls for bedding 1458	top layer of products of
sieve frames . 539	top layer of, products of
	under piston type
Kinds of 525	unwatering boxes
Krom's penumatic 824 Krupp Harz 1446	Utsch 519, 640,
Krupp Harz 1446	versus Ferraris tables. M. Lenicque
	magnets
Lamarche and Schwarz . 641	tables 606.
Lemière's 643	Vezin
	water for 537,
length of stroke . 594	
length of stroke 594 life of 604	Wendt 500
life of . 604	wentt . 530 .
length of stroke 594 life of 604 limits of sizes treated by 604 longitudinal partition 524 Luhrig 538	Wendt . 530, whole bed of, products of width of sieves

7 51 11 1	Water Digities and
Jigs with movable sieves	Káván, Rittinger table
Woodbury	Kayser, H. W. F. and Richard Provis, tin dressing at
Johannesborg, Sweden, mill at	Káván, Rittinger table 668 Kavicic, J., Rittinger table 728 Kayser, H. W. F. and Richard Provis, tin dressing at Bischoff, Tasmania 1182 Kearsarge mine 997
South Africa, mill at	Keedy dry-ore sizer
Johnson 324 figures on sampling 852	Keewann, Omario, min at 1197
hgures on sampling 852 hlter press at Mill 117 1674 F M, on Griffin mill 284 G and A Trelour, magnetic separation of tin and wolfram 2029	vanners at
F M, on Griffin mill 284	Ketth, N. S., amalgamating plates 747, 765, 789 Ketlogg, Idaho, mill at 937, 951 Kelly mill, Socorro, New Mevico. W M Johnson 2046 Kemp, J. F., Desloge mill for galena in Missouri 1185
and wolfram 2029	Kelly mill. Socorro. New Mexico. W. M. Johnson 2046
G. R., log washer at Longdale, Virginia 1175	Kemp, J. F., Desloge mill for galena in Missouri . 1185
log washing plant at Longdale, Va	
reservoirs for tailings of the Longdale Iron Co 477	Kennedy gyratory breakers 1213 Mining and Milling Company mill xxviii, 1031, 1037
mechanical sand shoveler 461, 899 at Mill 155 . 1817	Spindle breaker 1223 Kennicutt system of softening water 1416, 1419
ore mill J Johnson 2015	Kensington, F. R., washing iron ore at Cabarceno.
ore mill J Johnson 2015 Paul, Cornish sampling at El Paso smelter 110 step 1 sampling 4 849	Spain 1182
steel for wearing parts of breakers 48	Frederick, wash trommel 335 Kent, centrifugal force 278, 827
Johnston vanner 652, 1499, 1501	cost of power 135, 206, 250
vanners at mills 1502, 1669, 1834, 1850, 1851, 1852, 1858	gauges . 1194 journal pressure in rolls 96
in California practice 1620	lubricants . 1097
John Taylor and Company 1137 Joints for belts 1093	mill
Jones, Clemens, costs of concentrating iron ore 1135	pulverizing mill 2014
Jones, Clemens, costs of concentrating iron ore 1135 magnetic separation of iron 1175 magnetizing hematite 833	roller mill, table of details of the 1304 screen gauge . 173
sampler 844, 1570	water pipes . 858
Joplin district, cost of milling producing zinc in 1971, 1972, 1973	William . 50, 93, 104, 1097, 1173
hand jigging practice . 894	engineers' pocket book . xx strength of stone
mill in the 1183	Kessler magnetic separator . 811
milling in the E Hedburg 2041 milling the sheet ore of D Brittain 2039	Kettle for amalgam
reverberatory furnace for magnetic separation 1545	to mill numbers xxv
Foundry Company, roll shells at Mill 148 1792 Jack table, a magnetic separator 2025	the outline of nulls 1614, 1615 Keys for stamp cams 191, 192
Missouri, mill at . 901, 907	stamp tappets 188
practice at Mill 148 1792 Separating Company, Cleveland-Knowles sepa-	Keystone Consolidated Mining Company nall xxviii, 1032, 1037
rator at 1542	mill, mortars 164
Jordan's centrifugal grinder and amalgamator 234 bibliography for 295	Kia Ora dredge 1184 Gold Dredging Company mill xxvii
pulverizer . 236	plant 1008
bibliography for 299 Joseph Wharton mill 1053, 1054, 1117	Kieves 726, 1464, 1510 at Mill 185 . 1916
Mining Co , mill 1058	bibhography for . 727
Joshua Hendy Iron Works Company, Pinder Con-	continuous 727 coupled with slime tables 1110
Machine Works. See Hendy, J.	depth of bed . 1511
Machine Works 196, 209, 229 breaker used 22	details of in mills
vanner . 652	principles of 644
Journal lubrication 1930 Journals, care of 1097	used in gold dredging 1013 Kiln for drying 881
for rolls 72	Kilo of water
friction in 95	or kilogram, equivalents of 1187 per square centimeter
Iudd, E. K., concentration at Virgilina 2038	Kilogram-meters, equivalents of 1188
	Kilometer, equivalents of
Julian and Smart, cyanidings of gold and silver ores 1323 Jumpers Deep mill 1185	Kimberley, diamond washing at 839, 1080
mine, weight of ore at 1191	mines, weight of ore 1191
	Kimberlite 1081
K	Kimberly Wilfley mill, Kokomo, Colorado 2046
Kalb, Courtenay de 257	Kinds of crushing actions 8 ore for gravity stamps 207
Kalgoorhe, ball mill practice in 1302	surface on slime tables 695
dry crushing at	King Brothers mines, mill
Kanawha freestone, strength of 301	Clarence, amalgamating pans 290
Kansas, hand jigging in	gravity stamps 223 settlers and agitators 787
Kaolin Mfg. Co., settling apparatus . 1149	
setting of	United States Geological explorations of 40th parallel xx
and follows from a stable to	Washoe and Reese River processes ! 1173
washing 1075, 1183 T. C. Hopkins 2026, 2028 Kaolimte, specific gravity of 1189	magnetic separator 832 revolving screen
Kaolinte, specific gravity of	advintages of the 2010
Karlik oscillating grizzly . 385, 386 screen . 386, 1185	screen, the 1356, 1360 Kingsford Foundry and Machine Company cent-
Karwin, jigs at 642	screen, the 1356, 1360 Kingsford Foundry and Machine Company cent- rifugal pump at Mill 127 1712
Karwin, jigs at 642 Kás, A., Distl Susky screw grate . 386 Karlik and Klein moving grizzlies . 386	
name and rated moving guarnes . 300	G. J. McKay

Kinkead ball mill 234	Krom rolling toggle breaker 2010
bibliography for	rolls 109, 110, 112, 224, 1182
at Goldfield, Nevada, use of the. C. T. Rice 2038	sectional breaker of Blake type 21 S R
at Goldfield, Nevada, use of the. C. T. Rice 2038 bibliography for 296 number used 231	advantages of air over water 838
Kirby, E. B., itgs	and H.Van F. Furman, pneumatic concentration 838 T. A. Blake, improvements by Krom 59
systems of ore dressing	boxes for rolls . 73
weight of broken ore	breakers . 57, 59, 60 Cornish rolls versus Krom rolls 110
Kirschner, L , breaking 56 Gates and Blake breakers 56	stamps 112
gold mills in Europe 1173	Krom breaker
gravity stamps 223	maker of Rutter breaker . 45
Kayan Kittinger and Luhrig tables . 729	roll speeds 87, 88 tires
Laszlo's amalgamator 787	rolls . 72, 77, 111
magnetic separation 832 movable sieve hand jig, Harz and Bilharz jigs 639	stamps and rolls 100 stamps and rolls 316
Pape-Henneberg concentrator 839	versus rolls 230
picking tables 492 pointed boxes, spitalutte 476	Sturtevant mill versus rolls 110, 298 Krupp amalgamating table 788
Schrauz nun	200, 1280, 2011, 2017
slime tables	at Mill 128 1714 cams 1272
Kirsten and Labram, greased table 831	cam shaft 1272
Klein classifier F. H. Regel 2020 principle of 2020	concentrating table . 2022 gyratory breakers 1215
jig, description of the . 2021	high-speed rolls 1238
L. A., dressing asbestos 1182 moving grizzly bars 386	description of 1244 magnetic separator 2025
Klein's solution . 1156	mining administration, magnetic plant of 1814
Kley breaker 55 knee frames for gravity stamps 157, 158	picking tables 1435 rock breaker 1202
Knife for scraping plates 762	roll shell tu ning device 1243
Knight water wheel 1033, 1035, 1089, 1090 Knobs, rolls with 104-106	sectional guides for gravity stamps 1270 spitalutten, the 1382
Knochenhauer, B., amalgam . 788	tables at Mill 128 1715
arrastra 290 California stamps 225	tube mills at Mill 118 1677 discharge of 1288
tigures on California gold mills 1177	Krupp's wearing triefs for the breakers 1994
Knop turbine 973 Knott dredge 1011	Krypton, atomic weight of 1188 Kubale, Sheppard coal jig 643
Knowles' duplex vacuum pumps at Vill 117 [6/3	Kunhardt, W. B. and G. W. Maynard, dressing of
New Century magnetic separator 1541, 1568 table of sizes, capacities, speeds, power,	iron ores 1185 jigging tests 643
weights, etc., of 1542	W B, breaker and mill separate 56
pump 872, 914, 922 triplex pump at Mill 117 1674	breakers 56 Brink and Hubner disintegrator 298
Knox amalgamating pan 776	buddles, slime tables, percussion tables, and
capacity of ugs 597	kieves 727 capacity of jigs 597
Gottesgabe and Hammerwasche mills in West-	corrosion of screens 354
ligs at Gottesgabe and Hammerwasche mills at	crushing concentrates 1113 Dingey mill 293
Westphalia 641	drop between no sieves 550
stroke of jigs 594	extent of crushing desirable . 315 general milling . 1173
H, ore dressing at Tarnowitz, Silesia 1186 Kohinoor mill 907	gravity stamps . 223
Empire Zinc Company xxv	Harzings 639
Köhlenon jigs 643 Kolar District, India, cost of producing gold in 1981, 1982,	intermittent discharge 584
1983	jig bed . 576 discharges 583
Kolshorn & Streckers grinder 232 bibliography for 292	plunger clearance 530 jigging unsized material 609
Kominor mill . 2017	length of pig sieves . 592
Konus breaker Kootenay Ore Company, B. C., the custom mill of	length of jug sieves 592 life of jugs 604 limit of jugging 605, 606
the 2045	Nicholas bulverizer 292
Koppel shoes and dies at Mill 97	ore dressing in Europe xx, 1185
Propfe mill 297	pneumatic stamps 143 removal of jig tailings 588
Kossmann, B., Nicholas pulverizer 292 Krause mortar discharge for steam stamps 997, 1003, 1256	roll shells . 109 speeds 87
at Mill 179 1897	running jigs 572
pneumatic stamp 141 Kreiss jerking conveyor 884	Schranz mill 276, 296 settling tests
Kretschmer, Franz, graphite dressing in Moravia 1183	Siemens and Friedrichssegen magnetic separ-
Krogh centrifugal pump at mills 1626, 1627, 1633, 1929, 1930	ators 832
Krom air #g 824	slime tables . 696
belted rolls 82	slope of jig sieves . 548 slime tables . 694
movement of jaws 34	stay boxes for iig discharges 551 585
of Dodge type 31	stroke of jigs . 594
pneumatic jig . 824	trommels and riddles
products from, on De Soto mine ore 824 results on Seminole ore 821	wear of jig screens
results on Seminole ore 621	matter of jig sieves
00	•

Kutscher, E., iigs at Clausthal		643	Lake Superior, rock houses	485
Kutscher, E., jigs at Clausthal	1	186	slime tables at	697
Kutter formula for flow of water		885	slime tables at stamp mill, power used at Lake View mill, Australia A. G. Charleton Lakes, Arthur, American pebbles for tube mills	310
			Lake View mill. Australia A. G. Charleton	2035
L			Lakes, Arthur, American pebbles for tube mills .	2015
			arrastra H. E. Woods testing plant	2013
Labor cost of	1	130	H. E. Woods testing plant	2048
for breakers .		51	Standard mill, Idaho	1183
breaking .		50	Lamar, J. R. de Lamarche and Schwarz coal jig	284
efficiency, effect on costs	. 1	127	Lamarche and Schwarz coal jig	641
for arrastras		239	Lamb automatic tailings sampler 1573,	1609
canvas tables .		701	H. M., mining in British Columbia M. R., cyaniding at Goldfield, Nevada	2035
cleaning plates	758,	760	M. R., cyaniding at Goldfield, Nevada	1922
Conkling jig		503	the Combination mill, Goldfield, Nevada Lamberton mill	2038
dredge		898	Lamberton mill	234
hand jigs	•	499	bibliography for	295
Hooper air jig	-0-	824	Lamprecht, R., breakers	56
ngs	507,	101	Brown's spindle breaker, Wolf's jaw breaker	56
mills	1	101	Carr disintegrator	298
pan amalgamation		250	classifiers for coal	476 574
trommels .		361	coal jigs	5/4
settling tanks		459	coarse and fine jigs for coal	639
stamps	•	206	cone mill	292
washing pans		333	Die Kohlenaufbereitung	XX
in the mills		931	grizzhes, riddles, and trommels	384
required at crushing plant of Mill 174	coo 1	003	revolving and belt tables	492
mins 1019, 1021, 1022, 1028, 1633, 1	705	100,	rolls for crushing coal	109
1004, 1070, 1075, 1053, 1088, 1098, 1	700, 1	764	Lancaster breaker 5	9, 60
required at crushing plant of Mill 174 mills 1619, 1621, 1622, 1628, 1633, 1 1664, 1676, 1678, 1685, 1688, 1698, 1 1712, 1730, 1739, 1745, 1757, 1759, 1 1768, 1788, 1701, 1702, 1801, 1816,	(01, I	104, 200	Company, James H., Lancaster rotary pumps J. H., the Lancaster gold amalgamator	1289
100, 100, 101, 100, 1001, 1010, 1	914, R	271	1 and realiste the relationship to	1920
1021, 1000, 1000, 1011, 1010, 1802, 1	1019 1	020	Land pebble phosphate	895
1712, 1730, 1739, 1745, 1757, 1759, 1 1768, 1786, 1791, 1793, 1801, 1816, 1 1827, 1830, 1835, 1841, 1848, 1852, 1 1881, 1887, 1890, by sampling department at Mill 174 wage scales at mils 1619, 1621, 1622, 16 1633, 1657, 1664, 1676, 1678, 1680, 1685, 1690, 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 1820, 1830, 1841, 1848, 1865, 1666, 1867, 1867, 1867, 1867, 1867, 1868, 1705, 1705, 1867, 18	1010, I	004	Co, mill xx: Landis, H K, blende mills in Missouri	v, 897
mara et da et mille 1610 1691 1790 37	1 365	004 190	Landrs, 11 K., Diende mins in Missouri	11/9
1022 1057 1064 1076 1079 1000 1005 1	1607 1	129,	hand ngs and Harz jigs jigs at Friedensville, Pa	642
1000, 1007, 1004, 1070, 1070, 1000, 1000, 1	1269 1	100, 704	ngs at rriedensville, ra .	642
1090, 1090, 1700, 1712, 1700, 1740, 1707, 1	1702, 17	/04,	Yeatman hydraulic classifier zinc ore dressing at Friedensville, Pennsylvania	1170
1194, 1604, 1610, 1620, 1660, 1641, 1646, 1	1001 1	509,	zinc ore dressing at Friedensville, Pennsylvania	1178
			Landolt and Bornstein	XX
Laboratory breaker, Case .		204	tables .	1188
ore grinder McKenna slime table H S Munroe	1285, 1	323	Lane Chili mills	2014
sume table 11 5 Munroe			milling practice with the	2016
tools for testing		137	J A Stewart	2015
Labradorite, specific gravity of	447	189		1308
Labyrinths	447,	4/0	at Bonita Mining Co's property	1309
La Cananea, concentration at M. Schwerin mining camp. D. E. Woodbridge		1923	Langerfeld, A, new coal picker Langguth, E, history of magnetic separation	2021
mining camp 17 is woodbridge			Langguin, E., nistory of magnetic separation	2031
Ladder for dredges		1093 1008	magnetic properties of minerals	837 296
		190	Langley's crusher, bibliography for	274
Lady Barkly mill, weight of stamps in		130	dry crusher	234
La France Copper Company Lagging for belts		093	improved dry crusher	820
Largeing for bens	,	837	Lannisdorf, centrifugal machine at	1188
Lagrange colliery, air blast at Lake City, Colorado, mill at .		935	Lanthanum, atomic weight of La Point Flour Gold Separating Company, the C. A.	1100
Limit of the man mill		178	Int Foint Flour Gold Separating Company, the C.A.	1509
Harold stamp mill . Superior, center discharge at		582	suspended riffles gold separators, table of sizes, capacities, and	1008
Collom jigs at	•	515	weights	1510
concentration motherly R D Robert		2040	Lard	1097
concentration methods R R Robert copper mills 114, 475, 1085, 1093, 1	กดง 1	108	Largest size of concentrates gaved in the mills	1119
	1109,	1113	tailings in the mills	1119
disposal of concentrates in		586	Lase hinger's formula for average grain	1293
mortar blocks in		148	Last Chance mill xxv	94
mortar blocks in T A Rickard		1419	Laszlo amalgamator	i, 945
mines, copper handbook		925	Lateral thrust, right and left hand cams	195
rock, settling slimes from		458	Latrobe steel die rings and roller shells, life of in mills	1728
size of grizzly used for		340	1749, 1771,	1773
cost of die, etc., at		121	wearing parts of Huntington mills, life of at	
milling at	1130.		Mill 139	1753
district, cost of producing copper in	1130, 1948, 1	949.	Latta & Martin Pump Company, displacement	
p. p. p. m		1950	pump 1589	, 1610
hammers used		10	at Mill 144 1590	1779
hog trough classitier	390,	476	Lattes, O., ore dressing at Przibram	1177
hydraulic classifier, products of in Mill 4 Mill 45	6	391	Laumontite, specific gravity of	1189
Mill 45		39 i	Launders 872	1592
MIII 40		1054	Launders 872 at Mill 152	1812
		47	bibliography for	888
iron ores works spindle breaker wearing parts		517	Blue's experiments with	1594
iron ores works spindle breaker wearing parts iigs		011	distributing or siving	
iron ores works spindle breaker wearing parts jigs life of Collom jigs at		604		1417
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at	:	604 833	description of pipe C W Van Law	1609
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at	:	604 833	description of pipe C W Van Law design and flow of sands F K. Blue	1609 2032
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at	. :	604 833	description of pape C w Van Law design and flow of sands F K. Blue flow of sand in F K Blue	1609 2032 1609
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at	. :	604 833	description of pape C w Van Law design and flow of sands F K. Blue flow of sand in F K Blue	1609 2032 1609
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at	1183, 1	604 833 549 2041 1997 186,	description of pape C W van Law design and flow of sands F K. Blue flow of sand in. F K. Blue for amalgamated plates canvas tables 700, 70	1609 2032 1609 743 11, 702
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at method of feeding jigs at miling practice A S Aktinson mills. T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1	1183, 1	604 833 549 2041 1997 186,	description of pipe (W van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue for amalgamated plates canvas tables shunting 700, 70	1609 2032 1609 743 11, 702
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at method of feeding jigs at milling practice A S Atkinson mills. T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1 automatic discharge in		604 833 549 2041 1997 186, 1997 577	description of pipe W van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue for amalgamated plates canvas tables shunting spitzkaten	1609 2032 1609 743 11, 702
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at method of feeding jigs at milling practice - A S Atkinson mills, T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1 automatic discharge in native copper mills		604 833 549 2041 1997 186, 1997 577 1103	description of pipe (W Van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue flow analgamated plates canvas tables canvas tables shunting vpitskaten hydraulic mean depth	1609 2032 1609 743 01, 702 1109 440 876
iron ores works spindle breaker wearing parts jigs jife of Collom jigs at magnetic concentration at method of feeding jigs at milling practice A S Atkinson mills. T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1 automatic discharge in native copper mills disposal of concentrates in		604 833 549 2041 1997 186, 1997 577 1103 587	description of pipe (W Van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue for amalgamated plates canvas tables canvas tables shunting spitiskasten hydraulic mean depth in the mills	1609 2032 1609 743 11, 702 1109 440 876 876
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at method of feeding jigs at milling practice A S Atkinson mills. T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1 automatic discharge in native copper mills disposal of concentrates in stage of grains in		604 833 549 2041 1997 186, 1997 577 1103 587 693	description of pipe (W Van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue for amalgamated plates canvas tables canvas tables shunting vpitskaten hydraulic mean depth in the mills linings for	1609 2032 1609 743 11, 702 1109 440 876 874 1598
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at method of feeding jigs at milling practice A S Atkinson mills. T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1 automatic discharge in native copper mills disposal of concentrates in size of grains in ore dressing, improvements in		604 833 549 2041 1997 186, 1997 577 1103 587 693 2037	description of pipe (W Van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue for amalgamated plates canvas tables 70€, 70 shunting spitzkasten hydraulic mean depth in the mills linings for mean velocities of water in	1609 2032 1609 743 11, 702 11, 703 440 876 877 1598
iron ores works spindle breaker wearing parts jigs life of Collom jigs at magnetic concentration at method of feeding jigs at milling practice A S Atkinson mills. T. A Rickard mills at 1089, 1102, 1174, 1175, 1184, 1 automatic discharge in native copper mills disposal of concentrates in stage of grains in		604 833 549 2041 1997 186, 1997 577 1103 587 693	description of pipe (W Van Law design and flow of sands F K. Blue flow of sand in. F. K. Blue for amalgamated plates canvas tables canvas tables shunting vpitskaten hydraulic mean depth in the mills linings for	1609 2032 1609 743 11, 702 1109 440 876 874 1598

~ mg, ·		
Launders, pipe launders at Guanajuato	1595	Le France Copper Company, copper handbook 1925
plate glass launder linings at Mill 173	1595	Leggett, Thomas H., diamond washing in South
quantities of water in	878 877	Africa
skimming as applied to clarifying tanks	1409	pans
skimming as applied to clarifying tanks speed of water current necessary to carry sand	878	Lehigh Mountain ore magnetic separation of 810
theory of flow in ,	876	Zinc & Iron Company, cost of screens 361
wetted perimeter Laurenburg, Prussia, hand picking at	876 492	Zinc & Iron Company, cost of screens
jigging at	609	lina 1183
mill at . 961, 1086, 1116,	1177	magnetic separators 1528
sieve scale at	367	Lemières coal ng 643
picking at running jigs at	487 572	Length and slope of trommels
Schlanz mill at	276	jig sieves 592, 599
Laurium, Greece, magnetic separation at	812	stroke of Card tables at mills 1660, 1830
Lautenthal, classifier at	479	Evans jigs at mills 1837, 1838, 1843, 1844,
hand picking at jigging at	492 609	feeder at Mill 125 1700
jigs at	643	Frue vanners at mills 1625, 1627, 1662, 1711, 1712, 1755, 1844, 1865
mill at	1086	1712, 1755, 1844, 1865
picking at	487 609	greased tables at Mill 188 1921
range of sizes at sieve scale in mill	367	Harcock jigs at mills . 170, 1846, 1869 Harz jigs at mills . 1692, 1693, 1694, 1701, 1702, 1703, 1725, 1728, 1744, 1750, 1751, 1752, 1753, 1727, 1773, 1774, 1775, 1829, 1837, 1843, 1854, 1855, 1809, 1877, 1878,
Lawrence, H. L., dressing zinc blende and magnetite	-	1702, 1703, 1725, 1728, 1744, 1750, 1751,
at new Pierrelitte mines, France	1182	1752, 1753, 1772, 1773, 1774, 1775, 1829, 1837, 1843, 1854, 1855, 1869, 1877, 1878,
Machine Co., centrifugal pumps	869 464	1837, 1843, 1854, 1855, 1869, 1877, 1878, 1879, 1885
Laws of classifying bibliography for	475	Hodge jigs at mills 1902, 1903, 1904, 1905,
crushing 300,	1325	1909, 1910, 1911
bibliography for	315	jigs 594
conditions under which crushing is effected fineness of the desired product	1325	at mills 1685, 1686, 1707, 1708, 1858, 1929 Johnston vanuers at Mill 167 1858
nature of material crushed	1325	mortar jigs at Mill 177 1892
power required for crushing	1334	Overstrom tables at mills 1711, 1712, 1730
relative efficiency of regrinding machines	1331	plunger feeders at mills 1749, 1750, 1751, 1857 shaking feeders at mills 1691, 1868
sources of lost power free-settling particles, method of investigation	1325	shaking feeders at mills 1691, 1868 grizzly at Mill 124 1690
of, in surface current box classifiers results of investigation of, in surface cur-	434	launders at mills 1693, 1694, 1761
results of investigation of, in surface cur-		simple steam stamp at Mill 182 1909
rent box classifier	434 1460	Sutton, Steele, and Steele dry table at Mill 151 1803
hibliography for	639	Triumph vanners at Mill 101 1627
L C Trent and Company	270	v.mn/s. it Mill 199 1687
L. C. Trent and Company Leach, A. H., picking belt of steel wire screen Leaching, bibliography for	492	Wilfley tables at mills 1625, 1633, 1661, 1662,
Leaching, bibliography for copper ores	$\frac{1173}{1167}$	Wilfley tables at mills 1625, 1633, 1661, 1662, 1669, 1689, 1729, 1738, 1739, 1744, 1745, 1754, 1829, 1830, 1844, 1855, 1858, 1894
for wolframite	829	Woodbury-Benedict jigs at Mill 177 1893
in tin ores	1081	concentrators at Mill 117 1669
silver ores with hyposulphite	1167	trommels 349
Lead amalgam separated by hot straining	$\frac{730}{781}$	units of 1187 Lenicque, M , testing of ores 2048
and silver ore, crushed by Blake breaker and		Lepidohte, specific gravity of 1189
Chili mill	271	Lester breaker 56
atomic weight of bullets for jig bed	$\frac{1188}{1081}$	Leupold spitzlutte 2020 Leuschner magnetic table separator 2031
City, South Dakota, mill at	1025	Levant mill for tin ore 1082
cost of producing 1960,	1968	Levelling mortar blocks 147
cost of producing 1960, ores, mile or 1982, 900, 908, 909, 910, 911, 913, 916, 916, 916, 916, 916, 916, 916, 916	915.	up Wilfley tables ♥ 1468
910, 920, 926, 935, 936, 901, 903, 1004, 1005,	1015,	Lever stamps 1246, 1261 Rapid Economy 1261
size of grizzly used for	340	type of Blake breaker 22
size of grizzly used for treated at Mills 24, 25	69	Leviathan conveyor belt 1585
by revolving knife buddle	$\frac{329}{251}$	pulverizer 236 hibliography of 299
removal of shot for jig beds	574	Lewis and Bartlett bag houses 885
tests on velocity of	626	1 V deaning corundum at Sapphire and Corun-
-silver ores, mills for 929	5, 936	dum Hill, N. C 1184
specific gravity of	1189 2041	corundum at Corundum Hill, North Carolina 1176 heating and quenching 57
zinc mill, outline of a. W R. Crane	1120	Libbey, W. L., amalgamated plates 765
ores, mills for Leadville, Colorado, filter bins at	1570	
mill at 909, 910, 1069	, 1179	Sodium amalgam 753 Liberty Bell Gold Mining Company 1631 mill, Telluride, Colo. A. Winslow 2033
mining district. T. Tonge	2035	mill Telluride, Colo. A. Winslow 2033
roasting for magnetism at Gold and Silver Extraction Company mill xxix	, 1070	Libra scales . 1000
Leak.ure of magnets .	793	Lidner, P. G. 1175
Leather belts Leavitt, E. D. Jr	1093	ilize in Sweden 640
pump designed by	viii 872	ore dressing in Sweden 1175
steam stamp 114, 115, 116, 118, 119, 120, 121	, 122,	roasing a biende ore
pump designed by steam stamp 114, 115, 116, 118, 119, 120, 121 ■ 123, 124, 126, 127, 128, 131, 132, 133, 13 at Mill 1777	4, 142	for friability
at Mill" 177	1892 993	stroke of jigs . 594
valve motion	124	Liebig condenser for retorts
Lebanon plant of the Pennsylvania Steel Company	1828	Life of amalgamated plate 741
Le Chatelier, decomposition of siderite	1544	battery screens at mills . 1618, 1624, 1632 belt conveyor at mills . 1585, 1631, 1667, 1670,
Ledoux, A. R., figures on sampling rules for sampling	852 849	belt conveyor at mills . 1585, 1631, 1667, 1670, 1710, 1853
Leffel turbine wheel916, 939, 1024, 1052, 1053	1089	belts and buckets on elevators . 863, 864
		57

Life of blanket tables	Life of wearing parts of Hodge and Cleaves sand jigs
brass wire jig sieves at Mill 1731877, 1878, 1879 bucket conveyor861	a. Mill 182
buckets in sand wheels at Mill 117 1668, 1669	Huntington mills
cam shaft 190	
canvas, blanket, and carpet tables	117
centrifugal pumps 870	McCully breakers at Mill 139 1222, 1749
chilled iron jaw plates at Mill 161 . 1837 crushing machinery, long 2009	
dewatering wheels at Mill 173 . 1878	Nordberg steeple-compound steam stamps at Mill 180 1901, 1902
dies at Mill 103	rolls at mills 1244, 1685, 1686, 1707, 1710, 1749, 1750, 1751, 1752, 1771, 1773, 1774,
duck for canvas tables at Mill 103 1633	' 1854
elevator belts at mills 1632, 1633, 1661, 1667, 1725	Straper conveyor at Mill 126 . 1709 Sherman Huntington mills at Mill 132 1728
buckets at mills 1632, 1633, 1661, 1667, 1725 parts at Mill 182 1910	Spindle breakers 46, 47
El Oro tube mill liming 1677	stemps at Mill 118 1677 Traylor centrifugal pumps at Mill 114 1662 trommels at Mill 166 1853, 1854, 1855
Frenier special sand pump at Mill 126 Frue vanner belts at Mill 127 1711, 1712	trommels at Mill 166 1853, 1854, 1855 Waddell Chili mills at Mill 174 1886
grizzlies 340	Wetherill magnetic separators 1525
Hancock jig sieves at Mill 127 1710 Huntington mill parts 280	Wilfley tables at Mill 126
screens at mills 1625, 1686, 1711 jaw plates for Blake breakers at Mill 100 1624	Lifting magnets, Eastwood improved
pgs 604	Light for hand picking 481
jig screens 546 sieves at mills 1687, 1707, 1708, 1909, 1910,	Lighting 1100 mills 1931
Koppel shoes and dies at Mill 97 1911 1620	Lightner mill 235
hnoleum top and rittles of Overstrom table at	bibliography for 296 Lignite as fuel for roasting furnace 1549
Mill 127 1711 Midvale steel roll shells at mills 1727, 1866, 1867,	Lime See also Quicklime
1877	crust on plates 767
open hearth crucible steel screens at Mill 178 1896 punched plate trommel screens at mills 1707, 1876,	for acid water 1105 coagulating slimes at Mill 185 1915
retorts 1877, 1902 782	settling
Robins belt conveyors at mills 1661, 1824, 1825,	at Mill 106 1416 1641
Conveying and picking belts at Mill 132 1876	Caldecott on 1416 in Arizona copper mills 1416
roll shells 66 at mills 1688, 1689, 1720, 1724	used in amalgamation
sand wheels 866	investigating classifier currents 434 settling tests 1147
screens 174 shoes and dies 182, 183, 184, 2011	slimes 1149 to remedy acidity in stamp mill 749
at mills 1622, 1632, 1668 for gravity stamps 1277	Limestone, Missouri, Jaw plates used in crushing 48
sieves on Hancock jigs 1441	Limestone to remedy acid water 751 strength of 301, 302
stamp cams 192 guides 156	weight of . 1190
screens 169, 170	crushing 303
stem 187, 188 tappets 189	hand picking tests 1164 screen sizing 1361
trommel screens 352, 362 at mills 1710, 1727, 1728, 1749, 1750, 1751,	settling 455
1752	Limits of drop in stamps 216
tube mill linings at Mill 103 1632 vanner belts 648, 650	sieve scale . 368 to number and height of drop of stamps . 218
wash tromniel 332 wearing parts of Allis-Chalmers rolls at Mill	Limitations of the hydraulic classifiers 1368 Limonite See also Iron
179 1898	concentrated by Bradford jig
ball mills at Mill 159 1828 Blake breakers 27	concentration of 1054 magnetic separation of 809 results of classifying in Mill 5 405
at mills 1621, 1724, 1749, 1853 breakers 1221	results of classifying in Mill 5 405
Bryan mills at Mill 173 1879	separated by magnets 790 specific gravity of 1189
Buchanan jaw breakers at Mill 157 1818 Butler's centrifugal pumps at Mill 117 1671,	washer xxv, 895, 896
1672, 1674	Lincoln mill, dies used in Linder, S. E and H Pictou, action of arsenic sulphide solution on electrodes 1178
centrifugal pump at mills 1632, 1633, 1711.	phide solution on electrodes 1178
1712, 1856, 1899, 1904, 1905 Chili mills 1898	
Cyclone beater at Mill 186 1917, 1918	Lindgren, W., amalgamating pans, Boss system at
dewatering screen at Mill 126 1708 Dodge breakers 31	placer mining 2041
drag or disc conveyors 1583 elevators at mills 1707, 1710, 1711, 1727, 1728	Liners, El Oro tube mill 1286, 1291, 1340
elevators at milk 1707, 1710, 1711, 1727, 1728, 1729, 1749, 1750, 1752, 1753, 1755, 1756, 1818, 1819, 1829, 1853, 1854, 1855, 1877,	Lines of force, magnetic
1880, 1888	Lining, discussion of iron tube mill 2016 for Abbé tube mills at Mill 101 1626
Forster breaker 28 Fraver centrifugal pump at Mill 159 1829	amaigamating pan 244
Gates breaker at mills 1661, 1706, 1716, 1727,	cars
1828, 1853 Griffin mills at Mill 105	gravity stamp mortars
grinding pans at Mill 105 1638	launders

Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol.	IV.
Lining for ore bins	842	Lock.	A. G., amalgamating pans	290
steam stamps	120		amaigamation	787
at Bodie, Calif. W. W. Bradley	2016		Dunk min and Dass	56
steam stamps tube mills. A. F., Drucker at Bodie, Calif. W. W. Bradley Mill 103 Link belt conveyors	1632		Sholl's penumatic stamp	143
Link belt conveyors Company elevator at Mill 125 elevators Linkenlach, C. xx, Blake breakers breakers and hammers bumping tables and elime tables	860		Sholl's penumatic stamp Fisher's stamp mill Fig. 1 was a mill	142
elevators	862		Prisoce Lucop nun	294
Linkenbach, C xx,	332		from sands and from your revi-	1173
Blake breakers	56		gravity stamps	223
bumping tables and slime tables	727		Harz and Bradford jigs	639 297
capacity of trommels	359		Jordan's pulverizer	299
classifier feed	389			837
cobbing	388 480		pointed boxes, spitalulle.	476 56
concave slime tables	692		sweral breakers Thompson's pulverizer G W., gold milling milling in Black Hills, South Dakota	294
density of pulp for slime tables .	695	C.	G W., gold milling	XX
drop between jig sieves . figures on limits of sieve scale	550 369	1	pan amalgamator	1182 789
spiral screen . gravity stamps	363		stamping amalgamating and concentrating	
gravity stamps hammers for breaking hand breaking and picking	223 11	т,	gold	1173
	492	Locke,	rt's automatic gem senarator (classifier)	, 477 430
Heberli mill	202	tu:	ouar cassiier	4/6
jig discharges plungers	583 529	Loevy,	J., definition of slimes	1398
igs for two mineral separation	589	Log wa	hmic plot of sizing tests 1139, shers 55 320	1065
labor for jigs life of jig screens . limit of screening jizs jigged 605, Linkenbach shime table magnetic separators	604		rt mills	1815
life of jig screens	$\frac{547}{369}$		Dibliography for	334
sizes jigged	606	i	crickboom, at Mili 147	1787 328
Linkenbach slime table	728		Thomas 324	, 335
	832		Turbo .	1341
mill schemes number of sieves for jigs	1173 590	W.i	shing plant	333 335
pointed boxes 412, 416, 441.	476		shing plant at Longdale, Virginia .	335
power for crushing ratio of sieve hole to jig feed .	315 573	Lohner	t's ball mill de, Virginia, limonite washer at	293 896
rolls	109	Dgaox	log washers at	335
roll speeds	87	1	mill at	1175
Schmidt spiral screen sieve scale, grizzlies, trommels, and spiral	363	cla	ssifier at Mill 155	1369
screens	384	110	on Co., clarifying reservoir mill	461 1816
sizes treated by slime tables	693		reservoirs for tailing	477
skimming jigs slime tables	576 697	Longfo	washer	322
slope of jig sieves .	548	Longiti	llow concentrator, water required at idinal partition for jigs	1931 524
sime tables	694	Longri	lge, C. C , gold dredging in rivers .	1179
spalling and cobbing hammers . 1	1, 56 594	1	hydraulic mining xx, 1006, probable development of stamps	1173 229
stroke of jigs use of box (lassifiers	433		river dredging	2036
V-box classifier	421	Long to	on	883
velocity of current in classifiers wash trommel	434 334	Lorum	equivalents of S. H., amalgamating pans & Bantield, dry placer machine	1187 788
fixed conical tables slime table	689	Lord 8	k Bantield, dry placer machine	839
slime table	690		dry Senarator	2030
Mill 147	1785 1790	Loring,	recovery of waste in stamp mill nner belt J, amalgam at the Utica mills amalgamated plates	266 647
Linnacite, specific gravity of Linoleum cover for deck of New Standard concen- trator .	1189	w	J, amalgam at the Utica mills .	788
Linoleum cover for deck of New Standard concen-	1479		amalgamated plates	757 224
table decks	1467		gravity stamps life of steel shoes	184
Wiltley table	672		mercury led to stamps	208
Linton's level Lintorf, Prussia, disintegration and screening at	1159		mortar linings	166
iigs at 641.	830 642		stamp mills at the Utica stamp mills, Cali- fornia	1176
limit of sizes jigged at	605	:	stamp mill practice in California	2033
mill at 1177	1179 594	T :	shoes .	181 1098
stroke of jigs at Valurt disintegrator at	289		friction melting	784
Lion mili . ,	234		steam transmission	1091
bibliography for	294 178		weight in retorting	783 1095
Lip apron for stamps	739		wire rope transmission gold	786
Liquition in bullion	785		mercury See Individual Gold mills in Chap- ter XX.	
Lisburne mines, Wales List of minerals floated by flotation processes	329		ter XX.	786
	1555	1	meacury	1663
static separation	1550		in amalgamating pans	250
Liter, equivalents of	1187 1188	T onne-	oil in separation	831 892
Little Giant quartz mill 1281,	1310	LASSES	in concentration lry concentration	825
Lixiviation	1676		ines	1119
Dibliography for	1175 143		magnetic concentration	1054 1945
Location of amalgamated plates	737		milling plate amalgamation	749
bibliography for Loam, M., Husband stamp Location of amalgamated plates machines in mills	1109		slimes	1121
main shaft for stamps	197 1085		stamping pyrite ores	1047 1172
	.000	`	go	

Pages 1-643, Vol. I.	ORE	DR	ESSING.	Pages 644-1197, Vol. II.
Losses of iron and mercury in pan amalga- on amalgamated plates	mation	249 747		M
slime tables		693	Mace mill	1685
vanners	9 167 900	656	Machine breake	ers
Louis, H	2, 167, 200, 15, 747, 750,	753	breaking distributors	
amalgamation		787	oil	
amalgams arrastra	238,	731	shop for mi	111
Blake, Dodge, and Gates breakers	200,	56	Reichenl	aris Exposition, exhibition of 2009 erg Exposition, exhibition of 2010
Chinese stamping machine		224	cost of	1123
connecting table with mortar crushing machines		$\frac{735}{316}$	crushing an	d grinding. Philip Argall . 1278
design of cams		197	t James	d operation of crushing and grinding. Douglas 2017
economy of stamp blow efficiency of stamps		$\frac{220}{219}$	Machines, arran	ngement of . 1107
gold milling	_	XX	design of guarding w	ork of 1096
gravity stamps	223, 224,	226	in series an	d in parallel 1110
grizzlies hammers for breaking		384 11	Macquisten, A	P. S., flotation process ocess W. R. Ingalls 1555, 1563 1569, 2027
Huntington mill		Q 97	at Golcor	nda, Nevada 1555, 1565, 1611
Krom rolls		109	Mill 14	1564
mercury wells nature of amalgam		$\frac{768}{208}$	Coates to	
pointed boxes		476		ion process F C Nicholas 2046 penumatic concentration 838
power for stamps	204,	205	Madison mili	1024
retorting size of stamp feed		$\frac{781}{207}$	of the Ut Madrid New V	ica Company XXVII lexico, electric power 1092
spring and pneumatic stamps		143	Magalia drift m	ill, plates in 789
stamp frames mortars		$\frac{153}{164}$	riffles r	n 770
stems		187	Magic crusher bibliograp	236 phy for 299
tappets		188	Magnesite, speci	the gravity of 1189
stamping, amalgamating, and con for gold	centrating	173	Magnesium, ato	
tables for supporting plates		733	Magnet for testi Magnetic combi	
use of sulphuric acid on plates		752	concentratir	ng mills 1053
water used in stamp mills weight of stamps		$\frac{222}{219}$	concentration at Broker	
Lovett Finney magnetic separators	832, 833,		Cañon	City, Colorado P Barker 2043
Lowe, F. A., amalgamating pans at Batopi	las, Mex-	291		poni, Italy E Ferraris 2046
concentration of silver lead ores	1	922	cost of principles	of magnetic separators 1135
stamp mill at Silver Islet mill, L.	ike Supe-		roasting b	before 1544
Lowe's mill	226, 1	$\frac{179}{233}$	the Hiber field	mia mill, New Jersey 2040
bibliography for		294		hty of substances in 791
Lowry breaker National breaker	58, 59	, 60 45	mill at Lyo	n Mt 2035
Lubrication	1	097	Montepor ore, Port H	ni . , 1068 enry, products of crushing 100
and care of journals	1	930	separation	See also Roasting for Magnetism.
of amalgamating pan		$\frac{247}{194}$	at Broker D-C	Hill, Australia 2034
cam shafts		191		Tark 1568 , Colorado 2044
stamp guides		156 095	mills	1663, 1735, 1741, 1793, 1810
Lucknow, New South Wales, mill at		181	Port H	lle, N. Y. 2040, 2047, cury, N. Y. F. Cirkel . 2034
plates at		788	the Joi	olin Separating Company mill 2038
Lucop & Cook mill Ludlow, E, report used by Choctaw Coal.	and Rail.	294	Kruj	op mining administration 1814
way Company	1	180	bibliograj	lon mill, Australia 2045 ohy for 832
Ludlow Saylor Wire Company, wire cloth s	creens 1	366	H Lunto	12030
Ludwigseck mine, magnetic concentration a Luhrig and Coppée coal washing plant	u 2	837 051	H Smits history of	. Witter 2026 2031
Buss concentrating table	1	492	FTS	Snyder . 1568
pg scraper for removing tailings	538,	640 588	in Cornw.	all E Skewes 1037
scraper for removing tailings picking table C Blomeke		021	Financ Hungar	I G Gröndel 2047 ry, dry and wet C Blömeke 2040
slimer		496	Sweden	2047
table capacity of at Diepenlinchen, Prussia		669 670		. Brunnberg . 2040 te and magnetite Dr. Weiskopf . 2047
type tables at Mill 134	1	734	iron ore	es in Sweden. G W Peterson 2047
vanners at mills Luhrmann, F. W., Pfeiffer's mill Luipaards Vlei Estate, ore reduction plant	. 1	$\frac{717}{295}$	tin oxid	le and wolfram 2027
Luipaards Vlei Estate, ore reduction plant	of 1	645	and and	l copper ores in Cornwall
Edmixt for mills, cost of	1	125	sor	1 . 2028
Luquer, L. M., minerals in rock sections separation of minerals by solutions	. 1	xx 173		on sulphides. G. H. Elmore . 2042 in Wisconsin H. A. Wheeler . 2042
Lurmann, separation processes		836	references	to 2028
Luster affecting separation		889	review of	H. Wedding 2028
of minerals, effect of Luting retorts		3 781	roasting z	int ores for 2030 otation process for zinc ores. CE.
Luttermann, rolls at Clausthal		110	Laught	on 2029
Lye, use of on amalgamating plates in Califused in amalgamation		619 751	with Wetl	herill's 804
Lyon mill, amalgamating pan 24	1, 243, 244, 3	751 246	separators at mills	t London mill, Queensland, Australia 2042 1741, 1763, 1765, 1808, 1810, 1815, 1862,
heat used in amalgamating in		248		1863, 1891, 1916
wings of amalgamating pans in Mountain, Conkling jig at		245 503		oni. E. Ferraris
mill at 901, 1175, 11	185, 2035, 20	039	Ball-Norte	
methods at the		046	or Mon	
		60)	

Manadia assessione Plata	Manager of the transfer of the
Magnetic separators, Blake 833 Bromilow 836 Brokenese 839	Magnetite, separation of in Finland 804 settling velocity of 466, 469
Duchanan	specific gravity of 1189 Magnetomotive force 792
C. Blömeke	Magnetomotive force 792
classification of 796, 1521	Magnets See also Electromagnets. Bilharz cobbing magnet 1532
Cieveiand-Knowles magnetic separator 1542	Broughton Asbestos Company magnet 1532
at Mill 148	cobbing 1439, 1531 Eastwood improved litting magnet 1532
comparison of W. A. Anthony 2026	heating of 795
Conkling . 809, 810 construction of 2030	leakage of . 793
construction of 2030 Cranberry magnet . 1530	Manhattan Asbestos Company magnet 1531 of Wetherill separator, proper distance apart for 1524
Dellvik Grondal • 804	relative attraction of various substances 796
description of different types of. C Bugge 2030 Dr. Weiskopf 2030	when applicable 790 Mahanoy City, shaking screens for coal 342
H. C. McNeill 2026	Maiern, Austria, hand picking at 487, 493
M Lenicque 2026	magnetic separator at 798, 836
O Simmerback 2030 S. W Osgood 2027	mill at 1185 roasting for magnetism at 815
Dings	Moder Win In description to the Market 1996
Edison 810, 812	stamps 229
Eriksson's electromagnetic separator 1529 F Schiff 2028	shaft for gravity stamps 197 location of 197
Ferraris 799, 1525	Maintaining height of drop in gravity stamps 200
drum-type 1528 for black sands. C.C. Longridge 2028	plates of the right consistency 756 Malachite, specific grayity of 1189
Forsgren's electromagnetic separator 1538	Malay Peninsula, tin dressing in 1084, 1182
full description of different types of 2028	Malleable iron elevator buckets at Mill 136 1737, 1738
Grondal Nos. 2, 3, 4, and 5 1537 Heberh . 799	Mallet for settling concentrates 1113 Mammoth, Arizona, screening tests on gold ore at 284
wet 810	shoes and dies at 183
Hoffman 832, 835	mill, screens in 175
Hughes Daviot 812 Humboklt 1530	Mining Co., mill xxviii, 1045 Utah, mili at 1045
in a lead zinc plant 2047	Management . 1947
Cornwall . 2028	effect on costs . 1128
International . 1533 Kessler 811	Manganese, amalgam 730 atomic weight of 1188
Knowles' New Century 1541, 1568	ore the dressing of E. K. Iudd 2027
Leighton 1528	specific gravity of
Lovett Finney 832, 833, 835 Mechernich 1535	specific gravity of 1189 steel. See Wearing Parts. ball mill hinings at Mill 159 1828
Payne 799	for breakers 1213
primary magnet type 1521	drag conveyor flights 1583
principles of 1521 Rowand 807	roll shells 68 toothed rolls 1244
secondary or induction magnet type 1521	wearing parts of rolls 1243
Siemens 803, 834	Gates' gunlock mantles for gyratory breakers 1220
& Halske . 798 suited for testing 1993	jaw plates at mills 1749, 1848, 1888, 1889 self-tightening mantles for McCully gyratory
theory and conditions of E Langguth 2031	breakers 1213
Trustedt 835 Ullrich 1535	trommel screen at Mill 117 1667 Mill 174 1882
used at Przibram 812	wearing parts of Blake breakers at Mill 98 1621
Monteponi . 810	Buchanan breakers at Mill 183 1913
using drums . 797 Vial . 835	Gates breakers at Mill 114 1661 Manganite, specific gravity of 1189
Waring at Mill 148 1792	Manhattan Asbestos Gompany, magnet 1531
Wenström 800	mill, Krom jigs at 838
• Wet 804, 810 Wetherill 804, 1521	Mannheim, Brink & Hubner disintegrator at 286 Mantey offset for Chili mills . 1305
with conveying belts 804	Mantles for McCully gyratory breakers, self-tighten
no moving parts O A P Srufeldt 2026 ore falling in front of magnets 812	ing, manganese steel 1213
ore falling in front of magnets 812 treatment of a high phosphorus iron ore 2047	breakers 1220
blende and barite. C Blomeke 2025	
iron ore in Sweden G W Peterson 2038 by the Grondal process P McBenne 2025	specific gravity of 1189 Mardin, E. M., amalgam 789
Magnetism 891, 1053, 1611	Marsaut, I. B., jigging plants 641
calcining for 1544	separation by jigs 043
change of by heat 4 effect of 4	Marsden breaker 56, 58, 59, 60 Marsdall Basin, Colorado, Browne hydrometric sizer at 410
carbon in roasting for 1544	vanners at 658
on free settling 465	Creek . 1015
roasting for 813, 890, 1544 a blende-marcasite concentrate for. H O.	Martin Iron Works breaker 2009 Martin's buddle . 1090
Hofman 2027	Maryland, mills in 1175
F. H. Trego 1568, 2027 N. S. Keith 2027	Mining Company mill xxvii, 1019 Marysville, Montana, Blanton cams at 194
N. S. Keth W. B. Phillips 2027	mill at 1027, 1040, 1181
uni of 791	Massachusetts Institute of Technology, testing ma-
use made of, in mills 890 Magnetite, concentrated on Conkling by 503	chines at tests on distribution of amalgam 764
deposits of New York 1923	effect of temperature on amalgamation 767
for jig bed 574	Materials for amalgamating plates 747, 1514
hindered settling test on 617, 618 mill for 1055, 1058, 1059	drag or disc convevor flights
ores, mills for	grizdy bars 339
separated by magnets 790	Harz jig bedding at Mill 183 1913
61	<u>l</u>

ages 1-643, Vol. I.	ORE	DRI	ESSING.	Pages 644-1197, Vol. 1
aterials for Huntington mill parts	;	280 522	S G gold	Calumet and Hecla mill scheme 1 ores at Ouro Preto mine, Brazil 1
jig tanks		522 574	McCully breake	r
mortar linings		166	compared	with Gates
riffle cleats .	1	467	gyratory br	l with Gates es
roll shells	66,	68		
at mills 1716	, 1720, 19	913	life of	wearing parts at Mill 139 1
round table decks at Mill 162	. 18	840	M-D	nese steel self tightening mantle for . 12
screens :		354	McDermott, W.	1
and cost		173 350	amaigam	ated plates W. Duffield, amalgamated shaking
in trommels shafts		351	and r.	w Dumeid, amaigamated snaking
stamp batteries		277		
lasses	1.	186	Calty m	amalgamation xx, 1 ll, Michigan 20
guides	. 155,	156	caracity	ll, Michigan 20 of Calumet classifier
parts	. 100,	225	concentr:	ation and amalgamation of silver 1
at Mill 143 .	1	769	Eureka I	Ill mill
tappets		188	hand con	Idl mill 20 centration test 2 zation of screens 20 ng in Bolivia 20
surface of Rittinger table	1	668	standardi	zation of screens 20
of stime tables	. 688, 9	695		
tube mill linings	. 1	287	McDonald, B,	Browne hydrometric sizer
wearing parts of Blake breakers			double di	scharge
at Mill 100		853	gold stan	p mill at Gibbonsville, Idaho 1
breakers	48, 1	220	mining re	eport
centrifugal pumps at Mill 103	1632, 1 1917, 1	633	SUPPLIS	
Cyclone beaters at Mill 186	1917, 1	918	size of st	amp feed
Dodge breakers at Mill 183		31 913	stamps a	t Gibbonsville, Idaho
at Mill 183 elevators at mills 1822, 1824, 1825, 185			weights (of ore
fans at Mill 186	1917, 1	918	McDougell to	re and after crushing 1
Gates breakers at Mill 166	1011, 1	853	McDowell E 1	roasting furnace . 13
Hodge and Cleaves sand pumps a			mine	
182	1910, 1	911	Conkling	separator at the Tilly Foster mine
Huntington mills at Mill 161	1	839	Tilly Fos	separator at the Tilly Foster mine ter magnetic plant 1
McCully breakers at Mill 139	1	749	McFarlane & C	o, design of cams
Nordberg steeple-compound steam :	stamps -		Manufactur	ring Company, parallel rolls 13
McCully breakers at Mill 139 Nordberg steeple-compound steam : at Mill 180	1901, 19	902	mortar bolt	\$
rolls .	13	213	parallel roll	s, description of . 12
at Mills 1737, 1738, 1742, 1743,			rolls	72,
. ACH 480	13	854	at Mill 1	42
screens at Mill 158 spindle breakers		824	stamp fram	ics
spinne breakers	40,	. 47 121	McKenna Brase	Company, laboratory ore grinder 1279, 1285, 13
team statis		851	Mataboratory	ore grinder 1279, 1285, 13
steam stamps trommels at Mill 165 Waddell Chili mills at Mill 174		886	phate washing	1 Stone Company, iron ore and phos
of belts for gravity stamps		197	log washer	1
bottom bed on jigs		573	single roll	crusher at Alleghany Ore and Iron
bucket elevators .		863	Company	. 1
cam shaft .		191	company	International Phosphate Company . 13
dies		180	de	International Phosphate Company . 1: scription of
jig screens		545	ta	ble of sizes, power and weights 1:
mortar blocks		145	iig	518, 538, 6
screens	169,	170	McLeod concen	trator 1-
shoes and dies	182, 183,	184	table, tests	at Mill 162 14 magnetic separators and plants in
stamp cams		192	McNeill, H C,	magnetic separators and plants in
screens .		173	Sweden	
stem		187	Means of getting	g a whole current in setding tanks
tappels		189	Measure, miner	inch . 1
athet, De Gournay and Suisse, Lochstrate	appa-	837	Measurement of	mineral particles 19
other roasting furnaces at Mill 148		792	ore grain	1
other A on drop of stamps	1,	220	Screen op	enings four spigot hydraulic classifier with
athines Creek, Huntington mill at curice, P. E., jigs motion of solid particles in a liquid		281	Sorting of	olumn of 3-inch pipe
turice, P. E., ngs		642	tables of	11
motion of solid particles in a liquid		477	Measuring	ii
centringar coar wasner, results from	20	050	Mechanical bate	na., (
aximum profit in concentration	1	118	cobbing des	rices 1
size of feed to folls .		63	efficiency of	sand wheels . 15
ore treated by Wetherill magnetic separ	ator 18	525	ore handlin	ices : 1- sand wheels : 18 g Blaisdell system : 16
Exwell's law of magnetic field by Brothers' jigs at mills 1714, W. J., close sizing before jigging		791	samplers	15
ty Brothers' jigs at mills 1714,	, 1717, 17	720	Brunton	18
w J., close sizing before jigging		022	oscillat	ing . 15
concentrating from ores		179 780	Lamb au	tomatic tailings sampler 18
nyflower drift mill, mercury wells in riffles at	:	789 770	Snyder	
mill, amalgamated plates in	740,	752	Vezin sampling	
pan concentrator at	170,	68 3	sampling Brunton	sampler
shaking screen in	. !	342	cleaning	
unwatering box in		450	Collom s	
unwatering box in aynard, G. W. and W. B. Kunhardt, dress	ing of		comparis	on of machines
iron ores	. 1	185	difficultie	s attending
		643		
jigging tests		643	moisture	samples
jigging tests av's jig				
av's jig	r 13	373.	principles	iof
av's jig cCabe & Company, New Standard classifier	r 13 1	373, 419	principles requisites	s of
av's jig cCabe & Company, New Standard classifier cCallum, A. C., design of mining machinery	r 13 1 7 2	373, 419 048	principles requisites size of sa	s of
av's jig cCabe & Company, New Standard classifier cCallum, A. C., design of mining machinery rolls, crushers and mortars	r 13 1 y 2 . 1	373, 419 048 178	size of sa winnowir	mples
av's jig cCabe & Company, New Standard classifier cCallum, A. C., design of mining machinery	r 13 1 y 2 1	373, 419 048 178 096	size of sa winnowir shovel for r	s of to accuracy in 11 Imples 1575, 11 g effect of air currents 11 emoval of jig tailings 11 r amalgam 11

Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vol. IV.
Mechanical trippers for discharging conveyor belts	1586	Merrall mill	phy for
unwatering Mechanism, accelerated, in jigs	533	Merrill, C. W.	Physica
crank arm for Bartlett table bumping tables Cammett table	. 535 . 678		
bumping tables	680	Mar	of Montana Mining Company, ysville, Montana 1181
jigs 510, 511, 517, 5	677 519 534	effect of	temperature on amalgamation
jigs	555, 657	treatmen	t at the Homestake mills 2044
sliding block	672 533	cone classif cones at M	1015 11 14111 104
sliding block Mechernich, classifier at	477	cylindrical	clarifying tanks
Heberwasche at	178, 520 ● 642	at M definition o	f slimes 1642
magnetic separator	1535	Differ press	at mills 1635, 1642
at Mill 135 15; mill at	36, 1736 1176	arge cone o	classifiers 1406 full 106 1640
process in the Harz	2030	slime cones	tinishing cones, and water cylinders, 1367
separator, results from the sieve scale at	2031	sman cone	classitiers 1371 fill 106 1641
stroke of jigs at Megraw, H. A., slimes Meer, E. D., Osterspey jig J. W., automatic feeders at Przibram	594 1419	Merril's mill	1310
Meier, E. D., Osterspey jig	642	ores, concer	s, washing plant for
J W., automatic feeders at Przibram	. 884 293	Meshes in scree	ns, values of 1196
Dingey mill Heberli mill	292	Metal riffles, ex	rco, mills at
Lubrig table	$\frac{670}{1180}$	Metallic Extract	tion Company, capacity of rolls 103
ore dressing at Przibram revolving picking table and picking belt Rittinger and Salzburg tables and buddles Przibram, Stein belt concentrator	492	Metallurgical te	11 TOUT-TUDE OFFEE AT
Rittinger and Salzburg tables and buddles	at 729	treatment, 1	problems involved in 1943
Schradz min .	290	Metals, specific	ned v gravities of
wash trommel Meihe's pulverizer	. 335 236	Meter, equivale Methods of cru-	ats of 1187
Meihe's pulverizer . bibliography of .	299	dressing a	and cleaning plates . 757
Meinecke classifier 430, 4	77, 478 461	feeding g jigs	ravity stamps 207 548
pointed box at Clausthal	477	prelimina	rv crushing . 9
spitalutte stamps at Clausthal	25, 477 225	running f iigs	rve-foot pans in combination mills 249 551
spitalute stamps at Clausthal Melones Mining Co. mill, Melones, California V W. Bradley Moltin Loudin	V	studving	mills 1613
W. Bradley Melting bullion	2044 784	testing working	amalgamating pan 1137 248
Melting bullion Men. See also Labor. Mercadel, magnetic separation at		Metric system o	f weights and measures 1187
Merced amalgamated plates at	835 767	ton.	ng and milling plant, a primitive F.
Merced amalgamated plates at Mercury, absorption of by amalgamating plates	1514	H Probert	2038
action of amount required to amalgamate copper plate	$\begin{array}{c} 4 \\ 753 \end{array}$	cost of prod	gold milling in. H T. Collins 2033 lucing gold in 1980, 1981
antidote for atomic weight of	730	mill in	1180
bibliography for	1188 787 785	munng at e	El Oro. E. Burt . 2046 . 2046
care and purification of effect of heat on cohesion	785 767	ore dressing	g at Santa Fe H. T. Collins 2040
fed to gravity stamps	208	silver mill i Meyer & Charlt	on, gold extraction at . 1647
mortars at mills 162 for stamps	20, 1640 206	Gold M	dining Company Ltd., mill of 1646 tails of stamps 221
gold in, after retorting	783	M Hoagland So	ons and Company 77
after straining in amalgamating pan	781 249	Miargyrite, spec	afic gravity of 1189 general article on G. W. Colles 2027
_riffle boxes	724	grinding of	scrap
riffles loss of. See Individual Gold Mills in Chapter	770 XX	milling of. Micas for washi	F. Cirkel
loss of	. 786	Michell & Tree	oning pulverizer . 233
lost in pan amalgamation ore, separated by oil	249 831	Michigamme ire	raphy of 294 on mine
mill for	1074		ne separation at
properties of . retained in retort residue .	730 786	mill at Michigan, cost o	of milling in 1175
sickening and flouring	751	mill, a rece	ntly completed . 2039
sink for clean-up specific gravity of	266 1189	mills in	per ore in. C. F. Jackson 2047
sprinkler for	760	Micrometer cali	per, Snyder . 1181, 1182 1362, 1366
Black Hill trap	71, 1516 773 . 773	gauge for measi	1159 uring grains 1138
box traps	. 773 774	microscope Microscope	1363, 1996
cleaning up Grass Valley trap lined with plate	774	microracter	for measuring grains . 470, 1146
lined with plate plain transverse troughs or riffles .	. 741 772		
position of	737	Middlings, crush	hing of
position of transverse with gates use and care of used on dredges english of column	772-773 2024	defined	318
used on dredges	1012		
weight of column wells	1188	on machine	s 1112 892
wells versus plates	768 771	Size of fect	usinik ,
versus plates Meronitz, Bohemia, weathering garnet rock at Merrall, individual mortar	31, 839 -1284	treatment of	of 1121 eaker, West Virginia. F. W. Parsons 2051
Merrall, individual mortar Mill Company, Merrall's stamp mill	1278	Midvale Co., st	eel for shoes and dies 185
	6:	3	

Midva	tle steel ring dies at mills, life of 1728, 1778
	lle steel ring dies at mills, life of 1728, 177. roll shell at mills 1701, 1727, 1750, 1751, 1752, 1771, 1772, 1773, 1774, 1803, 1837, 1838, 1854 trunnion tires at Mill 144, life of 1771, 1772, 1773, 1774, 1806, 1807, 1877
Milla.	ra's crushing rolls
Miles,	William A, wash trommel 335
	of time, use of at Crown Reef Gold Mining ipany's mill . 1416
Mill 1 2	339, 486, 498, 499, 892, 893, 1113, 1116, 1119 10, 319, 339, 486, 498, 499, 522, 892, 893, 1100,
3	1101, 1112, 1116, 1119 24, 64, 66, 87, 498, 499, 892, 902, 1091, 1100, 1101,
4 5	(William 4, wash trommel of hime, use of at Crown Reef Gold Mining Jany's mill 334, 486, 498, 499, 892, 893, 1113, 1116, 1119 (119, 319, 339, 486, 498, 499, 892, 893, 1113, 1116, 1119 (129, 319, 339, 486, 498, 499, 592, 892, 893, 1100, 1116, 1119, 1129 (116, 321, 362, 364, 364, 364, 364, 364, 364, 364, 364
6 7	873, 879, 895, 896, 1098, 1114, 1116 341, 870, 895, 897
8 9	327, 334, 341, 872, 895, 897, 1116 895, 899 61116
9	524, 528, 533, 548, 550, 552, 571, 574, 575, 587, 590, 592, 593, 606, 609, 900, 902, 1116, 1126
10	24, 26, 64, 66, 72, 76, 90, 91, 101, 347, 350, 352, 358, 350, 361, 366, 591, 598, 597, 540, 545, 547, 548, 547, 548, 548, 548, 548, 548, 548, 548, 548
	550, 552, 571, 575, 587, 590, 592, 593, 596, 599,
	001, 003-606, 609, 863, 900-902, 908, 917, 1091, 1100, 1105, 1112, 1113, 1116, 1126, 1129
11 12	362, 366, 706, 707, 900, 902, 1116
12	491, 506, 524, 528, 540, 550 552, 577, 604, 865,
13	900, 903, 1091, 1100, 1103, 1105, 1111, 1116
	488, 491, 498, 499, 515, 523, 524, 528, 529, 540,
	605, 875, 900, 904, 1091, 1099, 1100, 1114, 1116, 1119
14	10, 339, 480, 485, 488, 491, 524, 530, 536, 540, 548, 550, 552, 572, 574, 592, 593, 596, 605, 900, 905
15	24, 26, 64, 66, 76, 87, 90, 91, 101, 347, 350, 359
	358, 359, 366, 399, 412 114, 485, 522-524, 528, 530, 533, 537, 538, 540, 550, 553, 573, 586, 590,
	592, 593, 604, 605, 684, 689, 696, 863, 874, 875,
16	24, 26, 64, 66, 69, 73, 76, 87, 90, 91, 97, 101, 347,
	350, 352, 354, 358, 366, 524, 528, 534, 540, 545, 546, 549, 550, 552, 570-572, 579, 592, 593, 604
17	605, 863, 893, 906, 908, 1091, 1105, 1111, 1116
	350, 352, 354, 358, 366, 400, 480, 486, 524, 528, 534, 540, 547, 550, 552, 554, 500, 500, 500, 500, 500, 500, 500
18	599, 605, 863, 893, 906, 908, 1091, 1105, 1111, 1116
10	369, 373, 410, 444, 522 525, 528, 530, 533, 537,
	538, 540, 550, 552, 590, 592, 593, 604, 648, 863, 906, 909, 911, 1090, 1091, 1100, 1112, 1114, 1116
19	24 64 66 76 347 350 352 358 427 444 456
	300, 303, 311, 1030, 1031, 1100, 1112, 1114, 1116, 1120, 24, 64, 66, 76, 347, 350, 352, 358, 427, 444, 456, 486, 489, 491, 524, 552, 550, 648, 906, 910, 1116, 1121, 24, 26, 64, 66, 69, 70, 79, 76, 83, 90, 91, 91, 91
20	24, 26, 64, 66, 69, 70, 72, 76, 83, 90, 91, 91, 91, 91, 91, 91, 92, 93, 93, 93, 93, 93, 93, 93, 93, 93, 93
	524, 528, 537, 540, 541, 550, 551, 554, 572, 574-
	872, 873, 875, 906, 913, 1091, 1100, 1103-1105,
21	24, 26, 64, 66, 72, 76, 87, 90, 97, 101, 280, 281
	347, 350, 352, 358, 359, 361, 366, 369, 413, 451, 525, 528, 527, 528, 541, 546, 547, 559, 557, 578, 578, 578, 578, 578, 578, 578
	577, 592, 593, 596, 601, 603, 605, 684, 691, 696,
	697, 863, 875, 906, 915, 1089, 1100, 1105, 1112, 1116, 1122
2 2	30, 31 34, 64, 66, 69, 72, 76, 87, 90, 91, 95, 97, 101 320 338 339 347 350 359 356 359 359
	361, 366, 381, 383, 399, 442, 456, 462, 523-525,
	528, 533, 534, 537, 538, 541, 550, 554, 572, 573, 579, 584, 587, 592, 593, 599, 604, 605, 684, 688
	30, 31 34, 64, 66, 69, 72, 76, 87, 90, 91, 95, 97, 101, 320, 338, 339, 347, 359-352, 356, 358, 359, 361, 366, 381, 383, 399, 442, 456, 462, 523-525, 528, 533, 534, 537, 538, 541, 550, 554, 572, 573, 579, 984, 587, 592, 593, 599, 604, 605, 684, 688, 636, 687, 856, 857, 870, 872, 874, 875, 916, 917, 1100, 1102, 1103, 1105, 1112, 1116, 1122, 1129, 1140, 1141
23	24 64 66 71 76 87 90 91 347 349 350 353
	1100, 1102, 1103, 1105, 1112, 1116, 1122, 1129, 129, 24, 64, 66, 71, 76, 87, 90, 91, 347, 349, 350, 352, 358, 359, 360, 442, 525, 528, 541, 554, 571, 592, 605, 684, 882, 916, 917, 920, 1116, 1122, 350, 352, 353, 353, 359, 361, 366, 414, 444, 446, 456, 517, 525, 528, 529, 536, 537, 538, 531, 546, 547, 549, 550, 554, 577, 579, 584, 589, 592, 593, 604, 605, 648, 663, 664, 684, 662, 863, 870, 916, 917, 921, 1091, 1092, 1104, 1101, 1105, 1106, 1112, 1129
24	24, 26, 50, 51, 64, 66, 69, 72, 76, 90, 91, 101, 347,
	350, 352, 355, 358, 359, 361, 366, 414, 444, 446, 456, 517, 525, 528, 529, 535, 537, 538, 541, 548,
	547, 549, 550, 554, 577, 579, 584, 589, 592, 593,
	917, 921, 1091, 1092, 1100, 1101, 1105, 1106, 1112.
	1114, 1116, 1122, 1129

Mill 25. .11, 24, 26, 47, 64, 66, 69, 70, 72, 73, 76, 87, 90, 91, 97, 98, 101, 321, 347, 350, 352, 358, 359, 366, 442, 444, 451, 456, 460, 517, 525, 528, 529, 537, 539, 541, 546, 647, 549, 556, 556, 571, 577, 587, 592, 593, 594, 599, 605, 607, 608, 682, 857, 863, 869, 870, 872, 874, 875, 916, 924, 1086, 1088, 1091, 1096, 1100, 1103, 1105, 1106, 1108, 1112, 1114, 1130, 1106, 1108, 1112, 1114, 1130, 1106, 1108, 1112, 1114, 1130, 1106, 1108, 1112, 1134, 1106, 1108, 1112, 1134, 1106, 1108, 1112, 1134, 1106, 1108, 1116, 1119, 1130, 1106, 1107, 1107, 1107, 1107, 1107, 1107, 1107, 1107, 1107, 1108, 1109, 1116, 1109, 1108, 1109, 1116, 1109, 1116, 1 24, 26, 64, 67, 69, 76, 91, 280, 281, 347, 351, 353, 358, 359, 366, 396, 403, 404, 415, 416, 444, 526, 527, 535, 537, 542, 545, 550, 562, 572, 575, 582, 592, 593, 602, 605, 607, 603, 648, 661, 662, 857, 863, 875, 973, 976, 1091, 1103-1105, 1112,

- - 53 30, 31, 167, 170, 199, 202, 205, 207, 205, 212, 219, 648, 655, 659, 663, 631, 1014, 1089, 1091, 1100, 1103, 1105, 1116, 54, 27, 46, 170, 199, 205, 207, 208, 212, 219, 339, 482, 648, 663, 1014, 1015, 1116, 1116, 1134, 155, 24, 145, 148, 156, 158, 164, 167, 170, 177, 178, 180, 182, 186, 187, 189, 192, 196-199, 201, 202, 205, 207, 209, 211, 212, 219, 222, 304, 482, 485, 491, 648, 665, 701, 708, 1014, 1016, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1004, 1018, 1030, 1091, 1018

- Mill 60. 38, 46, 145, 156, 167, 169, 180, 182, 189, 199, 201, 205, 207, 208, 212, 214, 219, 222, 648, 650, 661, 737, 740, 742, 744, 748, 1018, 1021, 1089
 - 661, 737, 740, 742, 744, 748, 1018, 1021, 1089, 661, 737, 740, 742, 744, 748, 1018, 1021, 1089, 179, 180, 182, 185-187, 189-192, 196-199, 201, 202, 205, 207-209, 212-214, 219, 222, 266, 338-340, 648, 659, 661, 603, 664, 737, 740, 746, 748, 756, 765, 768, 783, 785, 848, 858, 860, 861, 875, 1018, 1021, 1030, 1089, 1090, 1100, 1103, 1104, 1102, 1103, 1089, 1090, 1100, 1103, 1104, 182, 185-187, 189-192, 197-199, 201, 202, 206, 207-209, 212, 214, 219, 222, 265, 339, 340, 648, 659, 661, 703, 733, 737, 741, 742, 748, 750, 756, 756, 768, 772, 783, 1018, 1022, 1089, 1100, 103, 1105, 1116, 1132, 185-187, 189, 192, 193, 191, 199, 201, 205, 207, 208, 212, 214, 219, 648, 737, 756, 776, 765, 708, 772, 783, 1018, 1022, 1089, 1106, 1104, 1107, 1108, 1105, 1116, 116, 116, 116, 117, 116, 177-180, 182, 185-192, 196-199, 201, 202, 205, 209, 212, 214, 219, 222, 339, 340, 648, 659, 663, 733, 737, 740, 742, 745, 756, 768, 772, 773, 864, 1018, 1023, 1089, 1100, 1103, 1104, 1116, 1132, 187, 189, 191, 196-199, 201, 202, 207, 209, 212, 214, 219, 222, 339, 340, 648, 659, 661, 733, 735, 737, 738, 842, 491, 647, 738, 1048, 1049, 1024, 1039, 1089, 1100, 103, 1104, 1116, 1132, 164, 164, 76, 76, 76, 76, 76, 782, 783, 848, 491, 647, 744, 746, 747, 748, 756, 752, 773, 783, 1018, 1024, 1039, 1089, 1006, 1103, 1104, 1116, 1132, 1044, 1039, 1089, 1006, 104, 1106, 1132, 1044, 116, 1132, 1039, 1089, 1006, 104, 1161, 1132, 1039, 1089, 1006, 104, 1161, 1132, 1044, 116, 1132, 1039, 1089, 1006, 104, 1161, 1132, 1044, 1161, 1

 - 168, 168, 166, 167, 169, 177, 180-182, 186, 187, 188-192, 197-200, 202, 205, 207, 212, 214, 219, 222, 252, 682, 735, 738, 741, 744, 745, 747, 753, 750, 760, 768, 773, 775, 781, 785, 1018, 1025, 1088, 1091, 1098, 1100, 1102, 1105, 1116, 1132, 1133
 - 1088, 1091, 1090, 1109, 1109, 1109, 120, 121, 122, 123, 124, 135, 156, 158, 166, 167, 169, 174, 175, 177-182, 184-187, 189-192, 194-199, 201, 202, 204, 205, 207-210, 212, 214, 219, 222, 482, 733, 735, 738, 740-742, 744, 746, 747, 752, 756, 759, 765, 768, 771, 773-775, 783, 785, 872, 1018, 1026, 1030, 1091, 1100, 1103, 1105, 1106, 1116
 - 68 24, 27, 145, 156, 158, 164, 166, 167, 170, 174, 177, 178, 180, 182, 185, 187, 189-192, 196-199, 202, 205-209, 212, 214, 219, 222, 252, 303, 339, 340, 482, 648, 659, 661, 664, 733, 735, 738, 741, 744-746, 748, 755, 756, 788, 785, 1018, 1027, 1028, 1040, 1091, 1100, 1103, 1104, 1111, 1114, 1113, 1134, 11
- 70 167, 169, 178, 179, 182, 199, 202, 209, 201, 205, 219, 586, 682, 738, 742, 744, 773, 1018, 1029, 1047, 71, 145, 156, 167, 170, 174, 177, 178, 182, 187, 189, 191, 196-199, 201, 205, 207-209, 212, 214, 219, 222, 205, 418, 648, 660-602, 665, 667, 738, 740, 743, 745, 748, 772, 773, 780, 1029-1031, 1037, 1089, 1092, 1116, 174, 178, 179, 182, 187, 189, 191, 192, 196-199, 201, 202, 205-209, 212, 214, 219, 222, 265, 320, 332, 448, 456, 648, 661, 676, 683, 738, 741, 743, 744, 747, 756, 772, 773, 777, 783, 856, 1030, 1032, 1037, 1038, 1088, 616, 676, 683, 738, 741, 743, 744, 747, 756, 772, 773, 777, 783, 856, 1030, 1032, 1037, 1038, 1089, 1002, 212, 214, 219, 222, 238, 255, 338, 330, 456, 482, 485, 491, 647, 648, 659, 733, 735, 738, 740, 741, 743, 744, 746, 748, 750, 754, 756, 778, 768, 768, 769, 738, 769, 202, 202, 212, 214, 219, 222, 238, 265, 338, 330, 456, 482, 485, 491, 647, 648, 659, 733, 735, 738, 740, 741, 743, 744, 746, 748, 750, 754, 756, 758, 756, 772, 209, 212, 214, 219, 222, 238, 265, 368, 369, 369, 207, 209, 207, 202, 202, 201, 201, 201, 201, 1010, 1101, 1103, 1116, 1132, 1168, 156, 158, 166, 167, 169, 174, 177, 182, 185, 187, 189-191, 190-199, 201, 202, 205, 207-209, 212, 214, 219, 222, 238, 265, 338, 339, 482, 485, 491, 647, 648, 650, 662, 659, 661, 733, 735, 738, 744, 746, 748, 750, 754, 756, 783, 1024, 1030, 1034, 1031, 117, 1132, 1168, 156, 158, 166, 167, 169, 174, 177, 182, 185, 187, 189-191, 190-199, 201, 202, 205, 207, 209, 212, 214, 219, 222, 238, 265, 338, 339, 442, 485, 491, 647, 648, 650, 662, 659, 661, 733, 735, 738, 744, 746, 748, 750, 754, 756, 783, 1024, 1030, 1034, 1038, 1089, 1092, 1100, 1101, 212, 214, 219, 222, 339, 648, 659, 663, 664, 700, 701, 703, 738, 744, 756, 772, 870, 1030, 1034, 1089, 1090, 1103, 1105, 1117

Mill 76.	. 145, 156, 158, 166, 167, 169, 177, 179, 180, 18 186, 187, 189, 190-192, 196, 198, 199, 201, 20 205, 207-209, 212, 214, 219, 268, 648, 664, 76	82, Mill 100
77	.145, 156, 158, 166, 167, 169, 177, 179, 180, 18 .186, 187, 189, 190-192, 196, 198, 199, 201, 22 .205, 207-209, 212, 214, 219, 265, 48, 664, 77 .738, 740, 743, 750, 765, 772, 879, 1030, 103 .10, 145, 148, 156, 158, 164, 166, 167, 169, 17 .177-182, 185-187, 189-192, 195-199, 201, 20 .204-209, 211, 212, 214, 219, 220, 222, 342, 48 .680-682, 703, 739, 741, 747, 753, 756, 757, 76 .763, 765, 766, 768, 774, 842, 1030, 1035, 104 .1047, 1089, 1091, 1100, 1105, 1117, 11 .1148, 444, 446, 648, 653, 655, 658, 660, 661, 66 .667, 701, 702, 703, 857, 874, 1017, 1029-103 .1035, 1037, 1038, 1089, 1090, 1100, 1101, 111 .11	32, Mill 100 1275, 1570, 1614, 1623, 192, 101 1489, 1623, 1626, 193, 102 1623, 1629, 193, 102 1623, 1629, 193, 194, 194, 194, 194, 194, 194, 194, 194
11.	177-182, 185-187, 189-192, 195-199, 201, 20 204-209, 211, 212, 214, 219, 220, 222, 342, 48 680-682, 703, 739, 741, 747, 753, 756, 757, 76	75, 1006, 1008, 1009, 19 122, 106
78	763, 765, 766, 768, 774, 842, 1030, 1035, 104 1047, 1089, 1091, 1100, 1105, 1117, 11 418, 444, 446, 648, 653, 655, 658, 660, 661, 66	16, 109
.0	667, 700, 702, 703, 857, 874, 1017, 1029–103 1035, 1037, 1038, 1089, 1090, 1100, 1101, 111	81, 112
79 80	456, 648, 655, 658, 700, 701, 703, 723, 875, 103 1032, 1033, 1037, 1038, 1100, 11 456, 700-703, 875, 1029, 1030, 1032, 1038, 103	100, 115
81 82	1100, 1101, 110 . 238, 1030, 1038, 1039, 1089, 1100, 11 24, 27, 145, 156, 158, 164, 166, 167, 170, 173, 17	17 118 1286, 1291, 1294, 1076, 19 17 119 1286, 1291, 1294, 1076, 19 18 190 1261, 1459, 1614, 1690, 19
02	180, 182, 185–187, 189, 192, 196–199, 201, 120, 120, 205, 209, 212, 214, 219, 222, 244, 248–250, 25, 230, 456, 458, 480, 486, 401, 648, 650, 661, 66	36, 120
	1035, 1037, 1038, 1089, 1099, 1100, 1101, 111, 111, 1456, 648, 655, 658, 700, 701, 703, 723, 875, 100, 1103, 1103, 1103, 1103, 1100, 1101, 110, 110	76, 126
83	46, 47, 145, 156, 167, 170, 174, 178, 183, 185-18	34 127 1361, 1458, 1487, 1706, 1709, 1932, 19 17, 128 1713, 1715, 10 19 129 1561, 1713, 1715, 10
	211, 219, 244, 246, 248, 249, 252, 456, 458, 46 482, 648, 663, 777, 778, 780, 783, 1039-104	130
84	24, 27, 42, 46, 145, 156, 158, 166, 167, 170, 17	17 133 1713, 1731, 1935, 19 14, 134 1713, 1731, 1935, 19 1536 1713 1732, 19
	199, 201, 202, 205-209, 212, 214, 219, 222, 24 246, 248, 249, 252, 339, 347, 351, 353, 354, 35 359, 366, 456, 458, 460, 648, 663, 739, 742, 74	44, 136
	748, 756, 768, 772, 777, 780, 783, 785, 860, 86 875, 1039, 1040, 1045, 1085, 1089, 1091, 109 1100, 1101, 1103, 1106, 1109, 1110, 1117, 111	105, 105, 113, 1142, 19 11, 1391244, 1365, 1535, 1748, 1932, 19 15, 1401546, 1548, 1551, 1748, 1758, 19 341411345 1361 1595 1501 1748 1750 10
85	24, 65, 67, 76, 167, 169, 178, 179, 199, 202, 20 207, 208, 219, 220, 351, 353, 411, 442, 451, 52 528, 508, 586, 592, 682, 739, 742, 773, 1029, 104	55, 142 1361, 1748, 1766, 196, 166, 144 1361, 1365, 1590, 1592, 1768, 1771, 1932, 1941, 1771, 1932, 1941, 1771, 1932, 1941, 1771, 1932, 1941, 1771, 1932, 1941, 1771, 1932, 1941, 1771, 1932, 1941, 1771, 1932, 1941, 19
86	1047, 1089, 11 24, 27, 65, 67, 72, 76, 87, 90, 101, 168, 169, 17 280, 281, 342, 347, 351, 353, 354, 366, 410, 41	17 145
	24, 27, 42, 46, 145, 156, 158, 166, 167, 170, 17 177, 178, 180, 181, 183, 185, 187, 189–182, 19 199, 201, 202, 205–209, 212, 214, 219, 222, 24 0, 248, 249, 252, 339, 347, 351, 353, 354, 35 359, 366, 456, 458, 460, 648, 663, 739, 742, 7 48, 756, 768, 772, 777, 780, 783, 785, 806, 8 875, 1039, 1040, 1045, 1085, 1089, 1091, 109, 1100, 1101, 1103, 1106, 1109, 1110, 1117, 11 24, 65, 67, 76, 167, 169, 178, 179, 199, 202, 20 207, 208, 210, 220, 351, 353, 441, 442, 451, 52 528, 568, 586, 592, 682, 739, 742, 773, 1029, 104 24, 27, 65, 67, 72, 76, 87, 90, 101, 168, 169, 17 250, 281, 342, 347, 351, 333, 354, 366, 440, 44 526, 528, 544, 545, 550, 568, 572, 588, 58 258, 568, 688, 592, 688, 696–688, 696–689, 703, 73 737, 739, 748, 756, 774, 785, 848, 857, 863, 87 879, 883, 1046–1048, 1091, 1100, 1105, 111	143
87	879, 883, 1046-1048, 1091, 1100, 1105, 111 11: 24, 27, 49, 65, 67, 72, 76, 87, 90, 101, 145, 156, 15	7, 151
	24, 27, 49, 65, 67, 72, 76, 87, 90, 101, 145, 156, 15 166, 167, 170, 178, 180, 183, 185, 187, 189, 19 192, 196, 199, 202, 205, 207-209, 212, 219, 34 351, 353, 358, 359, 413, 427, 450, 451, 526, 52 373, 544, 568, 586, 592, 593, 648, 739, 742, 78 848, 856, 863, 872, 1040, 1050, 1089, 1082, 111	01, 154 . 1341, 1815, 1932, 19 17, 155 . 1368, 1369, 1815, 1816, 1932, 19 18, 156 . 1361, 1530, 1531, 1815, 1817, 193
	537, 544, 568, 586, 592, 593, 648, 739, 742, 76 848, 856, 863, 872, 1040, 1050, 1089, 1092, 111	18, 157
88	24, 27, 65, 67, 76, 87, 90, 101, 145, 156, 158, 1167, 169, 178, 180, 183, 189, 191, 192, 197-1201, 205, 207, 208, 212, 214, 219, 347, 351, 35, 359, 341, 450, 451, 526-528, 537, 544, 55, 568, 592, 593, 665, 648, 682, 739, 742, 773, 87, 502, 593, 1044, 1052, 1089, 1105, 1112, 112, 24, 27, 45, 46, 65, 67, 77, 87, 90, 91, 101, 33, 1353, 363, 362, 366, 780, 798, 863, 808, 883, 106, 23, 24, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 27, 30, 31, 65, 67, 77, 87, 90, 101, 302, 34, 32, 32, 32, 32, 32, 32, 32, 32, 32, 32	66, 160 1831, 19 19, 161 1361, 1836, 1932, 19 33, 162 1328, 1329, 1361, 1391, 1449, 1493, 1615, 183
	358, 359, 414, 450, 451, 526-528, 537, 544, 55 568, 592, 593, 605, 648, 682, 739, 742, 773, 87 1030, 1046, 1052, 1089, 1105, 1112, 11	60, 1841, 1932, 19 12, 163
89	21, 24, 27, 45, 46, 65, 67, 77, 87, 90, 91, 101, 34 351, 353, 362, 366, 790, 798, 863, 880, 883, 105 1055, 11	77, 165 1264 1836, 1850, 19 73, 166 1305, 1861, 1836, 1932, 19 77 167 1305, 1502, 1503, 1585, 1836, 1932, 19
90	251 252 202 201 202 1052 1055 1001 110	NO 100 1901 1090 1004 1099 10
91	351, 355, 863, 801, 863, 1093, 1093, 1094, 118, 813, 818, 856, 858, 801, 863, 864, 881, 882, 883, 1054, 1056, 1091-1094, 1096, 1098, 1100, 11, 112, 114, 117, 11, 124, 27, 65, 67, 77, 90, 101, 304, 338, 339, 347, 351, 353, 366, 451, 486, 489, 491, 522, 55, 528, 544, 550, 570, 592, 593, 605, 790, 805, 84, 848, 849, 849, 849, 106, 1063, 1088, 1091, 1094, 1112, 1113, 1117, 11, 116, 24, 27, 65, 67, 69, 87, 90, 347, 351, 353, 354, 37, 351, 368, 361, 361, 361, 361, 361, 361, 361, 361	90.
92	24, 27, 65, 67, 77, 90, 101, 304, 338, 339, 34 347, 351, 353, 366, 451, 486, 489, 491, 522, 52	35 1929, 1930, 1931, 1937, 19 11, 174 1361, 1478, 1585, 1836, 1882, 1932, 19 17, 175 1888, 19
	528, 544, 550, 570, 592, 593, 605, 790, 805, 80 814, 843, 860, 862–864, 880, 882, 883, 891, 100 1063, 1088, 1091, 1094, 1112, 1113, 1117, 11	174
93 94	24, 27, 65, 67, 69, 87, 90, 347, 351, 353, 354, 36 790, 800, 814, 895, 1060, 1065, 11 96, 103, 104, 309, 346, 848, 856, 861, 880, 88	66, 179 1256, 1361, 1891, 1897, 19 17 180 1256, 1891, 1901, 19 32, 181
95	883, 1070, 1091, 1094, 1096, 11 1616, 19	90 182 1254, 1256, 1891, 1908, 1931, 19 34 183
96 97 98		40 184
99	1620, 1622, 19	34 187

_			
Mill 188	1937	Mills saving iron and copper values 16 manganese values 16 lead and zinc values 16 zinc and copper 16 zinc and copper 16 only asbestos 16 copper values 16 copper values	16 1828
arrastra at Monteponi, Sardinia buildings, construction of Clausthal	1039	manganese values 16	16. 1814
at Monteponi, Sardinia	1066	lead and zinc values	16, 1780
buildings, construction of	1088	zinc and copper 16	16, 1794
Clausthal	965	iron values 16	16, 1783
constants for the engineer importance of F		only asbestos	16, 1916
Snyder	2048		
Snyder		diamonds 10	16, 1921
saving of mill height at Mill 158	1826	iron values 16 lead values 16	16, 1815
	46	lead values . 16	16, 1706
distributors	857	mercury values	16, 1919
for aspesios	1079	pyrite	16, 1913
clay and kaolin	1075	silver values 16	16, 1679
Elmore oil process	1072	silver and lead values 16 lead, and zinc values 16	16, 1680
grapnite	1074 1074	lead, and zinc values . 16	16, 1713
tim over	1081	tin and tungsten values	16, 1915
hasting of	1098	zinc and manganese values . 16.	16, 1804
Himmalf that	958	sectional sieve scales in American, table of	1108
Iron Mountain	897	sieve scales in American, table of .	. 1361 1039
Joseph Wharton	1058	silver formbunation simple jigging	1039
Laurenburg	961	· simple naging	900
Mons phosphate	899	simple jigging	892
Monteponi	1066		1013
numbers, key to	AXV	with plates and vanners	. 1018
plant	1087	no vanners	. 1017
practice in California, gold. E. B. Preston	1278	without amalgamated plates steam stamp in Montana	1014
	888	steam stamp in Montana	984
practice in California, gold. E. B. Preston processes and management	1912		1004
screens	1365	hydraulicking or dredging	1006
sites	1085	magnetism	1053
Sulphur Mines & Railroad Co	905	magnetism with jigs, vanners and tables	. 1103
testing 1996, sieve for 1996, tests treatment, schemes of Vieille Montagne Co	1168	log washers.	895
sieve for 1996,	1997	Millstones, discu sion of	2000
tests	1104	Milwaukee Mining Co, mill	. 940
Visita Mantagan Ca	011	Mimetite, specifi gravity of	. 1189
with a man and convertable	1038	with jigs, valuers and tables log washers. Milstones, then sion of Milwatike Mining Co, mill Mmetite, specifi gravity of Minas Ceraes, Brazil, strakes at Tecolotes y Anexas mill. G. A. Burr	725
	1059	recolotes y Anexas mill. G. A. Burr	2037
Work	381	Mine 1	482 481, 482
	1168	24	481, 482
Miller pump	927	25	482
Robert, Hick revolving grizzly	385	26	481 489
Robert, Hick revolving grizzly Millerite, specific gravity of	1189	30	481, 482 481, 482
Milligram, equivalents of .	1187	31	481, 482
Millimeter, equivalents of	1187	35 .	481, 482
Millimeter, equivalents of Milling. See under Ore Dressing and Concentration.		38	481
accounts .	1122	39 .	482
at Gundling No 5 Jophn Missouri D But-		42	481
	2046	44	12
costs of at mills	1793	46	12, 843
expenses	1123	47	12
experiences R. D. O Johnson	2048	54 .	481
improvements in 1904 in 2 in Western Chihuahua	2047 1664	57	482
losses	1945	67	482
	1073	77.	. 482 482
plants for small mines. F. L. Bartlett practice in the Witwatersrand, South Africa	2036	83	481
practice in the Witwatersrand South Africa 1	1643		481, 482
	1107	93	481
bibliography for	1173	and Smelter Supply Company, cone classifiers	
California versus Colorado	1030	Mill 141 .	1761
canvas plants	1029	blisting in	. 9
care of	1114	fines, treatment of	1111
choice of	1161	La Motte mill x	xvi, 921
complex jigging, at Lake Superior in Colorado and Utah Idaho and Europe	990	fines, treatment of La Motte mill x packing in water used	481
in Colorado and Utah	925 937		1105
Montana	973	Mineral Resources of the United States, pan amalg	ta - 1520
southeastern Missouri	916	mation	1163
construction of	1088	aggregate	1100
	1124	oils	1162 1097
	1111	Minerals, adhesion of	4
for corundum and emery	1078	aggregation of	3
gold combination	1046	changed by heat color and luster of	, ,
key to numbers	XXV	color and luster of	3
location, capacity, etc.	xxv	decrepitation of .	5
	1085	effect of greasiness of	4 3 5 . 4
magnetic combination	1060	magnetism of	4
method of studying	1613	momentum of	. 4
Mining and Reduction Company	1792	settling power	4
name, location, minerals and capacity	XXV	specific gravity of	3
order of	1616	floated by flotation processes, list of Flotation Company, flotation processes	1555
principles in	889 889		1560
method of studying Mining and Reduction Company name, Boation, minerals and capacity order of outlines of principles in pulverzing	200	hardness of	Z
saving copper and sulphur values 1616,	1888	list of good and poor conductors for electr static separation	1550
gold and copper values	1831	magnetism of .	790
pulverizing saving copper and sulphur values gold and copper values silver and copper values led or copper values 1616,	1836	magnetism of separated in mills. See Individual Mills	in
silver and copper values . 1616, lead and copper values 1616,	1786	Chapter XX	
zinc values 1616,	1748	Chapter XX Separation Company, flotation process	. 1555
,	67		
	51		

nerals Separation process at Mill 130 1560,	1719 1721	Monitor and Air	x fraction
	1723	hydraulic gia	int
specific gravities of structure and fracture of	1188	mill Mana Palainas	phosphate dressing at
tenacity and brittleness	3	plant for pho	phosphate dressing at 1
tenacity and brittleness which become magnetic on roasting .	. 1995	Montana & Deny	er Reduction Company mill. F. D.
ners' inch measure for water .	. 1197	Smith	
ton	. 883 . 1780	Coal and Co	oke Company, coal washing at the.
nes de Pierrelitte neville, New York, mill at nimum difference in specific gravity for jigg	. 1059	J V Scha copper mills	In
nimum difference in specific gravity for jigg	ing 609	sulphide n	nilis
ning, cost of	1126 1947	cost of mili	n
costs, statement of wire cloth screens, sizes of	. 1196	milling district, cost	in 1 of producing copper in 1950, 1951, 1
wire cloth screens, sizes of nnesota iron mine, Blake breaker at	. 23		, ,
cost of crushing at crushing at	. 60 . 57	dredging in	rolls
Iron Co., cost of breaking ore	. 51	mills in	1136 1181 1
Silver Company, Ltd nnic & A Y mill nor processes of separation	1731	Mining Co	1136, 1181, 1 Limited, mill xxviii, 1027, 1040, 1
nnie & A V mill	xxv, 909	sapphire wa	shing _ 1
scellaneous apparatus	839 882	Zine Compa	ll F L. Bosqui 2 nv Blake Morscher separator at . 1
machines using agitation	682	Monte Cristo mi	ll, Huntington mill at
plates	741	Monteponi, calar	nine plant at. E. Ferraris . 2
processes of separation ssouri, capacity of jigs in	790 602	cost of mill Ferraris belt	at
concentration in southwest R B Brinsi		classifier a	t
cost of mill in .	1126	drum type	magnetic separator at
milling in	1129	jig at	
producing lead and zinc in 1968 1971, 1972	. 1973, 1970,	magnetic screen at	separator at
arop between hig sieves	990		
hand jigging in	893	jigs at	f tadings
jigs in jig plunger clearance in	E90	magnetic mi	italings
ius in 507 !	599 649 643	magnetic mi Separation	at 834.
-Kansas district, milling in the O. Ruhl concentration in the H. A. Titcoml	2045		.a 799
lead and zinc mills, methods of jigging in	be 2036 571	roasting for	magnetism at
mills in	571	mill at	sts at 1066, 1179, 1181, 1
	303	stay boxes	s used at
limestone, jaw plates used in crushing	48	zinc mill .	it . 1
mills in 900, 1120, 1179, 1180, 1181, 1185	2, 1183, 1185 2034	Mounts Australi	d Company mill G. A. Burr ta, concentration at 5
zinc ore, sizing test on limestoae, jaw plates used in crushing mills in 900, 1120, 1179, 1180, 1181, 118; milling in O. M. Bilharz southwest O. Ruhl	2043	mines, Hand	ock pg at
number of sieves on jigs in	9,40	Moore filter-pres	s system at Mill 103
Robinson jig in typical milling practice in Joplin C L	504	Moravia, graphit mill in	e dressing in
son.	2042	Morel & Hall's	mill, bibliography for
R L Herrick	2042	ball mill	
Zinc and Lead Company mill	2036	Morenci, Artzon.	i, type of settling tank used at . 1 pulverizer
jugs in mills general scheme of R. H. Rich	609 ards 2040	bibliogr	aphy for
mills, general scheme of R H Rich ore, improvements in milling W E.	Ford 2039	Morgan, P. G.,	gold dredging in New Zealand 1
xed sizes, tests on jugging xer Blaisdell mechanical mixer for oil separation	630	Morison, D. B.	215.
for oil separation	1603 831	efficiency limits of c	of stamps frop in stamps
xing box at Mill 162 pans at Mill 188	1843	Morison's	pneumatic stamp
pans at Mill 188	1921	stamp bat	tery .
vats at Mill 130	1722 1831		of velocity of stamps
octezuma Copper Company odern practice in California gold mills odifications of Collom jig	1619	high-speed s	stamp 141. 2
odifications of Collom jig	515	Morning mill M	
Evans jig	517	stamp mo	rtar
Frue vanner	651 880	Morris centrifue	rtar gravel mine dl pump at Mill 139 175 . & Co., plate glass for launder lin-
drained ore	1106	at Mill	175
removed in driers	881	Theodore W	7. & Co., plate glass for launder lin-
samples blasses spigot for jigs	. 846, 1575 528	Marro Valha mi	no bought of the harm of tames
olyl»lemte, concentration of. J Oldy	2029	stamp mi	ne, height of discharge of stamps ne, Brazil
dressing	1567	Morscher, Lawre	ne, Brazil ence N , electrostatic separation hinery & Supply Company, the Wild
separated by oil specific gravity of	881	Morse Bros. Mac mill	hinery & Supply Company, the Wild
dybdenum	1569	F B, corru	gated vanner belt
atomic weight of	1188	Tustin mi	gated vanner belt
omentum and trajectory	1611		
of minerals	889	Mortar beds for	steam stamps
used in dry separation onadnock Chili mills at mills	819	of Nordbe	erg steam stamps
onadnock Chili mills at mills	1775, 1850	blocks for g	ravity stamps
onarch breaker, cost of crushing by of Blake type	51 20	marshy	ground
table of sizes of	. 21	or concret	n
magnetic separator	797	box, Bremn	er's 2
onazite dressing in the Carolinas	. 2030	Morison o	mine 224 mine 224 mine 224 mine 224 mine 224 mine mine
sands, concentration of F Katzer	2030	discharge of	Min 181
sand washing in the Carolinas	2027	Mortar discharge	e for Leavitt stamp
separated by magnets	790		amalgam

Mortar hand, for testing	Muller, in amalgamating pans 245
Mortar hand, for testing 1137 housing for steam stamps 119, 120 jig discharge for steam stamps 1256 jigs at Mill 177 1892 linings 166 at Mill 117 1668	Muller, in amalgamating pans 245 mortar for cleaning amalgam 204 grinding amalgam 780 process for corundum 1078 Stanwood gravity 1285 Multiple jaw bracker 28 Mumford & Moodie dry separator 818 Mundic 900 Munch 168 Munch 168
jigs at Mill 177	process for corundum
linings	Stanwood gravity
Mortars at Mill 117	Mumford & Moodie dry separator 818
Boss individual mortars 1265 standard battery mortar 1267	Mundic 900 Mundt 168 Mundt's creeps 168
Dahlonega . 152	
for gravity stamps	Munich, tests on strength of stone at
Homestake type	Blake breakers at Bonne Terre 57
introducing water into	breakers 57
Northerg steam stamp , 1005	comparison of the English and Continental system of jigging 1463
Rapid Economy individual 1266 Schorr stay-overflow, the 1266	density of pulp on slime tables 695 Evans classifier 496
single and double discharge 107	table at Lake Superior 728
standard ten-stamp battery	figures on practice with Lake Superior hydrau- lic classifiers . 390
table of dimensions of	formula for pulsion velocity in jigging . 1460
weights of 164	gravity stamps
sectional mortars 1267	laboratory slime table . 1155, 2023
Mosler, C., Ball stamp . 143 Collom jig . 643 copper dressing at Lake Supperior . 1186	Lake Superior hog-trough classifier . 401, 476
copper dressing at Lake Supperior 1186	new Liberatory classifier 2020
	Parson's ugs at Bonne Terre, Collom jigs at
stamps in Quincy mill . 230 Mosser W. F. & Co. rolls	Lake Superior 640 Rattinger table 728 40 640
Motion of a solid through a liquid H. S. Allen . 1433	separation by jigs
Poynting and Thomson 1433 Motors, increased use of induction motors in milling 1927 Motte's breaker 58 Marchet C. Harring in the Vancron mill. 641	sizing tests of jig products
Motte's breaker 58	Slime tables 697
Mouchet, C., Harz pgs in the Vaucron mill 641 pointed boxes at the Vaucron mill 477	Steam, pneumatic, and gravity stamps
rolls at Vaucron mill . 110	tests on hindered settling 626
stroke of jigs 594 Vaucron, Var, France, mill for galena blende 1178	Munroe's laboratory sline table 1155 Muntz metal amalgamating plates 747, 750, 1515
Mould for menting	for amplicam atom plates 1519 9094
Mount Bischoff, costs and results at mill D Clark 2034	plates, preparation of
stamps at 225	Muscovite, specific gravity of 1189
Tasmania, tin mill at 1182	Musterschutz feeder 884 Mysore, India, cost of producing gold in 1981
mill 1083	
Hope mine, ore, magnetic separation of 810	N
Trope nine, ore, magnetic separation of	• •
Light Tasmania costs of producing copper in 1957, 1958	Nacosari, Mexico, the new concentrator at. H B.
Lvell Tasmania, costs of producing copper in 1957, 1958 Shasta, California, mill at 1047 Mounting a Blake breaker 18	Nacosari, Mexico, the new concentrator at. H B. Layton 2036
Lvell Tasmania, costs of producing copper in 1957, 1998 Shasta, California, mill at 1047 Mounting a Blake breaker 18 of jig steves 540 Moustier centrioxtal breaker 2010	Layton 2036 Nagel, M. L., free-settling velocities 1421 Nagle's formula for belt transmission 97
Lvell Tasmania, costs of producing copper in 1957, 1998 Shasta, California, mill at 1047 Mounting a Blake breaker 18 of jig steves 540 Moustier centrioxtal breaker 2010	Layton 2036 Nagel, M. L., free-settling velocities 1421 Nagle's formula for belt transmission 97
Lvell Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill 1047 Mounting a Blake breaker 18 Moustier centripetal breaker 2010 Mouth of spandle and jaw breaker 54 feed openings of gravity stamps 166	Layton 2036 Nagel, M. L., free-settling velocities 1421 Nagle-'s formula for belt transmission 97 Naphtha, specific gravity of 1189 Nard pulverizer 235, 282 I ibiliography for 297
Lvell Tasmama, costs of producing copper in 1957, 1958	Layton 2036 Nagel, M. L., free-settling velocities 1421 Nagle's formula for belt transmission 97 Naphtha, specific gravity of Nariod pullerizer 1189 Narrod pullerizer 235, 282 Iibhography for 297 National Concentration Company, description of the 160
Leel Tasmama, costs of producing copper in 1957, 1958 Shasta, California, mill 1047 Mounting a Blake breaker 18 of jig steves 540 Moustier centripetal breaker 2010 Mouth of spindle and jaw breaker 541 feed openings of gravity stamps 166 Moyable sieve power jugs, Bilharz oblong 503 Bradford excentre 500 Conking 503	Layton 2036
Leel Tasmama, costs of producing copper in 1957, 1958	Layton 2038
Leel Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 of jug sieves 540 Moustier centrijetal breaker 2010 Mouth of spindle and jaw breaker 166 feed openings of gravity stamps 166 Movable sieve power jugs, Bilhazz oldong 503 Bradford excentic 500 Conkling 503 Hancock vanning 504 Hooper vanning 505 intermittent 506	Layton 2036
Leel Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 Mounting a Blake breaker 2010 Mouth of spundle and pay breaker 540 Mouth of spundle and pay breaker 561 feed openings of gravity stamps 166 Movable sace power jue, Bilharz oblong 503 Bradford exentine 500 Conkling 504 Haccock vanning 504 Hooper vanning 505 intermittent 500 Colamson 504 Schranz 505 Sol 503 Sol 504 Sol 505 Sol	Layton 2038
Lvell Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill particular of 1967 Mounting a Blake breaker 18 of jig steves 540 Moustier centripetal breaker 2010 Mouth of spindle and jaw breaker 551 feed openings of gravity stamps 166 Movable sieve power jigs, Bilbazz oblong 503 Bradford extentic 500 Conkling 503 Hancock vanning 504 Hooper vanning 505 intermittent 506 Schran 504 Schran 504 Server 1968 Serv	Layton 2038
Lvell Tasmama, costs of producing copper in 1957, 1958. Shasta, Califorma, mill and the state of 195 gives. Moustier centripetal breaker 540 Moustier centripetal breaker 540 Mouth of spandle and Jaw breaker 561 feed openings of gravity stamps 166 Movable sever power jugs, Bibarz oblong 503 Bradford excentric 500 Conkling 503 Hancock vanning 504 Hooper vanning 505 intermittent 500 Schran 5504 Schran 5504 sieve continuous power jügs 499 hand jügs 1955 method of working 497	Layton 2038
Lvell Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill at 1047 Monnting a Blake breaker 540 Moustier centrijetal breaker 2010 Mouth of spande and jaw breaker 551 feed openings of gravity stamps 166 Movable sever power juse, Bilharz oblong 503 Bradford excentric 500 Conking 503 Hanook vanning 504 Hooper vanning 505 intermitten 506 Schranz 503 Schranz 503 sieve continuous power jigs 499 hand jugs 195 method of working 497 table of practice in the mills 494 1140	Layton 2038
Lvell Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 186 Moustier centripetal breaker 2010 Mouth of spundle and pay breaker 540 Moustier centripetal breaker 516 feed openings of gravity stamps 166 Movable sieve power jue, Bilharz oblong 503 Bradford excentire 500 Conkling 503 Hancock vanning 505 intermittent 500 Colaboron 504 Colamon 504 Schranz 503 sieve continuous power jüg 499 hand jüg 497 table of practice in the mills 498 jüg 494, 1440 Llamock jür 1140	Layton 2038
Leel Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill ad Mounting a Blake breaker 18 Mousting sprease 540 Moustier centripetal breaker 2010 Mouth of spinule and paw breaker 540 feed openings of gravity stamps 166 Movable seves power jugs. Bilbarz oblong 503 Bradford excentric 500 Conkling 503 Harnock vanning 504 Hooper vanning 505 intermittent 506 Schranz 507 seive continuous power jugs 499 hand jugs method of working 497 table of practice in the mills jügs 498 Hannock jüg 491 Hannock jüg 491 testing jüg 491 testing jüg 627 tables for amalæamated plates 733	Layton 2036
Lvell Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 186 Moustier centripetal breaker 2010 Mouth of spinuthe and paw breaker 540 Moustier centripetal breaker 550 Geol openings of gravity stamps 166 Movable succe power jugs. Bitharz oblong 503 Bradford centric 500 Conkling 1503 Harticok vanning 504 Hooper vanning 506 Kolanson 506 Kolanson 506 Stranz 507 sieve continuous power jigs 499 hand jugs 950 method of working 497 table of practice in the mills 195 method of working 498 jigs 494, 1440 testing jig 627 tables for amaleamated plates 733	Layton 2038 1421
Lvell Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 197 Mounting a Blake breaker 186 Moustier centripetal breaker 2010 Mouth of spinntle and jaw breaker 2010 Mouth of spinntle and jaw breaker 516 feed openings of gravity stamps 166 Movable succe power jugs, Bilharz oblong 503 Brailford eccentric 500 Conkling 1503 Harnock vanning 504 Hooper vanning 504 Hooper vanning 505 intermittent 506 Collaboro 505 intermittent 506 Stormar 5503 sieve continuous power jigs 499 method of working 497 table of practice in the mills 498 jigs 494, 1440 testing jig 497 tables for amalgamated plates Movements, head motion for Card concentrator 1143 Movements, head motion for Card concentrator 1147	Layton 2035
Leel Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 Of jug stevs 540 Mouth of spande and jaw breaker 2010 Mouth of spande and jaw breaker 51 feed openings of gravity stamps 166 Movable succept ower jugs, Bilharz oblong 503 Bradford excentric 500 Conkling 504 Hancock vanning 504 Hooper vanning 505 Hooper vanning 505 Hooper vanning 506 Solarson 506 Solarson 507 sieve continuous power jügs 408 jugs 494 140 Hancock jüg 494 140 testing jüg 494 testing jüg 494 tables for amalgamated plates 488 Movements, head motion for Card concentrator 1183 Movements, head motion for Card concentrator 1478 New Standard concentrator 1478 West Standard concentrator 1	Layton 2036
Leel Tasmama, costs of producing copper in 1957, 1958. Shasta, Califorma, mill ad 1047 Mounting a Blake breaker 540 Moustier centrijetal breaker 540 Moustier centrijetal breaker 540 Mouth of spandle and jaw breaker 541 feed openings of gravity stamps 550 Movable sucet power jug., Bilbarz oblong 5503 Bradford excentric 5500 Conkling 5503 Hancock vanning 5504 Hooper vanning 5505 intermittent 5506 Schranz 5503 Schranz 5503 sieve continuous power jigs 499 hand jug, 995 method of working 497 table of practice in the mills 498 jigs 494 Hancock jig 494 Hesting jig at labes for amalgamated plates 194 Movements, head motion for Card concentrator 1948 Wernerds, head motion for Card concentrator 1948 Werstendard concentrator 1948 Werstendard concentrator 1948 Hancock jig 494 Han	Layton 2036
Leel Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 Of justeves 540 Mousth of spanule and jaw breaker 2010 Mouth of spanule and jaw breaker 51 feed openings of gravity stamps 166 Movable succe power juse, Bilharz obloing 503 Brailford excentric 500 Conkling 504 Hooper vanning 504 Hooper vanning 504 Hooper vanning 505 intermittent 506 Conkling 507 Storman 508 seve continuous power jigs 499 hand jus 498 juster 49	Layton 2038 1421
Leel Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 Of justeves 540 Mousth of spanule and jaw breaker 2010 Mouth of spanule and jaw breaker 51 feed openings of gravity stamps 166 Movable succe power juse, Bilharz obloing 503 Brailford excentric 500 Conkling 504 Hooper vanning 504 Hooper vanning 504 Hooper vanning 505 intermittent 506 Conkling 507 Storman 508 seve continuous power jigs 499 hand jus 498 juster 49	Layton 2036 1421 Nagel, M L., free-settling velocities 1421 Nagel, Sermula for belt transmission 9.7 Naphtha, specific gravity of 235, 282 11450 1189 235, 282 11450 247
Level Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 Of igs seves 540 Mouth of spande and jaw breaker 2010 Mouth of spande and jaw breaker 51 feed openings of gravity stamps 166 Movable seves power jigs, Bilbarz oblong 503 Bradford excentric 500 Conking 503 Hancock vanning 504 Hooper vanning 505 Hooper vanning 505 intermittent 506 Conking 505 Hooper vanning 505 Hooper vanning 506 Sever continuous power jigs 493 sieve continuous power jigs 495 hand jig 495 table of practice in the mills 498 jigs 494 testing jig 494 testing jig 494 tables for amalgamated plates 498 Movements, head motion for Card concentrator 1183 Wilfley slimer 1166 of breaker jaws 223 Adving power of water 878 Moving power of water 878 Mover mill 233 Mover metal 24 Mover mill 23 Mover metal 24 Mover mill 25 Mover mill	Layton 2036
Level Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 18 Of igs seves 540 Mouth of spande and jaw breaker 2010 Mouth of spande and jaw breaker 51 feed openings of gravity stamps 166 Movable seves power jigs, Bilbarz oblong 503 Bradford excentric 500 Conking 503 Hancock vanning 504 Hooper vanning 505 Hooper vanning 505 intermittent 506 Conking 505 Hooper vanning 505 Hooper vanning 506 Sever continuous power jigs 493 sieve continuous power jigs 495 hand jig 495 table of practice in the mills 498 jigs 494 testing jig 494 testing jig 494 tables for amalgamated plates 498 Movements, head motion for Card concentrator 1183 Wilfley slimer 1166 of breaker jaws 223 Adving power of water 878 Moving power of water 878 Mover mill 233 Mover metal 24 Mover mill 23 Mover metal 24 Mover mill 25 Mover mill	Layton 2036
Leel Tasmama, costs of producing copper in 1957, 1958. Shasta, Califorma, mill at Mounting a Blake breaker 186 of jug steves 540 Moustier centrijetal breaker 2010 Mouth of spinule and jaw breaker 540 Moustier centrijetal breaker 540 Mouth of spinule and jaw breaker 540 Mouth of spinule and jaw breaker 550 Geel openings of gravity stamps 563 Bradford excentric 560 Conkling 5503 Harnock vanning 5603 Harnock vanning 5603 Harnock vanning 5603 Harnock vanning 5603 Schranz 5603 Schranz 5603 Serve continuous power jigs 499, 1955 method of working 497, 1955 method of working 497, 1955 tables for amalgamated plates 1956 Hannock jig 627, 1956 Uses Standard concentrator 1183 New Standard concentrator 1183 New Standard concentrator 1183 Wovements, head motion for Card concentrator 1183 New Standard concentrator 1183 Wovements, head motion for Card concentrator 1183 Wowing power of water 1186 Williev slimer 1186 Williev slimer 1186 Williev slimer 1180 Wover mill 183 Would in water 1180 Wolf gravity stamps 152	Layton 2036
Leel Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047	Layton 2036 Nagel, M. L., free-settling velocities 1421 Nagle, Sormula for belt transmission 97 Naphtha, specific gravity of 235, 282 Libhography for 297 National Concentration Company, description of the Woodbury system 1459 Drill and Manufacturing Company, 1848 Drenker 203 Native amalgam 731 Nother and layam 1470 Natural feed on Wilfley table 1471 Navaho mill 203 Needle wire gauge 1195 Needle for streems, sizes of 1272 Needle wire gauge 1195 Needle for streems, sizes of 1188 Needle wire gauge 1195 Needle, W. On roasting and magnetism 1188 Needle, W. On roasting and magnetism 1188 Needle, W. On roasting and magnetism 1188 Neidle, W. W. analysis of products of hand picking at Freiberg, Saxony 482 and O. Bilharz 478 dressing at Freiberg, Saxony 482 and O. Bilharz 478 dressing at Freiberg, Saxony 174 Neuerlerg's mill, bibliography for 293 Neuerlerg's mill, bibliography for 293 Neuerlerg's system of trommels 364 Neuber mill 180 Neuerlerg's mill, bibliography for 385 Neuerlerg's will 180 Neuerlerg's will 180
Leel Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill at 1047	Layton 2035
Leel Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill a	Layton 2035
Level Tasmama, costs of producing copper in 1957, 1988 Shasta, Califorma, mill a	Layton 2036 Nagel, M. L., free-settling velocities 1421 Nagel, M. L., free-settling velocities 1421 Nagel, Stormula for belt transmission 9.7 Naphtha, specific gravity of 235, 282 Libiography for 207 National Concentration Company, description of the Woodbury system 1459 Woodbury system 1459 Drill and Manufacturing Company, 1459 Drill and Manufacturing Company, 1459 Native arnaligam 721 Native arnaligam 722 Nederland mill, wear of amalgamating pans 724 Nederland mill, wear of amalgamating pans 724 Nederland mill, wear of amalgamating pans 726 Negaunee, Michigan, mill at 727 Neill, J. W., on roasting and magnetism 728 Neill, J. W., on roasting and magnetism 728 Neill, J. W., on roasting and magnetism 728 Neubert, E. W., analysis of products of hand picking 728 At Freiberg, Saxony 728 Add Stormali 728 Neubert, E. W., analysis of products of hand picking 728 At Freiberg, Saxony 728 Add Stormali 728 Neuerland mill, billography for 728 Neuerland simil, bibliography for 728 Neuerland similant 728 Neuerl
Leel Tasmama, costs of producing copper in 1957, 1958 Shasta, Califorma, mill at 1047 Mounting a Blake breaker 540 Moustier centrijetal breaker 540 Moustier centrijetal breaker 540 Mouth of spundle and jaw breaker 541 Mouth of spundle and jaw breaker 540 Mouth of spundle and jaw breaker 540 Geel openings of gravity stamps 540 Movable sevet power jug, Bilbarz obloing 540 Bradford excentric 540 Conkling 150 Hancock vanning 540 Mouper vanning 550 Schran 550 Schran 550 Schran 550 Schran 195 Siew continuous power jigs 499 hand jugs 497 table of practice in the mills 494 Jigs 497 Hancock jig 141 testing jig 141 does for amalgamated plates 148 Movements, head motion for Card concentrator 148 New Standard concentrator 148 Wilfley simer 1504 Moving power of water 150 Moving power of water 150 Moving power of water 161 Moyer mill 166 Moyer mill 167 Mullen 161 Mullen 161 Mullen 161 Mullen 161 Mullen 161 Mullen 161 Mullen 162 Wilfley stamps 152 Mullen, Idaho, mill at 946, 1179 Muller 201 Wilfley stimer 151 Mullen 161 Miller 161	Layton 2038 1421 Nagel, M L., free-settling velocities 1421 Nagel, Sermula for belt transmission 9.75 Narod pulverizer 235, 282 235, 282 236, 282 237, 282 238, 2

Pages 1-643, Vol. I.	ORE	DRE	SSING.	Pages 644-11	.97, Vol.	II.
Newaygo Portland Cement Company, Newayg arator screen, data on the	13	360	Nip, angle of . for gyrate	ory breakers		89 1218
screen, data on the	. 20 1350, 13	סבט	rous	ests at Boston Consolidated		1226
table of capacities with various sizes of s	creens 13	351	individual s	tamp mortar		1263
New Blanton cam Bulfontein Diamond Co.	839, 10	194 081		tamp mortar Boston Consolidated Run Mill, Prescott, Arizona 55	1	1278 1264
Caledonia, chromite milt in .	10	074 786	Mill 10 capacity o			1852 2011
ore dressing plant, Clausthal Century Blake breaker	17	795	at Mill descriptio	165		1264
differential motion µg at mills 1760,	1203, 12 1765, 18	222 812	Niter for melting	mot.,		2012 784
disintegrating screen drop motion jig	537, 20	018 029	Nitric acid used	on amalgamated plates	•	752 1188
iig	1444, 14	459	Nitze, H. B. C.,	and H. A. J. Wilkens, grav netic separation s at the Haile gold mine herill magnetic separators	ity stamps	224
magnetic separator, Knowles Chum Consolidated mill, amalgamated pla	ites in	541 745	magt	netic separation s at the Haile gold mine		835 787
Comet mill details of stames		221 228	Weth Norbom vanner	herill magnetic separators		833 652
Newcum, W A, Elkhorn mill	1	134	North Brookfiel	d, Nova Scotia, ore from .		1147
Newell & Newell, plates in Penn and Iron City Colorado	mills,	789	Nordberg Corlis Manufactur	s engines ring Company, tests on	Nordberg	987
stamps at the Penn mill, Gilpin County	, Col-	229	steam sta	ring Company, tests on		$\frac{1261}{998}$
S V on drop of stamps		220	pump rolls at Mil	1 182		1911
Newfoundland chromite concentrated by free s crushed by rolls, sizing test sized in Richards' classifier		475 99	india	der steam stamp at Mill 17 ator diagrams of	1250,	1897 1251
sized in Richards' classifier New Himmelfahrt mill		407 958	test : steam stam	at Mill 181 .		1250 2011
Newhouse mine and mill .	2	037	compa	rison between single cylinder	and com-	
Mines and Smelter Company New Humboldt concentrator	1	923 493	pour founda	tions, anvil blocks, mortar	beds, sills,	1254
improved Huntington mill Jersey & Pennsylvania Concentrating Co	1. . mill 1:	313 056	and	girders piston rod, dash pot, flan		1247
Jersey & Pennsylvania Concentrating Co Fluestone rock, treated in Frisbee Luco	p mill	267 135	ing j	pulley, stamp stem, stamp s	hoe of .	1247
costs of milling in Iron Mining Company, mill	axix, 1	199	single steam	cylinder cylinders, valves, and valv n compound at Osceola ar	e gears of	1249 1249
mill in Zinc Company	1179, 1	183 804	tanden r.ick	n compound at Osceola ar	id Tama-	1254
Kleinfontein Company, conveying belt at p mill, S. Africa, E. G. Wary	dant of 1	585		pound steam stamp at mill	s1894,	1895,
Mexico, min in			North American	Lead Company, Missouri, r	nill of the	1901
stamps in plate error		226 747	R. B. Brinsm Brookfield	ade Nova Scotia, plates at		$\frac{2042}{765}$
Primrose mill, detail of stamps Smuggler concentrator		221 xvii	Butte Mini	ng Company		1836 788
mili	1	004	mills in	malgamator		1180
South Wales, stamps in hydraulicking in	1006, 1	$\frac{227}{179}$	Northey pump	n of corundum in		9 1027
Standard classifier concentrator	1369, 1	$\frac{373}{478}$	North Star mill	nia A D Foote	1175,	1182 2045
concentrator W.G. Weatherby	2	023	dies us	nia, A. D. Foote		180
Newton gold mill jigging mill	xxviii, 1	cviti	the	Valley, California, milling p G. E. Alexander	practice at	2043
mill mortar	227, 1	$\frac{047}{165}$	mortar plates	•		165 787
rate of crushing in shoes and dies		165 181	stamps	dation		224 145
mortar	163.	227	Wase .	f choose and due		183
slope of screens Sir Isaac, law of eddying resistance	i	176 425	Mines Co	ompany. A. D. Foote	:	$\frac{1925}{1617}$
New Woodbury concentrator York mill, and water		494 173	mill mortar		xxvii,	
Zealand, dredging in 1009	, 1179, 1	181	mouth		161,	167
dredges in gold yield for April, 1899	2	184 949	on Sultar Si	n mill Iverton Mining Company		1050 xxix
plates in stamps is	226,	788 227	Stamp m Nova Scotia, co	ill		149 1133
water used in stamp mills N. Henninger's limonite washer		222 895	gold mill	ing in .		1174
Niagara crusher and pulverizer		233	ore, te mill in			1184
bibliography for Falls, power at	1	294 090	T) on the	ing plant at Salmon River	. В. Мс-	2034
pulverizer, sizing test on	1	315 189				2034 2043
Nicholas pulverizer		233 292	Nozzles for wet	er wheels		1090
F C, the Elmore flotation process	2	2030	drops of	stamps		507 215
Falls, power at pulverizer, sizing test on Niccolte, specific gravity of Nicholas pulverizer bibliography for F C, the Elmore flotation process H, S, slime settling Nichols Chemical Co, mill slime table at Mill 174 Nicholson Fernik Jlonde in the Jordin distriction of the pulsar from the Michael on the Jordin distriction.	. xxv,	414	Tret	actice er wheels partments on jigs stamps		138 51
slime table at Mill 174 Nicholson, Frank, blende in the Joplin distric	. 1	1478 183	mills, ke	v to		TTV
concentrating blende in Missouri	1	183	strokes o	n jigs		592
Nichter spiral slate picker Nickel amalgam	2	730	See als			
atomic weight of in steel roll shells at Mill 128	1	1188 1714		О		
magnetic separation of		833	Oakum for cau	lking		735
ore, dressing of specific gravity of		l 185 l 189	gyrating sc	jig. V. Walti	· · · · · · · · · · · · · · · · · · ·	2022 386
		70)			

Oceasional expenses 1909 Oceasional exp	Pages 1199-1610, Vol. III.	IND	EX. Pages 1611-2052, Vol. IV.
Tomones 382		2021	- · ·
Tommels Octave mill. W. A. Root. Octave mill.			in wire screens, sizes of
Tomones 382	Ochre washing	1173	percentage of, in jig screens
Colling magnetic exparator 1908 1908 1908 1908 1908 1908 1908 1908 1908 1909	Octagonal revolving screens	1353	Operating costs 1940
Colling magnetic exparator 1928 1938	Octave mill. W. A. Root	2046	American Process Company's drives 1800
Office for mill Office for mil	stamp mill, Weaver, Arizona. D. E. Bigelow .	2043	Argall 4-tube drier
Ogle 1.7	Odling magnetic separator	2028	
Concentration at Santa Barkara, Van Meter process in America, bistory of cress in America, bistory of increasing efficiency of. A. Schwartz 2029 increasing efficiency of. A. Schwartz 2029 of as alfections ore. C. M. Fassett 2029 of as alfection of the continuous process of the blain of the continuous process and the continuo	Office for mill		minerals separation process
Concentration at Santa Barkara, Van Meter process 1992	fine jaw breaker	59	Trego roasting furnace 1548
Concentration at Santa Barbara, Van Meter process in America, history of a silicensy of A. Schwartz 2027 2072 2073 2074 2072 2075 207	On, attraction of minerals for residuum. J. F.	€2025	Operation of blake breaker
in America, history of in America, history of increasing efficiency of A. Schwartz 2027 mill of silicenus ore. C. M. Fassett 2022 tests at Mill 172 test at Mil	concentration at Santa Barbara, Van Meter pro-		circular slime tables
increasing efficiency of. A. Schwartz 2027 mill of a silicense one. C. M. Fassett 2027 cets at M. M. Demott 2027 tets at Mill 172 consumed in driers 2027 cets at Mill 172 consumed in driers 2027 cets of the Mill 172 cets of the Early 2027 cets of	in America, history of		Gates breaker
or a siliceous ore. C. M. Fassett 2029 or s. W. McDermot 2027 (1985) at Mill 172 mill 272 mill and process of the process of t	increasing efficiency of. A. Schwartz	2027	settlers 778
Construction Cons	of a siliceous ore. C M Fassett	2029	
Construction Cons	ores. W. McDermott	2027	· Wilfley roasting furnace, attendance required
Content of the cont	consumed in driers		Ophir Con Mines Co. Colorado, the mill of the 2044
The composition of the composi	cost of for breakers	49	Oppermann, M., Harz jig at Ammeberg, Sweden,
Indirectation 1097	for belts		zine dressing at Ammehorg Sweden 1176
Start For New Section 155 156 15	lubrication .	1097	Orange peel dredge 1009
suted for use in Elmore process 1558 at Mill 114 1661 166	process of separation .	831	
Clear E. F. on cost of gold milling 1155 1156 1616	required for breakers	1559	stamps 194, 214
Old Bed magnetic concentration mill 134 136 137 138 13	testing by	1155	Mill 117 . 1668
Core bins Section Se	Olcott, E. E., on cost of gold milling	1134	mills 1616 Ordinary direct plot
Dominon Copper Mining and Smelting Company 1882 1882 1882 1882 1882 1882 1882 1882 1882 1882 1882 1883 1882	Buchanan breaker, table of movements of	23	Ore ons . 842
Dam			
Globe, Arrona, concentration at H Eaglesh gauge 1193, 1999 5 s reen gauge 1195, 1999 5 s reen gauge 1364 173 173 174 174 174 174 174 174 174 174 174 175 184	pany	1882	deposits of U.S. and Canada J. F. Kemp. 1924
Earton 2013 Printsples, summary of 1611 Street aguage 1195, 1999 Streen gauge 173 3364 Street aguage 173 Street aguage 174 Street aguage 175 Street	Globe, Arizona, concentration at. H I	1925	dressing compared with smelting . 1 divisions 5
Screen gauge 173	Baron .		principles, summary of 1611
Wire gauge 1364 Ammalgam from 732, 1133 Amalgam from 732, 1133 Sorting in S African gold mine Webb and Yeatman 2021 Veatman 1366 Veatma	English gauge 1195, screen gauge	1999	handling, Blaisdell system 1600
Amalgam from 765 Veatman 2021	wire gauge	1364	kind of, in gravity stamps 207
blow of stamps 220	amalgam from	765	Yeatman Yeatman 2021
Chuck blocks in discussion 177, 178 discussed in 180 180 Colorad after breaking 1190 Coregon, dredging in 100 10	blow of stamps	220	testing . 1136
Golden Gate table in	chuck blocks in 17	7. 178	weighing of 883
mortar plates in plates in 1310	dies used in	180	weight of, before and after breaking 1190
Parties in rate of crushing in rate crushing in rate of stamp shoes and dies stems 187	mortar	165	muller quartz mill
Shore in stamp bosses 187			Organization of labor in mill . 1101
Screens	shoes in .	181	life of guides . 155
Stems			mercury wells in . 769, 771
Wear of stamp shoes and dies 183 162 163 164	stems	187	Oro Fina mill, heavy stamps 220
stamp mill Old Hundred mill, Howardsville, Colorado Jordan & Galena Mining Co., mill xxv, 913 Star of the East mill, Australia, mercury wells in gold caught in wells in 771 Union mill, Breckenrelge, Colo., practice at the. D H. Laurence 2045 Summit County, Colorado, flow sheet of the. D H. Laurence 2046 Oligoclave, specific gravity of 2045 Oligoclave, specific gravity of 2046 Oligoclave, specific gravity of 2046 Oligoclave, specific gravity of 3189 Oliver Iron Mining Company, washing plant for monores 2046 Oligoclave, specific gravity of 2048 Oligoclave, specific gravity of 2049 Opening, disease and place at Mill 180, life of 2048 Oligoclave, specific gravity of 2049 Opening, disease and place at Mill 180, life of 2048 Opening, disease and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 180, life of 2048 Orional place and place at Mill 204 Orional place and mill grave and place at Mill 204 Orional place and mill grave and place at Mill 204 Orional place and mill grave and place at Mill 204 Orional place and mill grave and place at Mill 204 Orional place and place at Mill		228 183	Plata mine, sizing thests of ore from . 309 Oroville California dredging at 1008 1012
Old Hundred mill, Howardsville, Colorado 2012 Jordan & Galena Mining Co., mill xxv, 913 5tar of the East mill, Australia, mercury wells in Gold caught in wells in 761 7	martar	162	concrete mortar block at . 148, 229
Union mill, Breckenridge, Colo., practice at the. D H. Laurence 2045 Summt County, Colorado, flow sheet of the. D H. Laurence 2045 Oligoclave, specific gravity of 1189 Oliver Iron Mining Company, washing plant for iron ores Oliver Iron Mining Company, oliver iron Mining Company, oliver iron ores Oliver Iron Mining Company, oliver	Stamp mill Old Hundred mill, Howardsville, Colorado		Oroya-Brownhill mines, Australia, the reduction works of the R. Allen 2045
Union mill, Breckenridge, Colo., practice at the. D. H. Laurence 2045 Summit County, Colorado, flow sheet of the. D. H. Laurence 2045 Oligoclase, specific gravity of 1189 Oliver Iron Mining Company, washing plant for iron ores Oliver Iron Mining Company, washing plant Iron ores Oliver Iron Mining Company, ore of the Oliver Iron Mining Company, or Iron Oliver, Colorado, or Ila ore or or or ores Oliver Iron Mining Company, or Iron Oliver, Colorado, mill at Carella Iron or	Jordan & Galena Mining Co., mill . xx	v. 913	Orpiment, specific gravity of 1189
Union mill, Breckenridge, Colo., practice at the. D. H. Laurence 2045 Summit County, Colorado, flow sheet of the. D. H. Laurence 2045 Oligoclase, specific gravity of 1189 Oliver Iron Mining Company, washing plant for iron ores Oliver Iron Mining Company, washing plant Iron ores Oliver Iron Mining Company, ore of the Oliver Iron Mining Company, or Iron Oliver, Colorado, or Ila ore or or or ores Oliver Iron Mining Company, or Iron Oliver, Colorado, mill at Carella Iron or			Orthocase, specific gravity of 1189 Osceola Consolidated Mining Co 1181, 1906
D. H. Laurence 2046 Oligoclase, specific gravity of Oligoclase, specific gravity of 1895 Oliver Iron Mining Company, washing plant for iron ores Olsen testing machine for strength of rock 311 Osmium, atomic weight of 1188 One-current classifier 1144 Ontario, copper sulphide mill in. H. J. C. Williams 2034 ig 538, 642	gold caught in wells in	771.	
D H. Laurence 2046 Oligoclase, specific gravity of Oligoclase, specific gravity of Oligoclase, specific gravity of Oliver Iron Mining Company, washing plant for iron ores Olsen testing machine for strength of rock 311 One-current classifier 1144 Ontario, copper sulphide mill in. H. J. C. Williams 2034 discharge for jigs 538, 642 jig jig 538, 642 jig	the. D H. Laurence	2045	Burgan classifier at 1371
Oligoclase, specific gravity of Oliver Iron Mining Company, washing plant for iron Oliver Iron Mining Company, washing plant for iron ores ores. 1815 One-testing machine for strength of rock 311 One-testing corondom dressing in 1144 1184			Lake Superior, Michigan L. Fraser . 2039
Oster per J. Classifier Investing machine for strength of rock S11 Oster-per, Classifier Investing machine for strength of rock S11 Oster-per, Classifier Investing machine for strength of rock S11 Oster-per, Classifier Investing S28 Oster-per S48 Oster Ost	Oligoclase, specific gravity of .	1189	slime tables in 697
Olsen testing machine for strength of rock 311 discharge for jigs 588, 642	Oliver Iron Mining Company, washing plant for iron	1815	Osmium, atomic weight of
One-current classifier 144 136 144 136 144 145	Olsen testing machine for strength of rock	311	discharge for jigs
Otago, dredge at Counter	One-current classifier .	1144	jig . 538, 642
mill	corundum dressing in	1181	Otago, dredge at
mill	custom mill at Keewatin. F H Probert		New Zealand, mills at
Ottawa Gold Mining Co. 1157	mill	1134	stamps at
	amplicamating pans at		
	silver mill 1174	, 1179	vanners used by 657
	Opal, specific gravity of	1189	Otto Abeling jig mechanism 641, 643 Ounce, equivalents of 1187
	life of	1902	Ouray, Colorado, mill at 928
	Upening, discussion of the designations of size of E. A. Hersam	2019	Ouro Preto, Brazil, amalgamating pan at 291 mill at

Ouro Preto, Brazil, milling at	Paper for lining cars
stamps at 227 Outlines of mills 889 Outside amalgamated plates 731	used in retorts
Outside amalgamated plates 731	Parabolic formula, Rittinger's
	for free settling 472, 473 Parallel arrangement of machines 1110
position of in the mills	rous 1244
principle of action	
total areas in mills 744	garaneism of rolls
Ovens district, amalgamated plates in 745, 748	Paramagnetic substances 796 Parent, preumatic concentration at the Rheinpreus-
mercury wells in 769	Parent, pneumatic concentration at the Rheinpreus- sen, the Zollverein collieries, at St. Louis and
plates in	Lagrange 837
plates in	Lagrange 837 Lucien, Karlik grizzly bars, trommels 385 Park City, speed of jigs at 593
Overflow battery for gravity stamps	Park City, speed of jugs at 503 Utah, mill at 1179 Parke and Lacy Company 30-34
Overhead crab	Parke and Lacy Company 1179 Parke and Lacy Company 30–34
Overlapping error on amalgamated plates 748, 757	Diake breaker law movements 34
Overshot water wheel 1036, 1089 Overstrom, G. A., experiments with launders 1592	Dodge breaker 28
Overstrom, G. A., experiments with launders concentrator 1592	sizing lox
sampler 2032	Giant rock breaker 22 Parker, R. A., false shoe 229
table 679, 1479, 1485 at mills 1487, 1711, 1712, 1730, 1886, 1897, 1898,	Parker, R. A., false shoe 229 Parkhurst & Whipple on Griffin mill 284 Park of Consum the story of Consumit 144
at mills 1487, 1711, 1712, 1730, 1886, 1897, 1898,	Parkhurst & Whipple on Griffin mill 284 Parkin, C., pneumatic stamps in Cornwall 143 Parkyn, T., tin dressing at St Dennis, Cornwall 1184 Parlow, P. G., on weight of stamps 220 Parnall Krause stamp mill mortar 2011
1899, 1901 1est at Mill 162 1493	Parkyn, T., tin dressing at St. Dennis, Cornwall . 1184
Owen, F., gold stamp mills in the Remedios district 1182	Parnall Krause stamp mill mortar 2011
tin placers in Perak, Malay Peninsula 1182	Parnall Krause stamp mill mortar 2011 Parrot mill, Wilfley table at 675
Owyhee mili banking in stamp mortar 218	Silver and Copper Mining Company 1836
breakage of stamp stems . 188 details of stamps . 223	mill xxvi, 982
details of stamps 223 silver mill, amalgamation at 787	rarsons & risher jig . 517
Oxidizing roast for magnetism . 1995	advantages of 518 construction of 525
Oxland furnace at Mill 137 . 1548, 1741	disadvantages of 518
Oxygen, atomic weight of . 1188	Cyril, Huntington mills in southern Rhodesia . 1323
effect of in copper plates	Huntington mills . 2016
Ozotetne, specine gravity or	life of screens in Huntington mill . 1317 wearing parts of Huntington mills . 1317
	Parsons' distributor 857
P	jig 640
Pachuca cams at Mill 101 1626	size of sieve and plunger . 529
Pachuca cams at Mill 101	water for 537 table 668 682
at Lonopuli Mining, Milling, and Develop-	Partial turbine 072
ment Company 1272	Partitions across jig sieves 574 Pasley, C. S., tin dressing in Bolivia 1183
Packard, G. A., dry concentration at Round Mt, Nevada 2038	Pasley, C. S., tin dressing in Bolivia 1183
Nevada 2038 Packing for jig screens 539	Passau, Bayaria, Germany, mili at 1074
Paddock air iig 820	Path of grains in trommel 376, 377
assay of products of 823	Settling particle 453 Patterson Elephant stamp 141, 143
Pahang corporation, tin mill 1084	Patton amalgamating pan 291
Pails for concentrates 1113 for moisture samples 846	Paul, A. B., California and Colorado systems 228
Paint for mills 1089	milling 1184
table tops 1483	Paul's arrastra 290 ball mill
Palladium, atomic weight of 1188	Paving blocks, strength of 303
specific gravity of 1189 Pallausch, A., graphite dressing in Bohemia 1177	Paxman mili 282, 297
Pan amalgamation 1167, 1517	Payne, C Q viii
cost of milling 1134	magnetic separator . 799 mine, British Columbia, New Century magnetic
for silver, cost of	separator at 1542
mils 1039 notes on 1520	Peace River Phosphate Company 897
settling tanks for 459	mill xkv, 897
test . 1157	Peak Hill mine, amalgamated plates in 751
bottom of amalgamating pans 241	retort residue at
conveyors 860 sampler 846	S H 884
Fandora mill 1016	and Caldecott, W. A. 1292
mill of Smugkler Umon Mining Company Axvii	crushing efficiency of tube mills 1323
Panning at clean up 203, 266	data on sampling 851 design of mining machinery 2048
gold ore, dry 825 Pans, amalgamating and clean up 232	discussion of H A White's results 1340
Pans, amalgamating and clean up 232 Colorado Iron Works grinding pan 1282	rules for sampling . 849
continuous grinding 1282	sampler for tailings 884
for amalgamating 239, 777	tube mill grinding in S. Africa 2014 Pearl (Australia) mill, wear of shoes and dies in 183
clean-up 250 diamond washing 1081	Pearl (Australia) mill, wear of shoes and dies in amalgamated plates in
hand panning 1152	(Idaho) camp, milling in the . 2043
mixing at Mill 188 . 1921	Pearline for boiler scale 1027
washing 333	Pebble, Florida, mill at 897
corundum and emery 333 grinding, Colorado Iron Works Company 1323	Pebbles, for tube mills, American A Lakes . 2015 amount charged, formula for . 1288
Australian practice . 1283	at mill 143
sizing tests of purp from 1284	C C Schnatterbeck 2016
wear of shoes and dies . 1284	consumption of 1291
Hendy 683 versus tube mills 1282	Peck's centrifugal elevator 2031
in Australia, efficiency of grinding 2014	separator 828, 839
water for 1105	Montana, concentrating mill. G. W. Winter . 2036
Pape Henneberg dry separator 818, 828, 890, 891	Peir, A. von, rolls with tension rods

1 4865 1100 1010, 7011 1111		1 4800 1011 1002, 1011	•	••
Pelton water wheels 931, 935, 939, 945, 947, 9	51,	Phillips, W. B. and A. Thies, stamp mill at Haile gold	١	
1015, 1019, 1020, 1021, 1022, 1023, 1029, 1032, 1034, 10	089,	mine, North Carolina	- 11	
	090 619	of Cranberry ore in North Carolina		333 180
	013	cost of milling		35
Penalties on Toplin zinc ores 1	939	magnetic concentration in Alabama		333
products at Mill 148 . 1	793 789	of Cranberry ore in North Carolina .		33 5 176
	229	roasting and magnetic separation of iron		314
effect of rapid drop of stamps	220	Wetherill separator in Alabama .		335
Pennsylvania, driving mechanism for trommels .	357	Phlogopite, specific gravity of		189 140
mill, Grass Valley, Calif	036 828	Phœnix atmospheric stamp mill		143
Parler ore feeder D. I. Pepler	032	false bottoms in mortar	. 1	180
Pepler's operative device for the Challenge feeder.	MAN 1	inside plates		178 165
	2031 1182	mortar		165
un dressing at .	084	screens in	. :	175
Percentage of extraction in mills 1115, 1	932	mine, stamp at		140
moisture in ore	1106 546	Phonolite and andesitic breccia crushed in Florence Colorado	•	103
screens 168,	369	Phosphate dressing	, 1	183
Percy, C. M., picking belt of steel plates	492	in Belgium	. 1	899
reduction in rolls, diagrams of shaking riddles	1227 385	Phosphates in Tennessee, milling of R D. O Johnson	. 20	027
Percussion tables, bibliography for	727	mill for 895, 897, 89	98	899
Bartsch rotary	1497	of the Pyrenees	2	033
	1496 2009	treated by hydraulic nozzle in log washer	. :	$\frac{334}{327}$
Perfection laboratory breaker ore feeder	1578	washing	. 1	180
Perforated board for riffles	724	Phosphor bronze cloth screens		174
in classifiers	437	plate screens Phosphorus, atomic weight of	٠,	174
plate and wire cloth screens, for medium and fine work	340	Physical properties of minerals	•	188
plates in settling tanks	453	adlesion		4
Peridotite weathering of	530 134	change of magnetism by heat porosity by heat		4
Periods of clean up in steam stamps Peripheral discharge tube mills of the Davidsen type	1297	color and luster		3
overflow, depth of discharge versus velocity of		decrepitation .		5
	1413	greasiness hardness		4
for slime tanks, use of lead strip for maintain- ing level	1406	magnetism		4 3 5 4 2 4 3 3 3
wood strip for maintaining level	1407	mineral aggregation		3
Periphery speed of rolls	86 1177	specific gravity structure and fracture		3
Perm mine, mill works, double discharge on jigs at	EUA.	tenacity and brittleness		2
Permeability for magnetic lines	792	Picker for slate		489
of iron	$\frac{792}{101}$	Picking See also Hand Picking belts	1	435
Pernolet A. Curr disintegrator	298	at mills 1438, 1617, 1737, 1749, 1806, 1815	5. 18	42.
A, Carr disintegrator Rexroth, Lamarche and Schwarz coal jigs	641	at mills 1438, 1617, 1737, 1749, 1806, 1815 1871, 1875, 188	2, 1	889
ribbon theory of roll capacity	101	detailed information on. E. H. Messiter of wire at Mill 137		021 740
V, pneumatic concentration 641, velocity of particles falling in water and air	477	Robins conveying	i	438
Day or or any or furnacion at Mill 105	1637	speed and capacity of		438
Pestarena, Italy, mill at Peter McFarlane Sons Iron Works Company, Horn	1182	chutes cost of hand picking	,	489 1438
rotary slime concentrator	1499	hand		480
Peters, hammers for breaking	11	houses		492
spalling E. D., Blake breaker at Sudbury, Canada	11 57	in the mine block system		481 481
breakers 56, 5		of rich ore for economy		481
copper smelting cost of breaking	λX	on conveyors .		489
	51 885	shaking table summary of, in the mills		489 491
dust chambers hand versus machine breaking	59	tables 485, 486, 488, 49	2, 1	
rolls	109	annular Mus-Unaimers types		1430
Peterson, G. W., magnetic separation in Sweden	$\frac{1569}{295}$	at mills 1783, 1786, 1787, 1792, 1795, 180 circular revolving	JD, I	490
Pfeiffer, J., Pfeiffer's mill Pfeiffer's horizontal ball mill	234	compared		491
mill bibliography for	295	Humboldt	į	1437
Pfordte, O. F., concentration at Casapalca, Peru	1180 295	intermittent motion of		491 1435
edge runners Frue vanners	728	Krupp type speed and capacity of		1438
Pheby, F. S., battery frames 158 Phelys breaker	, 228	of , ,		491
Phelos breaker	58	stationary Dial line a proper telesco	7.50	488 754
Philadelphia & Reading Coal Co., shaking screens Graphite Co., mill	342 1075	Pickling copper plates . Pick points, removal of	140,	882
Phillip	1035	Pick points, removal of Pictou, H and S. E. Linder, action of arsenic st	ıl-	
dry gold concentrator. F. B. Allen	2025	phide solution on electrodes powers of metallic salts on arsenious st	.1	1178
J. A., amalgamation for silver	787 1174	phide		1178
amagamating pans.	290	Pierce amalgamators 1517, 15	20,	2024
arrastra	$\frac{290}{223}$	at mills 1517, 160 Mill 114, saving effected	ю,	1661 1663
gravity stamps Krom's rolls	109	W I., gold milling in Nova Scotia		1174
metallurgy	213	Pierrefitte mines, France, mill at		1182
on height of discharge	213 1039	Sautter magnet at		798 1891
silver amalgamation . separation processes	339	Pike Hill mines	• •	1925
repartment processes		· · ·		

	Til e a constation de la constation de l
Pilling Air Engine Company, pneumatic hoists 1608, 1610 table of sizes, capacities, speeds, weights, etc. of	Plate screens, stationary
etc. of 1609	thickness of 371
Pillow blocks for rolls	mercury by amalyamating plates 1514
Pine board for amalgamation	acid water on
Pillow blocks for rolls 71, 80 Pinder concentrator 1479, 2022, 2023 Pine beard for amalgamation 750 for riffles 721 Hill crad washing Pennsylvania 2051	amalgamation
Pine beard for amalgamation 750 for riffles 721 Hill coal washing, Pennsylvania 2051 Pinte, specific gravity of 1189 Pipe and plug jug spigot 527 conveyor 861 covering 1091 discharge for jugs 583 at Mill 137 1458 distributors 857 launders at Guanajuato 1595 sampler 845	apron
Pine and plug ng spigot	bibliography for
conveyor 861	bibliography for 787 buckling to remove hard amalgam 760
covering	buckling to remove hard amalgam 760 cleaning 757 coated with amalgam 747 4 quicksilver 747 connection to mortar 757 copper and silver plated 764 versus silver-plated 758 details of dressing and cleaning 757 dimensions, area, and thickness 744 distribution of amalgam from 764 distributions and collectors 743 dressing and cleaning 757 drops between 733, 743
discharge for jigs	toated with amalgam
distributors	connection to mortar
launders at Guanajuato 1595	copper and silver plated
launders at Guanajuato 1595 sampler 845 sizes of 405	tersus silver plated
	details of dressing and cleaning 757 dimensions, area, and thickness
Pipes for gravity stamps 199	distribution of amalgam from 764
launders 873	distributors and collectors
water	dressing and cleaning 756 drops between . 733, 743
	drops between . 733, 743 due to cyanide, loss on B. C. Wilson 2024
Piston in jig discharge 580 of Nordberg steam stamp 1247	effect of warm water
Pitch angle in trommels . 376 for smoking moulds . 784	for amalgamation, plain copper versus silver- plated E Halse 2024
for smoking moulds . 784 Pitterints Finland magnetic separation at 804 836	from battery, author advocates separating. P.
plant at E Promosigh 2047	
Pitkaranta, Finland, magnetic separation at plant at E Promosigh 2047 Pittsburg and Montana Copper Company 1836	graphite coating on
Coll jig	grease on
Ditt. Large Foundry and Machine Co. rolls 76	gyrating
Witsher, or drawings of Witshurg Foundry and Machine Co , rolls 76 Monarch breaker at 21 Silver Peak Gold Mining Company 1634 Placer County, Californa, string tests of stamp pulp deposits, testing of R Nye 2014 deposits, testing of R Nye 2040 2030 2040 2040 2040	inside amalgamated . 178
Silver Peak Gold Mining Company 1634	lin 739
Placer County, California, sizing tests of stamp pulp 211	loss of gold on
helds of northwest America, T. Tonge, 2040	materials for amalgamated . 747, 1514
gord A McDougan 2049	maintaining of right consistency 756 materials for amalgamated 747, 1514 method of electroplating 754 method of method of chectroplating 741
burler process for several D. Macanire 2041	
recovered by dry panning recovered by dry panning ground, working of J. W Pinder 2036 2036 2036 2036 2036 2036 2036 2036	Muntz metal, coated with mercury 750 new scheme at Mill 66 . 1026
machines, dry . 838, 839 Tierra Seca . 838	
Tierra Seca 838	of pure silver coated with amaigam
material in sluices, mathematical discussion of the action of A. St. Raimer . 2030	splash board . 739 vanners and bumping tables . 740 contride any learnested . 731
material in sluices, mathematical discussion of the action of. L St Raimer . 2030 mines, cost of operation of C W Purington 2047	outside amalgamated
	position of 737
ancient stream gravel in W Lindgren 2041 history of J M. Mackaren in Alaska C W Purington 2042, 2045, 2047 costs of C W Purington 2042, 2042, 2041	preparation of new
in Alack C W Purington 2042 2045 2047	proportions of gold and silver caught on
costs of C W Purington 2041	removal of amalgam from
	removal of amalgam from
California, G. L. Holmes 2046 Columbia, S. America, F. F. Sharpless 2037 Guiana H. Tweddle 2036	rubber for
Guiana H. Tweddle 2036	
	shaking 740 sickening and flouring of mercury on 751 slope of 744
the Philippines G. D. Rice 2036	Stute
on the Yukon J. M Bell 2047 history of 2035	speed of waves and thickness of film on
	speed of waves and thickness of film on
of La Cienaga, Sonora, Mexico R. T. Hill 2036	sulphuric acid used on • 752 sweating with hot water 759
Alaska L. M Prindle 2047 the Seward Peninsula F H Moffit	sweating with not water 735 swinging 741
tin plants . 1084	tables for
	speed of waves and thickness of film on 746
washing 702, 723 Placerville, California, mill at 1017, 1022, 1035 Placing of screens 170, 373	use of galvanic couple and electric current on . 752
the mortar in stamp mills . 148	wire cloth for testing screens
Plain copper plates coated with amalgam 747	with electric current
	yield of hard amalgam
comparison of, with silver plated plates 748	for gravity stamps
transverse troughs or riffles	scales
Plaminek, A, air blast for coal 838 Hochstrate apparatus at the Rheinpreussen	Plating copper plates with silver
Hochstrate apparatus at the Rheinpreussen colliery 837	Platiniridium, specific gravity of 1189
colliery 837 Planet mill, bibliography for 234, 294 Plant for mill 1087 Plaque for vanning 1152	atomic weight of
Plant for mill . 1087	deposits of the Urals. C W. Purington 2033
Plaque for vanning 1152	in dredging, the saving of
Plate amargam ratio of gold to silver in	strap, recovery of
amalgamation	pure
annealing of, before amalgamating 747	washing in Russia 2029
conveyors	Platt mine ore, magnetic separation of 810
picking on	Plomb. A. M., results from the Blake-Morscher sep-
amaignmation use made of, in mills	tables for 733 treatment of 750 use of galvanic couple and electric current on 752 versus mercury wells 771 wire choth for testing screens 1138 with electric current 740 yield of hard amalgam 761 Platform elevators 846 for gravity stamps 156 scales 8833 Plating copper plates with silver 754 Platiniridium, specific gravity of 1189 Platnum amalgam 730 atomic weight of 1188 deposits of the Urals. C W. Purington 2033 in dredging, the saving of 2040 strap, recovery of 1146 specific gravity of native 1189 washing in Russia 2029 Platt mum for magnetic separation of 810 Ploermel, France, mill at Plomb, A. M., results from the Blake-Morscher separator 10ts of sizing tests 1139, 1148 Plotting sizing tests 1139, 1148
screens, cost of	Plots of sizing tests
for gravity stamps	1 forming storing feets

Plug spigot for jigs	Power and Mining Machinery Co., improved Hunt-
Plumb circular jig 44 Plunger clearance on jigs	ington mill 131 range of adjustment of gyratory breakers 121
teeders at mills 1749, 1750, 1751, 1853, 1857, 1864	rolls
throw on jigs	at Mill 166 185 size of crushed products from breakers . 121
versus centritugai pumps	surface measurements in stone crushing by Von
Plungers and sieves, sizes of in mills	Reytt 30
connecting rods for in jigs	applied to belt conveyors 86 computed for concentrator No. 1, Mill 173 1929
Plush for tables	193
tables on dredges 1012 Pneumatic and spring stamps 113	cost of for breakers
belt concentrator	crushing 31 in pan amalgamation 25
Products of	data in regard to
concentration 815 See also Air.	effect of strength and specific gravity on 31 for Alsing cylinder 26
bibliography for 837	amalgamating pan . 24
concentrator, Hooper 820 hydraulic, and spring stamps	arrastra 238, 23
jigs, Krom	ball mill 26 Ball Norton magnet 79
pulverizer	bucket conveyor . 86
bibliography for	buhrstone mill . 25
separators 1553	breakers
Freid gravity dry process separator Sutton, Steele & Steele dry table 1479, 1554	Bryan mill 272, 27
Sutton, Steele & Steele dry table 1479, 1554 stamps	Cammett table 67 centrifugal pumps 86
bibliography for . 143	clean-up pans . 25
Hughes' 143	cone mill 25
Krause's	Cylcone pulverizer 28 Delvik-Grondal magnetic separator 80
Poech, F. J., Siemens and Friedrichssegen separators 833	Dodge pulverizer 26
Pointed boxes	Edison magnetic separators
details of	electroplating copper plates 75 Ferraris magnetic separator 79
Rittinger type 411	Fraser and Chalmers rolls
tube classifier	Frisbee Lucop mill
Poles of magnets	Griffin centrifugal stamp mill 26
Polybasite, specific gravity of 1189	roller mill . 28
Pomeroy dredge	Hancock jig 50 hand electromagnet 81
Pontoon in hydraulicking	Heberli mill
Poor ore treated separately 1111	magnetic separator 79 Hooper air iig 82
Porcelain lining for Alsing cylinder 267 Porosity changed by heating 4	Hooper air jig 82 Huntington mill
roasting for 828 890	jigs 596, 59
Porphyry, strength of	Krom air jig
weight of 1190 Portable belt conveyor at Mill 135 1735	magnetic separator used at Monteponi . 81
conveyors at Mill 167 1857	mechanical batea . 68
stump mill	mills 108 See Individual Mills in Chapter XX.
Portage Lake foundry 1446 Porter Allen engine	movable sieve jig at Przibram 50
Dwight . viii	Narod pulverizer 28 Pape-Henneberg dry separator 82
electrolytic dissociation of slimes	Pape-Henneberg dry separator
mine, Telluride, Colorado 1176	rolls • 97, 11
J B, tabulated results of crushing tests . 2017	Salzburg table
♠ R., Bahol mill, Sutters Creek, California 1184 Port Henry iron ore concentrated by magnets . 802	Sautter magnetic separator 79
magnetite crushed by Sturtevant mill 288	Schmidt spiral screen . 36
sizing test on 100	Schranz mill
ore, magnetic separation of .798, 810 Portland mill, Colorado City, Colorado .2044	
Cripple Creek, Colorado, practice at the 2042	stamps, calculation of A W Warwick 204
Port Oram, New Jersey, mill at 1055	steam stamps, table of
Position of amalgamated plates	Sturtevant mili 28
Kia Ora dredge, Feather River, California 1184	tronmels
Posts for gravity stamps 153	vanners 66
Potash for cleaning mercury 786	and slime tables compared . 69
amalgam 730	wash trommel 330, 33 Wenström magnetic separator 80
Pot distributor	Wetherill magnetic separator 805, 807, 80
retorts	Whelpley & Storer pulverizer 28 house for mill
D Clark	house for mill
testing for 1993	jigs, Bilharz circular sieve 50
Pound, equivalents of	continuous movable sieve 49
per square inch 1188	Hooper vanning
	Robinson movable sieve 50
Powell, F., gold dredges on Snake River, Idaho 1181 the black sand problem 1511	Schranz 56 measures of 118
	of Blake and Dodge breakers compared
amalgam squeezer	Cummings granulating mill

	Til e a constation de la constation de l
Pilling Air Engine Company, pneumatic hoists 1608, 1610 table of sizes, capacities, speeds, weights, etc. of	Plate screens, stationary
etc. of 1609	thickness of 371
Pillow blocks for rolls	mercury by amalyamating plates 1514
Pine board for amalgamation	acid water on
Pillow blocks for rolls 71, 80 Pinder concentrator 1479, 2022, 2023 Pine beard for amalgamation 750 for riffles 721 Hill crad washing Pennsylvania 2051	amalgamation
Pine beard for amalgamation 750 for riffles 721 Hill coal washing, Pennsylvania 2051 Pinte, specific gravity of 1189 Pipe and plug jug spigot 527 conveyor 861 covering 1091 discharge for jugs 583 at Mill 137 1458 distributors 857 launders at Guanajuato 1595 sampler 845	apron
Pine and plug ng spigot 527	bibliography for
conveyor 861	bibliography for 787 buckling to remove hard amalgam 760
covering	buckling to remove hard amalgam 760 cleaning 757 coated with amalgam 747 4 quicksilver 747 connection to mortar 757 copper and silver plated 764 versus silver-plated 758 details of dressing and cleaning 757 dimensions, area, and thickness 744 distribution of amalgam from 764 distributions and collectors 743 dressing and cleaning 757 drops between 733, 743
discharge for jigs	toated with amalgam
distributors	connection to mortar
launders at Guanajuato 1595	copper and silver plated
launders at Guanajuato 1595 sampler 845 sizes of 405	tersus silver plated
	details of dressing and cleaning 757 dimensions, area, and thickness
Pipes for gravity stamps 199	distribution of amalgam from 764
launders 873	distributors and collectors
water	dressing and cleaning 756 drops between . 733, 743
	drops between . 733, 743 due to cyanide, loss on B. C. Wilson 2024
Piston in jig discharge 580 of Nordberg steam stamp 1247	effect of warm water
Pitch angle in trommels . 376 for smoking moulds . 784	for amalgamation, plain copper versus silver- plated E Halse 2024
for smoking moulds . 784 Pitterints Finland magnetic separation at 804 836	from battery, author advocates separating. P.
plant at E Promosigh 2047	
Pitkaranta, Finland, magnetic separation at plant at E Promosigh 2047 Pittsburg and Montana Copper Company 1836	graphite coating on
Coll jig	grease on
Ditt. Large Foundry and Machine Co. rolls 76	gyrating
Witsher, or drawings of Witshurg Foundry and Machine Co , rolls 76 Monarch breaker at 21 Silver Peak Gold Mining Company 1634 Placer County, Californa, string tests of stamp pulp deposits, testing of R Nye 2014 deposits, testing of R Nye 2040 2030 2040 2040 2040	inside amalgamated . 178
Silver Peak Gold Mining Company 1634	lin 739
Placer County, California, sizing tests of stamp pulp 211	loss of gold on
helds of northwest America, T. Tonge, 2040	materials for amalgamated . 747, 1514
gord A McDougan 2049	maintaining of right consistency 756 materials for amalgamated 747, 1514 method of electroplating 754 method of method of chectroplating 741
burler process for several D. Macanire 2041	
recovered by dry panning recovered by dry panning ground, working of J. W Pinder 2036 2036 2036 2036 2036 2036 2036 2036	Muntz metal, coated with mercury 750 new scheme at Mill 66 . 1026
machines, dry . 838, 839 Tierra Seca . 838	
Tierra Seca 838	of pure silver coated with amaigam
material in sluices, mathematical discussion of the action of A. St. Raimer . 2030	splash board . 739 vanners and bumping tables . 740 contride any learnested . 731
material in sluices, mathematical discussion of the action of. L St Raimer . 2030 mines, cost of operation of C W Purington 2047	outside amalgamated
	position of 737
ancient stream gravel in W Lindgren 2041 history of J M. Mackaren in Alaska C W Purington 2042, 2045, 2047 costs of C W Purington 2042, 2042, 2041	preparation of new
in Alack C W Purington 2042 2045 2047	proportions of gold and silver caught on
costs of C W Purington 2041	removal of amalgam from
	removal of amalgam from
California, G. L. Holmes 2046 Columbia, S. America, F. F. Sharpless 2037 Guiana H. Tweddle 2036	rubber for
Guiana H. Tweddle 2036	
	shaking 740 sickening and flouring of mercury on 751 slope of 744
the Philippines G. D. Rice 2036	Stute
on the Yukon J. M Bell 2047 history of 2035	speed of waves and thickness of film on
	speed of waves and thickness of film on
of La Cienaga, Sonora, Mexico R. T. Hill 2036	sulphuric acid used on • 752 sweating with hot water 759
Alaska L. M Prindle 2047 the Seward Peninsula F H Moffit	sweating with not water 735 swinging 741
tin plants . 1084	tables for
	speed of waves and thickness of film on 746
washing 702, 723 Placerville, California, mill at 1017, 1022, 1035 Placing of screens 170, 373	use of galvanic couple and electric current on . 752
the mortar in stamp mills . 148	wire cloth for testing screens
Plain copper plates coated with amalgam 747	with electric current
	yield of hard amalgam
comparison of, with silver plated plates 748	for gravity stamps
transverse troughs or riffles	scales
Plaminek, A, air blast for coal 838 Hochstrate apparatus at the Rheinpreussen	Plating copper plates with silver
Hochstrate apparatus at the Rheinpreussen colliery 837	Platiniridium, specific gravity of 1189
colliery 837 Planet mill, bibliography for 234, 294 Plant for mill 1087 Plaque for vanning 1152	atomic weight of
Plant for mill . 1087	deposits of the Urals. C W. Purington 2033
Plaque for vanning 1152	in dredging, the saving of
Plate amargam ratio of gold to silver in	strap, recovery of
amalgamation	pure
annealing of, before amalgamating 747	washing in Russia 2029
conveyors	Platt mine ore, magnetic separation of 810
picking on	Plomb. A. M., results from the Blake-Morscher sep-
amaignmation use made of, in mills	tables for 733 treatment of 750 use of galvanic couple and electric current on 752 versus mercury wells 771 wire choth for testing screens 1138 with electric current 740 yield of hard amalgam 761 Platform elevators 846 for gravity stamps 156 scales 8833 Plating copper plates with silver 754 Platiniridium, specific gravity of 1189 Platnum amalgam 730 atomic weight of 1188 deposits of the Urals. C W. Purington 2033 in dredging, the saving of 2040 strap, recovery of 1146 specific gravity of native 1189 washing in Russia 2029 Platt mum for magnetic separation of 810 Ploermel, France, mill at Plomb, A. M., results from the Blake-Morscher separator 10ts of sizing tests 1139, 1148 Plotting sizing tests 1139, 1148
screens, cost of	Plots of sizing tests
for gravity stamps	1 forming storing feets

Power required by sand wheels at Mill 117 . 1668, 1669, 189	94 Preparation of pulp previous to amalgamation 1514
Power required by sand wheels at Mill 117 . 1668, 1669, 188 scraper conveyor at Mill 126 170	09 Preservation of belts
screw conveyors	
shaking feeders at Mill 124 168	01 Danua fan an abita
grizzly at Mill 124 169	90 Presses for amalgam, Chalmers and Williams power 94 press
at Mill 105 at Mill 105 shaking feeders at Mill 124 figrizzly at Mill 124 faunders at Mill 124 faunders at Mill 124 Sherman regrinders at Mill 132 1728, 172	94 press
Shaking feeders at Mill 124 1693, 16 grizzly at Mill 124 1693, 16 Sherman regrinders at Mill 132 1728, 17: simple steam stamp at Mill 182 1728, 164, 164, 164, 164, 1668, 167	09 Pressure box in classifiers
stamps at mus 1010, 1024, 1034, 1005, 107	
Stroud mills, table of 1320, 132	21 measures of 1188
Sturtevant balanced rolls, table of 123 Dodge type breakers, table of 120	34 of rolls 108 05 springs on rolls 73
emery mill at Mill 186 191	18 Preston, E. B., amalgam 788
Dodge type breakers, table of emery mill at Mill 186 191 rotary breakers at Mill 186 191 testing plant at Mill 141 177	000
trommels at mills 1690, 1691, 1692, 1693, 170	66 arrastra 290 16, Blake and Gates breakers 58
trommels at mills 1690, 1691, 1692, 1693, 170 1707, 1714, 1742, 1743, 1749, 1750, 1751, 175 1771, 1772, 1773, 1774, 1830, 1928, 1929, 193	52, breakers
tube mills 128	30 Bryan mill 295 89 California gold stamp mills 1179
at mills . 1634, 177	70 gold mill practice 1278
Turbo log washer at Mill 154 181 Ullrich magnetic separator 155	
Ullrich magnetic separator 15: vanner at mills 1634, 1778, 19: various groups of machines at mills 1706, 178 1835, 18:	30 Gates hydraulic classifier . 477
various groups of machines at mills 1706, 178	80, gravity stamps
Vezin samplers at mills 1091, 173	50 Hunnington miti
Wetherd magnetic separators 15:	
Rowand magnetic separators at Mill 141 17t Wharton magnetic cobber at Mill 157 18	19 Shaking plates
Wild rolfer mills, table of 130	04 stamping
Wilfley slimers 150 at Mill 132 17:	90 stone breaker 2009
tables at mills 1625, 1634, 1669, 1687, 168 1694, 1695, 1708, 1715, 1729, 1744, 174 1777, 1929, 193	38, Prichard, W. A., definitions of slime 1398, 1419
1694, 1695, 1708, 1715, 1729, 1744, 174	 Primosigh, E., separator at Pitkaranta, Finland Principles and purposes of gravity stamps 1262
Woodbury concentrators 149	96 rolls 62
at Mill 117 160	69 governing costs . 1940 45 of action of breakers compared 52
at Mill 175 189	90 classifiers . 387, 1368
rule for 109	92 Wilfley table group 1465
sources of losses in crushing 13: summary for Mill 124 16:	25 amalgamated plates 731 98 crushing machines 300
tests at Mill 173 193	27 deep pocket classifiers 409
transmission	74 electrostatic separation 1199, 1549 94 flotation processes 1199, 1555
transmitted by belts 109	93 gravity stamps 144
used by breakers	53 hindered settling 610 97 jugs 494
steam stamps 3:	10 magnetic separators . 1521
	50 mechanical sampling 1574 03 operation of Wiltley slimer 1504
friction of piston on water - 60 on jig walls - 60	02 order of drop of stamps 215
	03 ore dressing, general 1199
	02 summary of . 1611 03 pneumatic and spring stamps . 139
oscillatory action 60	03 pulsion, general
	02 pulverizers • . 231 09 roll crushing 1224
ingging 60	02 sampling 843, 849
Practical limits of settling in settling tanks Practice, roasting practice in Wisconsin 45 Practice, roasting practice in Wisconsin	55 screen sizing 366 48 bibhography for 384
Praseodymium, atomic weight of 118	88 separation, combined 891, 1611
Pratt ore sizer 134 A H Wethey 130	45 stamps 113, 1246 60 suction 1461
at Mill 164	50 vanner separation . 665
-Wethey screen 201	18 Wilfley table . • 670
Precipitating agents for slimes 141 Precipitation of gold solutions at Mill 117 167	73 used in mills
Precipitation of gold solutions at Mill 117 Prehnute, specific gravity of	89 Prinz and Rau dust collector at Mill 141 1765
Preliminary breakers, classification of 120 crushing	00 Prism form of frommels
hibliography for	
blasting in the mine	9 Probert, F. P., comparison between Bryan mills and 9 rolls for crushing ug tailings
calcining for friability with or without quench-	sizing tests on Bryan mills 1323
ing by water	9 F. H _a concentration of copper ore 1419, 1997 18 in Arizona 2033, 2037, 2041
methods of	9 custom mill in Ontario
washers 319, 134	9 custom mit in Ontario 2040 41 primitive Mexican mill 2038 34 Process, testing for 1160
bibliography for	34 Process, testing for
Premier diamond mine	22 of separation, miscellaneous 790
Premium for picking rich ore	141
Prentiss, G W	95 table of sizing tests of
E H the Elmone detation process 156	94 Hancock jig
Preparation of new amalgamated plates	52 picking 486
	77

Product of jugs Section Sectio	D. J		
protected by public actions piles to allow piles to	Product of jigs	3, 590	Pulp thickeners used at Mill 173 1408
protected by public actions piles to allow piles to	Willey roasting furnace, fines sink in water	. 1547	Centrinest screen
Indiance pills and analysis of the maximum maximum maximum maximum in the mills and the mill of the A. C. Mahl mill of the Mill 175 and the mill 186 heldingstaphy for 299 properties of mercury 730 feelings and tables 1827 properties of mercury 730 feelings all silver on successor plates 703 feelings and tables 1827 properties of mercury 730 feelings all silver on successor plates 703 feelings and tables 1828 provided mill 181 feelings and tables 1828 provided mill 181 feelings and tables 1829 feelings a	treated by rolls	. 63	Impact screen 1351
mill of the A C Mahl of or dereshing 1119 Progresse, guberizer 236 of or dereshing 1119 Progresse, guberizer 236 Projective of mercury 236 Projective of mercury 237 Projective of mercury 238 Projective of mercury			Imperial ore screen
mill of the A C Mahl of or dereshing 1119 Progresse, guberizer 236 of or dereshing 1119 Progresse, guberizer 236 Projective of mercury 236 Projective of mercury 237 Projective of mercury 238 Projective of mercury	maximum	1117	In the milis 1346
Forgresching price of ore dressing properties of mercury 7.20 (and properties of mercury 7.20 (billing	Progress Mining Company, Mexico, jigging at th	e	Vibracone separator 1359
Progressic guiderizer 1256 Idalography for 1296 Properties of mercury 730 73	mill of the A C Mahl	2045	Pulsator classifier at Mill 175 1890
Addiography for 299 190	Progressive pulverizer		direct form 1391
Proportions between parts of stamps of gold and silver on successor plates 170	bibliography for	. 299	use with jigs and tables 1479
halitiography for 2079 Part P	Properties of mercury	. 730	house for diamonds
Proportions between parts of stamps 189	bibliography for		
Sample 190	Proportions between parts of stamps		Pulsion and suction in jurging 1465
Provisite, specific gravity of Providence mill, Webb City, Missouri. D. T Board-map 189 18	of gold and silver on successive plates		
Provise of the prov	Proprietary mine		on air jigs
man plates in shoes sh	Proustite, specific gravity of	1189	nand jigs 499
battes in shoes and these in shoes are shortested as the shortest of list of the shoes and the sin shoes and the shoes at the shoes and	Providence mill, Webb City, Missouri. D. T Board		
shoes in stamps			tests on 628
Section Sect	shoes in		general principles of
Provisite Ruchard and II W F Kayser, tin dressing at Bischoff, Instantian	stamps in		
Bischoff, Lasmania 1182 For hindered settling tests 623 Pruss, an imagent concentration 1182 Pruss, an image, air separation at 1180 Pruss, and packing at 476, 477, 484 Anal packing at 476, 477, 484 Anal packing at 259 jig connecting rods at 530 feeler at 549 Secrees at 540 S	Provis Richard and H. W. F. Kaysor, tip drawing of	. 183	definition of 558
Prus, G. magneth concentration plant at Worstade, Kessler and Val separators 825 Prussan mine, air separation at 1882 Prussan mine, air separation at 1880 breaker at 1880 bre	Bischoff, Lasmania	1182	for hindered settling tests
Praibram, Botherma, null at	Prus, G, magnetic concentration	1182	Pulsometer pump 971
Praibram, Botherma, null at	Prussian mine, air separation at	rs 835	Pulverizers, Bartle 294
Decaker at center displarage at center at center at a center display at a ce	Przibram, Bohemia, mill at		bibliography for
Index	breaker at	57	Cyclone 293
Index	Center discharge at Classifiers at 476-47	582	bibliography for 298
Hickern mil at 1006 1174 1176 1177 1185 116 118	feeders at	884	232
Howland No. 1, bibliography for 2207	hand picking at	492	Griffin 200
Section Sect		259	Howland No 1, bibliography for 297
Series at 597, 640, 641	feeder at	549	Jordan's 299
Marcall's bibliography for 296	screens at		Leviathan 299 Meibe's 200
mill at 1096, 1174, 1176, 1177, 1185 mossture in ore 1107 mostable sieve jig at 1 107 mostable sieve jig at 1 107 mostable sieve jig at 1 1089 central sizes of locaker product of 477 work necessary for crushing one kilo of different sizes of 1089 for jigs at 1 1089 from jigs at 1 1089 from jigs at 1 1089 from six 1 1		0, 641	Merrall's, bibliography for 296
mill at 1096, 1174, 1176, 1177, 1185 mossture in ore movable sieve jig at ore, stangt test of breaker product of ore, stangt test of breaker product of ore, stangt test of breaker product of to stazes of power at for jigs at 1089 power at 1089 picking at 1081 picking at	magnets at 833	8.836	Michell and Tregoning 292
Michalas, bibliography for 292 292 294 295 295 296	mill at 1096, 1174, 1176, 1177	1185	Morey and Sperry 295
ore, stang test of breaker product of work necessary for crushing one kilo of different sizes of proposer at commets at 305 for jigs at 308 trommets at 307 removal of jig tathings at 588 roatsing for magnetism at 410, stanger of jig tathings at 588 spiraltine at 421 stanges at 588 spiraltine at 4224, 225 stroke of jigs at 231 roads at 588 spiraltine at 4224, 225 stroke of jigs at 2324 stanges at 588 spiraltine at 4224, 225 stroke of jigs at 2324 stroke of jigs at 423 stroke of jigs at 424 stromels at 423 stroke of jigs at 424 stromels at 424 st	moisture in ore		Nicholas, bibliography for 292
work necessary for crushing one kilo of different stages of payer at 1089 power at 1089 for jigs at 1089 trommets at 357 picking at 458 picking at 458 prosting for magnetism at 588 roasting for magnetism at 110, 111 Saldurg table at 683 slove of jigs taction at 458 spirelatine a	ore, sizing test of breaker product of		other than gravity stamps . 231
Power at for jigs at for jigs at trommets at the picking at trommets at trommets at the picking at picking at the picking at picki	work necessary for crushing one kilo of differ-		penumatic, bibliography for 299 principles of 231
trommets at picking at picking at picking at picking at premoval of jig tathings at prosting for magnetism at prosting for magnetism at prosting for magnetism at prosting for magnetism at prostating at plant at prostating at plant at mills plant at mills plant			purpose of . 231
picking at 167 177 178	for jigs at	603	Thompson's, bibliography for . 294
removal of jig tathings at 588 roasting for magnetism at 10, 111 Saldwarg table at 10, 111 Saldwarg table at 548 spire of jig sieves at 548 spire of jig sieves at 548 spire of jigs at 224, 225, 229 stroke of jigs at 224, 225, 229 stroke of jigs at 324 spire of jigs at 128 stunjus at 100, 111 spire of jigs at 128 stunjus at 100 strommels at terommels at terommels at terommels at terommels at terommels at 100 spire of jigs at 128 spire of jigs	trommels at	357	Will or 200
rostsing for magnetism at 106, 111 Saldaurg table at 518, 518 slope of pig sieves at 624, 225, 229 stroke of jigs at 224, 225, 229 stroke of jigs at 728, 729 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for crushing ore at 100 tests on work required for handling pulp, centrifugal and Frenier 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 sand and water 1610 water 1610 for handling pulp, centrifugal and Frenier 1610 sand and water 1610 water 1610 sand and water 16			Whelpley and Storer 289, 299
Salzburg table at 548 54	roasting for magnetism at	815	Pulverizing mill, Tustin's rotating . 262
Solar of jug sieves at 548 Splant at mills 1709, 1757, 1859, 1881, 1895, 1899, 1891 Stroke of jugs at 224, 225, 229 Stroke of jugs at 228 Stroke of jugs at 1610 Stroke of jugs 1899, 1	rolls at	0, 111	Pumping costs at Mill 180 1906
Spiriclution at 224, 255 229 water 1906, 1912	slope of ug sieves at .		plant at mills 1709, 1757, 1859, 1881, 1895, 1899,
Statistics of jigs at tables and vanners tables tables and vanners tables are tables and tables are tables at tables are tables at tab	spitalutten at	423	1906, 1912
tables at tests on work required for crushing ore at tests on work required for crushing ore at 305 termined at 1580 termined	Stamps at 224, 226		Pumps, bibliography for a 884
tests on work required for crushing ore at 305 trommels at trommels and warrent supply surface trommels and water supply and w	tables at 728	3. 729	centritugal . 1610
Pailor for gravity stamps 197 198 197 198 197 198 197 198 197 198	tests on work required for crushing ore at	305	sand
Pulley for gravity stamps 197 1522 1522 1523 1524 1524 1524 1525 1	Psilomelane specific gravity of	385	for handling pulp, centrifugal and Frener 1610
jus	Pulley for gravity stamps		sand and water 869
In gravity stamps 128 Oregon, five step 2033	jigs	532	water supply . 871
Pulp bed on vanners 661 Lancaster rotary 589 587 consistent y for Wilfley tables and vanners 1848 587		128	Oregon five step 2022
Culrow constraint Callow cone Calssification of Colorado Iron Works, slime tank Calssification of Colorado Iron Works, slime tank Large cones Calssification of Calcsis Carifornia Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Calssificatio	Pulp bed on vanners		Lancaster rotary 1589
Culrow constraint Callow cone Calssification of Colorado Iron Works, slime tank Calssification of Colorado Iron Works, slime tank Large cones Calssification of Calcsis Carifornia Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Callow cone Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Calssification of Colorado Iron Works, slime tank Callow cone Calssification of Calssificatio	consistency for Wilfley tables and vanners .	1848	sand 1587
For Anner feed 660 660 660 660 660 660 660 600	current in amalgamating pans		Punched plate iig screens at mills 1700 1800
In amalgamating pairs 246 Compared with wire cloth 171, 354	for vanner feed		screens 395
amount of tank room required per ton of roate- rial treated Mill 173 1413, 1880, 1885 Ayton internuttent thick pulp extractor 1408 Berenger and Stingls slime tank 407 Callow cone 1402 classification of 1401 Colorado Iron Works, slime tanks 1407 De Kall's perforated board classifier 1402 Merrill cylindrical clarifying tanks 1406 Richards-Shepard spitzkasten 1401 Richards-Shepard spitzkasten 1401 Sherman fanks 1404 Sherman fanks 1406 Sherman fanks 1407 Sherman fanks 1406 Sherman fanks 1407 Sherman fanks 1411 Sher in the Urals 2033 Shuringian in Siberia 2033 Shuringian in the Urals 2033 Shuringian in	in amalgamating pans	246	compared with wire cloth 171, 354
Tail treated Mil 1/3 1413, 1880, 1885 Ayton intermuttent thick pulp extractor 1408 Berenger and Stingls slime tank 1407 Callow cone 1402 Classification of 1401 Golden 1402 Classification of 1401 Igs 1407 Golden 1408 Igs Igs 1408 Igs Igs 1408 Igs Ig	amount of tank room required per the of the	1394	
Callow cone 1402 Purpose of classifiers 389, 1367 classification of classification of classification of classification of classifier 1401 jigs 494, 552 Colorado fron Works, slime tanks 1407 affecting number of sieves 589 De Kalb's perforated board classifier 1402 preliminary washers 1341 Merrill cylindrical clarifying tanks 1406 pulverizers 231 large cones 1406 rolk 62 Richards-Shepard spitzkasten 1401 stamps stamps Sherman fanks 1404 power and capacity of Huntington mill 280	riai treated Mill 113	1413	Purification of mercury 788
Callow cone 1402 Purpose of classifiers 389, 1367 classification of classification of classification of classification of classifier 1401 jigs 494, 552 Colorado fron Works, slime tanks 1407 affecting number of sieves 589 De Kalb's perforated board classifier 1402 preliminary washers 1341 Merrill cylindrical clarifying tanks 1406 pulverizers 231 large cones 1406 rolk 62 Richards-Shepard spitzkasten 1401 stamps stamps Sherman fanks 1404 power and capacity of Huntington mill 280	at mills 1413, 1880,	1885	Purington, C W, dredging in Siberia 2035
Callow cone 1402 Purpose of classifiers 389, 1367 classification of classification of classification of classification of classifier 1401 jigs 494, 552 Colorado fron Works, slime tanks 1407 affecting number of sieves 589 De Kalb's perforated board classifier 1402 preliminary washers 1341 Merrill cylindrical clarifying tanks 1406 pulverizers 231 large cones 1406 rolk 62 Richards-Shepard spitzkasten 1401 stamps stamps Sherman fanks 1404 power and capacity of Huntington mill 280	Ayton intermittent thick pulp extractor	1408	Purity of concentrates 2033
Classification of 1401 168 308 3	Callon cone	1407	
Merrill cylindrical clarifying tanks	classification of	1401	jigs 389, 1367
Merrill cylindrical clarifying tanks	Colorado Iron Works, slime tanks	1407	affecting number of sieves 589
Richards Shepard spitzkasten 1401 stamps 113, 1246 Sherman fanks 1404 power and capacity of Huntington mill 280	Merrill cylindrical clarifying tanks		preliminary washers
Sherman tanks	large cones	1406	
power and capacity of Huntington mill 280	Sherman fanks		
	oquimum manco		power and capacity of Huntington mill 280

Pages 1199-1610, Vol. III.	INL	EX.	Pages 1611-2052,	Vol.	IV.
Purtscher, E	1185	Ouickeilvor ora dansa			
Push conveyors	1584	ores the dressing of	d at Idria, Austria	• • • • •	481
at Mill 105	1637	Quincy granite, result	of crushing		33
Pushing block feeder	855	mill, stamps in			230
Purtscher, E. Push conveyors 1582, at Mill 105 1581, Pushing block feeder Putting on new shoes Putty knile for scraping plates Pyramid form of trommels Pyramyrite specific gravity of Pyrite and blende separation angle of nip required to crush concentration in New York crushed in Mill 13 dressing in Massachusetts. J. J. Rutledge plant of the Verein Chemischer Fabriken for j.ig beds	201	Dractice of t	d at Idria, Austria of, of crushing gan he. C K. Hitchcock, Jr.	9027	2041
Putty knife for scraping plates	762	Mining Co.	C R. Intelledek, Jr.	1181.	1908
Pyrargyrite, specific gravity of	301 1180	copper handboo	k		1925
Pyrite and blende separation	900	шш		. xxvi	i, 998
angle of nip required to crush	94		R		
crushed in Mill 13	2038 47	Robors W A		•	
dressing in Massachusetts. J. J. Rutledge	2038	Radiators for heating	ting graphite from gang	ue	1186 1099
plant of the Verein Chemischer Fabriken	1914	Radium, atomic weigh	tof		1188
in New York, concentration of, R. Brinsmade	2037	Radius of slime tables Raff wheels			697
mill for	, 965			864,	1715
ore mill for 000 000 010 010	2047	for new Humbo	ldt concentrator		1494
test on	1165	Wilfley table Rag frames	ldt concentrator		1468
plant of the Verein Chemischer Fabriken for j.g beds in New York, concentration of. R. Brinsmade mill for 904, 905, 958, 961, milling in New York. ore, mill for 900, 909, 910, 913 test on weight of rendered magnetic by heat roasted for magnetism porosity specific gravity of with quartz and porphyry crushing in Mill 20 Pyrollusite, specific gravity of Pyrometer for regulating temperature in Willey fur-	1190	Ragian Township One	السان سنالية	1083,	1507 1078
rendered magnetic by heat	814	Kathi mili at		1177,	1185
porosity	828	rolls at Salzburg tables at			110
specific gravity of	1189	Railway Master Mech	anics Association on so	TAOD	1115
With quartz and porphyry crushing in Mill 20 . Pyrolusite specific gravity of	95	gauges	·· · ·	recu	173
with quartz and porphyry crushing in Mill 20 Pyrolustic, specific gravity of Pyrometer for regulating temperature in Williey furnace Pyromorphite, specific gravity of Pyrosene, specific gravity of Pyrrhoute, hindered-settling test on 617, settling velocity of 466, specific gravity of	1100	Rain to settle dust Rainy River district, ()			1099
nace	1548	Rakes for discharmer	ur concentrator		1178 502
Pyroxene specific gravity of	1189		igat .		492
Pyrrhotite, hindered-settling test on 617.	619	Duning taine at .			670
settling velocity of	469	Dicking at	1086, 1102,	1121,	487
specific gravity of	1189	sieve scale at			367
Q		mill at picking at sieve scale at Ramsey sludge tank Rand, cost of hand pic district, circular ta	libra and all a		446
Overlos miss. Herete et a seill et	801	district, circular ta	king on the		491
Quaker mine, Huntington mill at Ouality of copper for plates	281 747	samping in			849
crushing by breakers	47	tailings wheels in weight of quartz	1		865 1160
Quality of copper for plates crushing by breakers rolls feed for vanners	98	hand picking on the metallurgical practi G. A. and H	ıc.		492
product of Blake and Dodge breakers com-	658	metallurgical pract	ice .		1419
pared	36	G. A. and H	S. Denny		$\frac{1923}{2041}$
work of classifiers trommels	461 380	milling practice	3. A and H. S. Denny		2013
Quantity crushed by rolls	100	mills on the			1185
of hydraulic water in jigs	598	ores, slimes from slime treatment on Randalph L.C. b. ame	the .		1121 1410
water for stamps in rectangular launders on circular slime table.	221 878	attandorphi, j. C. I., and	algamation plant at Bate	pilas	
on circular strine tables	694	Cmmanua,			1174
vanners	659	Blake breaker at breakers		•	57 57
	118 7 1577	dressing at Claus	thal		1174
Quartering, toning and for sampling Quartz and galena, jig tests on used for film-sizing tests sphalerite, jig tests on angle of nip required to crush	844	gravity stamps			220
Quartz and galena, jig tests on	62 9 707	pointed boxes at	Clausthal		640 476
sphalerite, jig tests on	628	rolls at Clausthal			109
angle of nip required to crush	94	stroke of jigs trommels at Clau	s that		594 385
free-settling velocity	707 471	mill, acid water Range of sizes fed to jig			173
grinding of	2017	Range of sizes fed to in	gs .		$\frac{606}{354}$
hindered-settling test on 617,	622	Rapid City chlorination Economy individual	works, trommets at		1266
sphalerite, its tests on angle of nip required to crush files-sizing tests on free-settling velocity grinding of hindered-setting test on in Banner mine mill, Bryan roller ore capacity of Trempin stamp for	271	Litumn		1961	1278
mill, Bryan roller ore, capacity of Tremain stamp for pulsion ng test on 624,	138	a camless stam	P . Ranid Economy s		2012
	625	stamp	p y, Rapid Economy s _I	1261. 1	1278
ing Company separating chalcopyrite or blende from separation from gold by amalgamated copper plate	674	Rasch, ball mill of Siller	r and Dubois		293
separating chalcopyrite or blende from	720	Rate of travel of ore in Ratio between quartz an	trommels	i	375 1460
separation from gold by amalgamated copper	4	total horse power	and that to overcome gra	ng 1	1 % (A)
settling velocity of	469	in gravity stam for currents in testi	Ja		205
specific gravity of	189	for currents in testii	ng classifiers		1146 1430
in Mill 4	202 502	hindered settling			617
separation from gold by amagamated copper plate settling velocity of	190	free to hindered sett hindered settling from experimen theoretical valu	nt		428
Quartzite, picked from gold in rock houses in the	489	of concentration	e for see Individual Mills in C	hap-	427
strength of	301				
weight of 1160, 1 Quartaire, picked from gold in rock houses in the Rand, South Africa strength of Quebec asketos dressing practice Queen & Co.	916	feed to space bety	ween rolls		90 763
Queen & Co. 1 Mary colliery, centrifugal apparatus at 820,	159 838	gold to silver cau	ght on successive plates	t	703 1226
Quéhant, Ch. and O. Dupont, dressing lead and zinc	000	reduction for rolls gyratory brea sieve hole to jig f Ratios for free settling hindered settling	kers	i	218
	185	sieve hole to jig f	eed	400	573
Quenching for breaking rock after heating	9 785	hindered settling		469,	625
Quicksilver. See Mercury.		sieve scale			367
Quicksilver. See Mercury. mill for	183 70	tree settling of quar	tz and galena	1	420

Duting from to hindand adding and the day of the	7) 1 4 7
Ratios free to hindered settling, application to classi- fier design	Removal of jig tailings 587
	1
or setting, definition of	4 sticks, bolts, pick points, etc
weights or stamps and mortals 10	4 wood at Mill 164
table of free settling	9 Irom ore previous to crushing at Mill 164. 1849
Rauft, T., gravity stamps	5 Repairs. See also each machine. 7 cost of for breakers
Ray Copper Company, the mines of the. A. Hill . 203	6 in vanners
Raymond automatic pulverizer 23	
George P., separation by decrepitation and	on Blake breakers
screening . 156	5 jigs 604
roller mill 2014, 201 R. W 88	7 rolls, cost of 104
amalgamating pans 29	Treatment adjusted acparators, cost of 1020
Balch's magnetic separator 83	Reports
breakers 5	7 Repumping water 1104
Crocker's stamps 22	9 Reserve caracity in mills
double cone classifier 42	b Reservoirs charifying 460
gravity stamps 22 jaw plates 5	for water. See Individual Mills in Chapter XX.
mortars 23	
sampling in testing mills	0 Residue after retorting 783 5 Residuum oil for separation 831
weathering at Meronitz, Bohemia 83	y for oil testing . 1155
Reaction wheel for sampling 84	8 Resin for Lelts . 1094
Read, Thomas I', absorption of mercury by amalga-	smoking moulds 784
mating plates 151 amalgamation of gold ores 152	5 Respirators
effect of temperature on amalgamation 151	
Realgar, specific gravity of 118	
Realgar, specific gravity of 118 Reardon, Ph., Colorado gold stamp mills 118	free settling tests 466
construction of jigs 64	3 the tubular classifier tests 613
Receipts 112	4 Von Reytt's Lower and surface measurements 306
Receiving cone for frommels 35: floors 84:	Retorting amalgam • 781
Recovery of brass from chips . 202	ś loss in 783
gold from ashes 177, 70:	
from waste 48	
gold in different parts of mill 74	scaing or 1919
metals from skimmings 202	5 Revenue tunnel mill 021
in refuse 202	Mines Co , mill xxxx 928
waste in stamp mill 26 Rectangluar buddle 70 Red Metal Mining Company 183	6 Reverberators furnaces for reasoning 814
Rectangluar buddle 70	for porosity 829
Red Metal Mining Company 183 River, Cornwall, tin washing 118	previous to magnetic separation 1544
tin works 108	
Reducing roast for magnetism 199	
Reduction, amount of, in rolls 9:	
of iron ore to magnetic oxide 813	3 Revolutions See speed.
ratio of, for gyratory breakers 121	and periphery speed of rolls 87
with rolls, diagram of percentage 122	ot rolls . 88
Reed dry placer machine 83 S.A. sampling 88	
Reese River process of applicantation 248, 1030, 117	5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
Refining at Mill 117 167-	† trommels . 349 † Revolver for bottle tests . 1157
Reiming at Mill 117 167- cost at Mill 106 164 plant of Mill 106 164	
plant of Mill 106 164	3 convex slime tables
Reflectoscopy for measuring mineral grains . 1990	689 convex slime table. Clark table
Re grinding machines 201	devices used on . 689
M. Schwerin 1344 relative efficiency of 133	
Regularity in feeding 111-	
Regular mill testing 116	
Regulation of height of discharge in stames 915	
temperature in Willey roasting furnace with	driers 880
	3 at mills
Regulators for water 855 Reichenecker, X., amalgam 788	Knife buddle 328
Reichenecker, X, amalgam 788	
dressing gold ores in Colorado 1177 gravity stamps 224, 229	
Reifsnyder, Shimer and, sampling 888 Reinforced concrete hins at Mill 160 183; Relation of angle of mp of rolls to feed and space 99	
Reinforced concrete bins at Mill 160 1833	
Relation of angle of mp of rolls to feed and space 92	
rous to angle of mp 94	octagonal 1353
speed of current to size of grain in settling	revolving grizzly of the Denver Engineering
tanks 452	
surface to diameter of ore particle 305	sectional 1353
weight to surface of crushed product o 310 Relative proportion of gold and silver in daily amal-	
gam as compared with hard amalgam . 762	strakes
TOZ	
on successive plates . 763	
on successive plates . 763 Rehance rolls 82,111	Corliss engine
Rehance rolls 82,111 at mills 1750, 1751, 1752, 1822, 1825	Corliss engine
Reliance rolls 82,111 at mills 1750, 1751, 1752, 1822, 1825 self tightening cam 229	Corliss engine . 1003 Edvin viii mill, fineness of amalgam . 764
Reliance rolls 82,111 at mills 1750, 1751, 1752, 1822, 1825 1826 1826 1827 1828 1827 1828 18	Corliss engine
Reliance rolls 82,111 at milk 1750, 1751, 1752, 1822, 1825 self tightening cam 229 Relutance in magnetic field 782 Remedies for sickening of mercury 751	Corliss engine
Reliance rolls 82,111 1750, 1751, 1752, 1822, 1825 1826	Corlise engine
Relance rolls 82,111 at mills 1750, 1751, 1752, 1822, 1825 self tightening cam 229 Reluctance in magnetic field 702 Remedies for sickening of mercury 751 Remedus district, Colomba, mill in 1182 Removal of amalgam from plates 757 coarse concentrates in igs 576	Corliss engine
Reliance rolls 82,111 1750, 1751, 1752, 1822, 1825 1826	Corliss engine

Pages 1199-1610, Vol. III.	IND	Pages 1611-205	2, Vol. IV	V.
Reytt, K. von, Karlik gyrating screen screen and jig at Przibram Linkenbach tables mill machines moisture in drained ore rolls versus other crushing machines Schranz mill Rheinpreussen colliery, air blast at 83 Hochstedt apparatus at Rhenish provinces, mills in Prussia, pakking in Rhodesia, S. Africa, milling practice at. F. C. Roserts	386	Rickard, T. A., amalgamation	7	87
screen and jig at Przibram	1185	at Ballarat, Australia		88
mill machines	1177	Hidden Transura mill Color do	7	88 88
moisture in drained ore	1185	Alexard, 1. A., amalgamation at a Ballarit, Australia Clunes, Australia Hidden Treasure mill, Colorado Premier mill, Otago, New Zealan in the Thames district, New Zealan breakers	d 7	88
rolls versus other crushing machines	112	in the Thames district, New Zealan	d 7	88
Schranz mill	296 7 838	breakers canvas and blanket tables, vanners an		56
Hochstedt apparatus at	816	ing tables	7.	28
Rhenish provinces, mills in	1176	Colorado system versus California syste	m 227, 11	75
Prussia, picking in	481	Colorado system revsus California syste copper mills of Lake Superior Gilpn County, Colorado, and C methods of gold stamp milling gold milling in Australia stamp mills at Bendigo, Australia Clunes, Victoria Grass Valley, California Otago, New Zealand Thames, New Zealand in Amador County, Colorado the Black Hills, South Dakota the Overn Sdisrict, Victoria	alifornia 14	19
Rhodesia, S. Africa, milling practice at. F. C. Roserts Rhodium atomic weight of Rhodochrosite, specific gravity of Rhodonite, specific gravity of Rhyolite, weight of Ribbon theory of roll capacity Ribtet aerial tramway at Mill 124 Rice, C. T., Kinkead mill at Goldfield, Nevada milling at Virginia City, Nevada Richards annular vortex dassafer 406	2044	methods of gold stamp milling .	11:	81
Rhodium atomic weight of	1188	gold milling in Australia .	11	80
Rhodonite specific gravity of	1189	Clunes, Victoria	. 11 11	50
Rhyolite, weight of	1190	Grass Valley, California	11	80
Ribbon theory of roll capacity	101	Otago, New Zealand	. 118	
Rice C T Kinkead mill at Goldfield Nevada	2038	in Amador County California		80
miling at Virginia City, Nevada	2038	Gilpin County, Colorado	. 11	80
miling at Virginia City, Nevada Richards annular vortex classifier at milis 1692, 1693, 1694, 1710, 1711, 1712, 1751, 1752, 1753, 1755, 1774, 1775, 1716 classifiers at milis	, 1382	the Black Hills, South Dakota the Ovens district, Victoria gravity stamps mill of the Guanajuata Reduction 8	11	81
1751 1752 1753 1755 1774 1775 1776	1778	gravity stamps 223	224 226 2	28
1816	1867	mill of the Guanajuata Reduction &	& Mines	
classifiers at mills. 1829, 1885 Coggin hydraulic classifier . 391 at mills 1878, 1879, 1896 details of in mills 1878, 1879, 1896 J. centrifugal pumps jig discharge other combons	, 1886	gravity stamps 223, mill of the Guanajuata Reduction & Company, Mexico milling in Lake Superior	. 20	45
at mills 1878 1879 1806	1898	miling in Lake Superior . mills at Bendigo, Australia	. 19	97 88
details of in mills	393	mortars	164. 1	65
J., centrifugal pumps	884	narrow sluce plates order of drop of stamps	7.	88 15
		plates and traps in the Black Hills	7	88
pocket vortex classifier	1373	plates and traps in the Black Hills and at Grass Valley at Gras Valley, California in Amador County mills, California the Owner and St. W. St. was the	7	88 87
pulsator classifier	1419	at Grass Valley, California	. 7	88
direct form fourteen-day test at Mill 162 nine-day test at Mill 162	1391	the Ovens district, Victoria		88 88
nine-day test at Mill 162	1394	pheumani contentration .	8	37
	1.590	removal of sulphurets from mercury rock breakers	7	37 70 56
ig 1453 depth of bed	1459 1456	shoes and dies	181, 1	83
iig 1453 depth of bed	1455	size of plates	7	88
size of feed for	1456 1155	sluice plates stamp milling	1020 11	40
test on	1456	of gold ores .	1000, 11	XX
Rapid Economy stamp R H. and Locke, C. E., dressing of tin ores tests on a surface current locat classifier A. E. Woodward, curves for free-settling particles from kittinger's formula	2012	of gold ores . in United States, Australia, a Zealand mills at Ballarat, Victoria	nd New	
tests on a surface current box classifier	1924 477	mills at Ballarat, Victoria	2	27 26
A E Woodward, curves for free-settling	•••	Clunes, Victoria Otago, New Zealand Thames, New Zealand in the Black Hills	2	26
particles from Rittinger's formula	476 2047	Otago, New Zealand	2	$\frac{126}{26}$
concentration of black sands edge runners	295	in the Black Hills	2	27
experiments to determine Lius of jugging	640	and at Grass Valley Gilpin County, Colorado	11	76
glass classifier and slime table gravity stamps Richards-Coggin classifier school laboratory work a free milling gold ore clayer dustifiers and lines.	1176	stamps for different purposes	2	$\frac{26}{27}$
Richards Coggin classifier	476	steam stamps for gold in Black Hills .	. î	42
school laboratory work a free milling gold ore .	2048	water used in stamp mills	. 2	22
sieves, Classifiers, and jigs	1175 787	Ricketts, L. D power tests by	18	375 127
steves, classifiers, and jigs silver amalgam slime tables spitalute spaty of the Wilitey table on different feeds testing a jig for a mill process	728	Riddles	341. 3	184
sputilutte	476 1511	and vibrating grizzhes comparison of	13	346 345
on different feeds	2022			165
testing a jig .	1176			
for a mill process	1183 1174	washing clays Riffle bars on revolving strakes	mels 3 1183, 11 7	.86 195
typical methods of milling in Missouri	2040	blocks .	· ···· 7	21
typical methods of milling in Missouri undercurrent for saving black sands 1419 velocity of galena and quartz falling in water	, 2020	boxes, with mercury cleats, arrangement in Deister concentra		24
velocity of galena and quartz falling in water	2020	cleats, arrangement in Deister concentra	tors 148	on 189
particles falling in water	. 476	cast rubber for copper	14	87
shallow pocket classifier hindered settling classifier	401	copper		186 181
hydraulic classifier, estimated capacities o	1384 f	for Deister concentrators for New Standard concentrator		88
with different sizes of sorting columns sizing test of products of	405	for New Standard concentrator	14	179
Shepard spitzkasten 140:	406 1, 1419	Willey tables .	14	68
tests of power required in crushing by rolls	. 311	Deister concentrators for New Standard concentrator Wilfley tables height of material for	14	167
		tacking on versus grooving .	14	198
undercurrent	1872	grooves of Card concentrator, shape of tables	670 11	183 120
undercurrent Richardson automatic weighing scales at Mill 132 C. S.	1727	mills	10	004
C. S. •	1276	on dredges 10	07, 1008, 10	112
order of drop of stamps Rich ore picked out for economy	1278 . 481	Riffles	7	$\frac{707}{123}$
treated separately	. 1111	mills on dredges 10 Riffles 10 splication of 10 bar 10 billiography for	7	/21
	. 1923	bibliography for		727 509
amalgamated plates 735, 737, 745, 74	7, 750,	cocoa matting, expanded metal and iror	n mesh in	
adaptation of gold stamp mills amalgamated plates 735, 737, 745, 74 amalgamating pans	68, 7 47 290	dredges	768	$\frac{653}{770}$
emerikementik beng	200		,	

Page 3/643, Vol. I.	OLE	DRESSING.	Pages 644-1197, V	'ol
Riffer containing mercury, advantages and	disad-	Rittinger P R vo	n, movable and fixed sieve ji	
vantages depth of bed expanded metal		71 setzpu	mpe boxes, spitzlutt, runs	B01
		11 pointed l	oxes, spitzlutt, runs	
expanded metal	٠.	44 schieuder	munic	
mercury traps		72 settlers	n by centrifugal force	٠.
sampling	844, 1		e and Harz jig	٠
forms of used in sluices		21 sieve scal	e and Harz jig e, screens, riddles and trommels	
Used in stuices .		23 Sixuing .	ing cobbing hammers	
Grass Valley Howland		io ttough w	ashers	
Hungarian		22 rectangular b 25 roll speeds	adde	•
La Point suspended riffles		09 round convex	buddle	•
on dredges		12 rule for middl	ings	::
tables advantages of	675-6	19 runs	•	٠.
Wilfley table		79 separation by 72 setzrad	centrifugal force .	
Wilfley table		22 sieve scale		e e
principle of		44 double	30	
revolving strakes	7	25 for test	ing screens	:
Robinson		21 skimming siev	res	÷
rock . sluice		21 Stope of jig sie	eves	
timber riffle blocks .	. 14	64 tables 21 spalling		٠.
undercurrents		26 specific gravity	u tost	٠
use upon slimers .	14	98 spilzkasten	, test	33,
Rigid rolls	112, 20	to principle		
at mills 1237, 1865, 1893	, 1901, 19	06 spitzlutti Stay battery	422, 424,	477
Denver Engineering Works Company, d	escrip-	stay buttery		
Right and left hand cams		35 and overf 95 stroke of jigs	low battery	
Ring and cone for sampling		95 stroke of jigs 44 sweeping table		
for amalgamating pan		44 table		•
stamp cams		92 compared w	ith Wilfley	
head		85 theory of adva	ntage of jig over free settling	•
Steam stamps Rings, details of, from mills		20 Crusning		
Rinsing cylinder		22 jigs 35 thickness of sc		
table for hand picking		35 thickness of se	reen plate	
Risdon Iron Works	viu. 18	59 Velocity of stre	Le of nos	
amalgamating tun 943 944 945 9	246, 247, 2	49 Wash trommel	•	
Blake Dreaker		22 width of jig si	eves	
Bryan mills at Mill 173 Clean-up pan	19	28 Kiver dredging for	gold	
crack proof vanner belt .	15	51 pebble phosph	ate .	
dredge	16		l pyrite, jigging of	
open-connected type	16	54 arsenopyrite fo	or magnetism at Mill 185	
vanner	651, 6	az tor madiny	56, 57,	58,
weight of spider and driving cone mad	te by 2	47 leaching		
Rittinger, beveled rolls capacity of jigs		71 magnetism	790, 799, 800, 813, 1543, 154	
Coarsest size ingred		97 at Mill 14 05 bibliograp		
coarsest size jigged concave buddle		06 effect of c		
double trough classifier			its in roasting pyrite	
duck tables	7	02 in testing		
feeding rolls		71 minerals	which become magnetic on roas	st-
figures on hand ng		19 ing		
formula for amount of throw of jigs free setting	471, 14	35 use made 21 porosity	of, in mills	
hammers for breaking		11 wolframite i	828, 839, 89	<i>7</i> 0,
hand jigs	497, 4	9 furnaces		
jig	6	13 at Erredrichs	ssegen, Germany C	
mechanism	5	37 mills .	1663, 1747, 1759, 176	55,
plunger clearance length of jig sieves		ou Dings	•	
movable, sieve power jig	. 5			
parabolic formula	4		148 . 179	19
pointed boxes	411, 4	19 Mathey, at 1	Mill 148	, £,
tables of sizes of	4-	O McDougall 1	ype .	. :
power for jigs required for crushing	60	3 ⊙xland furn	ace .	
principles of ore dressing	3	Trego	v	
principles of ore dressing P. R. von 330, 334, 342, 434, 1038	1050 117		8	
amalgamation	, 1003, 110		же	
DIAKE DICAKET			ower required for crushing	
breakers, hammers, and toasting for fri-	ability !	6 practice. Wisco	nsin	•
buddles, percussion tables, slime table	s 7	8 silver ores		. :
Carr disintegrator , cone mill	29	8 tin ores		
crushing machines	29 3		um sulphate .	
details of hand picking	49	2 Davion Nevel	nalgamation and concentration a	11 . :
edge runners .	29		disintegrator	: '
elevators, sand wheels, and conveyors	- 88	restor const	ructing a 20-stamp ma.	:
fluted rolls	. 10	9 Huet and Ge	eyler's ing	
gravity stamps grist mill or buhrstone mill Harz jigs movable sieve jig	25	3 North Star st	tamp mill at Grass Valley	1
Harz nes monable neve sig	6	Koberts, slime table	or 805, 859, 1585, 1610, 203 336, 1687, 1661, 1727, 1750, 1808 108, 1809, 1810, 1811, 1812, 1813 23, 1824, 1825, 1826, 1828, 1870	
	62	a Accounted mine mill		1
Lehrbuch		x Robins belt convey	N 805 850 1505 1610 000	11 .

ages 1135-1010, voi. 111.	111 DB	1 ages 1011 2002, vol. 1
obins belt conveyor in Blaisdell system		Roll shells, truing with emery wheel 12
stamp mus	2031 1438	wear of 65,
picking belt		Rolls
at the West Aurora mill Thomas, Jr., Robins belt, rollers, etc. obinson coal washer (classifier)	884	action of on ores
obinson coal washer (classifier)	478	Allis-Chalmers
Deep Gold Mining Co., Lid., mill of	1648	Reliance
Diamond Mining Co	839 1184	an article on
gold mine, mill at	504	
mill, details of stamps .	221	as regrinding machine 1332, 13
rine	721	at mills 1244, 1667, 1685, 1686, 1688, 1689, 169
washer for coal	447	1691, 1693, 1701, 1707, 1710, 1716, 1720, 1724, 173
oche-la-Monere colliery, coal washing at	2050 493	1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760, 176
sche-la-Mohere colliery, coal washing at schelt, F., automatic slate picker for coal s scheux, double discharge on jugs at	584	Argal rolls as regrinding machine at mills 1214, 1667, 1685, 1686, 1688, 1688, 1689, 169 1, 1693, 1701, 1707, 1710, 1716, 1720, 1724, 173, 1748, 1742, 1743, 1749, 1760, 1751, 1752, 1760, 176, 1766, 1767, 1771, 1772, 1773, 1792, 1793, 180, 1806, 1807, 1808, 1819, 1822, 1824, 1825, 1828, 183, 1834, 1834, 1834, 1834, 1834, 1834, 1837, 1838, 1834, 1835, 1836, 1867, 1877, 1877, 1877, 1878, 1869, 1877, 1878, 1879, 1879, 1877, 1878, 1879, 1879, 1877, 1878, 1879, 18
ork oreakers. See dreakers, Jaw Dreakers, Spin-		1832, 1833, 1837, 1838, 1843, 1844, 1853, 1854, 185
dle Breakers.		1859, 1864, 1865, 1866, 1867, 1868, 1869, 1877, 187
Breakers Gates' style "K"	13 1207	1863, 1890, 1910, 1913, 1928, 1929, 19
Hathaway gyratory	1215	auxiliary spring babbitting
in reserve	1109	Becket Foundry & Machine Co
kinds of	13	belted
Krupp	1202	and geared beveled
gyratory logation of	1215 1109	beveled
location of McCully gyratory	1210	Birmingham Iron Foundry
method of operating .	13	Bowers 1
separate motor for	1092	boxes or bearings for
emery mill 232	, 253	Buchanan . 64, 100, 106, 1226, 20
bibliography for horizontal	291 255	capacity of . 64, 100, 106, 1226, 20 speed, power, wear, etc.
vertical .	255	Chicago Iron Works
house, picking in	482	choke and f ee crushing by .
houses 483, 485, 991, 995, 998, 1000,	1109	classification of
powders, effect of water on A. S. Cushman rifles	$\frac{1419}{721}$	coarse and line C. Blomeke
cker .	723	compared with stamps
cking stone mill	1084	Sturtevant mills
table 320,	1032	comparison between free and choke fed rolls 12
cky Mountain mill xxix,	1048	convex and concave
dda, J. F., new form of stamp	228 1195	core of corrugated 106, 1
ebling ebling's gauge	1193	rolls and rolls with inserted teeth 12
Screen gauge	173	table of sizes, capacities, and
screen gauge ogers, A N	787	power 15
Colorado versus California system of milling	1174	cost of crushing by
data concerning slime tanks	1408 , 226	repurs on
gravity stamps 224 gers' dewatering screen	1591	diagram of percentage reduction in
at Mill 144	1592	diameter of
jig	642	different types of 20
hrmuhle	293	discussion of 20
lker, C. M., Allouez mill, Lake Superior Ball stamp	1174 142	driving mechanism Fagle Foundry Co.
Collom jig at Lake Superior	640	Eckart
concentration at Glasdir, Wales	1183	Edison's 110, 1
cross pieces on jigs Evans slime table and kieve	551	corrugated .
Evans slime table and kieve	728 476	gunt three high
hog trough classifier m il l capacity	1109	effect of ores on angle of nip
milling in Utah	1174	efficiency of
dled saw plates at Mill 180, life of	1902	E P Allis Co. 72,
steel for wearing parts of rolls	1243	features and faults of
ller feeder	854 1303	feed to 63, 12 feeders for
mills Griffin	282	feeders for
Huntington centrifugal .	276	fines produced by
Kent mill	1303	finger geared 77, F. M. Davis Iron Works Co.
number used	231	F M Davis Iron Works Co.
table of details of Kent mill	1304	formula for angle of mp for removal of vanner concentrates
Wild mill table of sizes, capacities, power, weight,	1304	vanners 652,
etc	1304	Fort Scott Foundry & Machine Co 76,
quartz mills, Bryan	271	frames of
shells for Huntington mill	280	Fraser & Chalmers
llers for belt conveyors	859 646	geared Fulton Iron Works
on vanners Il jaw breaker, Sturtevant	32	Gates Economic
Blake breakers, Sturtevant	1205	Iron Works
Blake breakers, Sturtevant crushing, R. K. Humphrey L. H. Sturtevant	2010	geared .
L H. Sturtevant .	2010	and belted compared .
SDEUS	1710	general construction Gever
	1716	Gever 70, 1
at Mill 129		
cost of	69 70	G. V. Cresson Co
cost of	70 68	G. V. Cresson Co
cost of	70	graded crushing by G. V. Cresson Co. Hendy & Meyer hexagonal cores high-speed

Rolls, high-speed versus Bryan mills	1309	Rolls, Tuttle Manufacturing & Supply Co	76
hoppers and housing horse-power of Humboldt high-speed rolls	83	types of	.75
Humboldt high-speed rolls	1241	use of for brittle ores	314
rumpiney rous	. 1201	used in brick manufacture 2	011
table of sizes, power, speeds, weights,	etc 12 35 1017	velocity of approach in	314
in stamp mill journal friction	95	Chili mills for clays	010
in stamp mill journal friction J. W. Jackson's kept true Krom belted	72, 76, 111	Rolls, Tuttle Manufacturing & Supply Co. types of Union Iron Works	298
kept true	70 82	gravity stamps	222
Gates, and other makes . 109, 11		Heberli mill	258
Gates, and other makes 109, 11 Krupp high speed	1238	Huntington mills	110
lever and weight made by Power and Mining Machinery	. 13	stamps	314
IMDV	1245	at Mill 179	900
material for wearing parts of	1243	Sturtevant mill	111
materials cost, wear, etc. McFarlane	66 72 76, 1232	Sturtevant mill Vezin, made by Colorado Iron Works Wallburn-Swenson Co. Wall's corrugated finger gear W F. Mosser & Co width of Wibls	84 76
McLanaban and Stone single-roll crusher	1241	Wall's corrugated finger gear	
method of cleaning M. Hoagland Sons Co	2011	W. F. Mosser & Co	76
M Hoagiand Sons Co Milburn's crusher	111	Wilds	83 72
Montana Iron Works	76		110
Neuerbergs	110	nate natities	109
Odell's	. 990	knols teeth	$\frac{100}{112}$
on native copper ore periphery speed and revolutions pillow blocks and alignment	88 71	sluggers and knobs	104
pillow blocks and alignment	71 80	without springs	74
for Pittsburg Foundry & Machine Co.	. 76	Roofs for mills	121 188
power and wear	108	Root rotary pump	Ĵ89
for	95, 106	sluggers and knobs without springs Rompf jig screen C. Blömeke 22 Roofs for mills Roof rotary pump 982, 5 W A , the Macquisten flotation process Cape convevors, picking on drive for sand wheels trainway 982	130
pressure exerted by . of .	311 108	drive for sand wheels	266 266
on	. 73		
principle and purpose of	62 1 2 24		094
of roll crushing products crushed by	63	Ropes, L. S., mill of Isel Corundum Company, Georgia . 11	183
proper amount of reduction	92	Rosales Henry auriferous quarte in Victoria 11	176
quality of cr u shing by ram for	98 112	gravity stamps Rose, T K	$\frac{224}{787}$
ratio of feed to space	90	amalgamating pans	290
reduction	1226	amalgamators .	290 787
relation of diameter, feed, space, and an	gle of		290
speed to angle of mp	94	blake and Schranz Breakers, Dodge and Gates breakers clean up Jain Crawford mill Cycloja mill cylland breakers and win reak	56
trommel hole to roll space	.95	clean up pan	291
Reliance ribbon theory of capacity	111 101	Cyclops mill	$\frac{295}{294}$
riou)	112 1235		174
Roger's	74, 110, 111 88		223
running at different speeds Schellenbach Sons	76	Harz jigs Huntington mills	639 297
Schwarzmann's	109, 110	riusiking pheumane and ratterson elephant	
scrapers for sectional	75 81	spring stamps 1 Jordan's centrifugal grinder 2	143 295
shaft, journal speed, etc.	76	Krom jig and Clarkson-Stanfield machine 8	295 837
shafts	65	rolls . 1	109
shims for side adjustment	74 71	large steam stamps	142
size of feed	90	lime for slime settling c14 metallurgy of gold pointed boxes	XX
speed, capacity, etc	107	pointed boxes 4	4/n
SIZES OF	$\frac{64}{72}$	reforts	783 385
sizes of speeds, etc treated by	63	ain af atomorphisal	207
weights, and specus	79	No cocity, D. C, concentiation at. 11. 11. 17yer 20	043
sizing tests on test on pulp of coarse and fine rolls at	99, 315 Mill	Roskelly I stamp mill construction 1 uscany 11	1//
162	1328, 1329	Ross, J., Jr., Wildman and Hector gold stamp mills 11	184
spaces between	64, 89 104	Rossland district, B. C., milling in the. R. Hookes 20)46
special forms speed of	64, 86	Rosenlecher, R., dressing quarksilver in Tuscany Roskelly, I., stamp mill construction Ross, J., Jr., Wildman and Hector gold stamp mills 11 Rossland district, B. C., milling in the. R. Hookes Rotary breaker at Mill 186 drier at Mill 186 percussion table, Bartsch pumps Rotation of gravity stamps	,17)17
rolls and speed curves	1224 72	percusion table, partient 13	197
spring pressures on	72 96	pumps 8 Rotation of gravity stamps 1 Rothwell, John E, belt elevators 8	371
affecting friction springs or weights for	73	Rothwell John E belt elevators	194 884
springs or weights for S. R. Krom's	72,77	rolls for chlorination process	111
Sturtevant balanced rolls	1232	R. P., Blake breaker in Ontario mill	57 57
table of sizes, power, weight, dimen	sions, 1234	Linkenbach tables 7	57 728
centrifugal rolls	74, 1237	Ontario Silver Reef and California silver	
Superior crushing rolls	1231 64	mines in Nevada	174
table of data from the mills value of forces acting at different angles	94	Rough-crushing department at Mill 159	SU2
tests on work required for rolls	306	Roughing jig	394
Thum's compound toothed	110 1243, 2010	Roughing jig st Mill 148 17 plane, definition of 14 (Roughness, effect of, in launders 18 pages 19 plane) and the plane of	/92 465
table of sizes, capacities, and power .	1243	'Roughness, effect of, in launders	377
Triplex rolls	1239	Rough, unplaned pine board surfaces used as plates	756

1 4500 1100 1010) 1 111 1111		
Robins belt conveyor in Blaisdell system	1602 F	Roll shells, truing with emery wheel 1243
stamp mills	2031	wear of 69
picking belt	1438	tires 65, 66
at the West Aurora mill	2021 F 884	Rolls
Thomas, Jr., Robins belt, rollers, etc Robinson coal washer (classifier)	478	action of on ores 62 Allis-Chalmers 1244
Deep Gold Mining Co., Ltd., mill of	1648	Reliance
Diamond Mining Co	839	an article on
gold mine, mill at	1184 504	angle of nip for 89, 109, 110, 1226 Argall rolls 1230
jig mill, details of stamps .	221	
rifle.	721	at mills 1214, 1667, 1685, 1686, 1688, 1689, 1690,
washer for coal .	447	1691, 1693, 1701, 1707, 1710, 1716, 1720, 1724, 1737,
Roche-la-Mohere colliery, coal washing at Rochelt, F., automatic slate picker for coal. Rocheux, double discharge on jugs at	2050	as regrinding machine 1532, 1333 at mills 1214, 1667, 1685, 1686, 1688, 1689, 1990, 1691, 1693, 1701, 1707, 1710, 1716, 1720, 1724, 1737, 1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760, 1761, 1762, 1766, 1767, 1771, 1772, 1773, 1792, 1793, 1803, 1806, 1807, 1808, 1819, 1822, 1824, 1825, 1828, 1829, 1823, 1823, 1828, 1827, 1828, 1829, 1828, 1829,
Rochell, F., automatic state picker for coal.	493 584	1702, 1700, 1707, 1771, 1772, 1773, 1792, 1793, 1803,
Rock breakers. See Breakers, Jaw Breakers, Spin-	004	1832, 1833, 1837, 1838, 1843, 1844, 1853, 1854, 1857.
dle Breakers.		1832, 1833, 1837, 1838, 1843, 1844, 1853, 1854, 1857, 1859, 1864, 1865, 1866, 1867, 1868, 1869, 1877, 1878
breakers	13	1883, 1890, 1910, 1913, 1928, 1929, 1930
breakers Gates' style "K"	1207 1215	auxiliary spring 80 habbitting
Hathaway gyratory in reserve	1109	babbitting 73 Becket Foundry & Machine Co. 76
kinds of	13	belted
Krupp	1202	and geared 79
gyratory	1215	beveled
location of McCully gyratory	1109 1210	bibliography for 109 Birmingham Iron Foundry 76
method of operating .	13	Bowers 111
separate motor for	1092	boxes or bearings for
emery mill 232	, 253	Buchanan . 72
bibliography for	291 255	capacity of
horizontal vertical	255 255	Speed, power, wear, etc. 109 Chicago Iron Works . 76
house, picking in	482	choke and f ee crushing by . 98
houses 483, 485, 991, 995, 998, 1000,	1109	classification of 62
powders, effect of water on A. S. Cushman	1419	Colorado Iron Works 2010 Colorado Iron Works 76
rifles . Rocker	721 723	Colorado Iron Works
Rocking stone mill	1084	Sturtevant mills 110
table 320.	1032	comparison between free and choke fed rolls 1229
Rocky Mountain mill xxix.	1048	convex and concave
Rodda, J. F., new form of stamp Roebling	228 1195	core of 65 corrugated 106, 110
Roebling's gauge	1194	rolls and rolls with inserted teeth 1242
screen gauge	173	table of sizes, capacities, and
Rogers, A. N. Colorado versus California system of milling	787	power 1243
data concerning slime tanks	1408	cost of crushing by 104 repurs on
gravity stamps 224	. 226	Davis 111
gravity stamps 224 Rogers' dewatering screen	1591	diagram of percentage reduction in 122
at Mill 144	1592	chameter of 83
jıg Rohrmuhle	642 293	different types of 2010 discussion of 2010
Rolker, C. M., Allouez mill, Lake Superior	1174	driving mechanism 75
Rolker, C. M., Allouez mill, Lake Superior Ball stamp	142	Eagle Foundry Co. 76
Collom jig at Lake Superior	640	Eckart 111 Edison's 110, 111
concentration at Glasdir, Wales	1183 551	Edison's 110, 111 corrugated . 106
Cross picces on jigs Evans slime table and kieve	728	giant . 105
hog trough classifier .	476	three high
mal capacity	1109	effect of ores on angle of nip 94 efficiency of 109
milling in Utah Rolled Saw plates at Mill 180, life of	1174 1902	efficiency of E P Allis Co. 72, 76
steel for wearing parts of rolls	1243	features and faults of
Koller feeder	854	feed to 63, 1224
mills	1303	feeders for
Griffin Huntington centrifugal .	282 276	feeding of
Kent mill	1303	
number used	231	F. M. Davis Iron Works Co. 72
table of details of Kent mill	1304	formula for angle of mp 93
Wild mill	1304	for removal of vanner concentrates 647 vanners 652, 653
table of sizes, capacities, power, weight,	1304	Fort Scott Foundry & Machine Co 76, 111
quartz mills, Bryan	271	frames of 63
shells for Huntington mill	280	Fraser & Chalmers
Rollers for belt conveyors	859	geared 78 Fulton Iron Works
on vanners Roll jaw breaker, Sturtevant	646 32	Gates Economic 81
Blake breakers, Sturtevant	1205	Iron Works 73, 79
Blake breakers, Sturtevant crushing, R. K. Humphrey L. H. Sturtevant	2010	geared . 75
L H. Sturtevant .	2010	and belted compared . 83 general construction 63
shells at Mill 129	66 1716	general construction 63 Geyer
cost of	69	graded crushing by
flanges on	7ŏ	C V C
materials for		G. V. Cresson Co
	68	Hendy & Meyer
of chilled steel	68 2011	Hendy & Meyer
of chilled steel	68	hexagonal cores

Sampling, cleaning mill between lots 157	77 Sapphire washing 108 78 Sardinia, ore dressing in. N. Pellati 203 78 Satelin I. de Hughes Daviet electromagnet 83
Sumplify Country Street Loss Training	
	77 Cardinia and descript in N. Pallati 203
cutting down crushed ore from sample rolls 15	and Saldina, of Curesting in. 14. Tenati
ground pulp	78 Salelin, J. de, Hughes Daviot electromagnet 83
ground pulp 157 department at mills 1667, 1691, 1742, 188 difficulties attending mechanical	777 Sardınia, ore dressing in. N. Pellati 203 787 Satelin, J. de, Hughes Daviot electromagnet 38 848 Saucon mine, movable sieve jig at 50 75 Sauer-Mayer riddle 34 833 Sautter magnetic separator 79 Savage, E. Plumb jig 64 73 Saving by canvas plant 101 475 from scrap 111 476 from scrap 111 477 in mills 111 406 gold mills 111 31 usc of electricity 109 60 of water 34 38 average extractions in various districts, table 16 6 of of
difficulties attending mechanical 157	75 Sauer-Maver riddle
general article on 203	33 Sautter magnetic separator 79
high grade telluride gold ores with Vezin sam-	Sauvaga F Plumb fire 64
might grade rendrate good ofes with verm sam-	70 Caring Language Inc.
Dier 15 15 16 17 17 18 19 19 19 19 19 19 19	3 Saving by canvas plant
in Colorado	44 new scheme in Mill 66 102
In Colorado 12 15 15 15 15 16 17 17 17 17 17 17 18 18	75 from scrap
mechanical sumpling 15	77 in mills 111
mechanical	te gold mills
mechanical 8-	910 KORU IIIII
methods at Broken Hill. H. W. Moss 207	use of electricity
mill 1051, 100	69 of water
merhanical merhanical methods at Broken Hill. H. W. Moss. 200 mill 1051, 100 S. H. Pearce 200 minunuang effect of air currents 155 moisture samples 157 notes on 200 minunuang effect of air currents 250 moisture samples	132 Savings, average extractions in various districts table
minimizing effect of air currents . 157	161 175 176 177
minimizing enect of an eurenis . 157	77 Com blade for an alread and an
moisture samples	75 Saw blade for scraping plates
notes on 200	32 Sawyer canvas elevator belt at Mill 125 170
of bullion . 78	'84 Saxon mill, mercury trans in
concentrating and slime tables. J. C. Bailor 200	129 wells in
will work	168 Shoes and dies
mill work	shoes and tiles
ores P Argall 160	509 Saxony, cobbing in 48
plant of mills 1629, 1831, 18	572 mills in 117
precautions in 8	345 Scaife trough washer
removable of	349 Scales for weighing ore
principles of	Sawyer carrise revaror ben at Min 125 170
requisites to accuracy 15	
rules for . 8	348 in American mills, table of 136
S II Pearce 200	ist we gaing devices 100
size of samples	76 Scandium dome weight of 118
tower at Mill 120	Standard, and Conference of Schooling at Alexandria Coal Company's plant, Greensburg, Pennsylvania 1176 Schamberger, J. W., Glay washing 118223 Schedules for calculating the value of zinc ores 193
tower at Mili 120	of Scharter, 1. V, toal washing at Alexandria Coal
trough for slime table 11	72 Company's plant, Greensburg, Pennsylvania 117
	367 Schamberger, J. W., clay washing 118
Same on band on 1909 199	23 Schedules for calculating the value of zinc ores 193
at Dives Pelican mine 120 Mill 113 166	232 Schedules for Gatcharding the state of 27th offers 183 203
Viil 113	50 Jopan zaic ores
VIII 113	59 western zinc ores
Manufacturing Company. Samson breaker 12:	223 zinc ores, foreign 193
San Antonia de Venana mili	80 Scheelite, specific gravity of
Sanborn, J. A., amalgam	67 Schellenbach Sons
temperature of water for amalgamation . 73	200 II-
competature of water for amargamation . 16	89 rolls 7
Sand and shine concentrators	544 Schemes of mill treatment 892, 161
	64 Schemnitz, Hungary, settling tests at . 114
Wilfley table	165 Ushaped classifier
corundum 10°	978 Schiff, F., magnetic separators 83
	700 (11 1 11
distributor, Blaisdell centrifugal 16	
	373 bibliography for 29
for bedding false bottoms in mortar . 13	80 Schleuderseparator, description of the. L. Kleritz
heated for sweating plates	59 and O Bilharz 202
in launders, flow of F K Blue 160	509 Schmidlieing Chili mill 201
m additions, now of the fraction of the first	100 Seminoneing Charles 201
heated for sweating plates 77 in launders, flow of F K Blue 160 movement of coarse T I Read 200	
Sandpaper used in scouring copper places	53 - Manderbach, Adolph, spiral sieves 38
Sand, preparation of moulding Kraus 20:	930 spiral screen 363, 364, 38
pumps . 868, 15: at Mill 182 1910, 19	88 Schnabel, Carl, bag rooms for zinc white 88
pumps 868, 153 at Mill 182	Handbuch x
Standard Consolidated mine 1516, 15	VI II I I I I I I I I I I I I I I I I I
Fremer 8	871 separation processes 83
	31 silver amalgamation 103
ratio to water in pumping 80	031 silver amalgamation 103 by Washoe and Reese River processes 117
ratio to water in pumping 80 Sands in classifiers and ugs action of G. G. Bring 200	031 silver amalgamation 103 by Washoe and Reese River processes 117
Sands in classifiers and pigs, action of G. G. Bring 20:	103
Sands in classifiers and jigs, action of G. G. Bring 20: mechanical settling and tiltering of 20:	103
Sands in classifiers and jigs, action of G. G. Bring 20; mechanical setting and filtering of 20; moisture in	103
Sands in classifiers and jigs, action of G. G. Bring 20; mechanical setting and filtering of 20; moisture in	103
Sands in classifiers and jugs, action of G. G. Bring 20; mechanical settling and littering of 20; moisture in 110 transported by water . 810 treatment at Mill 117 16	103
Sands in classifiers and jugs, action of G. G. Bring 20; mechanical settling and littering of 20; moisture in 110 transported by water . 810 treatment at Mill 117 16	103
Sands in classifiers and jigs, action of G. G. Bring. 20; mechanical settling and filtering of mosture in transported by water 8 treatment at Mill 117 used for scouring copper plates 7.	103
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and littering of 20 moisture in 11 transported by water reatment at Mill 117 16 used for scouring copper plates washing in New Jersey, glass 20	331 silver amalgamation 108 369 by Washoe and Riese River processes 117 220 Scholl, G. P., modern gold milling 203 212 Schone tubular classiter 47 67 School laboratory work, a free milling gold ore. 204 78 R. H. Richarls and E. E. Bugbe. 204 770 Schorr battery, R. Schorr on the. 127 8 Schranz breaker 56, 57, 60, 60
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and littering of insister in transported by water	331 silver amalgamation 108 369 by Washoe and Riese River processes 117 220 Scholl, G. P., modern gold milling 203 212 Schone tubular classiter 47 67 School laboratory work, a free milling gold ore. 204 78 R. H. Richarls and E. E. Bugbe. 204 770 Schorr battery, R. Schorr on the. 127 8 Schranz breaker 56, 57, 60, 60
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and littering of 20 moisture in transported by water treatment at Mill 117 16 used for scouring copper plates washing in New Jersey, glass 20 weight of 15 whools 15 each	331 silver amalgamation 108 369 by Washoe and Riese River processes 117 220 Scholl, G. P., modern gold milling 203 212 Schone tubular classiter 47 67 School laboratory work, a free milling gold ore. 204 78 R. H. Richarls and E. E. Bugbe. 204 770 Schorr battery, R. Schorr on the. 127 8 Schranz breaker 56, 57, 60, 60
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and littering of 20 moisture in transported by water treatment at Mill 117 16 used for scouring copper plates washing in New Jersey, glass 20 weight of 15 whools 15 each	331 silver amalgamation 108 369 by Washoe and Riese River processes 117 220 Scholl, G. P., modern gold milling 203 212 Schone tubular classiter 47 67 School laboratory work, a free milling gold ore. 204 78 R. H. Richarls and E. E. Bugbe. 204 770 Schorr battery, R. Schorr on the. 127 8 Schranz breaker 56, 57, 60, 60
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and filtering of moisture in transported by water 8 treatment at Mill 117 used for souring copper plates washing in New Jersey, glass weight of 84, 15 at mills 1587, 1668, 1669, 1677, 1715, 1893, 18 Calumet and Hecka 200.	331 silver amalgamation 108 369 by Washoe and Riese River processes 117 220 Scholl, G. P., modern gold milling 203 212 Schone tubular classiter 47 67 School laboratory work, a free milling gold ore. 204 78 R. H. Richarls and E. E. Bugbe. 204 770 Schorr battery, R. Schorr on the. 127 8 Schranz breaker 56, 57, 60, 60
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and filtering of moisture in transported by water 8 treatment at Mill 117 used for souring copper plates washing in New Jersey, glass weight of 84, 15 at mills 1587, 1668, 1669, 1677, 1715, 1893, 18 Calumet and Hecka 200.	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 31 Stay-overflow mortar 126 32 Scharz breaker 56, 57, 60, 69 39 of Dodge type 3 38 section of 3 39 jig 503, 64 30 mill 235, 274, 29
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and filtering of moisture in transported by water 8 treatment at Mill 117 used for souring copper plates washing in New Jersey, glass weight of 84, 15 at mills 1587, 1668, 1669, 1677, 1715, 1893, 18 Calumet and Hecka 200.	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 31 Stay-overflow mortar 126 32 Scharz breaker 56, 57, 60, 69 39 of Dodge type 3 38 section of 3 39 jig 503, 64 30 mill 235, 274, 29
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water 18 treatment at Mill 117 16 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 31 Stay-overflow mortar 126 32 Scharz breaker 56, 57, 60, 69 39 of Dodge type 3 38 section of 3 39 jig 503, 64 30 mill 235, 274, 29
Sands in classifiers and jugs, action of G. G. Bring 20 mechanical settling and filtering of 20 moisture in transported by water treatment at Mill 117 16 treatment at Mill 117 16 16 vasing in New Jersey, glass weight of 18, 18, 18, 18, 18, 18, 18, 18, 18, 18,	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 31 Stay-overflow mortar 126 32 Scharz breaker 56, 57, 60, 69 39 of Dodge type 3 38 section of 3 39 jig 503, 64 30 mill 235, 274, 29
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water reatment at Mill 117	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 30 Schorr battery, R. Schorr on the 127 32 Scharz breaker 56, 57, 60, 69 90 of Dodge type 3 866 section of 3 894 jig 503, 64 mill 235, 274, 29
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water 20 mesture in transported by water 18 treatment at Mill 177 16 used for scouring copper plates washing in New Jersey, glass 20 weight of wheels tat mills 1587, 1668, 1669, 1677, 1715, 1893, 18 31, 18 Calumet and Hecladel 8 Calumet and Hecladel 8 in the Transparal mechanical efficiency of on the Randel efficiency of interview jumps in Witwatersrand 16	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 30 Schorr battery, R. Schorr on the 127 32 Scharz breaker 56, 57, 60, 69 90 of Dodge type 3 866 section of 3 894 jig 503, 64 mill 235, 274, 29
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water 10 moisture in transported by water 16 moisture 17 moisture in transported by water 18 moisture in transported by water 18 moisture in transported by water 18 moisture in transported by washing in New Jersey, glass 20 moisture in the last 18 moisture in	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 30 Schorr battery, R. Schorr on the 127 32 Scharz breaker 56, 57, 60, 69 90 of Dodge type 3 866 section of 3 894 jig 503, 64 mill 235, 274, 29
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water 10 moisture in transported by water 16 moisture 17 moisture in transported by water 18 moisture in transported by water 18 moisture in transported by water 18 moisture in transported by washing in New Jersey, glass 20 moisture in the last 18 moisture in	331 silver amalgamation 103 369 by Washoe and Reese River processes 117 220 Scholl, G. P. modern gold milling 203 212 Schoel tablar classiter 47 37 School laboratory work, a free milling gold orc. 204 38 R. H. Richarls and E. E. Bugbee 127 30 Schorr battery, R. Schorr on the 127 32 Scharz breaker 56, 57, 60, 69 90 of Dodge type 3 866 section of 3 894 jig 503, 64 mill 235, 274, 29
Sands in classifiers and jugs, action of mechanical settling and filtering of mosture in transported by water 20 mosture in transported by water 18 treatment at Mill 177 16 used for scoring copper plates washing in New Jersey, glass 20 weight of wheels tat mills 1587, 1668, 1669, 1677, 1715, 1893, 18 31, 18 Calimet and Hecla details of in the Transparl mechanical efficiency of on the Rand dersus pumps in Witwatersrand Willey middlings elevator 16 San Dimas, arrastras at 238, 288, 288, 288, 288, 288, 288, 288,	103
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water 18 treatment at Mill 117 16 16 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18	103
Sands in classifiers and jugs, action of mechanical settling and filtering of mosture in transported by water 18 treatment at Mill 117 used for souring copper plates washing in New Jersey, glass 20 weight of 18 the start mills 1587, 1668, 1669, 1677, 1715, 1893, 18 Calimet and Hecka 20 details of in the Transstal 20 mechanical efficiency of on the Rand 27 user jumps in Witwatersrand 28 mechanical efficiency of 15 on the Rand 27 user jumps in Witwatersrand 28 and stone, angle of nip required to crush 28 as Sandstone, angle of nip required to crush 28 compressive strength of 3 38 details of 28 as	103
Sands in classifiers and jugs, action of mechanical settling and littering of mosture in transported by water retainent at Mill 117 16 18 18 19 19 19 19 19 19	103
Sands in classifiers and jigs, action of mechanical settling and littering of mosture in transported by water retainent at Mill 117 is 16 is 18 is 1	
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water 18 treatment at Mill 117 used for scorning copper plates washing in New Jersey, glass weight of 18 the property of the proper	
Sands in classifiers and jugs, action of mechanical settling and littering of mosture in transported by water retainent at Mill 117 16 16 18 19 19 19 19 19 19 19	
Sands in classifiers and jigs, action of mechanical settling and littering of mosture in transported by water retardent at Mill 117	
Sands in classifiers and jigs, action of mechanical settling and littering of mosture in transported by water retardent at Mill 117	
Sands in classifiers and jugs, action of mechanical settling and filtering of mosture in transported by water 18 treatment at Mill 117 16 treatment at Mill 118 18 treatment at M	
Sands in classifiers and jugs, action of mechanical settling and filtering of mosture in transported by water 18 treatment at Mill 117 16 treatment at Mill 118 18 treatment at M	
Sands in classifiers and jugs, action of mechanical settling and littering of mosture in transported by water retainent at Mill 117 16 16 18 19 19 19 19 19 19 19	
Sands in classifiers and jugs, action of mechanical settling and filtering of mosture in transported by water retainent at Mill 117 16 16 17 16 18 18 18 18 18 18 18	
Sands in classifiers and jugs, action of mechanical settling and littering of mosture in transported by water retarment at Mill 117	
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water retainent at Mill 117 16 16 17 16 18 18 19 19 19 19 19 19	
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water retainent at Mill 117 16 16 17 16 18 18 19 19 19 19 19 19	
Sands in classifiers and jugs, action of mechanical settling and littering of mosture in transported by water retainent at Mill 117	
Sands in classifiers and jugs, action of mechanical settling and filtering of moisture in transported by water retainent at Mill 117 16 16 17 16 18 18 19 19 19 19 19 19	Silver_amalgamation 108

Scrap iron recovered by magnets	Screens for gravity stamps
Scrap fron recovered by magnets 790	Screens for gravity stamps 1270
Mill 126	at Mill 162
for belt conveyors	jigs 496, 510, 552
plates 757, 758	cost of removing sticks, bolts, pick points, etc 882
rolls	removing sticks, bolts, pick points, etc. 882 settling tanks 458 stamps, size of 221 table of details of 121 steam stamps 119 material, size, life, etc. 121 testing 1137 Tremain stamp 136
slime tables 689, 696	stamps, size of
Scraping conveyors 860	table of details of
and lamp chimney for sampling jig hed	muteral size life etc 191
area on stamps 209	testing 1137
for dredges 1012	testing 1137 Tremain stamp 136 trommels, life, cost, etc. 352, 354
frames 176	trommels, life, cost, etc
for jig	jig tailings . 587
steam tamps 120	Gates all-iron frame revolving 1353
gauges 171 172	gravel
meshes, tables of	gyrating 342
of hand jig	Harrington & King's standard plate . 369, 370
measurements of 1362	Hicks revolving grizzly
plate, cost of 361	Imperial screen
sizing limit of 1361	in granty stamps
Screening after decrepitation 200, 366, 1361	size of holes in 210 mills, use made of
Slime tables	
by trommels system of 364	plate 173
cost of	jig, details of
economic limit of P. Argall 1366	Karop 386 King screen 1356, 1360
following disintegration . 830	Klein mo ing grizzly . 386
hot and cold ore 385 separation by crushing and screening 1566	me on jig- 546
decrepitation and . 1565	limits of 368 Linkenbach's figures on 547
tests 1138	material, cost, life, etc. 173, 174
graphic records of. C. De Kalb	for 354, 384 jig 545
wet	jig 545 means of designation P Argall 1366
wet cersus dry	meshes of 172
trommel 335 wet <i>crrsus</i> dry	mill 1365
action of 2019	amount of screening surface for given output 1365 cost of municipance of 1365
aluminum bronze cloth . 174	needle gauge 172
plate	proper peripheral speed for . 1365
arrangement of holes	Newaygo separator 1350 numbers 172
at Mill 158 1894	Oberegger gyrating 386
Monte pom, hand	octagonal trommels 1353 of corrugated type 226
the Washi mill, New Zealand, size of 2019	of corrugated type 226 gun-metal at Mill 185 1915
Monte poin, hand 2018 Truesdale coal washery, shaking 2018 the Waiti mill, New Zealand, size of 2019 attachment of in trommels 355 balancing of shaking 342	plate or wire cloth . 340
balancing of shaking 342 bar 336 belt type 1357 belt type 384	on a fixed shaft, rotary 2018 opening in mortars 167
belt type 1357	percentage of opening in 369, 546
	percentage of opening in 369,546 with hole in 60° and 90° rows 168
blinding of 175 Borgmann & Emde 386	phosphor bronze cloth 174
bes cloth	plate 174 placing of 170
Briart bar	plate, for gravity stamps . 167
Briart bar 346	Pratt ore sizer 1345 prevention of blinding 373
capacity of	prevention of bunding . 373
Centripact	relation of thickness of plates and wires to diam-
Choice of	cter of holes, in the mills 372 to diameter of holes in punched screens as quoted 372
Catastified 336 Cloth 170 Coal F W. Parsons 2019 Columbian pulsating 343 Comparison of 345 Shaking and cylindrical 2019 Coper plate 174 Corrosion of 354 Cost of per ton of ore crushed 174 Denver Engineering Works Company revolving 21353	screens as quoted 372
coal F W. Parsons	revolving 340, 1353
Columbian pulsating	raddles, and vibrating grizzlies 341 round and square holes 369
shaking and cylindrical	versus slotted holes 169
copper plate 174	
corrosion of	Schmidt spiral
Denyer Engineering Works Company revolving	sectional trommels
grizzly 1353	shape and arrangement of holes
designation of holes 172	sieve scale for 366
different types of 2018	
Distl-Suskin screw grate 386	slope of
Dunlap perfect clay screen 1357	speed of shaking 342, 3 <u>45</u>
Edison stationary	splash board 177
size of holes in stamping	laboratory, W S Hutchinson
elongated punched holes 370	stationary 336, 1345
Denver Engineering Works Company revolving grazly 1353 designation of holes 172 dewatering 1591 different types of 2018 Distl-Jusk pacrew grate 386 Dunlap perfect clay screen 1367 Edison stationary 341 effect of acid water 173 size of holes in stamping 210 elongated punched holes 370 Ferraris hand 1360 shaking 342 347 for box classifiers 433 443 Second 1360 Second 136	Sizing 330, 1395
for box classifiers	plate
	•

0 1.17	Company of managery	1207
Screens suited for testing	Separation of molybdenite	1567 590
submerged trommel at Mill 125	unree minerals on jigs	889
table of clear punched slotted	principles used in	
tinickness of	Separators at the Kalgoorlie mines, hydraulic	2034
nii bronze piate	Ball-Norton magnetic separator	
table of clear punched slotted 109 thickness of 341, 371 tin bronze plate 174 plate 173 Traylor Centripact 1352 trommel, life, cost, and details of 352 Tyler 171	Clarkson-Stanfield centrifugal classification of magnetic separators	820
trommel life cost and details of 352	classification of magnetic separators	1521
Tyler		
double crumbed	cobbing magnets	1531
mining wire cloth	Conkling dry magnetic	809
used for free settling tests 465	Cranberry magnet	1530
in trommels	Dellvik-Grondal	804
variations in the percentage of opening of, in the	Ding's magnetic	1540
mills 371 versus classifiers 368 Vibracone sejarators 1352	Edison magnetic	812
versus classitiers	electrostatic	1549
Vibracone sepirators	Eriksson's electromagnetic	1529
Vibromotor 385 wear of 169, 170, 356	Eriksson's electromagnetic Ferraris magnetic	1020
Wear of	final	480
screening surface 1365 wire cloth, of copper, brass, phosphor-bronze, galvanized and tinned 1365 wire for ground stamps 170	final for fine materials	810
galvaniad and tinned	steam	1091
wire, for gravity stamps 170	Forsgren's electromagnetic separator	1538
versus plate 171	Gröndal Nos. 2. 3, 4, and 5 magnetic	1537
with round holes laid out in equilateral triangles 168	Heberli magnetic	799
S010705 168	wet	810
W S Tyler Co. double crimped 370	Hughes Daviot electromagnet Humboldt magnetic	812
Screw conveyors	Humboldt magnetic	1530
	International magnetic Kessler magnetic	1533
for removing by fallings	Kessler magnetic	811
table of sizes, capacities, and speeds of 1583	Knowles' New Century magnetic	1541
tappets for stamps	Leighton magnetic magnetic with conveying belts	1528 804
Scrubber for cleaning copper plates	Machaniah magnetic corumtor	1535
Scrubbarg of amalgamated plates 758 Seager, J. B. viii Scaling of retorts 1519 Sea water, use of 1106 1106 1106	Mechernich magnetic separator	818
Scaling of retorts 1519	Newsygo	1360
Sea water use of 1106	Newaygo of the primary-magnet type	1521
Sea water, use of	secondary or induced magnet type	1533
weight of	Pape-Henneberg	818 799
Second hand machinery, experiments with 2012 Sectional Blake breaker 20, 21	Pape-Henneborg Payne magnetic Peck centrifugal pneumatic	799
Sectional Blake breaker	Peck centrifugal	828
breaker of Blake type	pneumatic	1553
guides for gravity stamps 104, 100, 1208	Sutton, Steele & Steele dry table principles of magnetic separators	1479 1521
mental Trader 1967	Dimend magnetic separators	807
for gravity stamps 163	Sigmone magnetic	803
rolls 81	Ullrich magnetic	1535
Dreaker of Blake type 22 guides for gravity stamps 154, 155, 1268 the Denny 1269 mortars, Traylor 1267 for gravity stamps 163 rolls 81 stamp came 192 mill 227	Rowand magnetic Siemens magnetic Ullrich magnetic Vibracone 1352,	1360
	wenstrom magnetic	800
trommels	Wetherill magnetic 804.	1521
Denver Engineering Works Company revolv-	with the ore falling in front of magnets Series arrangement of machines	812
ing grizzly	Series arrangement of machines	1110
Sections in mills 1108	Series arrangement of machines Serpentine, specific gravity of strength of Setting up a stamp Willey tables Settlers Settling, bibliography for beakers or jars	1109
Seeman, L., centrifugal pumps 870, 885 classifier with helical current 478	Setting up a stamp	200
sizing, jigging, and wet stamping 1182	Wilfley tables	1468
sixing, jigging, and wet stamping 1182 Stein table 729 Segregator (classifier), G. G. Gates 418 Seitz coal loading and screening machine 2018 Selenide sliver mill 1622 Selenium, atomic weight of 1188 silver ores, concentration of 1925 Self-tughtening cams 193	Settlers	777
Segregator (classifier), G. G. Gates 418	Settling, bibliography for	475
Seitz coal loading and screening machine 2018	beakers or jars	1146
Selenide silver mill 1622	box for Johnston vanner concentrates	1502
Selenium, atomic weight of	concentrates in barrels	1113
Silver ores, concentration of	definition of free and findered	1000
Self-tightening cams 193 manganese steel mantles for McCully gyratory	fine climes 1147 1185	1186
breakers	concentrates in barrels definition of free and hindered	1460
breakers	limit of	455
Sell, L., ball mills 293 Sellers, William & Co., steam hammer 12		
Seminole mine ore, Krom air jig on 825	pits for tin ores	1083
Separating 5	pits for tin ores pond in the Harz, a concrete power of minerals, effect of	2020
concentrating or washing	power of minerals, effect of	64
Separation by adhesion	rates in different mediums	826
crushing and screening	ratio, defined	0 471
decrepitation 830	recorner for	460
1565	power of university, effect of rates in different mediums ratio, defined ratios	1184
disintegration and screening	use of chemicals for	1413
and screening 1969 disintegration and screening 830 heavy solution 1156 magnetic concentration 790 oil 831 weathering 830	tanks	1109
magnetic concentration 790	and pits for clay	1076
oil	at mills 1408, 1776, 1777,	1779
weathering	tanks 450, and pits for clay 1408, 1776, 1777, Morenci, Arizona 1408 (1776, 1777, haffle board 1408	1413
combinations of principles of	haffle board Berenger and Stingls slime tank Binkley settling system calculation of	459 1407
ease of	Derenger and Sungis stime tank	1400
Huntoon's experiments on telluride gold ores 1566	calculation of	454
in vanners, principle of	Callow cone	1402
700	capacities of, 15 feet square	455
of fluorspar, lead, and zinc. F. Julius 2028	Colorado Iron Works Company	1407
galena-sphalerite ores at Broken Hill 1611	data from the mills concerning	458
misceilaneous prices of of fluorspar, lead, and zinc. F. Julius 2028 galena-sphalerite ores at Broken Hill 1611 grease from diamond at Mill 188 1921 mixed sulphides. R. C. Canby 1923	Callow cone capacities of, 15 feet square colorado Iron Works Company data from the mills concerning details of, in the mills dimensions of	458
mixed sulphides. R. C. Canby 1923	uimensions of	453

1 450 110 1010, 101. 111.	1110	EA. Fages 1011-2052, Vol. 1V.
Settling tanks for graphite ores jig concentrates ore dressing, a kaolin 1077,	1075	Shermon F W system of settling tanks
jig concentrates	586	Sherman, F. W., system of settling tanks 1400- slime treatment at Mill 132 1725
ore dressing, a	2020	
kaolin 1077,	1149	slime concentrator 202: Shield for grease from stamp cams 19
Vanner concentrates	647	Shield for grease from stamp cams
vanner concentrates	1406	of canvas for stamps
practical limits of settling in	455	of canvas for stamps 17 Shimer and Reifsnyder sampling 88 Shums for rolls 7 Shipping concentrates 111
relations of length and width to the settling	452	Shipping concentrates
relations of length and width to the settling speed of current to size of grain Scobey system in Arizona Sherman system slime table of details of in the mills tests on fine slimes theory tube use made of in mills of lime and alum for 458, velocities, curves of 467, water 524 pumpe 520, 595 Setzrand Severing minerals, methods of 520, 595 Severing minerals, methods of	452	expenses 1123
Scobey system in Arizona	1411	Shoe and die channels in annulum at
Sherman system	1404	Shoes and dies for grinding pans, wear of 1286
slime	1419	life of 184, 185, 2011
tests	456	Shoes and dies for grinding pans, wear of
on fine slimes	1176	wear in amalgamating pans 249
theory	476	false for etamps
tube	621	for amalgamating page
use made of in mills	889	gravity stamps
of lime and alum for 458,	459	life of 1277
velocities, curves of 467,	473	settlers
Setzpumpe 590 505	1104	steam stamp 120
Setzrad	478	of Northern steams towns 122
Severing minerals, methods of	- 8	Dut on gravity stamps
or detaching	5	shanks and butts
Sexton, F. H., the ore dressing apparatus at Dal-		Sholl pneumatic stamp
Source dynamometer for work of courts a	2048	Short head and concaves, Gates' breaker with 1208
Sexton, F. H., the ore dressing apparatus at Dalhousie University, Halifax Seyss dynamometer for work of crushing Shackeftord's materia box deaning devices	สบอ 1503	Should for a making
Seyss dynamometer for work of crushing Shackelford's patent box cleaning device. Shaft drier at mills. furnaces for drying roasting furnace at mills. Shafts, boxes or bearings for for amalgamating pain jigs. diameters of rolls steam stamps Tremain stamp trommels. Shafting in mills.	1822	184 185 2011
furnaces for drying	880	Shoveler mechanical 995 976
roasting furnace at mills 1663, 1759,	1765	Shoveling, sampling by
Shafts, boxes or bearings for	72	Siberia, dredging in 1009
ior amaigamating pan	248	gold milling in. L. Tovey 2038
diameters of	522	Sickening of mercury 750, 751
rolls	65	burns tables comparison with and burns (200
steam stamps	128	bump tables comparison with end-bump
Tremain stamp	138	Rittinger table
trommels	351	Stein, Corning, Bilharz, and Luhrig 669
Shafting in mills Shaking amalgamating tables at mills . 1645, 1650,	1108	with plane surfaces
in South Africa	1513	plane surfaces 667 Rittinger table 667 Rittinger table 667 Sten, Corning, Bilharz, and Luhrig 669 with plane surfaces 667 discharge for jugs 580 hill site for mills ierk tables communication of Wildew and Pittinger 870
feeders at mills 1691 1837 1868		jerk tables, comparison of Wilfley and Rittinger 679
frame for I'rue vanners .	645	jerk tables, comparison of Wilfley and Rittinger 679 Bartlett table
grizzly at mills	1866	
mercury trap	774	Cammett tables 676 Dodd table 675 Hallett table 675 Giverstrom table 679 Wildey table 670 With rilled surfaces 670 Woodbury table 670 Gamalgamating table 676 Companyating table 676 Company
plates	740	Overstrom table
platesscreens	341	Willey table 670
at mills 1694,	1889 1012	with riffled surfaces 670
	11137	Woodbury table 676
new spring for	2018	of amalgamating pain 244 plunger jigs 529 shake vanners 645, 1499 Frue vanner 1499
table for picking	489	shake vanners
Shallow-pocket hindered-settling classifiers	1384	Frue vanner 1499
hydraulic classifiers the Richards	389	
Shanks and butts of stamp shoes	401 181	170th rotary spine concentrator 1499 170th rotary spine concentrator 170th rotary spine concentrator
Shannon concentrator	1931	Nortom concentrator
		versus end-shake
settling at	1416	Siderite. See also Iron.
Snape of grains, effect of, on slime tables	694	angle of nip required to crush 94
screen holes	404 260	calcining for magnetism
Sharpless, F. F	196	separated by decrepitation 829
Copper Company, the use of lime for slime settling at Shape of grains, effect of, on slime tables particles, effect on free settling screen holes Sharpless, F. F	767	Siderite. See also Iron. 94 angle of nip required to crush 94 calcining for magnetism 1544 separated by decrepitation 829 by magnets 790 specific gravity of 1189 Siemens & Halske magnetic separator 798 rolls 2010 magnetic separator 803, 834 Sierra Buttes mill, amalgamated plates in 748 Sieve box for jige 524
Atlantic mill, Lake Superior	1183	Siemens & Halske magnetic separator
Ball, Leavitt, and Allis stamps	142	rolls
stamp keys steel ends of tappet keys	188 227	magnetic separator 803, 834
temperature of water for amalgamation	780	Sierra Buttes mill, amalgamated plates in 748
Sharpneck steam stamp 136	142	for mill testing 1006 1007
Sharwood, W. J., definition of slimes 1398,	1419	frames, double iron
Shaw mine, Huntington mill at	281	for jigs 538
Shells for rolls	1095	iron 539
steel ends of tappet keys temperature of water for amalgamation Sharpneck steam stamp 136, Sharwood, W. J. definition of slimes 1398, Shaw mine, Huntington mill at Sheaves for ropes Shells for rolls net cost of Shepard, F. E., tube mills at the Gold King mill, Colorado Shepard, F. E., tube mills at the Gold King mill, Colorado Sheppard for al fig. Sheprad for the state of the sta	69	Sierra Buttes mill, amalgamated plates in 748
Shepard, F. E., tube mills at the Gold King mill, Col-		at mills
orado	2014	for jigging 606
Sherman F W contributed and a selection of the selection	643	testing screens
classifiers at Mill 139	1313 1720	1. M. M. standard laboratory sieve scale 1362
Huntington mill	1313	in American mills, table of
improved Huntington mill at Mill 132 . 1728, 1	1729	mills
re-grinders at Mill 132 1728, 1	1729	limits of
Huntington mill at Mill 132 1728, improved Huntington mill at Mill 132 1728, re-grinders at Mill 132 1728, separating and distributing tanks at Mill 132 settling tanks at Mill 132 1404, 1729 slimer	1728 7720	
slimer	1506	wires and prices
	00	Die ver com pag

Sieves	Silverton Coloredo hammers used et 10
Can also Comany	Silverton, Colorado, hammers used at
and plungers, sizes of, in mills 528–529 brass wire on jigs at Mill 121 1686 drop between, on jigs 549	typical mill of. W. G. Swart 2042
drop between, on jigs 549	Mining Co., mill
for hand jigs 499	notes on. G. O. Swart 2035
three-mineral separation	Deep Ltd. ore reduction plant of 1651
length of in jigs 592	Mining Co., mill
life of m jigs 546	
number of on jigs	Simple-cylinder steam stamp at Mill 179 1897 jigging mills
slope of, in jigs 548	using power jigs 900
width of, in jigs	steam stamp at Mill 182 1900, 1912 Simplex ore feeder
Silting and decrepitation 5 Silberau mill 1087, 1136	Simplicity in machines
mill at	mills 1004
sieve scale in	Simpson pulverizer 2014 Single (vlinder and compound steam stamps, com-
Silesia, mill m	parison between . 1254
Silex liners for tube mills at Mill 143 1770 Silica crushed in Blue Bird mill	roll crusher, McLanahan and Stone 167
for melting	table of sizes, power, and weights . 1241
Silicon, atomic weight of 1188 Siller & Dubois ball mill 293	514K 11, 1144 CHI 1144 100 1702
Sills and girders for steam stamps	stage crushing
for Nordberg steam stamps 1247	103 103
Silver Age mill xxv, 915 amalgam 730, 731, 747, 1512	Sintering sames at Mili 129
Xxx, 915 Axx, 915	at Mechernich 421, 475, 477, 478
amalgamated plates	Sites for mills
assay for in Mill 55	of amalgamated plates
Mill 68 303	of amalgamated plates 737 feed to hydraulic classifiers 389 grains affecting capacity of pgs 600
atomic weight of 1188 Combination mills . 1039	grains affecting capacity of pgs 600 for film sizing
-copper ores, mills for . 973, 984	ig bed
cost of producing 1960 Cup, British Columbia, handling of ore at the	1000 to serective 210
G Allwood 2039	jig sieves and plungers 528
fineness in bullion 785 horn, crushed in Harshaw mill 207	material for roasting for magnetism 814, 815
in Lake Superior copper . 766	treated by amalgamating pairs 248 needles for screens 172
Islet mill 1179	sieve hole on jigs 573
stamps 226 King mill, Fleming dewatering wheel at 1590	treated by amalgamating pans 248 needles for screen 5172 steve hole on jigs 573 slime tables 684, 696 Sized feed for Willey tables 1473
Park City, Utah 2038	versus classified feeds for the Wilfley table 1478
Park City, Utah 2038 II L. J. Warten 2036 J. H. Steele 2044	Sizers Browne hydrometric conical 409
1.ake miii 1040, 1092, 1771	Sizes and weights of ore for sampling 851, 852
dewatering screen at Mill 139 1751 lead ores, crushed by Blake breaker and Chili	
mili 271	Vanners
ores, mills for 925, 936 treated at Broken Hill by Collom jigs 515	of Akron Chili mills, table of 1308
mills 1039	Allis Chalmers toothed and corrugated rolls, table of 1243
settlers in 777	Alsing tube mills, table of 1296
milling, bibliography for te . 1173 cost of	American Process Company driers 1598 Argall driers 1600 Austra gratery breakers table of 1210
ore, amalgamation of 1167	Austin gyratory breakers, table of 1210
crushed at Geddes and Bertrand mill 100 by arrastras 238	Argan Grees 1000 Austin gyratory breakers, table of 1210 Blake breakers 17, 21, 24 boxes for rolls 72 cam shafts 191 Comet breaker 41, 45, 46
leathing and amalgamating 1167	boxes for rolls
loss of	Comet breaker 41, 45, 46
pan for itsting 1157	crushed product from breakers
separated by oil 831 treated in amalgamating pans . 348	Denver Engineering Works Company's Blake
plated amalgamated plates 179 747	breakers, table of 1204 Dodge breaker
at Mill 143 . 1769	double-tone hydraulic classifiers, table of 1384 Farrel Blake breakers, table of 1200 feed for gravity stamps 207
copper plates, coated with mercury 747 comparison of with plain copper 748	Farrel Blake breakers, table of 1200 feed for greatly stamps 207
plating as a preservative for copper plates	1
effect on fineness of amalgam	patent tables, table of
method of	
method of 754 plates coated with amalgam 750 Plume, Colorado, description of two mills at 2043	breakers 38, 46 style "K" breakers, table of 1208
	style "K" breakers, table of 1208 with short head and concaves, table of 1209 grizzlies 339, 340 Hathaway gyratory breakers, table of 1217
proportion of gold and silver on successive plates 763	grizzlies . 339, 340 Hathaway gyratory breakers, table of 1217
in daily and hard amalgam . 764 Reef mill . 1174	Humphrey rolls, table of 1235 Imperial screens, table of 1350 improved Huntington mills, table of 1312
	improved Huntington mills, table of 1312
removed by picking 486 specific gravity of native 1189 treated in mills 44, 46, 47, 48 486	ron pipe 405
used on copper plates	Jeffrey swing hammer pulverizers, table of 1322 Kennedy gyratory breakers, table of 1214
per square foot of copper plate 754	Kent roller mili 1304
"Silverion Brand" elevator belting at Mill 126 1707	Knowles New Century magnetic separators, table of 1542
Colorado, electric power at 1092	Krupp gyratory breakers, table of 1215

C' CT D' C II	0 0.1 W. 1
Sizes of La Point flour gold separators, table of 1510	Sizing test on Schranz mill product. 276 spigot products of Richards' vortex classifiers at Mill 144 1775, 1776, 1778 stamp mortar product at Mill 180 1905 Sturtevant mill product 288
McCully breakers	at Mill 144 . 1775, 1776, 1778
McLanahan and Stone single-roll crushers,	stamp mortar product at Mill 180 1905
table of	Sturtevant mill product 288
new Humboldt concentrator	Lane Chili mill, comparative . 1309
table of 1241 mortar blocks 145 new Humboldt concentrator 1494 ore hand picked 487 particles, effect on free settling 464 Pilling air hoists, table of 1609 products of mills 1116 Bi hardels injustice classifier table of 1200	tailings and concentrates from stamps and Lane Chili mill, comparative tailings and feed of classifier jig at Mill 120 of Mill 174 1887. Tustin mill product Will 162 1449 1450 1450 1450 1450 1450 1450 1450 1450
Pilling air hoists table of 1609	120
products of mills	Tustin mill product 264
Richards' pulsator classifier, table of 1390	
1455 Fig. 1456 1455 Folls	tests, film, on quartz and galena 707
samples 1575, 1576	from Mil 78 667 graphical representation of 1139 on breaker products 47 Bryan mills F. P. Probert 1323 classifier products 4611
Samson breakers, table of	on breaker products 47
for free-settling tests 108, 109, 170	Bryan mills. F. P. Probert 1323 classifier products 461
serew conveyors, table of 1969	crushed ore 303
shoes and dies 182, 183, 184	products
Stroud mills, tables of 1320, 1321 Sturtevant balanced rolls, table of 1234	gravity stamps
Sturtevant Dodge type breakers, table of . 1205	hindered-settling products
trommer screens . 352	i sur and camello hand one
Wild roller mills, table of 1304 Wilfley rousting furnace 1548	jig products products of Gates and McCully breakers Kichards' Indraulic classifier quartz and galena, results of Richards' classifier yeard History Company Hi
treated by jugs	Richards' hydraulic classifier . 406
kieves	guartz and galena, results of 719
rolls	
vanners . 648	throw and cinds A.S. Danny 9010
Wenstrom magnets 801	stamp and Bryan mill products 273
Sizing	stamped ore
and assaying tests	Samp and Bryan mill products 273
before amalgamation	trommet and classifier products 1140, 1144
J. O. Dimmick	products 901, 304
dry jigging 822 jigging . 629, 631, 1463	Tustin mills and stamps 309 vanner products 664, 666 to show grinding by centrifugal pumps 870
(105)	to show grinding by centrifugal pumps 870 Skewes, E, washing tin slimes from Red River, Corn-
sorting	Skewes, E., washing tin slimes from Red River, Cornwall wall Shidayam, W. A., brashow, 80
by a water film on a surface 1611	Skidmore, W. A., breakers 60
screens	Dodge breaker
Servens 1011 2019 1011 2019 1011 2019 1011 2019 1011 2019 1011 2019 1011 2019 1011 2019	1182 Skidmore, W. A., breakers 60 Dodge breaker 66 two stamp steam battery 143 Skimning launders, in Binkley settling system 1409 14097
magnetism and by sorting 891	of hand jug . 497
in mills, use made of	jigs 506, 576
of emery	versus automatic discharge on jigs 584 Skinner, H. R., elevators and conveyors on the Rand 884
principles of screen 1361	Skips for ore
principles of screen	Skirt boards for belt conveyors 859 Skylights
screens	Slag formed in melting
testing of 1170	Slate picker . 489
test and assays of feed and products of Hunting- ton mills 1317	
on ball mill rule 1202	strength of
Browne hydrometric sizer . 410	
Bryan mill product 1310 Chih mill product 269, 271	by hand
Cyanide tailings . 1107	Sliding block mechanism for jigs . 533
Dodge pulverizer product 262	ore feeder
feed and discharge of Abbé tube mill 1290 and products of Drake cone classifiers 1668	mechanism 534
of Huntington mills . 1316	Slime agitators, Blaisdell 1602
tube mills 1290 to flotation plant at Mill 130 1721, 1724 Harz jigs at Mill 144 1772, 1773, 1774 Woodbury slime classifier at Mill 162 1449	Classifiers, classifier jig
Harz jigs at Mill 144 1772, 1773, 1774	concentration of gold mill. W. E. Darrow 2045
Woodbury slime classifier at Mill 162 1449	concentrators
Griffin mill product 284	classification of
Hancock jig feed and middlings 1443	Horn
Heberli mill product	Geyer
Huntington mill product 281, 1669 mill feed at mills 1750 1772	definition of W A Prichard 1419
ore broken by hand and machine . 13	J. H. Collins
product of De Kalb's classifier 1402	M. P. Boss
nne grinding system at Mill 105 1638 settling tanks at Mill 144 1776 1777 1770	pig
 Sherman settling tanks at Mill 132 1406 	Kosmann 2039
spilzkasten at Mill 144 1777, 1778	pressed and dried 1075
at Mill 105 1636 Hancock jig feed and middlings 1443 Heberli mill product 259 Huntington mill product 281, 1669 mill feed at mills 1750, 1772 ore broken by hand and machine 13 product of De Kalb's classifier 1402 fine grinding system at Mill 105 settling tanks at Mill 144 1776, 1777, 1779 Slegman settling tanks at Mill 132 spakessfen at Mill 144 1777, 1778 Sturrevant breaker pulp from Bryan mill, high-speed rolls, and	E. A. H. Tays 1419
Huntington mill 1317 coarse and fine rolls at Mill 162 1328, 1329 grinding pans 1284	by aid of milk of lime. T. K. Rose 1419
coarse and fine rolls at Mill 162 1328, 1329	the Sherman system
at Mill 130 1720. 1724	by hand 50 hammers 57
grinding pans 1284 at Mill 130 1720 1724 sand treatment at Mill 117 1671	relative efficiency of heat and electrolytes 1410
sample grinder product	tanks
93	1

iges 1–043, voi. 1.)NE	DM	ESSING. \ Fages 044-1197, Vol.
me settling tanks with steam coils at Mill 144	!	1779	Slocan, British Columbia, treatment of ores by flotation processes. 1 Slope and length of trommels angles, measurement of 1 table of 1 effect of in trommels 737, amalgamated plates 737, amalgamating plates at mills 1622, 1624, 1 in California 1 Argall drier belt conveyor at mills 1667, 1681, 1707, 17
theory	• • • • • •	1149	tion processes
use of chemical to promote	ani :	1418	Slope and length of trommels
heat to promote	1000,	1114	angles, measurement of
at Clausthal	• •	606	effect of in trommels
at Clausthal Mill 177 bibliography for	٠	1893	of amalgamated plates 737
bibliography for		727	amalgamating plates at mills 1622 1624 1
capacity of		697	in California
circular, quantity of water on		694	Argall drier
capacity of circular, quantity of water on		693	Argall drier belt conveyor at mills 1667, 1681, 1707, 17 1709, 1710, 1759, 1760, 1762, 1763, 1764, 18 1831, 1851, 1860, 1861, 1862, 1863, 1868, 18
classification of pulp for		693	1709, 1710, 1759, 1760, 1762, 1763, 1764, 18
slimes for	•	720 692	1831, 1851, 1860, 1861, 1862, 1863, 1868, 18
compared	• •	698	1882, 1 tables 698,
with belt film tables comparison of different circular	:		
construction and operation		684	at mills 1624, 1631, 1633, 1661, 1663, 17 1727, 1743, 1756, 1760, 1761, 1762, 1763, 18 1803, 1805, 1831, 1833, 1
convex versus vanners		691	1727 1743 1756 1760 1761 1762 1763 18
cost of .		691	1803, 1805, 1831, 1833, 1
coupled with Lieve	1	1110	canvas, blanket and carpet tables
vanner	1		tables . 700,
Willley table	1		at mills 1627, 1696, 1755, 1
density of pulp on		695	chutes
diameter and working radius of		697	concentric trommel at Mill 154
fixed circular convex .	4	689 1154	cylindrical drier at Mill 135 1 dewatering screens at Mill 167 1
for testing	,	880	
investigation on		707	elevators at mills
operation of		692	slime tables at Mill 177 1
revolving circular concave .		692	feed chute at Mill 179
convex		686	sole for classifiers
scrapers on		696	spitalutte
size of grains treated	m	693	film sizing tables
slope of . 694, speed of	, 719,	/20	floors in mills 1
speed of		696	Mill 161
step form surface for		689 69 5	German sweeping table
testing .	1	1172	grizdies 1694 1691 1695 1655 1660 14
thickness of water film on		695	grizzites at mills 1624, 1631, 1635, 1655, 1660, 14 1737, 1759, 1792, 1805, 1821, 1828, 1831, 19 1860, 1888, 1892, 1909, 1
velocity of water current .		719	1860 1888 1892 1909 1
water films on .		718	rialien tame
for		695	Hooper air jig
work, effect of shape of grains on tanks, Berenger and Stingls Colorado Iron Works Company		694	Impact screens at Mill 151 1
tanks, Berenger and Stingls	. !	1407	jig hutches
colorado fron works Company	695, 1	1407	screens
use of steam pipes in	642, 1	1671	launders 873, 874, at Mill 152
in Arizona, Scobey		1411	Linkenbach slime table
on the Rand		1410	ore bin bottoms
on the Rand use of steam for settling. A. Salkinson what constitutes a. W. J. Sharwood		2020	picking belts at mills . 1806, 1
what constitutes a. W. J. Sharwood	. 1	1419	Pierce amalgamators 1
mers	884,	1504	plates .
Akens and Evans Bartich rotter percussion table		1500 1497	revolving driers at Mill 138 . 1
Bartsch rotary percussion table belt percussion table		1497 1496	Roberts slime table Robins belt conveyors at mills 1805, 1806, 18 1808, 1809, 1810, 1811, 1812, 1813, 1821, 18 1895, 1826, 1
comparison of Woodbury and Evans slimers		1490	1908 1900 1810 1811 1819 1813 1891 18
Mill 162		1451	1825, 1826, 1
James		1491	rotary driers at Mill 186 . 1320, 1320, 1
Luhrig	1	1496	round tables at Mill 180 1904, 1
Sherman	1	1506	Salzburg table
use of riffles on	1	1498	scraping conveyors at mills 1662, 9
Wilfley		1504	screens
table as		1478	at Mill 158
nes and sand separation at Mill 106		1640	shaking feeders at mills 1837, 1868, 1 grizzlies at Mill 170 launders at Mill 152 1 screens at Mill 111
at Tarnowitz, control of A. W Warwkk, on finely ground chemicals for stilling. W. R. Whitney colloidal silicic acid in. W. A. Caldecott	2	2047 1420	grizzlies at Mill 170
chemicals for a tiling. W. R. Whitney		1419	screens at Mill 111
colloidal silicic acid in. W. A. Caldecott		1419	sides of spitzkasten
theory of wintney and Ober	1	1419	sides of spitzkasten 684, 694,
definitions of 1	394, 1	1397	
De Kalb on .	1	1419	splash plates splash plates Stein, Bilharz, and Luhrig tables tables in film sizing tests
department at Mill 163		1848	Stein, Bilharz, and Luhrig tables .
effect of heat in settling slimy water		1414	tables in film sizing tests 707, 718,
H. A. Megraw on in Cœur d'Alene, the saving of. W.	ر ج	1419	on dredges
in Cœur d'Alene, the saving of. W. Clark		2041	tower screen plates at Mill 158 . 1822, 1824, 1
investigation of slimes by the United States	De-	~11	trommel conveyors at Mill 125
partment of Agriculture	1	1400	
moisture in		1107	at mills 1655,1681, 162'8 1685, 1690, 1691, 16
plant at Mill 162	1	1846	1693, 1701, 1702, 1703, 1710, 1714, 1724, 17
question	1	1120	rommeis at mills 1655,1681, 162'8 1685, 1690, 1691, 16 1693, 1701, 1702, 1703, 1710, 1714, 1724, 17 1737, 1742, 1743, 1749, 1750, 1751, 1752, 17 1818, 1828, 1829, 1832, 1837, 1832, 1842, 1846, 1853, 1854, 1855, 1857, 1869, 1876, 18 1884, 1888, 18988, 18988, 18988, 18988, 18988, 18988, 18
	1	1147	1818, 1828, 1829, 1832, 1837, 1837, 1842, 18
settling of		1419	1846, 1853, 1854, 1855, 1857, 1869, 1876, 18
roasted. P Argall	1		
roasted. P Argall	2	2026	1002, 1000, 1090, 1
roasted. P Argall	1	2026 401	under unents
roasted. P Argall	2	2026 401 2020	vanners 648, 653, 654, 659,
roasted. P Argall steel bar riffles for gold ultra microscope for the study of what constitutes. A. W. Warwick my water affecting jig work	2	2026 401 2020 599	vanners 648, 653, 654, 659, table of, in degrees and inches 1
roasted. P Argall steel bar riffles for gold ultra microscope for the study of	2	2026 401 2020 599 1149	vanners 648, 653, 654, 659,

1435	·	,
Source, new Australian shaking	Sludge from hand jigs	Sorting in small mills, hand, A. W. Warwick 2032
Source, new Australian shaking	mill 902	tables, Allis-Chalmers annular picking or sorting
Stages, Sona wire lian shaking 916	practice of Missouri-Kansas district 2043	table 1435
Pate Company	tank, Ramsey 440	and belts, speed and capacity of 1438
Pate Company	Sluice, new Australian shaking 2029	Humboldt picking table 1437
Statics, Bowle's figures on sizes and carrying power of corundum or 1078 rifles 1070, 1000, 1012 rifles 1070, 1010, 1012 rifles 1070, 1012 rifle	plates 740	Krupp picking tables 1435
Statics, Bowle's figures on sizes and carrying power of corundum or 1078 rifles 1070, 1000, 1012 rifles 1070, 1010, 1012 rifles 1070, 1012 rifle	article on 2012	tube, Bardwell
riffles of defection of the state of the sta	riffes 1464	investigation of free settling 465
riffles of defection of the state of the sta		discussion of results of
riffles of defection of the state of the sta	for comindum one	results, fastest grains 400
Smattle, spectine gravity of surreview and bloomed contentation of surreview and plate traing telluride ore 1175 O., gravity stamps 123 Kaude for gravity of surreview and plate 1775 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smyth's formula, 1880 Smyth's formu	riffles 723	stowest grains Too
Smattle, spectine gravity of surreview and bloomed contentation of surreview and plate traing telluride ore 1175 O., gravity stamps 123 Kaude for gravity of surreview and plate 1775 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smyth's formula, 1880 Smyth's formu	on dredges 1007, 1008, 1012	use made of in mills 889
Smattle, spectine gravity of surreview and bloomed contentation of surreview and plate traing telluride ore 1175 O., gravity stamps 123 Kaude for gravity of surreview and plate 1775 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smyth's formula, 1880 Smyth's formu	undercurrents	Source of water 1105
Smattle, spectine gravity of surreview and bloomed contentation of surreview and plate traing telluride ore 1175 O., gravity stamps 123 Kaude for gravity of surreview and plate 1775 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smithsonite and limonite separated by roasting and magnetism specific gravity of 1889 Smyth's formula, 1880 Smyth's formu	Small steam stamps 136	South Africa, diamond washing in
Smelting compared with concentration 1	Smallite, specific gravity of 1189	gold mills
Smith, F. C., stamping, analgamating, and concentrating tellurated or training tellurated	Smalting compared with concentration	nanu picking in
Second Process of Wire and plate 174 Stamp practice 221 Stamps in 222 Stamps in 223 Stamps in 224 Stamps in 225	Smith, F. C., stamping, amalgamating, and concen-	mills in 1173, 1179, 1185
Second Process of Wire and plate 174 Stamp practice 221 Stamps in 222 Stamps in 223 Stamps in 224 Stamps in 225	trating telluride ore . 1175	picking tables in 491
R. G., settling fine silmes 1185 Valle tiller press at Mill 101 1028 Valle tiller press at Mill 101 1028 Valle tiller press at Mill 101 1038 Valle tiller press at Mill 107 1858, 1859 Smooth belss for Frue vanners at Mill 107 1858, 1859 Smougler Munng Company 1700 Mill of Mills at Mill	O., gravity stamps	screen meshes
Vaile filter press at Mill 101 Smithsonite and limonite separated by roasting and magnetism magnetism magnetism Mill 101 Smooth belts for Frue vanners at mills 1704, 1808, 1870 Johnston vanners at Mill 107 Smooth belts for Frue vanners at mills 1704, 1808, 1870 Johnston vanners at Mill 107 Smooth belts for Frue vanners at Mill 107 South for Brooth for the engineer 108 Smooth of Vanner at Newton mill, Colorado 227 Sampler mirometer gauge for ore grade of the part of the standard of th	gauges for wire and plate 1174	stamp practice
magnetism spectic gravity of Smitter specific gravity of S	Voils files range at Mill 101	stamps in 220
magnetism spectic gravity of Smitter specific gravity of S	Smith-onite and limonite separated by roasting and	weight of quartz in 1185
spectife gravity of Smittem Smittem Smooth beits for Frue vanners at mills 1704, 1808, 1870 Johnston vanners at Mill 167 1808, 1870 Johnston vanners at Mill 1701, 1808, 1870 Johnston vanners at Mill 167 1808, 1870 Smuggler Mining Company 1700 Mining Co, mill 1709, 2033 Smythis formula 1904 Smake River, Caribou rifile on 1509 Snake River, Caribou rifile on 1509 Snake River, Caribou rifile on 1600 Idaha, dredging on 1013, 1181 hydraulicking on 1013, 1181 hydraulicking on 1013, 1181 hydraulicking on 1013, 1181 hydraulicking on 1014, 1181 hydraulicking on 1016, 1818 Synder of CA La Point gold separator on 1500 Snyder, F. T., amalgamating plates 742 gyrating amalgamated plates 788 gyrating amalgamating plates 788 gyrating amalgamated plates 788 gyrating amalgamating 788 gyrating amalgamating 788 gyrating amal	magnetism 814	Carolina, phosphate dressing in
Smooth belis for Frue vanners at mills 1704, 1808, 1870 Smooth belis for Frue vanners at mills 1704, 1808, 1870 Johnston vanners at Mill 167 1885, 1859 Smogler Mining Company 180, 180, 180, 180, 180, 180, 180, 180,	specific gravity of 1189	washing in
John-ston vanners at Mill 167 1858, 1859 United mill, mercury wells in 768, 769 mill mill ming Company 1700 plates in plates in 164 plate in 164 plates in 768, 769 mill Minning Co., mill 1011 1	Smittem 894. 901	Clunes, false bottoms in mortar 180
Union mill, Telluride, Colorado 1176, 2043 Summing Co., mill 1016 Smyth mill, Stamps at 228 Smyth's formula 22	Smooth belts for Frue vanners at mills . 1704, 1868, 1870	
Union mill, Telluride, Colorado 1176, 2043 Summing Co., mill 1016 Smyth mill, Stamps at 228 Smyth's formula 22	Smurrler Muner Company 1700	United mill, mercury wells in 708, 709
Smyth mill, stamps at 228 Smyth's formula 1944 1		plates in 177
Smyth mill, stamps at 228 Smyth's formula 1944 1	Union mill, Telluride, Colorado . 1176, 2043	Spring Hill mine, false bottoms in mortars . 180
Smyth's formula 1944 connecting rows in blende Jugs in 550 552 552 553 553 554	Mining Co., mill 1016	Southwest Missouri, clearance of plunger in blende
oredges on hydraulicking on 1013, 1187 cost of Space Between rois. Cost of Space Fellows product of, crushing Przibram ore grains grain gamalgamated plates 728, 2022 importance of mill constants for the engineer 2048 yanner 2049 grains	Smyth mill, stamps at	jigs in 530
oredges on hydraulicking on 1013, 1187 cost of Space Between rois. Cost of Space Fellows product of, crushing Przibram ore grains grain gamalgamated plates 728, 2022 importance of mill constants for the engineer 2048 yanner 2049 grains	Smyth's formula . 1944	connecting rods in blende jigs in
Idaho, derdging on	Snake River, Caribou riffic on	Space between rolls 64 80
hydraulicking on use of C A La Point gold-separator on 1500	Idaho dredging on 1013 1181	
Spain F. T. amalgamating plates discussion of costs, micrometer gauge for ore grains 1178 Spain, iron ore dressing in 1178 Spain, iron ore dressing 1178 Spain, iron ore dressing in 1178 Spain, iron ore dressing 1178 Spain, iron or dressilating table 1178 Spain, iron or dressilating table 1178 Spain, iron or dressilating in 1178 Spain, iron or dressilating in degree 1082 Spain, iron or dressilating in degree 1082 Spain, iron or dressilating in degree 1082 Spain degree is degree is degree is degree is degree	hydraulicking on 1006	Spaced rolls, product of, crushing Przibram ore 308
Spudger, F. T., amalgamating plates discussion of costs, micrometer gauge for ore grains 1168	use of C. A. La Point gold separator on 1510	Spadone concentrator belt, the 1503
grains 11,55,56 2022 2022 2024 2025 2024 2025 2026 2	Snyder, F. T., amalgamating plates 741	Spain, iron ore dressing in
Spartage Spart S	discussion of costs, micrometer gauge for ore	Spalling, definition of 480
importance of mill constants for the engineer 2048 magnetic separation 1568 measurement of screen openings 1362 measurement of screen openings 1362 micrometer gauge 1138 measurement of screen openings 1362 surface sizing 728 metallurgal attandards 2019 micrometer gauge 1138 surface sizing surface sizing 844, 815 mortar at Newton mill, Colorado 227 sampler 884 shoes and dies 818 Sayder micrometer caliper 1362, 1366 magnetic separator, F. T. Snyder 2027 changed by roasting 889 magnetic separator, F. T. Snyder 2027 changed by roasting 889 magnetic separator, F. T. Snyder 2027 changed by roasting 889 sampler 846, 1572 difference in for jigging 609 vanner 657 changed by roasting 889 of belts 891 of belt	grams 1176 gyrating amalgamated plates 788	Span of wire rope 1095
importance of mill constants for the engineer 2048 magnetic separation 5568 measurement of screen openings 1362 sime tables 2729 micrometer gauge 1138 mortar at Newton mill, Colorado 227 sampler 884 shoes and dies 181 Snyder micrometer caliper 1362, 1366 separation at Allevard 9, 492 sampler 181 Snyder micrometer caliper 1362, 1366 separation at Allevard 9, 492 sampler 181 Snyder micrometer caliper 184, 1572 definition 1832 difference in 67 jigging 889 magnetic separator. F. T. Snyder 2027 definition 67 silver plating 1930 societé Minière du Gard, Ferraris ball mill at 1300 societé Minière du Gard, Ferraris ball mill at 1300 societé Minière du Gard, Ferraris ball mill at 1300 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 of copper 38 societé Minière du Gard, Ferraris ball mill at 1300 occan water 38 societé Minière du Gard, Ferraris ball mill at 1300 occan water 38 societé Minière du Gard, Ferraris du Minière du Gard, Fer	vanner 728, 2022	Sparre circular oscillating table
magnetic separation 1568 criticism of Rittinger's theory 476, 639 measurement of screen openings 1362 sime tables 728 metallurgical standards 2019 surface sizing 728 micrometer gauge 1138 Spathic iron ore roasted for magnetism 814, 815 sampler 884 Special forms of rolls 104 Shoes and dies 181 Special forms of rolls 104 Support micrometer caliper 1362, 1366 separation at Allevard 9.492 sampler 846, 1572 changed by roasting 889 sampler parator. F. T. Snyder 846, 1572 changed by roasting 889 sampler at mills 1667, 1832 definition of 3 sampler at mills 1667, 1832 definerance in for jigging 3 sampler at mills 1667, 1832 definerance in f	importance of mill constants for the engineer 2048	
metallurgical standards 2019 micrometer gauge 1138 275		criticism of Rittinger's theory 476, 639
micrometer gauge mortar at Newton mill, Colorado sampler shoes and dres shoes and dres shoes and dres shoes and dres sampler s		
Sampler Shoes and dies Shoes and d	metallurgical standards . 2019	Spathic iron are receted for magnetism 814 815
Sampler Shoes and dies Shoes and d	mortar at Newton mill Colorado 227	separation at Allevard 9, 492
Shoes and dies	sampler 884	
at mills vanner Soa For belts Soap	shoes and dies 181	Specific gravity affecting momentum
at mills vanner Soa For belts Soap	Snyder micrometer caliper 1362, 1366	separation 889
at mills vanner Soa For belts Soap	magnetic separator. F. I. Snyder 2027	detunition of 3
Sockets in stamp bosses		difference in for jigging 609
Sockets in stamp bosses	vanner . 657	effect on cost of milling 1128
Sockets in stamp bosses	Soap for belts 1094	free settling 464
Sockets in stamp bosses	Soapstone for lubricating 1097	slime tables 693
Sodi for melting 784 mercury 785	Societé Minière du Gard, Ferraris ball mill at 1300	of copper
Sodium amalgam 730, 1156 minerals and metals 1188 for brightening mercury 785 effect of 3 3 3 3 3 3 4 3 5 5 5 6 5 3 3 3 3 3 3 3 3 3	Sockets in stamp bosses 187	mercury 730
for brightening mercury 785 effect of 3 used in stamp mills 752 ocan water 3 atomic weight of 1188 oils oils oils oils phosphate for brightening mercury 785 our 785 Soft rock phosphate 895 rock affecting power consumption 313 Solution for silver plating 755 sea water 1106 Sondericker, J viii settling power consumption 313 Sorting 892 settling power 1106 Sorting 892 settling power 1455 Sorting 893 settling power 1455 Defore sizing 891 see also each machine Defore sizing 1438 height of drop, limits of, due to mortar 218 Defore settling 1611 septling tables or belts for 1435 settling in air 1611 Sorting 1611 suspended frame vanner 1508 Sorting tables or belts for 4435 settling in air 1611 Sorting 1611 suspended frame vanner 1508 Sorting tables or least of Albis (Chalmers rolls at Mill 179 888 Sorting tables or least of Albis (Chalmers rolls at Mill 139 1788 Sorting 1611 suspended frame vanner 1508 Sorting 1438 suspended frame vanner 238 Sorting 1438 suspended frame vanner 243 Sorting 1611 suspended frame vanner 243 Sorting 1611 suspended frame vanner 243 Sorting 1611 suspended frame vanner 243 Sorting 243 suspended frame vanner 243 Sorting 245 suspended frame vanner 243 Sorting 245 suspended frame vanner 246 Sorting 246 suspended frame vanner 247 Sorting 247 suspended frame vanner 248 So	C di 790 1156	minerals and metals
Solution for Silver Plating Soluting	for brightening mercury 785	effect of 3
Solution for Silver Plating Soluting	used in stamp mills	ocean water
Solution for Silver Plating Soluting	atomic weight of 1188	oils 1098
Solution for silver plating 755 sea water 1106	prospirate for originating mercury	
Sondericker, J. Sondericke	Soft rock phosphate	see water 1106
Sorted products obtained by air Sile Sorting Section Sile Section Stamp Section	Sondericker I viii	settling power 4
Sorting	Sorted products obtained by air 819	test 1159
Robins sorting beit 1435 1631 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635	Sorting	Specimen stamp
Robins sorting beit 1435 1631 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635	before sizing	Speed. See also each machine
Robins sorting beit 1435 1631 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635 1636 1637 1635	belts at Mill 137 1438	and capacity of picking tables and belts 1438
breaking for 1435 of Abb's tube mills at mills 1626, 1677 1435 of Abb's tube mills at mills 1626, 1677 1435 Akron Chili mills, table of 1308 1435 Akron Chili mills, table of 1308 1435 Akron Chili mills, table of 1308 1436 settling in air 1611 suspended frame vanner 1508 1438 vanners at Mill 179 1898 1438 defined 387 Aking cylinder 207 1438 for Richards' classifier 1429 1438 American Blower Company fans at Mill 151 1804 1438 American Blower Company fans at Mill 151 1804 1438 Argald drier 881	by free settling 1611	neight of drop, filling of, due to mortal
Setting in air 101 Suspendent 1186 1739	hand 1435	kept constant
Setting in air 101 Suspendent 1186 1739	breaking for	of Abbi tube mills at mills
Setting in air 101 Suspendent 1186 1739	presing tables or belts for	Akron Chili mills, table of 1308
Setting in air 101 Suspendent 1186 1739	hindered settling 1611	Allis-Chalmers rolls at Mill 179 1898
followed by agritation 891 Argall drier 881	settling in air	suspended frame vanner
followed by agritation 891 Argall drier 881	defined 387	Alsing cylinder 267
followed by agritation 891 Argall drier 881	for Richards' classifier	amalgamating pan . 243, 249
followed by agitation	cost of hand sorting 1438	
suction	followed by agitation	Argall drier 881
	suction	arrastra

Speed of Atwood amalgamator	Speed of Gates breakers at mills
hall mill	Gebruder Sulzer centrifugal pump at Mill
	118 1678
at Mill 159	Gilpin County bumping table 681, 682
	Colden Cute table 681
Barrlett shaking picking table 4499 belt conveyors at mils 1667, 1670, 1690, 1691, 1707, 1708, 1709, 1710, 1759, 1760, 1762, 1763, 1764, 1771, 1772, 1819, 1828, 1831, 1853, 1868, 1	Gould centrifugal pumps at Mill 139
1707, 1708, 1709, 1710, 1759, 1700, 1702, 1703,	Griffin centrifugal stamp mill
1869, 1882, 1883, 1913	mills at Mill 105 1636
of Wetherill magnetic separator 1523	grinding pans at Mill 130 . 1720
percussion tables 1496	Grondal magnetic separators at Mili 199 1626
tables 698, 700	Hallett table 676
belts	Hancock jigs at mills 1710, 1846, 1869, 1930
Bilbarz jig 504, 518	Harticki jigs at little 1710, 1639, 1694, 1791, 1792, 1793, 1794, 1795, 1794, 1795, 1794, 1795, 1794, 1795, 1794, 1795, 1794, 1795, 1797, 1772, 1773, 1774, 1775, 1829, 1837, 1854, 1875, 1877, 1878, 1879, 1885, 1871, 1878, 1885, 1877, 1878, 1879, 1885, 1877, 1878, 1879, 1885, 1877, 1878, 1879, 1885, 1877, 1878, 1879, 1885, 1877, 1878, 1879, 1885, 1877, 1878, 1879, 1885, 1877, 1878, 1879, 1885, 1879,
Blake breakers 17, 21, 24	1703, 1725, 1728, 1744, 1750, 1751, 1752, 1753,
at Mill 139	1767, 1772, 1773, 1774, 1775, 1829, 1837, 1854,
Bogardus mill	Hathaway gyratory breakers, table of . 1217
Bradford jig	Hathaway gyratory breakers, table of 1217 Heberh mill 257
Bryan mill	Hendy concentrator 683
mills at Mill 173 1879, 1928	Hodge and Cleaves sand pumps at Mill 182 . 1910,
Buchanan magnetic separator 600	1911 jigs at mills1902, 1903, 1904, 1905, 1909, 1910,
bucket conveyor	pgs at mins1902, 1903, 1904, 1900, 1909, 1910,
Butters' centrifugal pumps at mills 1671, 1672,	Hooper air jig
1074, 1677	
Byron Jackson centrifugal pumps at mills . 1662,	Huntington mill 278, 279
1673 C. B	Humphrey rolls, table of
Callow screens at mills 1661, 1662, 1887 Card tables at mills 1660, 1770, 1830	Imlay table 681
centrifugal pumps 869, 870	Impact screens at Mill 151 1803
at mills 1694, 1695, 1711, 1712, 1890, 1899,	Impact screens at Mill 151
1904, 1905 Chalmers & Williams vanners at Mill 122 1687	International separators at Mill 1381746, 1747, 1748
Chalmers & Williams vanners at Mill 122 1687 Chili mill 269, 270	Leffrey conveyors at Mill 126 1706
mills at mills 1767, 1893, 1898	Jeffrey conveyors at Mill 126
cleaner pgs at Mill 148 1793	at mills . 1685, 1686, 1707, 1708, 1737, 1738, 1832,
clean up barrels . 265	1846, 1808, 1929
at Mill 111 1656 pans	Johnston vanners
Cole shovel wheel at Mill 124 1693	Kennedy gyratory breakers, table of 1214
Comet breaker 41, 46 concentric frommels at Mill 154 1816	Kent roller mill . 1304
concentric trommels at Mill 154 1816	Knowles duplex vacuum pumps at Mill 117 1673
cone mill 256 Conking ug 503	New Century magnetic separators, table of 1542 triplex pump at Mill 117 1674 Krogh centrifugal pumps at Mill 173 1929
Conking pg 503 conveying and draining belts at Mill 130 1721	Krogh centrifugal numps at Mill 173 1929
picking belts at Mill 139 1749	Krom air jig 824
conveyors . 861	Kenny hall mills at Mill 198 1714
Crane log washer at Mill 95 1617	gyratory breakers, table of 1215
Crickboom wash trommel	Linkenbach stime table 091
Cyclone pulverzer 288	log washer 327 washers at Mill 154
cymorical uriers . 660	machines 1097
De Laval cream separator 827	
Denver Engineering Works Company's Blake breakers, table of 1204	gyratory breakers, table of
breakers, table of 1204 dewatering wheels at Mill 144, 1772, 1773	magnetic separator used at Monteponi 810
disc conveyors 1583	May Brothers' jigs at Mill 128 1714
Dodge breaker 30	methanical balea vosa
pulverizer	Monadnock Chih mills at Mill 144 . 1775
	mortar jigs at Mill 177 1892 movable sieve jig 500
at mills 1667, 1681, 1685, 1689, 1690, 1691,	movable sieve jig 500 Narod pulverizer
1693, 1701, 1702, 1703, 1707, 1710, 1711, 1725,	New Century jigs at Mill 141 1760
elevators 862, 863 at mills 1667, 1681, 1685, 1689, 1690, 1691, 1693, 1701, 1702, 1703, 1707, 1710, 1711, 1725, 1727, 4728, 1729, 1742, 1743, 1749, 1750, 1752, 1753, 1755, 1759, 1760, 1761, 1762, 1763, 1771, 1772, 1771, 1772, 1793, 1894, 1822, 1824, 1825, 1829, 1837, 1838, 1839, 1840, 1842, 1843, 1844, 1845, 1846, 1847, 1853, 1854, 1855, 1857, 1858, 1866, 1867, 1869, 1871, 1877, 1880, 1883, 1889, 1890, 1898, 1910, 1928, 1889, 1890, 1898, 1910, 1928, 1889, 18	New Humboldt concentrators . 1494
1753, 1725, 1759, 1760, 1761, 1762, 1763, 1771,	Overstrom tables at mins 1711, 1750, 1950
1879 1837 1838 1839 1840 1849 1843 1844	Pape-Henneberg dry separator 819 Peck centrifugal separator 828
1845, 1846, 1847, 1853, 1854, 1855, 1857, 1858,	picking belts at mills . 1737, 1806, 1815, 1842, 1882.
1866, 1867, 1869, 1871, 1877, 1880, 1883, 1888,	1880
1889, 1890, 1898, 1910, 1928	conveyor
	tables
Evans jigs at mills 1837, 1838, 1843, 1844, 1845, 1930	tables
round tables at Mill 162 1846	plunger feeders at mills 1749 1750 1857
slime tables at Mill 1//	pneumatic belt concentrator 818
Fans at Mill 186 1917, 1918	
Farrel Blake breakers, table of	push conveyors at Mill 105
Ferraris magnetic separator 799	push conveyors at Mill 105
Frayer centrifugal pumps at Mill 159 1829	Riblet aerial tramway at Mill 124 etc. 1696 Rittinger table Robins belt conveyors at mills 1750, 1805, 1806, 1807, 1808, 1809, 1810, 1811, 1812, 1813, 1824, 1825, 1826, 1876 Conveying and picking belts at Mill 132 1727
Frenier sand pumps at mills 1708, 1769, 1812	Robins belt conveyors at mills . 1750, 1805, 1806,
spiral sand pump 871	1807, 1808, 1809, 1810, 1811, 1812, 1813, 1824,
Frue vanners at mills 1625, 1627, 1662, 1689, 1694, 1695, 1711, 1712, 1844, 1865, 1868, 1870,	conveying and picking belts at Mill 132 . 1727
1029	Robinson iig
Garland disc conveyors at Mill 124 1695	Rock Emery mills
Gates breaker 38, 46	rolls
	94

Speed of rolls and angle of nip	Speed of Willow to Line
speed curves	5peed of willey tables at mills 1708, 1715 1729, 1738, 1739
at mills 1667, 1685, 1688, 1690, 1691, 1693, 1701,	1780, 1829, 1830, 1839, 1844, 1851, 1855
speed curves . 1224 at mills 1667, 1685, 1688, 1690, 1691, 1693, 1701, 1707, 1710, 1714, 1716, 1720, 1724, 1727, 1737, 1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760,	1858, 1867, 1868, 1870, 1894, 1929, 1940
1760, 1742, 1743, 1749, 1750, 1751, 1752, 1760,	Woodbury-Benedict jigs at Mill 177 1893
1735, 1742, 1743, 1749, 1750, 1751, 1752, 1760, 1761, 1762, 1771, 1773, 1792, 1803, 1806, 1807, 1808, 1819, 1822, 1824, 1825, 1828, 1829, 1832, 1833, 1837, 1838, 1843, 1844, 1851, 1857, 1858, 1864, 1865, 1866, 1867, 1868, 1869, 1883, 1890, 1883, 1890, 1883, 1890, 1891, 1911, 1911, 1913, 1928, 1834, 1835,	Speed of Willey tables at mills 1708, 1715 1729, 1738, 1739 1744, 1745, 1745, 1761, 1776, 1777, 1779 1780, 1829, 1830, 1839, 1844, 1815, 1855 1838, 1867, 1868, 1870, 1894, 1929, 1944 Woodbury-Benedict jigs at Mill 177 1896, 1897, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898, 1897, 1898
1833, 1837, 1838, 1843, 1844, 1851, 1857, 1858,	Worthington pump at Mill 175 189
1864, 1865, 1866, 1867, 1868, 1869, 1883, 1890,	proper speeds for sand wheels of various diam-
rotary driers at Mill 186	eters
rotary driers at Mill 186. 1917 rotation for tube mills 1289 round tables at Mill 180 1904 1905 Salzburg table 683 sample grander 257 samplers 848	Sperm oil 17aylor centrifugal pumps 1589
round tables at Mill 180 1904, 1905	Sperry 13
Salzburg table	É. A., amalgamated plates 745, 762, 76
sample grinder	plates for Tremain steam stamps
	mercury traps
sand wheels 865, 866	Tremain stamp 136 139 14
at miles 1008, 1009, 1077, 1715	trap in Cross mill
Sautter magnetic separator 798 scraping conveyor at mills 1662, 1709 screw conveyors at Mill 105 table of 1582 settler 1783	use of lve on plates
screw conveyors at Mill 105 1636 1637	Sphalerite and quartz, jig tests on
table of	hindered-settling test on 617 62
	pulsion jig test on 624
settlers 777 shaking feeders at mills	settling velocity of
grizzlies at mills 1690, 1866 launders at mills 1693, 1694, 1761 plattes 7761 streens 342, 345 at Mill 175 1889	specific gravity of
plates	Spiders for trompole 250 25
screens	Spigots for classitiers 388, 404, 433, 442, 44
at Mill 175 1889 Sherman re-grinders at Mill 132 1728, 1729	jigs 507, 52
Sherman re-grinders at Mill 132 . 1728, 1729 Siemens and Halske magnetic separator 798	spitzkasten 44
Siemens and Halske magnetic separator 798 magnetic separator 804	Spilsbury, E. G., breakers 6
simple steam stamp at Mill 182 . 1909	Engis machine 83
slime tables . 684, 696	jıg 52
sorting tables at Mill 177 1892	riddles versus trommels 38
stamps at milk 1618, 1620, 1621, 1624, 1626, 1632, 1640, 1658, 1661, 1668, 1677, 1769, 1915	Spindle and jaw breakers, table of products of 5
in California	
steam stamps 126	compared
Stedman disintegrator 286	compared 45, 4 comparison with jaw 5
Stem, Bilharz, and Luhrig tables 670 Sturtevant Dodge type breakers, table of 1205	continuous action of 5
Sturtevant Dodge type breakers, table of emery mill at Mill 186 1918	Cost of 5 details in the mills 4 distribution of crushing in the mill 5
mill	details in the mills
roll jaw breaker	fine crushing in . 5
roll jaw breaker 33 rotary breakers at Mill 186 1917 Sutton, Steele, and Steele dry tables at Mill	friction . 5
151 1803	having greatest movement on smallest lump 36, 120
take-off belts of Wetherill magnetic separators 1524	heads and concaves 4 mill data on 4
Traylor Centrifugal pump at Mill 114 1662	number used
jugs at Mill 170 1867	power of 5
Tremain stamp 138 Priumph vanners at Mill 101 1627 1627	principle of action 5
Friumph vanners at Mill 101 1627 trommel conveyor at Mill 125 1700 trommels 347, 349, 362	running cost
trommel 347, 349, 362	table of comparative tests of 4
trommels 347, 349, 362 at mills 1617, 1655, 1667, 1681, 1682, 1685, 1690, 1691, 1692, 1693, 1701, 1702, 1703, 1707, 1710, 1714, 1724, 1725, 1727, 1728, 1737, 1738, 1742, 1743, 1749, 1750, 1751, 1752, 1760, 1766, 1767, 1771, 1772, 1773, 1774, 1792, 1803, 1818, 1828, 1829, 1832, 1837, 1838, 1842, 1843, 1846, 1853, 1857, 1867, 1869, 1876, 1877, 1882, 1890, 1898, 1913, 1928, 1930, effect, of	heads and concaves 4 mill data on 4 mumber used 5 power of 5 principle of action 5 running cost 5 size and shape of mouth 5 table of comparative tests of 4 cost of crushing by 5 details of sizing tests of opportunity tests of 4 sizing tests of opportunity to 5 sizing tests of opportunity cost of crushing by 5 sizing tests of opportunity cost of crushing by 5 sizing tests of opportunity cost of crushing cost of
1090, 1091, 1692, 1693, 1701, 1702, 1703, 1707,	details of 4
1742 1743 1749 1750 1751 1752 1760 1766	taper
1767, 1771, 1772, 1773, 1774, 1792, 1803, 1818,	taper
1828, 1829, 1832, 1837, 1838, 1842, 1843, 1846,	weight of
1853, 1854, 1855, 1857, 1864, 1866, 1867, 1869,	with equal movement on large and small
effect of	lumps 4. greatest movement on largest lump 4
tube mills at mills	or gyrating breakers 120
Tustin's mill	or gyrating breakers 120
vanner belts 648	Spinel, specific gravity of • 118
vanners 648, 653, 654, 655, 657, 658, 659 at mills 1686, 1687, 1778, 1780, 1930	
Vapart disintegrator 830	the Schmidt
Vezin samplers at mills. 1691, 1701, 1742, 1748,	washing blue for stime tables
1750, 1772	Spitzgerinne 44 Spitzkasten. See Pointed Boxes.
vibration of Sutton, Steele, & Steele dry table 1555 Wilfley table deck 1465	Spitzkasten. See Pointed Boxes.
Wilfley table deck . 1465 Waddell Chili mills at Mill 174 . 1886	Spitzkasten 43 at mills 1777, 1778, 1878, 1878 Richards-Shepard 1401, 1419 Bittings 1401, 1419
wash trommels . 329, 332	Richards-Shepard
pans 333	
water current to move sand and gravel 878	slope, spigots, deflectors, etc 44
waves and thickness of films on amalgamated plates 746	Spitzluite See Tubular Classifier.
Wanstrom magnetic separator 802	Rittinger
wetherm magnetic separator 809	Splash board
Wharton magnetic cobbers at Mili 157 1819	for stamps <u>17</u>
Wheel agitator 780	plates
at Mill 139 1790	Split shovel 157
tables	for sampling 84
tables 673, 675, 1469 at mills 1625, 1633, 1656, 1661, 1662, 1669, 1686, 1687, 1689, 1694, 1695, 1703, 704	SptEdulte See Tubular Classifier. 476, 773, 138 SpicIntuite 420, 242 Splash board 73 for stamps 17 plates 73 Splice for belt 109 Split shovel 157 for sampling 84 Spodumene, specific gravity of 118 Spodumene, specific gravity of 86 Spotes for sand wheels 86
	DODKES FOR SARD WREEK

Spots on amalgamated plates		762 358	Stamp shaft, pulley, and guides	128 182
pipes on slime tables		688	Sholl	141
vanners		647	stems for grizzly bars table of details of	187
Spring board for hand jig	496), 894 1246	table of details of	338 187
hydraulic, and pneumatic stamps pressure on rolls at Mill 167		72		187
at Mill 167	100	1857	Stamping, high speed	2011
stamps	138), 141 143	mills 1645, 1651, 1668, 1	1679
Froitzheim's		143	mills	2012
timbers for hand jigs steam stamps	114	497	Stamps. See Steam, Gravity, Pheumatic, Spring.	2013
Valley coal dressing plant. L. Gluck	117	1, 118 2051	and mortars, table of weights of	164
Valley coal dressing plant. L. Gluck Springs for Bradford jig		501	arrangement of	1108
rolls on Collom jig	••	73 515	at the Simmer Deep, heavy	2013 130
Sprinkler for mercury		760	comparative work of gravity stamps and Hunt-	
Sprocket and chain		1096 356	ington mills 1	1262
for trommels Square Deal mine, Wisconsin, cost of hand pi	cking at	1439	Nordberg single cylinder and compound steam stamps	1254
measures, equivalents of		1187	comparison of	2012
Squeezer, power amalgam Squeezing amalgam	791	1519 1517	Denny hydraulic	1257
Stacker for dredges	1008,	1012	details of steam cylinders, water used and capac- ity	126
Stackpole, M. D., slime precipitating agents settlings	,	1416	die, ring, staves, and shoes for	120
Stack row ting furn on at Mill 138		1419 1747	discharge	129
Stack roasting furnace at Mill 138 . Stage crushing. J. A. Wauchope Stahl, A. W., power by wire ropes Stanly on amalgamated plates		2015	duty of	2013 134
Stahl, A. W., power by wire ropes	XX,	1174	feed for . 1	1224
Stains on amalgamated plates See also Tarnish.	. 750	, 762	floors, bins, and feeding arrangements for crushing lime at Mill 106	128
Stamp battery, definition of		145	foundation, mortar beds, and sills and girders	$\frac{1416}{114}$
foundation of .		145	frame of	118
mortar block of bosses, weight and dimensions		145 186	gravity. See Gravity Stamps.	1948
Dunham's spring		141	at mills 1640, 1658, 1769, 1	1915
for crushing coal, an electrically driven		2013	gravity	1273
frames in the mills		152 158	Candlever frame for	$\frac{1272}{1271}$
Fraser and Chalmers		114	head for lever-operated finger, for	1273
head		185	wedge grip tappet for	1272
Boss Husband		1271 141	cams for	1272
Krause's pneumatic	. '	141	Canda cams for	1276
mill, adjustments of the. C. De Kalb		2011		1270
apphances, some accessory. G. A. Sv bolts for holding down mortar in	vart	2031 1 50	guide blocks for heavy stamps at Mill 107 in South African practice	1267 1645
California		144	heavy stamps at Mill 107	
experiences. A. Del Mar		2049	Krupp cam shaft for	1272
experiments for testing		2011 1137	materials for Wearing parts of	1277 1277
for testing practice. C. De Kalb		2048	mortars	1263
notes on in South Africa	• •	2035 221	Krupp cam shaft for life of shoes and dies materials for wearing parts of mortars order of drop for Pachuca stamp battery	1274
pulp, sizing test and analyses of records. E. P. Brown		303	power for	1274
records. E. P. Brown		2048	principle of	113
tests waste, recovery of		1165 266	and purpose of proportions between weights of parts	$\frac{1262}{1272}$
with gravity stamp and canvas table	•	1038	proportions beliween weights of parts sectional guides for heavy at Simmer Deep hydraulic pneumatic, and spring Krause pneumatic lever Rapid Economy mortar and screens for Nissen, at Boston Consolidated Home Run mill	1268
wooden	2011,	2012	heavy	2013
milling, California versus Colorado discussion of D. Harmon		$\frac{1030}{2012}$	at Simmer Deep	2011 1257
discussion of D. Harmon in California, cost of A Del Mar of free gold ores. D. Harmenn		2045	pneumatic, and spring	1246
of free gold ores. D. Harmenn		2047 2046	Krause pneumatic	141
some suggestions on mills		1013	Rapid Economy	1201 1261
bibliography for		1173	mortar and screens for	119
classifiers in	1101	658	Nissen, at Boston Consolidated	1278
cost of milling cross sills in	1131,	153	Home Run mill	$1204 \\ 1851$
description of two new		2036	gravity	1263
feeding of water to. B. McDonald gravity, forms of frames for		2044 156	gravity Nordberg single-cylinder steam stamp 1247, stamp single-cylinder, indicator diagram, 1	1249
guides in	•	155		250, 1251
timbers		155	tandem-compound steam stamp at Tamarack	
improvements in. C. C. Christensen		2011	and Osceola mills	1254
mud sills for platforms for	١.	152 156	and Oxeola mills on the Rand, heavy piston, piston rod, dash pot, flange, revolving pulley, stamp stem, stamp shoe of Nordberg	2012
posts for .		153	pulley, stamp stem, stamp shoe of Nordberg	
using plates, vanners, and canvas or	blanket	1029	steam stamp	1247
tables with plates and vancers		1018	pulley, stamp stem, stamp shoe of Nordberg steam stamp pneumatic and spring principle of	130
without amalgamated plates		1014	principle of	113
Morison's high speed Patterson Elephant		141 141	See Pneumatic and Spring stamps.	
Patterson Elephant Phœnix atmospheric		141 140	steam, and gravity	224 131
portable prospectors	:	2011	principle, purpose and classification	113
pulp consistency of		413	ring	120
Rapid Economy	. 1261,		safety devices	127
		9	0	

Pages 1199-1610, Vol. III.	INDE	X. Pages 1611-2052, Vol. IV.
Stamps, screen for shaft, pulley, and guides shoes sizing tests on spring stawes stawes steam See Steam Stamps	120	Steam pipe for amalgamating pan 243
shaft, pulley, and guides	128 120	pipes for drying
sizing tests on	315	power in mills. See Individual Mills in Chapter XX.
small steam	136	Steam pipe for amalgamating pan 243
spring	141 120	on steam stamps 126
steam. See Steam Stamps.	120	separator 1091
steam	113	stamp, Allis 114, 116, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 131, 133 area of discharge 129
discharges for	1256	area of discharge 190
discharges for foundations, anvil blocks, mortar beds, sills, and girders of Nordberg steam stamp indicator diagrams of tandem or steeple-com-	1045	Ball .114, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 130, 131, 132, 133, 134 Cuyahoga .114, 118, 119, 121, 122, 123, 126, 127,
indicator diagrams of tandem or steeple.com	1247	128, 130, 131, 132, 133, 134
	1255	128, 133
Krause mortar discharge for mortar jig discharge for Nordberg steeple-compound at Mill 181 pneumatic and spring principles of action	1256 1256	Fisher's
Nordberg steeple-compound at Mill 181	1254	Fraser & Chalmers 114, 116, 118, 119, 120, 121, 122, 123, 126, 127, 128, 131, 133 indicator bell
pneumatic and spring	113	marcator ben
single-cylinder at Mill 182	1246 1254	Laboratory 2011
principles of action single-cylinder at Mill 182 sizing test on Butte ore crushed by		Laboratory 2011 Leavitt .114, 115, 116, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 131, 132, 133, 134
steam cylinder, valves, and valve gears of	1940	120 mings
table of efficiency of	1249 133	mills in Montana 984 at Lake Superior 990 mortar discharges 993 Nordberg 997, 1247
tandem or steeple-compound	1250	mortar discharges
use of and quality of work of	134 121	Nordberg 997, 1247
of valve action	127	foundations, anvil blocks, mortar beds, sills, and girders 1247 single-cylinder stamp 1249
foundations and mortar beds	118	single-cylinder stamp 1249
sills and girders for tests on work required for	118 306	single-cylinder stamp
their principle, purpose, and classification 113	1246	ola mills
Traylor gravity velocity of fall in	1278 315	prospector's
versus ball mills, as slime makers at Mill 185	1916	prospector's 2011 screens, material, size, life, etc. 121 shaft, pulley, and guides 128 Sharpneck 136
Bryan mill Griffin mill	273	Sharpneck 136
	284 314	Tremain 136 Union Iron Works .114, 117, 118, 119, 122, 123,
weight of and effectiveness of blow	218	126, 127, 128
weights and duty of Wellman, Seaver, Morgan gravity	2013 1278	Wilson's 126, 127, 128
Stand pipes	1106	Wood
Stand pipes for Tamarack classifier Standard Consolidated mill	397	action of
amiliam ted plate in	$\frac{228}{766}$	at mills 1892, 1895, 1897, 1899, 1901, 1906, 1909 bibliography for 142 capacity of 130 cards of 131
	1588 1308	capacity of
Iron Works, Lane slow-speed mill machines	1308 1097	cards of
The state of the s	1183	clean-up 134 comparative performance of Nordberg single-
mill Idaho, milling at the. J. R. Finlay mine, tube mill lining at the Bodie, Cal., slope of launder at Mining Co., mill	2033	
Bodie, Cal., slope of launder at	2014 1549	cost of crushing by 134 cross-compound 1250
Mining Co., mill .	947	cylinder clearance
ten-stamp battery Standardization of laboratory screens. W. S. Hutch-	1267	dash pot on
inson	1366	die, ring, staves, and shoes 120 different makes of 2011 discharge of 129, 1256 efficiency of 131
inson	1361	discharge of 129, 1256
	2019 2019	efficiency of 131 energy, momentum, and efficiency 133 floors, bins, and feeding 128
Standards, metallurgical. F. T. Snyder	2019	floors, bins, and feeding 128
Stanwood gravity muller 1970	1285	foundation, mortar peds, sins, and girders 114
Stapff, F. M., Stapff jig 642	643	history of . 2011
report of committee on Standards, metallurgical. F. T. Snyder Stanford, C. P. Stanwood gravity muller Stapft, F. M Stapft ig Star Canon, Nevada, Krom jig at of the East mill, amalgamated plates in Ballarat, acid water mercury wells in	824	indicator diagrams of single-cylinder Nords
Ballarat, acid water	173	berg 1250, 1251 tandem or steeple compound . 1255
mercury wells in	771	Krause discharge • 1003 1256
Starr G. W. Empire gold stamp mill at Grace Val-	880	Leavitt differential cylinder . 124
ley Stationary picking tables . screens	1184	mortar and screens 119 housing 119, 120
Stationary picking tables	488	jig discharge for . 1256
for dredges	1012	on gold ores 135 piston, stroke, speed, water, capacity 126
Staurolite, specific gravity of	1189	piston rod, dash pot, flange, revolving pulley.
Staves, details of from mills	1189 214 123	stamp stem, stamp shoe
for steam stamps	120	principle of
Stay battery	224	action 1246
box for jigs	214 551	rupper cushion for 116, 127
boxes for jig discharges	584	Stamp stem, stamp shoe 1247
overflow mediar, Schorr	1266	single-cylinder at Mill 182 1254
of Nordberg steam stamps	1249	sizing tests
for heating	1098	spring timbers for . 114, 118
hammers	1091	steam cylinder, valve, and valve motion 122 tandem or steeple-compound 1250
Staurolite, specific gravity of Stausatz Staves, details of, from mills for steam stamps Stay battery for stamps box for jigs boxes feg jig discharges overflow fine arr, Schorr Steam cylinder for steam stamps of Nordberg steam stamps for heating. power hammers jacket for amalgamating pan jig	243	
Jig	£19	at Mill 182 1909
	97	

Pages 1-643, Vol. I. ORE DE	Pages 644-1197, Vol. II.
Steam stamps, types of	Stokes, G. G., velocity of a sphere falling through
used for malleable minerals	a viscous liquid A, asbestos milling in Canada. Britannia Copper Co. mill, B. C. 2046 Britannia Copper Co. mill, B. C. 2046 Coniagas mill, Colalt, Ontario 2046 damond washing in Africa 2046 milling at Broken Hill 2046 Ressland datret, B. C. 2046 2046
uses and sizing tests	R., aspesios milling in Canada 2046
versus gravity stamps	Coniagas mill, Cobalt, Ontario 2046
versus gravity stamps 134 rolls at Mill 179 1900 water used 129 121 121	diamond washing in Africa 2046
water used	milling at Broken Hill
weights, life, etc., of shoes, dies, rings, staves 122	Compressive strength of each of the multing at the Manual State of the multing at the Manual State of the multing at the Manual State of the Man
used for heating water for amalgamation	mill practice in Australia 2046
Stearns Roger Manufacturing Company has con-	tin industry of Tasmania
Stearns-Roger Manufacturing Company, hoe conveyor at Mill 141 1762 1807 1761 1807 1807 1662 1807 1662 1807 1662 1807 1662 1807	tube milling in New Zealand
Mill 152 1807	Stolberg, jig eccentrics at 532
roll speeds	Stone, compressive strength of
Wetherill magnetic separator	rifiles 721
Stedman's disintegrator 236, 284	riffles 721 riffles 721 tests on at Watertown arsenal 300 Stoppages in mills 1115 Storage bins 843
bibliography for	Stoppages in mills
fertilizers 286	Storage Diffs 043 1106 1106 1106 1106 1106 1106 1107 1106 1107
of, at Eagle, West Virginia 285	Storehouse for mill
	Storing concentrates 1112
consumption of shoes and dies at Mill 117 1668	Storms, W. H., California gold mills
consumption of shoes and dies at Mill 117 1668 for jig screens 545 roll shells 68 springe 73 shoes and dies 182, 183, 184 steum stamp wearing parts 122 frame for mills 1088 log washer 325 McLanahan's 325 plate screens 173	Storms, W. H., Catifornia gold mills 1179
springs	Story in mill building 1086
shoes and dies	Stoves for heating 1099
frame for mills 1088	Yguana, Mexico
log washer	Strainer for classifiers
McLanahan's	water 858
plate screens	Strakes 725 Strainer for amalgam 781
scraper for amalgamated plates 758, 762	Strands in wire rope 1095
specific gravity of	Strength of culve and prisms tested at Rerlin 302
plate screens 173 173 174 175	machines
Steep end shake vanner	stone 300, 315
indicator diagrams 1255	before and after heating, tested at Berlin 302
steam stamp at mills . 1254, 1895, 1899, 1901	parallel and perpendicular to bedding
Stelan, H., Bryan mili	Streese in machines 1000
Stein table	Stretch of belt
Steeple compound or tandem steams stamps 1250 Indicator diagrams 1254 1895, 1899, 1901 Stefan, H., Bryan mill 1254, 1895, 1899, 1901 Stefan, H., Bryan mill 1177 Stein table 660, 698 Stemenbruck, mill at 1176 Rittinger tables at 668 Stem for gravity stamps 187 guides at Mill 96 1618 Stem Winder Mill xxxi, 951 Stem Mills Stem Winder Mill xxxi, 951 Stems, fatigue of stamp 2012 of Northers steam stamps 1249 2012	Store
Stem for gravity stamps 187	Stroke of jure 553 594
guides at Mill 96	Stroke of jigs 553, 594 movable sieve jig 500 steam stamps 126 on Wiltley table 673, 675
Stem Winder Mill xxvi, 951	steam stamps
of Nordborg storm stamps 1949	See also Throw.
removal of broken stamp	Strokes, number of, in jigs 592
Steins, fatigue of stamp 2012 of Nordberg steam stamps 1249 removal of broken stamp 2011 Stephante, specific gravity of 1188 Stephen Lavagnino's arrastras xxviii, 1039 Stephens-Adamson Manufacturing Company, belt conveyors at Mill 171 1868, 1869 elevator buckets at Mill 126 1868, 1869 elevator buckets at Mill 126 1868, 1869	Strontunite, specific gravity of
Stephen Lavagnino's arrastras	Strontium, atomic weight of Strond, E. H. and Company, disintegrator and pul-
conveyors at Mill 171	verizer
elevator buckets at Mill 126 1707 self-oiling carrier for conveyor belt	
activiting carrier to conveyor bent 1000	tables of sizes, capacities, power, etc., of the 1320,
tripper for discharging conveyor belts 1586 Vibracone separator 1352, 1360	Structure and fracture of minerals
Step roller (rusher mill 2017	Stubbs wire gauge 1194 screen gauge 172
Steps on slime tables	screen gauge
Mill Elv. Nevada, W. R. Ingalls 2039	Studying mills, method of
Steps on slime tables Steps on slime tables Steps or slime tables Steps or Valley Smelting and Mining Company 1852 1	Stuff treated by pans, table of size of 248
magnetic separation	Stupakoff, S. H., on wire gauges 2019
Sterrett, D. B., monazite sand dressing in the Carolinas 2030	Sturm, Friedrich, separation processes
Stetefeldt, C. A., gravity crushers	balanced rolls, description of 1232
stamps 226	table of sizes, power, weights, dimensions,
leaching silver with hyposulphite 1174	etc 1234 B. F. Co. heating apparatus 1000
lixiviation	breaker 1223
of silver ores xx	diagram of
Stewart jig in coal washing	for testing
system of coal washing D T Blaker 2051	table of sizes, power, weights, dimensions, etc. 1234 B. F., Co., heating apparatus 1099 breaker 1223 diagram of 32 for testing 1137 centrifugal rolls 2010 description of 1237 Dodge-type breaker 1205 fan at Mill 105 1636 borzontal emery mill at Mill 186 1918
Stewart's mill, wear of amalgamating pans 249	Dodge-type breaker
Stibilite, specific gravity of	fan at Mill 105 1636
Stewart's mill, wear of amalgamating pans . 249 Stibinite, specific gravity of . 1189 Stickles mill of the Utica Company . xxviii, 1034 Sticks, removal of . 882 Stilbite, specific gravity of . 1189 Stilb relations	horizontal emery mill at Mill 186
Stilbite, specific gravity of	rock emery mill 253
Suc pulverizer	sample grinders
	Sturtevant breaker
in settling fine slimes	bibliography for
Stirring arms in trough washers 320 in settling fine slimes 1148 Stirrup feeder 854	details of
Stock house for ore	Mill Company, rolls 1918
Stokes, G. G., law of viscous resistance 1423	data of sizes 33

Pages 1199-1610, Vol. III.	INDE	X. Pages 1611-2052, Vol. IV.
Stamps, screen for shaft, pulley, and guides shoes sizing tests on spring stawes stawes steam See Steam Stamps	120	Steam pipe for amalgamating pan 243
shaft, pulley, and guides	128 120	pipes for drying
sizing tests on	315	power in mills. See Individual Mills in Chapter XX.
small steam	136	Steam pipe for amalgamating pan 243 pipes for drying 882 power in mills 1089 power for mills 1090 pressure in mills 1090 on steam stamps 126 pumps 871 separator 1091 stamp, Allis 114, 116, 118, 119, 120, 121, 122, 123, 124 124, 125, 126, 127, 128, 131, 134
spring	141 120	on steam stamps 126
steam. See Steam Stamps.	120	separator 1091
steam	113	stamp, Allis 114, 116, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 131, 133 area of discharge 129
discharges for	1256	area of discharge 190
discharges for foundations, anvil blocks, mortar beds, sills, and girders of Nordberg steam stamp indicator diagrams of tandem or steeple-com-	1045	Ball .114, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 130, 131, 132, 133, 134 Cuyahoga .114, 118, 119, 121, 122, 123, 126, 127,
indicator diagrams of tandem or steeple.com	1247	128, 130, 131, 132, 133, 134
	1255	128, 133
Krause mortar discharge for mortar jig discharge for Nordberg steeple-compound at Mill 181 pneumatic and spring principles of action	1256 1256	Fisher's
Nordberg steeple-compound at Mill 181	1254	Fraser & Chalmers 114, 116, 118, 119, 120, 121, 122, 123, 126, 127, 128, 131, 133 indicator bell
pneumatic and spring	113	marcator ben
single-cylinder at Mill 182	1246 1254	Laboratory 2011
principles of action single-cylinder at Mill 182 sizing test on Butte ore crushed by		Laboratory 2011 Leavitt .114, 115, 116, 118, 119, 120, 121, 122, 123, 124, 126, 127, 128, 131, 132, 133, 134
steam cylinder, valves, and valve gears of	1940	120 mings
table of efficiency of	1249 133	mills in Montana 984 at Lake Superior 990 mortar discharges 993 Nordberg 997, 1247
tandem or steeple-compound	1250	mortar discharges
use of and quality of work of	134 121	Nordberg 997, 1247
of valve action	127	foundations, anvil blocks, mortar beds, sills, and girders 1247 single-cylinder stamp 1249
foundations and mortar beds	118	single-cylinder stamp 1249
sills and girders for tests on work required for	118 306	single-cylinder stamp
their principle, purpose, and classification 113	1246	ola mills
Traylor gravity velocity of fall in	1278 315	prospector's
versus ball mills, as slime makers at Mill 185	1916	prospector's 2011 screens, material, size, life, etc. 121 shaft, pulley, and guides 128 Sharpneck 136
Bryan mill Griffin mill	273	Sharpneck 136
	284 314	Tremain 136 Union Iron Works .114, 117, 118, 119, 122, 123,
weight of and effectiveness of blow	218	126, 127, 128
weights and duty of Wellman, Seaver, Morgan gravity	2013 1278	Wilson's 126, 127, 128
Stand pipes	1106	Wood
Stand pipes for Tamarack classifier Standard Consolidated mill	397	action of
amiliam ted plate in	$\frac{228}{766}$	at mills 1892, 1895, 1897, 1899, 1901, 1906, 1909 bibliography for 142 capacity of 130 cards of 131
	1588 1308	capacity of
Iron Works, Lane slow-speed mill machines	1308 1097	cards of
The state of the s	1183	clean-up 134 comparative performance of Nordberg single-
mill Idaho, milling at the. J. R. Finlay mine, tube mill lining at the Bodie, Cal., slope of launder at Mining Co., mill	2033	
Bodie, Cal., slope of launder at	2014 1549	cost of crushing by 134 cross-compound 1250
Mining Co., mill .	947	cylinder clearance
ten-stamp battery Standardization of laboratory screens. W. S. Hutch-	1267	dash pot on
inson	1366	die, ring, staves, and shoes 120 different makes of 2011 discharge of 129, 1256 efficiency of 131
inson	1361	discharge of 129, 1256
	2019 2019	efficiency of 131 energy, momentum, and efficiency 133 floors, bins, and feeding 128
Standards, metallurgical. F. T. Snyder	2019	floors, bins, and feeding 128
Stanwood gravity muller 1970	1285	foundation, mortar peds, sins, and girders 114
Stapff, F. M., Stapff jig 642	643	history of . 2011
report of committee on Standards, metallurgical. F. T. Snyder Stanford, C. P. Stanwood gravity muller Stapft, F. M Stapft ig Star Canon, Nevada, Krom jig at of the East mill, amalgamated plates in Ballarat, acid water mercury wells in	824	indicator diagrams of single-cylinder Nords
Ballarat, acid water	173	berg 1250, 1251 tandem or steeple compound . 1255
mercury wells in	771	Krause discharge • 1003 1256
Starr G. W. Empire gold stamp mill at Grace Val-	880	Leavitt differential cylinder . 124
ley Stationary picking tables . screens	1184	mortar and screens 119 housing 119, 120
Stationary picking tables	488	jig discharge for . 1256
for dredges	1012	on gold ores 135 piston, stroke, speed, water, capacity 126
Staurolite, specific gravity of	1189	piston rod, dash pot, flange, revolving pulley.
Staves, details of from mills	1189 214 123	stamp stem, stamp shoe
for steam stamps	120	principle of
Stay battery	224	action 1246
box for jigs	214 551	rupper cushion for 116, 127
boxes for jig discharges	584	Stamp stem, stamp shoe 1247
overflow mediar, Schorr	1266	single-cylinder at Mill 182 1254
of Nordberg steam stamps	1249	sizing tests
for heating	1098	spring timbers for . 114, 118
hammers	1091	steam cylinder, valve, and valve motion 122 tandem or steeple-compound 1250
Staurolite, specific gravity of Stausatz Staves, details of, from mills for steam stamps Stay battery for stamps box for jigs boxes feg jig discharges overflow fine arr, Schorr Steam cylinder for steam stamps of Nordberg steam stamps for heating. power hammers jacket for amalgamating pan jig	243	
Jig	£19	at Mill 182 1909
	97	

Tables, blanket .703, 1464, 1507 building type .704 bumping .1497 and jerking .667 canvas .700, 1035, 1464, 1507 carpet and blanket .703	Tailings plant at Kellogg, Idaho 2048
bumping	of Calumet & Hecla Mining Co., Michigan 2046
and jerking	Mill 177 1894
carpet and blanket 703	removal of, from jigs
carves of Wilfley group caryet and blanket 703, 1035, 1464, 1507 carpet and blanket 703, 1035, 1464, 1507 classification of Wilfley group coord matting 702	reservoirs
classification of Wilfley group	sampler 848
Bartsch rotary percussion table 1497	sand and slimes in the Witwatersrand, handling
belt-percussion table 1496	of. H. R. Skinner 2047
Card concentrator	treatment of 1110 2048
Christensen concentrator	at Tintic, Utah,
cleaned ore plane in	used for filling 925
deck of Wilfley	weight of
Deister concentrators	wheels
elevator or raff wheel for Wilfley table 1468	mechanical efficiency of 1609
feed box for Wiltley table 1468	spokeless. L. H. Lavenstein 2032
Ferraris 1490 foundation for Wilfley table 1465	versus pumps in Wilwalersrand 1645
general comments on 1498	and proper speed
head motion for Wilfley table 1466 height of riffle cleats for Wilfley table 1468	Talc, angle of nip required to crush 94
investigation of Wilfley table work 1469	effect on mercury
James table 1490	ground in buhrstone mill 253
slimer	specific gravity of 1189
Luhrig-Buss concentrating table 1492	for belts
shmer 1496	Tamarack clasifier
1491	Take-off belts of Wetherill separator, width, thickness, and proper speed 1524 Talc, angle of nip required to crush 94 effect on mercury 751 grinding mill. J. N. Nevins 2014 ground in buhrstone mill 253 specific gravity of 1189 Tallow 1097 for belts 1903 Tamarack clastiter 397 mill, Burgan classifier at 1371 Nordberg tandem-compound stamps at 1254
new Standard concentrator 1493 new Standard concentrator 1478 operating conditions for Wiltley table 1469 Overstrom table Pinder concentrator 1479 riftle cleats for Wiltley tables 1479, 1485 roughing plane in 1465	Nordberg tandem-compound stamps at 1254 rigid rolls at 1237 Mining Company mill xxvii, 1000, 1181 Tandem-compound steam stamps 1250 at Tamarack and Osceola mills 1254 indicator diagrams 1255
operating conditions for Wiltley table 1469	Mining Company mill xxvii, 1000, 1181
Pinder concentrator	at Tamarack and Osceola mills 1254
riffle cleats for Wilfley tables 1467	indicator diagrams 1255 trommels 302 Tank for constant head 858 washing with hand picking 488 house at Mill 161 1840
roughing plane in 1465 "setting up" and "leveling up" Wilfley tables 1468	Tank for constant head 858
sized versus classified feed for	washing with hand picking 488
speeds for Wiltley table 1469	house at Mill 161 . 1840
roughing plane in 1465 "setting up" and "leveling up" Wilfley tables 1468 sized versus classified feed for 1478 speeds for Wilfley table 1469 Sutton, Steele & Steele dry table 1479, 1544 tilling frame for Wilfley table 1457 wash water for Wilfley table 1469 Wilfley 1469	washing with hard picking 488 house at Mill 161 1840 system of working amalgamating pans 248 Tanks, Callow 2020 distributing 449 for water 1106 settling 450 Tantalum, atomic weight of 1188 Taper of breakers 52 stamp stems 187, 188 Tappan pump 1046 Tappets for gravity stamps 188 the Boss wedge-grip 1272 resetting 201 screw type 189
wash water for Wilfley table 1469	distributing
Wilfley 1465 table as a slimer 1478	for water
Woodbury table . 1494	settling 450 Tantalum, atomic weight of 1188 Taper of breakers 52 127 128
continuous surface round tables . 1506	Taper of breakers
Cornish frames 704 end-bump	Stamp stems 187, 188
film-sizing . 685, 1506	Tappets for gravity stamps
fixed circular convex slime . 689 for amalgamated plates . 733	resetting 201
dredges 1012	screw type 189 table of dimensions of 189
picking 488 greased 831	table of dimensions of Tarasca Gold Mining Company, Pinder concen-
Humboldt picking 1437	
intermittent surface type 700	Tators at 1201 Tarnishing of amalgamated plates 749 Tarnowitz, Buttgenbach's separator at 447 447 449
investigation of film sizing	Heberli mill at
	settling reservoir at
principle of concentrating, C. W. Comstock 2023 principles of action of Willey group 1465 revolving circular convex slime 686 strakes 725 Salzburg 1115	tanks at
revolving circular convex slime 686	Silesia, mill at
strakes	
Salzburg 1115 shaking amalgamating tables in South Africa 1513	Tasmania, costs of producing copper at 1957, 1958
	tallow for guides in 156
Strin Corning Bilbary and Lubria 669	tin milling in
tye	Tatum, L. W., amalgamating pans 291
versus jigs 606, 641	Taylor and Brunton horizontal riffle sampler . 1577
Side-nump 684	Tasmania, costs of producing copper at 1957, 1958
Tailboard for jigs	hand breaker 59, 1137
height of	Iron & Steel Co., manganese steel 68
Tail-discharges for jigs 581 Tailings and sludge mills of Joplin, Missouri 2042 Tailings at Broken Hill, disposal of 2003 Kalgoorlie, disposal of 2003	hand breaker 59, 1137 Iron & Steel Co., manganese steel 68 J. & Co., stamp mill 1137 mine of Idlewild Gold Mining Company, mill 1137 mine, mill at 1021
Tailing at Broken Hill, disposal of	mine, mill at
Kalgoorlie, disposal of . 2032 the Arizona Copper Co. disposal of . 2039	pipe sampler used by
definition of	mine of the wind of sold winning Company, mine Aviling mine, mill at 1022 pipe sampler used by 845 portable stamp mill 2012 Richard, revolving knife buddle 335 W. W., sampling 884, 885 Tays, E. A. H., Bryan mill 273
disposal of 1113	W. W., sampling 884, 885
Tailings and sludge mills of Joplin, Missouri 2042 Tailings at Broken Hill, disposal of 2032 Kalgoorlie, disposal of 2032 the Arizona Copper Co., disposal of 2032 definition of 494 disposal of 1113 for future use, storage of H. F. Durant 2032 handled by mechanical shoveler 879 launders 873 of vanners, testing of 1171	Tays, E. A. H., Bryan mill comments on Binkley slime-settling system 1410 slime settlings 1419 Taggue on kieves 727
launders 873	slime settlings
or vanners, testing of 1171	Tangue on kieves 727

Pages 1199-1610, Vol. III.	INDI	EX. Pages 1611-2052, Vol. IV.
Tecolotes mill Telluride, Colorado, mill at	1748	Tests of American Process Company drier 1599
Telluride, Colorado, mili at	1176 1925	
goldore, cost of producing gold from	1014	Callow cone on Butte copper slimes 1404 classifier jig at Mill 120 1452 Deister concentrator at Mill 101 1489
ore, cost of producing gold from	1974 1175	Deister concentrator at Mill 101
		feed and discharge of Abbe tube mill 1290 finished products of tube mill 1290 Gates and McCully breakers 45
Tellurium, atomic weight of	1640	Gates and McCully breakers 45 grains in free settling 465
settling slimes 1149,	1848	Grill drier at plant of Empire Portland Cement
straining amalgam of heating for decrepitation	781 829	
	831	Company 1897 Hancock jig on Montana sulphide copper ore 1442 hindered settling 1428 by pulsion jig 623 McLeod, Wilfley and Overstrom tables at Mill 162 1493
oil separation pag amalgamation roasting for magnetism	248 814	by pulsion jig 623
regulated by pyrometer in Wilfley roasting fur-		Mill 162 1493
Template for stamp cams	1548 193	
Templates	1097	oil concentration at Mill 172 1874 ores on Wetherill magnetic separators 808
Templeton roller feeder Templeton roller feeder for gravity stamps Tenacity, affecting separation and brittleness, effect of in dressing ores	854	oil concentration at Mill 172 1874 ores on Weherill magnetic separators 808 power at Mill 173 1927 Richards' pulsator jig 1456 roasting pyrite for magnetism 1544 simple Allis-Chalmers type steam stamp at Mill 182
Tenacity, affecting separation	199 891	Richards' pulsator jig 1456 roasting pyrite for magnetism 1544
and brittleness, effect of in dressing ores	2	simple Allis-Chalmers type steam stamp at
Tendency of ore dressing Tennessee Copper Company, cost of producing cop-	1119	Mill 182 1909 single-cylinder steam stamp at Mill 182 1254 steeple compound steam stamp at Mill 181 1254
per at 1990,	1957	
Tenorite, specific gravity of Tension in belts	1189 1093	Sutton, Steele & Steele dry table 1555 telluride gold ores separation by crushing and
Tenth U. S. Census, order of drop of stamps .	215	screening 1566, 1567
Tephroite, specific gravity of Terbium, atomic weight of	1189 1188	trommel products at Iron Mountain, Missouri 384 Woodbury jig at Mill 162 1449, 1450, 1451
Terraced mill site	1085	
Terry, G., pigments, paint and painting washing china clay	1174	on absorption of gold by plates 765 British Columbia ores, flotation 2048 compressive strength of stone 300
Test, directions for carrying out a concentration. J. P. Porter in Platteville, Wisconsin, results of a mill. B.		compressive strength of stone
J. P. Porter	2048	nim sizing . 107
House	2048	Haverstraw sandstone at Watertown Arsenal. 300 hindered settling 610
jigging of gold ore lubricants	1165	insterstitial currents 626
of gold ore	1166 1098	jigging mixed sizes. 630 Nordberg steam stamps . 1261 sands, regrinding. C. Butters 2014
mill machines 1170,	1171	sands, regrinding. C. Butters 2014
specific gravity Testing	1159 1988	smooth and corrugated vanners 650 stone at Berlin 301
	1171	Munich 301
a Frue vanner Bardwell sorting tube bibliography for	1988 1173	strength of rock
bibliography for by bottle amalgamation	1996	
heavy solutions . 1156, oil	1993 11 55	place and value of small ore. E. H. Simonds 2049 screen sizing test and assays on feed and products of Huntington mills 1317
classifiers suited for	1144	products of Huntington mills 1317
suited for for a process	1989	food and products of double cone class
flotation	1562	sitiers 1668
Delprat and Potter processes	1993 1993	Huntington mills 1316 feed to flotation plant at Mill 130 1721, 1724
Elmore process Van Meter process . 1991, 1992,	1993	Hancock jig, also on middlings 1443
jigs	1150 1989	Hancock jig, also on middlings 1443 Harz jigs at Mill 144 1772, 1773, 1774 Woodbury slime classifier at Mill
suited for magnetic separators suited for	1993	
magnets, double-pole	1993 1994	material conveyed in pipe launder at
of black sand. W. Fawcett	2048	Guanajuato 1595 mill feed at Mill 139 1750
magnets, double-pole Wetherill separators of black sand. W. Fawcett gold mill tailings. W. E. Darrow ores. H. Van F. Furman	2049 2048	Mill 144 1772 . products from ball mills 1302
ores. H. Van F. Furman mill .	1168	Bryan mills 1302
ore from mine .	482 2048	Bryan mills 1310 Bryan mills, high speed rolls and Huntington mills 1317
plant at Denver, G, R, Delamater	1997	coarse and fine rolls at Mill 162
T. Tonge .	2049 1764	1328, 1329
ore from mine ores. M. Lenicque plant at Denver. G. R. Delamater T. Tonge Mill 141 of H. F. Woods, A. Lakes the California Ore Testing Company	2048	De Kalb's classifier 1402 fine grinding system, Mill 105 1638 Griffin mill 1636
the California Ore Testing Company	2049	Griffin mill 1636 grinding pans 1284
	1995 1988	at Mill 130 1720 1724
under water .	1139	Huntington mill at Mill 117 1669
wire versus plate	1137 1137	Richards' vortex classifier at Mill • 144 1775, 1776, 1778
Wilfley table suited for	1990	sand treatment at Milt 117 1671
	1156 2047	settling tanks at Mill 144 1776, 1777, 1779
at the Homestake mill in 1897. A. J. Clark Bring's to an suction jig by Elmore vacuum oil process	1461	Sherman settling tanks at Mill 132 1406
by Elmore vacuum oil process 1559,	1560 1163	spitzkasten at Mill 144 1777, 1778 stamp mortar at Mill 180 1905
compared with mill work	1168	tailings and concentrates from stamps
fourteen-day test of Richards' pulsator classifier	1391	and Lane Chili mill, comparative 1309 from Mill 174 1887
hand concentration. W. McDermott	2049	Woodbury jig at Mill 162 1449, 1450,
sorting, at Mill 162	1842	1451
metallurgical	107	
	101	•

Pages 1-643, Vol. I.	ORE	DRE	SSING.	Pages 644-1197, Vol. II.
Tests to show relative efficiency of regrinding n	nachines	1331	Thyng, W. S.,	details of a hand jig
See Sizing Tests. Tetradymite, specific gravity of		1189	Tierra Seca go	ld separator
Tetrahedrite, specific gravity of		1189	Tiger & Poort	101 102 103
Tetradymite, specific gravity of Tetrahedrite, specific gravity of Tetrahedrite, specific gravity of Thallium, atomic weight of Thames district, amalgamated plates in		750	Tight and loos	e pulleys for jigs 532
mills in		1111	Tighteners for	e puneys for jugs 932 selt conveyors 860 belts 1094 selts 198 ill 1175
mills in		788	stamp b	elts 198
New Zealand, mills at shoes and dies at stamps at Thatcher, Arthur		1180 183	magn	etic concentration at
stamps at		226	mine, co	ests at
Thatcher, Arthur		vni 1137	Tilting frame f	for Wilfley table 1467 ortar blocks 146 ss 721 ng plates 757
Thayer portable one stamp mill stamp mill		1181	riffle block	S
Theoretical and actual crushing ribbons of re	olls .	101	Time of cleaning	ng plates
capacity of trommels value for hindered-settling ratio		377 '427	required b	y Cyanide operations at Milit 117 1072
of free settling velocities		1421	retorti	netic roast 1544 ing 788 in galena roaster 1548 ight of 738 ight of 1188 te screens 1700 in the Carolinas 2046, 2047
Theory of crushing .		303	roast	ın galena roaster 1548
electromagnets flotation processes		790 1555	Tin amalgam	ight of
flow in launders		876	bronze pla	le screens 174
of sand and water in launders 159	2, 1593,	1594,	concentrat	ion in the Carolinas 2046, 2047
slime settling		1595 1149	dressing i	n New South Wales
suction		1462	at Mt. l	Bischoff, Tasmania. S. Fawns 2037, 2040
tube mill action work required for crushing		1336 304	at the ol	ld Clitters mine
Thermo-electric couple with pyrometer in	Wilfley	304	in Bohy	ia. D. H. Bradley, Jr . 2041
roasting furnace		1548	Corny	ia. D. H. Bradley, Jr
Thetford, Quebec, asbestos dressing at	517, 838,	1079	the M	ania, R. Stokes 2046 falay Pennsula, W. H. Derrick 2039 f Tasmania, R. Stokes 2046
Thickness of amalgamated plates .		, 744	industry o	f Tasmania. R. Stokes 2046
bank in trommels		378		
bed on fine concentrators . on vanners		644 660	Cornish	ntration. J. B. Hill, D. A. MacAlister 2046, crushed by Husband stamp 141
bottom bed on jigs		575	ir.une	5 IOF . 109
film in film sizing tests	716	718	crushed	by Sturtevant mill 228 of. R. H. Richards and C. E. Locke 1924
on slime tables canyas tables	090	6, 697 702	roasted	for porosity 829, 839
hard amalgam on plates		761	roasting	for porosity 829, 839 of
ore on belts of magnetic separators stamp die		807 207	runs in Separati	on of at Altenberg 9
plate or wire		371	worked	at Irish Creek, Virginia 200
screens		341	pellets, rec	overy of. M. Baldauf 2030
screens, effect on percentage of openin water film on amalgamated plates		$\frac{369}{746}$	Specific gr	
Thick pulp extractor, Avton Thies, A., and W. B. Phillips, stamp mill.		1419	wasning.	J. 11, 12, James 2000
gold mine, North Carolina	il Haile	1175	in Corn	Inlan D Stalens 90.46
method of chlerination at Mill 98		1622	Tintic district,	Utah mills in 1040 1041, 1045
Thire, A., gravity stamps .	224	, 225	Tires of rolls	
Thirion classifier Thomas breaker		475 57	Titanium, ator	the gravity of
J. log washer	004	228	Toggle, for F	int valuers vie
log washer R. A., Dolcoath tin mill, Cernwall	324	, 335 1183	Toldt, F., chill	led iron shells
slag, mill for		1177	Lin	nited. "The 60 Mill" 1660
Thompson, experiments on magnet		794	Tombstone, an	nalgamating pans at . 290
 N. dressing asbestos at Thetford, Quebec 		1178 1178	silver m	nill at
pneumatic concentration at Thetford,	Quebec	838	mill, jigs i	n 639
pulverizer		234 294	Ton, definition	nill at .1175, 1180 illing at . (1016 n
bibliography for S. P., electromagnets on magnets Thomson Houston dynamo Thorium, atomic weight of	. xx	r, 833	of water	1187
on magnets	794	, 795 1055	Tonge, Thoma	is, concentration from dumps at Lead-
Thorium, atomic weight of		1188		Colorado 1179 ng plants 2049
Thoulet, J., experiments on very fine kaolin		477	Tonopah Mini	ng Company's mill. S. A. Worcester 2037 and Development Company, Boss
on settling rates of fine grains	•	474 1176	Milling,	and Development Company, Boss cantilever stamp-frame at 1272
settling in water velocity of spheres of different density	and size	477		Pachuca stamp battery at 1272
Thoulet's solution		1156	Tools for testing	ng . 1137
Three-high rolls -mineral separation	. 906	107 3, 911	Toothed rolls	oll shells 70
on jigs	200	590	descript	ion of Allis Chalmers type 1242
riffle tables .		680 43	table of	sizes, capacities, and power 1246
Throw of Comet breaker Gilpin County bumping table		681	Topaz, specific Top layer on j	gravity of 1189
Hooper vanning jig	F10 FF0	506	Total cost	1199
jigs . 514, Johnston vanner	518, 553	5, 594 1503	Totten & Hou	s, area, and thickness of plates
Rittinger tables		668	Toughness of	minerals, effect of
				pecific gravity of
Salzburg table .		683		
Salzburg table .		741		
Salzburg table shaking plates Stein, Bilharz, and Luhrig tables vanners	654, 655	741 670 5, 658		
Salzburg table shaking plates Stein, Bilharz, and Luhrig tables vanners Thrust of gravity stamps	6 54 , 655	741 670 5, 658 195		
Salzburg table shaking plates Stein, Bilharz, and Luhrig tables vanners		741 670 5, 658	Tower driers at mills screens at Trachyte, strer weight of	1807, 1813, 1866 mills 1809, 1822, 1824, 1825, 1861, 1865 agth of

Pages 1199-1610, Vol. III.	INDI	EX. Pages 1611-2052, Vol. IV.
Tecolotes mill Telluride, Colorado, mill at	1748	Tests of American Process Company drier 1599
Telluride, Colorado, mili at	1176 1925	
goldore, cost of producing gold from	1014	Callow cone on Butte copper slimes 1404 classifier jig at Mill 120 1452 Deister concentrator at Mill 101 1489
ore, cost of producing gold from	1974 1175	Deister concentrator at Mill 101
		feed and discharge of Abbe tube mill 1290 finished products of tube mill 1290 Gates and McCully breakers 45
Tellurium, atomic weight of	1640	Gates and McCully breakers 45 grains in free settling 465
settling slimes 1149,	1848	Grill drier at plant of Empire Portland Cement
straining amalgam of heating for decrepitation	781 829	
	831	Company 1897 Hancock jig on Montana sulphide copper ore 1442 hindered settling 1428 by pulsion jig 623 McLeod, Wilfley and Overstrom tables at Mill 162 1493
oil separation pag amalgamation roasting for magnetism	248 814	by pulsion jig 623
regulated by pyrometer in Wilfley roasting fur-		Mill 162 1493
Template for stamp cams	1548 193	
Templates	1097	oil concentration at Mill 172 1874 ores on Wetherill magnetic separators 808
Templeton roller feeder Templeton roller feeder for gravity stamps Tenacity, affecting separation and brittleness, effect of in dressing ores	854	oil concentration at Mill 172 1874 ores on Weherill magnetic separators 808 power at Mill 173 1927 Richards' pulsator jig 1456 roasting pyrite for magnetism 1544 simple Allis-Chalmers type steam stamp at Mill 182
Tenacity, affecting separation	199 891	Richards' pulsator jig 1456 roasting pyrite for magnetism 1544
and brittleness, effect of in dressing ores	2	simple Allis-Chalmers type steam stamp at
Tendency of ore dressing Tennessee Copper Company, cost of producing cop-	1119	Mill 182 1909 single-cylinder steam stamp at Mill 182 1254 steeple compound steam stamp at Mill 181 1254
per at 1990,	1957	
Tenorite, specific gravity of Tension in belts	1189 1093	Sutton, Steele & Steele dry table 1555 telluride gold ores separation by crushing and
Tenth U. S. Census, order of drop of stamps .	215	screening 1566, 1567
Tephroite, specific gravity of Terbium, atomic weight of	1189 1188	trommel products at Iron Mountain, Missouri 384 Woodbury jig at Mill 162 1449, 1450, 1451
Terraced mill site	1085	
Terry, G., pigments, paint and painting washing china clay	1174	on absorption of gold by plates 765 British Columbia ores, flotation 2048 compressive strength of stone 300
Test, directions for carrying out a concentration. J. P. Porter in Platteville, Wisconsin, results of a mill. B.		compressive strength of stone
J. P. Porter	2048	nim sizing . 107
House	2048	Haverstraw sandstone at Watertown Arsenal. 300 hindered settling 610
jigging of gold ore lubricants	1165	insterstitial currents 626
of gold ore	1166 1098	jigging mixed sizes. 630 Nordberg steam stamps . 1261 sands, regrinding. C. Butters 2014
mill machines 1170,	1171	sands, regrinding. C. Butters 2014
specific gravity Testing	1159 1988	smooth and corrugated vanners 650 stone at Berlin 301
	1171	Munich 301
a Frue vanner Bardwell sorting tube bibliography for	1988 1173	strength of rock
bibliography for by bottle amalgamation	1996	
heavy solutions . 1156, oil	1993 11 55	place and value of small ore. E. H. Simonds 2049 screen sizing test and assays on feed and products of Huntington mills 1317
classifiers suited for	1144	products of Huntington mills 1317
suited for for a process	1989	food and products of double cone class
flotation	1562	sitiers 1668
Delprat and Potter processes	1993 1993	Huntington mills 1316 feed to flotation plant at Mill 130 1721, 1724
Elmore process Van Meter process . 1991, 1992,	1993	Hancock jig, also on middlings 1443
jigs	1150 1989	Hancock jig, also on middlings 1443 Harz jigs at Mill 144 1772, 1773, 1774 Woodbury slime classifier at Mill
suited for magnetic separators suited for	1993	
magnets, double-pole	1993 1994	material conveyed in pipe launder at
of black sand. W. Fawcett	2048	Guanajuato 1595 mill feed at Mill 139 1750
magnets, double-pole Wetherill separators of black sand. W. Fawcett gold mill tailings. W. E. Darrow ores. H. Van F. Furman	2049 2048	Mill 144 1772 . products from ball mills 1302
ores. H. Van F. Furman mill .	1168	Bryan mills 1302
ore from mine .	482 2048	Bryan mills 1310 Bryan mills, high speed rolls and Huntington mills 1317
plant at Denver, G, R, Delamater	1997	coarse and fine rolls at Mill 162
T. Tonge .	2049 1764	1328, 1329
ore from mine ores. M. Lenicque plant at Denver. G. R. Delamater T. Tonge Mill 141 of H. F. Woods, A. Lakes the California Ore Testing Company	2048	De Kalb's classifier 1402 fine grinding system, Mill 105 1638 Griffin mill 1636
the California Ore Testing Company	2049	Griffin mill 1636 grinding pans 1284
	1995 1988	at Mill 130 1720 1724
under water .	1139	Huntington mill at Mill 117 1669
wire versus plate	1137 1137	Richards' vortex classifier at Mill • 144 1775, 1776, 1778
Wilfley table suited for	1990	sand treatment at Milt 117 1671
	1156 2047	settling tanks at Mill 144 1776, 1777, 1779
at the Homestake mill in 1897. A. J. Clark Bring's to an suction jig by Elmore vacuum oil process	1461	Sherman settling tanks at Mill 132 1406
by Elmore vacuum oil process 1559,	1560 1163	spitzkasten at Mill 144 1777, 1778 stamp mortar at Mill 180 1905
compared with mill work	1168	tailings and concentrates from stamps
fourteen-day test of Richards' pulsator classifier	1391	and Lane Chili mill, comparative 1309 from Mill 174 1887
hand concentration. W. McDermott	2049	Woodbury jig at Mill 162 1449, 1450,
sorting, at Mill 162	1842	1451
metallurgical	107	
	101	•

ges 1-643, Vol. I.	ORE	DRESSING.	Pages 644-1197, Vol.
inking table for cleaning jig concentrates	8	i87 Tullock feeder for ji	gs
stedt magnetic separator		335 rolls	n mills on mill
ne mill, a double action, theory of. H. A. White crushing efficiency of. W. A. Caldec S. H. Pearce	15	123 trommets	mille
crushing efficiency of. W. A. Calded	ott and	Huntingt	on mill
S. H. Pearce	. 13	vanner	
experiences in El Oro, valuable. C	Butters 20	16 Tumbler on dredges	
E. G. Banks	20	113 in Colorado	cight of
grinding in New Zealand	20	13 Wagenen	oncentration of H. K. van
on the Rand	20	mills of Colorac	lo, ideas on the
installations, design of A. James .	. 20	ore concentrates	cost of producing in Colorado
S. H. Pearce experiences in El Oro, valuable. C. feeder, a special. W. H. Fox E. G. Banks grinding in New Zealand. on the Rand installations, design of A. James liners, wear, cost. S. D. McNicken lining at the Standard mine. W. W. patents	Bradley 20	013 Wagenen	o, concentration of. H. K. van
patents practice in S. Africa New Zealand S. Africa. K. L. Graham W. R. Dowling results in S. Africa. H. Leupold	20	117 treatmen	t of. W. Greenawalt
Practice in S. Africa	. 2015, 20 2014, 20	of Colorado,	mills that treat the
S. Africa. K. L. Graham	2013, 20	110 treatmen	l OI
W. R. Dowling	20	013 Turbo log washer	
results in S. Africa. H. Leupold	20	016 at Mill 154	
mills	233, 12	285 power requ	ired for
mill at Cumain to	1200, 1	290 Tuscany mills in	vity of
capacity of	i	291 mill for quicksi	ver ores
at Mill 103	1.	71 Tustin mill	
capacity of	50, 1294, 1	523 bibliography	o, concentration of. H. R. Van t of. W. Greenawalt inills that treat the construction of
an article on. A. H. Bromlev	20	113 number used	for
at El Oro. E. Burt	20	013 sizing tests of	products of, in Oro Plata, and
		014 Utica mine	s
mills 15 the Gold King mill, Colorado. F. l	32, 1770, 19 E. Shen-	722 theory of crus	mill 233,
ard	20	1 Tuttle, E. G., doubl	e discharge on the tail of a jig
the Waihi mines. R. Stokes .	20	014 tail discharge	& Supply Company, rolls
bibliography for	1	93 Manufacturing	& Supply Company, rolls
bibliography for capacity of classification of		285 Tutty, E. I. on car	de
consumption of pebbles and liners at Mill 118	1	291 Twelve Apostles mil	l, amalgam in 767,
at Mill 118	1:	291 Two-current classific	r
cost of grinding by Davidsen	1280, 1		
Denver Engineering Works Compan	v's mill	97 -mineral separa Tye	10n on jigs 707.
	1280, 13	296 Tyler Company, W	S., wire cloth screens
direction of rotation for discharge of discussion of the A. James A. W. Warwick efficiency of El Oro lining for feeding of P. Argall feed opening for for cement grinding fing grinding foundations for Gates	1	289 double-crimped	screens e cloth
discussion of the A. James	. 1.	115 creen cloth use	e cloth d at Mill 101
A. W. Warwick	. 2	015 gauge .	
efficiency of	. 1	292 screens	dell Chili mills at Mill 174
farding of	. 1	340 used on Wad	dell Chili mills at Mill 174
P. Argall	1	323 W. S. Co., cost	of screens
feed opening for	1	287 double crin	of screens
for cement grinding	20	117 mining wir	e'cloth
foundations for	20	915 table of scr	een meshes
Gates .	1280, 1	296 on materia	for screens
general notes	1	294 Wire Works Co	mpany
Gates general notes Hardinge conical in S. Africa, work of S. H. Pearce	1280, 13	296 Types of rolls	nped wire screens e c doth een meshes ens i for screens mpany
A. Caldecott	and w.	steam stamps	***************************************
miers for	17	286	
linings for, discussion by H. A. White		340	U .
management of on the Rand, advantages of	1/	290 344 Ullrich magnetic set	parator
complete account of	20		
complete account of operation of . H. Fischer	1	340 Ultra-microscope	
pebbles or flints for power required to operate	. 1.	288 the, for the st 289 -violet rays for t	udy of slimes he detection of willemite. E. K.
quality of work done by tube mills	19	290 - Violet rays for t	he detection of willemite. E. K.
sizes best suited for feed to	. 12	288 Ulzer, F. and A. Fr	aenkel, chemical-technical anal-
speed of rotation for theory of tube mill action	1289, 13	337 ysis .	
theory of tube mill action	13	336 Schone 282 Uncle Sam Console	's tubular classifier .
versus grinding pans R. C. Clark	2014, 20		lated Mining Company, Callow
in Australia	20	014 Undercurrent	
with central end discharge		294 classifier Richa	rds'
work of oular classifier		113 for saving black	sands. R. H. Richards :
investigation of free settling	•	169 Undershot water wh	eels
on fine grains		173 Undersize, by differ	ent speeds of crushing, variation
Richards'		128 in the per cent. of	. A. W. Gartrell :
tests on hindered settling . results of		610 Unfinished grains 613 Union Bay, Vancou	ver Island, coal washer at
driers, cylindrical driers .		596 Iron Works	•
free settling classifiers ker, W. A.	1	381 amalgamat	ing pan 243, 244, 245, 246,
Ker, W. A. f, machine best suited for crushing		viii D10 Blake brea	kar
lock concentrators, water used in	. 2	359 Dodd table	s at Mill 96
feeder	136,	354 grizzlies	

mills

ages 1–643, Vol. I. ORE I	Pages 644-1197, Vol. 1
nners, side-shake versus end shake 65	Vezin jig 1
slope in degrees and inches 119 Snyder 65 Spadone concentrator belt 150	journal pressure in rolls
Snyder	rolls
Spadone concentrator belt	journal pressure in rolls rolls sampler 846, 1572, 20
speed, travel, slope, water, etc	for sampling high-grade telluride gold ores 1
speet, travel, stope, water, etc	requisites to accuracy when using 15 samples at mills . 1691, 1701, 1737, 1742, 1748, 17
tests on	Samples at mins . 1091, 1701, 1797, 1742, 1748, 17
thickness of bed on 666	springs for rolls
Triumph 652, 1499	springs for rolls Vial magnetit separator Vial magnetit separator Vibracone separator, the
Tulloch 652, 650	Vibracone separator, the
Union Iron Works, iron frame	Vibrating grizzlies
Union Iron Works, iron frame	Vibrations in vanners
with tipping or undulating motion 150	Vibrometer screen W W Resument
Johnston vanner	Vibromotor screen
Johnston vanner	Vibromotor screen Vickers-Maxim steel roll shells at Mill 128 1
Woodbury	Victor turbine wheel 1
tout	victoria mili xxix, l
plante 1155	New Zealand weight of ore
part disintegrator	milling in
at Lintorf, Prussia 830	stamps in
bibliography for 299	Vieille mill
Woodburv 65	Montagne Company
ts for electroplating copper plates . 758	Vickers-Maxim steel roll shells at Mill 128 1 1 1 1 1 1 1 1 1
ts for electroplating copper plates	mill Separation of pyrite and blende
ucron mill 1178 classitiers at	separation of pyrite and blende new Central mill 1 Vigeon, E. C., wear of steel halls 1
jigs in 641	Vigeon, E. C., wear of steel balls 1
jigs in 641 number of sieves for jigs 590	
rolls at	mill at
sieve scale at 367 stroke of µgs at 594	Virgilina, concentration at. E. K. Judd
box classifiers 419	Rice 2
in quartz, weight of	mill, amalgamated plates in
tch, Alexander, on Hancock jig 1441	pyrite mills. R. H. Painter 20
ardena Mining and Smelting Company 1742	zinc ore, concentration of. T. L. Watson 20
ocities, application of free settling to classified de-	Viscosity of liquid, effect on free settling
ratio free to hindered settling to classifier	Vivianite, specific gravity of 1
design 1433	
full teeter velocities of quartz and galena 1430	Volts. See also Power.
free settling . 471	
of currents in classifier . 429	units of
fall of minerals in water 621	Von Dessauer, H. A.
settling curves of 467, 473 particles falling in water and in air 837	on amaigamated plates
water in film signatures 716 710	Hauer, J
ocity card of steam stamp	breaking
	moisture in ore 11
of a sphere falling through a viscous body. Sir	
	results of for stamps used by rolls
fall of lead shot	need by rolle
flow in launders . 877	used by rolls sizing test of breaker product tests on work required for crushing
galena and quartz falling in water. R. H.	tests on work required for crushing
Richards 1433	tests on work required for crushing Vortex classifiers, Richards' annular vortex classifiers, 12 at mil 124 Richards' pocket vortex classifier single-spagot 12 tank vortex classifier 13 for classifier 14 15
pulsion in jigging	at mill 124 1692, 1693, 16
rous and stamps	Kichards' pocket vortex classifier 13
of fine grains	tank vortex classifier
grains	for classifier
under free settling conditions 1421	
galena and quartz falling in water. R. H. Richards 1433 pulsion in jigging 4 1460 rolls and stamps 34 settling, effect of 4 4 of fine grains 473 46 grains 466 under free settling conditions 1421 vibrations of Willey table deck 1466 water on jigs 505	W
Water on jigs	Wed apositio amounts of
waves on amargamated plates 746 ezuela mill in * 1197	Wad, Specific gravity of
water on jigs 595 waves on amalgamated plates 746 ezuela, mill in * 1127 thation 1099	Wad, specific gravity of Waddell Chili mill at Mill 174 Wagemann, C., tin concentration at Ploermel, France 11 Wage scale at mills 1619, 1621, 1622, 1626, 1629, 16 1657, 1664, 1676, 1678, 1689, 1685, 1687, 1688, 16 1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 18 1830, 1841, 1848, 1852, 1859, 1865, 1881, 18 in the San Juan district of Colorado Wages of labor 11
ngris on amaigamated plates	Wage scale at mills 1619, 1621, 1622, 1626, 1629, 16
ein Chemischer Fabriken . 1914	1657, 1664, 1676, 1678, 1680, 1685, 1687, 1688, 16
milion hematite, action of Monarch breaker on 28	1698, 1705, 1712, 1730, 1745, 1757, 1794, 1804, 1816, 18
tical and horizontal shafts of amalgamating pans mills 255	1850, 1841, 1848, 1852, 1859, 1865, 1881, 19
in feeder for rolls	Wages of labor
H. A., viii	Wagner mica-plate static machine used with Blake-
	Wagner mica-plate static machine used with Blake- Morscher electrical ore separator
ing power	Wagoner, L.
on belts	formula for free settling 4 free settling in water 4
dust provention 1000	free settling in water
heating mills 1099	theory of power required in crushing Tustin mill 264 294, 3
intermediary iigs	velocity of particles falling in water
jig plunger clearance	Tustin mill
samplers versus hand sampling 884	Walburn and Swensen Company
sampling 850	rolls
effect of strength and specific gravity on crushing power	rolls breaker of Blake type Waldeyer on riffles Wales, dry scraration in 8
waight of broken ore	Waldeyer on riffles
weight of broken ore	Wales, dry separation in 8 Wales, gold milling in. W. H. Booth 20

Walker, E., be Elmore floating process 1569 pulverizer 236 fibliography for 239 Walker 24, be Elmore floating process 1569 pulverizer 236 fibliography for 239 Walk and the second process 1569 Walk inger gear rolls 1111 fig the second process 1292 Walk and the second process 1293 Walk V. Olberegger grading screens 2366 Walk L. Gold and the second process 1293 Walk V. Olberegger grading screens 2366 Walk L. Gold and the second process 1293 Walk V. Olberegger grading screens 2366 Warper, A. F. Frölel's Mittinger's settrard, 1294 Walk C. Gold and Screens 2364 Warder, Hold, mill at 245, 1183 Warder, Malk, mill at 245, 1184 Warder, Hold, mill at 245, 1184 Warder, H	W. I 101 Ct. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Waller, Index In	Walker E. the Elmore flotation process	39 Wash water for trommels
Waller, Index In	pulverizer	36 pipes on slime table
Waller, Index In	bibliography for	99 required by canvas tables at Mill 139 1755
Waller, Index In	Walker's patent stamp 2	Chalmers & Williams vanners at Mill 122 1687
Waller, Index In	iig	11 Frue vanners at mills 1002, 1094, 1095, 1706, 21 1755 1880
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Wallace, Idaho, mill at 9	47 Harz jigs at mills 1744, 1751, 1752, 1753
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Steel breaker	10 1877, 1878, 1879
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Walth, V., Oberegger gyrating screens 38	30 James sumer
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Wunderlich trough classifier for coal 4	78 New Standard concentrator 1479
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Wann, E. E., discusses fine grinding 20	16 picking belt at Mill 154
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Ward W P Hundt's cottling tub Rittinger's setered	91 Richards'-Coggin classifier at Mill 173 1878
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Rittinger's pointed boxes . 47	78 1694, 1743, 1744, 1751, 1752, 1753, 1755
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Stapff and Cazin jigs . 64	43 1775, 1776, 1778
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	Wardner, Idaho, mill at 945, 118	83 rolls at Mill 173 1877
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	separators at Mill 148	92 round tables at Will 180 . 1904, 1905
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	pulverator 2	34 trommels at mills 1691, 1692, 1693, 1743.
Warp and woof on canwas tables 700 Warp A. Subney, free setting velocities 710 Warp A. Subney, free setting velocities 710 Wasp No. 2 mill, Kirk, S. Dakota 2044 Wasp R. A. Subney free setting velocities 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 441 Wasp R. A. W. definition of slime 710 Wasp picked out in mme for stowing 710 Wasp picked 710	bibliography for 29	94 1772, 1773, 1774, 1816, 1876, 1877
Warp and woof on canvas tables 700 Warren, A. Sadew, free settling velocities 1421 Warren, A. Sadew, free settling velocities 1421 Warwick, A. W., definition of slime 1399 Warwick, A. W., definition of slime 1399 decursion of the tube mill 2015 fine ground slimes 1429 n the tube mill 2015 finely ground slimes 1429 hand sorting in small mills 2022 on slime 1420 power for stamp mills 2042 power for stamp mills 2044 stamp mill foundations 2044 stamp mill foundations 2044 washburn & Moen 171, 1196 Washburn & Moen screen gauge 171, 1196 Washburn & Moen screen gauge 1194, 1364, 1999 Washburn & Moen screen gauge 1194, 1364, 1999 Washurn & Moen screen gauge 1194, 1364, 1999 Washurn & Moen screen gauge 172, 1796 pristininary 150, 201 pristininary 150, 201 pristininary 150, 201	system of magnetic separations, description of the 909	Willey tables 1469 26 at rolls 1661 1662 1687 1706 1744 1745
for corundum 335, 1078 gravity stamps, amount and temperature 221	Warp and woof on canvas tables	00 at mins . 1001, 1002, 1007, 1700, 1744, 1745,
for corundum 335, 1078 gravity stamps, amount and temperature 221	Warren, A. Sidney, free settling velocities . 142	21 Wasp No. 2 mill, Kirk, S. Dakota . 2044
for corundum 335, 1078 gravity stamps, amount and temperature 221	belt vanners at Mill 128 17) Warmick A. W. definition of clima 126	Waste picked out in mine for stowing . 481
for corundum 335, 1078 gravity stamps, amount and temperature 221	discussion of the tube mill	15 column, weight of
for corundum 335, 1078 gravity stamps, amount and temperature 221	fine grinding 134	40 consumption
for corundum 335, 1078 gravity stamps, amount and temperature 221	in the tube mill	15 at Arizona mills 1931
for corundum 335, 1078 gravity stamps, amount and temperature 221	hand sorting in small mills 905	20 Butte. C. W. Goodale 1420, 1997
for corundum 335, 1078 gravity stamps, amount and temperature 221	history of concentration	49 Eureka Hill, G. W. Riter 2036
for corundum 335, 1078 gravity stamps, amount and temperature 221	on slimes 202	20 Longfellow concentrator 1931
for corundum 335, 1078 gravity stamps, amount and temperature 221	power for stamp mills . 204	44 mills 1413, 1622, 1640, 1648, 1664, 1698, 1699,
for corundum 335, 1078 gravity stamps, amount and temperature 221	the A. M. W. mill at Leadville Colo. 204	1700, 1700, 1709, 1712, 1710, 1730, 1731, 1746, 1731, 1757, 1769, 1796, 1704, 1909, 1916, 1917, 1940
for corundum 335, 1078 gravity stamps, amount and temperature 221	Wascott, stamps in Gilpin County, Colorado . 22	29 1848, 1853, 1856, 1859, 1865, 1875, 1882, 1887,
for corundum 335, 1078 gravity stamps, amount and temperature 221	Washburn & Moen 171, 119	96 1891, 1894, 1897, 1912, 1932
for corundum 335, 1078 gravity stamps, amount and temperature 221	Washburn & Moen screen gauge	Montana copper sulphide mills 1931
for corundum 335, 1078 gravity stamps, amount and temperature 221	Washers. See Log Washers.	Shannon concentrator : 1931
for corundum 335, 1078 gravity stamps, amount and temperature 221	Dorr mechanical classifier	43 Washington, Arizona, plant 1411
for corundum 335, 1078 gravity stamps, amount and temperature 221	for clay	76 in Arizona. D. E. Woodbridge . 1997
for corundum 335, 1078 gravity stamps, amount and temperature 221	log	Australasian practice
for corundum 335, 1078 gravity stamps, amount and temperature 221	trough	19 current in launders, speed necessary to carry
for corundum 335, 1078 gravity stamps, amount and temperature 221	using rotating stirrers 134	41 sand 878
for corundum 335, 1078 gravity stamps, amount and temperature 221	Washing before hand picking	st economy in mill. J. C. Scobey
for corundum 335, 1078 gravity stamps, amount and temperature 221	canvas tables 701 70	2011 Stamp milling. A. W. Warwick
for corundum 335, 1078 gravity stamps, amount and temperature 221	clay and kaohn 107	75 flow of 885
for corundum 335, 1078 gravity stamps, amount and temperature 221	cocoa matting	of for Atwood amalgamator
for corundum 335, 1078 gravity stamps, amount and temperature 221	devices on stime tables	59 breaking rock after heating
for corundum 335, 1078 gravity stamps, amount and temperature 221	drum at Mill 95	17 calculation of
for corundum 335, 1078 gravity stamps, amount and temperature 221	followed by hand picking and sizing 161	16 Conkling jig
for corundum 335, 1078 gravity stamps, amount and temperature 221	machinery 124	14 dredging
for corundum 335, 1078 gravity stamps, amount and temperature 221	wans	33 classifier 401
damondiferous earth 335		
Part	for corundum	gravity stamps, amount and temperature 221
Lank with hand packing 488 log washer 3324 Maniperon, gold mill at Republic 2936 mills 1102 Washington, gold mill at Republic 2936 mills 1102 Washington, gold mill at Republic 1836, 2042, 2045 Parsons table 668 Copper Company 1836 & Fisher jig 312 district 1105 Richards-Coggin classifier 382 plant of the Anaconda Copper Co. L. S. Austracy Rittinger table 668 process 1039, 1173 Schmidt spiral screen 263 of amalgamation 248 Schrazz jig 503 smelter 2042 suices 723 Montana 1924 *ptiglute 424 Wash trommels 55, 329, 1341 stamps 206 bibliography for 334 Strin, Bilharz, and Luhrig tables 670	Dits 33	50 Frailett table
Lank with hand packing 488 log washer 3324 Maniperon, gold mill at Republic 2936 mills 1102 Washington, gold mill at Republic 2936 mills 1102 Washington, gold mill at Republic 1836, 2042, 2045 Parsons table 668 Copper Company 1836 & Fisher jig 312 district 1105 Richards-Coggin classifier 382 plant of the Anaconda Copper Co. L. S. Austracy Rittinger table 668 process 1039, 1173 Schmidt spiral screen 263 of amalgamation 248 Schrazz jig 503 smelter 2042 suices 723 Montana 1924 *ptiglute 424 Wash trommels 55, 329, 1341 stamps 206 bibliography for 334 Strin, Bilharz, and Luhrig tables 670	placer gravel	23 jigs 510, 519, 537, 598
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	preliminary, bibliography for	Lake Superior hog trough classifier . 390
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	Washington gold mill at Republic 902	55 log washer
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	Washoe concentrator	45 Parsons table
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	Copper Company	36 & Fisher jig
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	district	D5 Richards-Coggin classifier 392
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	tin	Knunger table
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	process 1039, 117	73 Schmidt spiral screen 363
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	of amalgamation	18 Schranz jig
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	smeiter . 204	12 sluices
bibliography for 334 Stein, Bilharz, and Luhrig tables 670	Wash trommels	11 stamps
Bradford 330 Tamarack classifier 398	bibliography for 33	34 Stein, Bilharz, and Luhrig tables 670
comprided with log washers 333 trommels 358 Crickboom 330 334 wash trommels 330, 331, 332 cylindrical, used at Cabarceno, Spain 330 334 wash trommels 330, 331, 332 in coal washing, recovery. F. W. Parsons 2020 for disintegrating clay 335 gravity stamps, amount and temperature of 221 krupp. 1341 launders, mean velocities of 877 stamp pulp 413 water distributor for vanners 646, 654 jet for disintegration 1007 measurement of 1161	Bradford 33	30 Tamarack classifier 398
Crickboom 330 - 334 330 330 - 334 330	compared with low washers 22	14 I remain steam stamp 139
cylindrical, used at Cabarceno, Spain 330 in Goal washing, recovery. F. W. Parsons 2020 for disintegrating clay 335 gravity stamps, amount and temperature of 221 krupp. 1341 launders, mean velocities of 877 versus log washers 333 stamp pulp 413 yater distributor for vanners 646, 654 jet for di-integration 1007 measurement of 1161	Crickboom 330–33	34 wash trommels 330 331 332
tor disintegrating clay	cylindrical, used at Cabarceno, Spain 33	in coal washing, recovery. F. W. Parsons 2020
101 102 103	tor disintegrating clay 33	gravity stamps, amount and temperature of 221
water distributor for vanners 646, 654 jet for disintegration 1007 Wilfley table 674 measurement of 1161	versus log washers	is taunours, mean velocities of 877 33 stamp pulp 412
Wilfley table	water distributor for vanners	4 jet for disintegration 1007
,		, in the second

	Waves on slime tables 685 Wear of Alsing cylinder 267 amalgamating pan 249 ball mill 261 belt conveyors 860 Blake breakers 25 breakers 56 Bryan mills 272 buhrstone mill 253 Chili mill 269 centrifugal pumps 870 Cyclone pulverizer 289 Dodge breakers 31 Forster breaker 28 Griffin roller mill 282 grizzlies 340 Heberli mill 259 Huntington mill 280 jigs 604 jig screens 547 log washer 324 pebbles in Alsing cylinder 267
Water on amalgamated plates 773 pipes for gravity stamps 199 jigs 538	Waves on slime tables
pipes for gravity stamps	Wear of Alsing cylinder 267
power	amalgamating pan
effect on cost 1128	helt conveyors 980
effect on cost	Blake breakers 25
pumps 868, 871	belt conveyors 860 Blake breakers 25 breakers 56
quantities of, in rectangular launders . 878	Bryan mills
quantities of, in rectangular launders S78 quantity for film sizing 707 707	buhrstone mill
	Chili mill
recovered by settling 460 recovery, G. E. Binckley 1419 at Goldfield, Nevada 2020	centrifugal pumps 870
recovery, G. E. Binckley 1419 at Goldfield, Nevada . 2020	Cyclone pulverizer
regulators	Dodge breakers
regulators	Forster breaker
Card tables at Mill 144 1777	grizzlies
classifiers at Mill 165 1852	Heberli mill
Evans and Hancock jurs compared 1449	Huntington mill
Ferraris patent tables, table of 1490	jigs
Frue vanners at Mill 100	jig screens
Hancock jigs 1441	log washer 324 pebbles in Alsing cylinder 267 punched steel screens at Mill 144 1365
	pebbles in Alsing cylinder 267
Harz jigs at mills 1692, 1693, 1694, 1772, 1773,	
1774, 1775 Hodge jigs at Mill 180 1902, 1903, 1904, 1905 Hodge jigs at Mill 180 1902, 1903, 1904, 1905	rolls 108 roll shells 66 at mills 1877, 1906 Schranz mill 276 screens 109, 170, 343 at Mill 139 109, 1305 effect of moisture on 344 in trommels 356 shoes and dies 182, 183, 184 in grinding pans 1284 steel ball in hall mills 1303 Sturtevant mill 288 Whelpiey & Storer pulverizer 289 Wearing parts. See also each machine.
Hodge jigs at Mill 180 1902, 1903, 1904, 1905 Huntungton mills at mills 1687, 1706, 1753 individual machines at mills 1698, 1699, 1709, 1780, 1816	roll shells 66
Huntington mills at mills 1087, 1700, 1753	at mills
individual machines at milis . 1096, 1099, 1700,	Schranz mill
jigs at Mill 126 1707, 1708	screens 109, 170, 343
jigs at Mill 126 1707, 1708 Johnston vinners	at Mill 109
Johnston vunners	in transpole 256
log washers at Mill 154 1816	shoe and dies 182 183 184
New Humboldt concentrator 1494	in grinding rans 1284
Nissen slamps at Mill 100 . 1852	steel ball in ball mills
Nordberg steeple compound steam stamp at	Sturtevant mill
Mill 180 . 1901	Whelpley & Storer pulverizer 289
stamps at mills 1621, 1624	Wearing parts. See also each machine. for jaw breakers, Krupp's
suspended frame vanner 1503	
turbo at Mill 154 1816	stamp batteries, materials for 1277
vanners at Mill 144 1778	steam stamps
water jackets of Wilfley roaster at Mill 140 1759	nie or 1222, 1223
Wilfley slimer 1506 tables at mills . 1625, 1694, 1695, 1708, 1776,	materials for
1777 1859 1904	of Allis-Chalmers rolls at Mill 179 1898
Woodbury table 1496 separation. W. J. May 2021 softening of 1027	ball mills at Mill 159
separation. W. J. May . 2021	
softening of 1027	life of 1221
Collett	Bryan mills at Mill 173 1879
spray pipe on Hallett table . 676	Buchanan jaw breakers at Mill 157 . 1818
supply at Mill 158 1827	Butters' centrifugal pumps at Mill 117 1671.
pumps for 871	1672, 1674
table of weights and measurements of . 1187	Byron-Jackson pump at Mill 114 1662
tanks . 1106	centrifugal pumps at mills 1711, 1712, 1856,
tube boilers 1090 used by Brink & Hubner's disintegrator 286	1904, 1905
used by Brink & Hubner's disintegrator 286 Heberh mill 259	drag or disc conveyors 1583 elevators at mills 1707, 1710, 1711, 1818, 1819, 1853, 1854, 1855, 1877, 1880, 1898 Gates breakers of mills 1706, 1718, 1737, 1898
Huntington mill 980	1952 1954 1955 1977 1990 1900
Schranz mill	Gates breakers at mills . 1706, 1716, 1727, 1828,
trommels (360	1853
in Blake breakers, table of 26	Griffin mills at Mill 105
breakers . 49	grinding pans, life of
Bryan mill	
Forster breaker in Mill 67 28	Hodge and Cleaves sand pumps at Mill 182
milis. See individual sillis in Chapter AA,	jigs at Mill 180 . 1902, 1903, 1904, 1905
steam stamps 126–129	jigs at Mill 180 . 1902, 1903, 1904, 1905
on amalgamated plates 745 jigs 596, 597	riuntington mills at mills 1317, 1009, 1087, 1711,
slime tables 694	V newles dupley recurre number at Mill 114 1679
steam stamps 129	triplex number at Mill 117 1674
vanners 659, 660	Knowles duplex vacuum pumps at Mill 114 1673 triplex pumps at Mill 117 1674 Krogh pumps at Mill 100 1266 life of 1633
value of miner's inch . 1197	life of 1633
versus air for concentration 825	MCCURY Dreakers at Mili 159 . 1222, 1749
weights and volumes of . 1187	
wheel for arrastra . 238, 239	Nordberg steeple-compound steam stamp at Mill 180 1901, 1902
wheels 1089	at Mill 180 . 1901, 1902
in mills. See Individual Mills in Chapter XX. with classifier pulp	rolls at mills . 1244, 1080, 1080, 1710, 1714, 1771,
with classifier pulp 418	1773, 1774, 1854
waters, I neodore, raison's plant in New Jersey 1183	materials for 1243
	Sherman Huntington mills at Mill 132 . 1728
strength of stone 300 Wauchope, J. A., stage crushing 2015	spindle breakers 46, 47
Wauchope, J. A., stage crushing 2015 Waugh and Bignell, dry concentration process. D. D. Wolff 2026 dry vanner 838 Waverly mill, breaker in 60	SpinGle breakers 40, 47
D. D. Wolff	Waddell Chili mills at Mill 174 1888
D. D. Wolff 2026 dry vanner 838	Wetherill magnetic separators 1525
Waverly mill, breaker in 60	Wilfley roasting furnace 1547
stamps in	tables at Mill 126 1708
Nova Scotia, mill at 1026	Weathering diamond ore
stamps in 228 Nova Scotia, mill at 1026 Waves in film-sizing tests 717	
on amatgamated plates	gurnets at Meronitz
canvas tables	of clay 1075
10	8

INDEX.

Weathering process at Mill 188. 1921 Webb City, Missouri, mills at 1175 Webb, H. H., and Pope Yeatman, hand picking in South Africa 483, 492 Webb, M. Stamp mills in South Africa 225	Weight of stamps at mills 1618, 1620, 1621, 1624, 1626
Webb City, Missouri, mills at	1830
Webb, H. H., and Pope Yeatman, hand picking in	1632, 1634, 1640, 1645, 1649, 1651, 1658, 1661 1665, 1666, 1668, 1677, 1679, 1769, 1911
South Africa	1665, 1666, 1668, 1677, 1679, 1769, 1911
stamp mills in South Africa 225	in California 1619
Webber, W. O., centrifugal and reciprocating pumps 885	Witwatersrand 164
on pumps 868	Sturtevant balanced rolls, table of 123
Webber, W. O., centritugal and reciprocating pumps 885 on pumps 886 on pumps 887 on pumps 888 on pump	1665, 1666, 1668, 1677, 1679, 1769, 1919
concentrating Thomas slag 1177	tappets at Mill 117
magnetic iron oxides 813	wearing parts, Blake breakers
separation of iron ore 2036	Dodge breaker
separators 833, 2030	Forster breaker 28
Mumford & Moodie's separator 837	Wetherill magnetic separators, table of 152:
processes of separation 835	Dodge breaker 3 3 5 5 5 5 5 5 5 5
Wetherill process 836	table of measurements of
Wedgewood mortar for amalgam 780, 1025	units of
Weighing 1160 conveyor, Richardson automatic 2032	Weights for rolls
conveyor, Richardson automatic 2032	Weisbach, hydraulic power 239
	P. J., manual x:
Avery automatic scales at Mill 105 1635 Blake-Denison continuous weighers 1603 Libra scales 1605 machines, the Blake-Denison 1609 ore 883 Weight and power of steam stamps 133	water motors
Blake-Denison continuous weighers 1603	Weiss, picking at
Libra scales 1605	sieve scale at
machines, the Blake-Denison 1609	Weldon, New Jersey, Lovett-Finney magnetic sep-
ore	arator at 83
	mii at
of Akron Chili milis, table of	Welkenraedt, double discharge on jigs at 584
of Akron Chili mills, table of	mill at 1170
arrastra 237, 238 Austin gyratory breakers, table of 1210	Rittinger tables at
Austin gyratory preakers, table of . 1210	Weller pulp thickener 2018 Weller pulp thickener Worgan, Company, Akron Chili mill 1300 Garfield Chili mill 1300 gravity stamps 1278
Plake beautiest of Mill 159 1991 1991	weuman-Seaver Morgan, Company, Akron Chili mill 1307
bosses at Mill 117	Garlield Chili mill . 1308
bucker one 1100	gravity stamps 1278
arrastra Austin gyratory breakers, table of 1210 Bartlett Simplex concentrator 1487 Blake breakers at Mill 158 1821, 1823, 1824 bosses at Mill 117 1668 broken ore 1160, 1190 quartz 1185	gravity stamps 1276 sectional guides for gravity stamps 1276 Wells, J. W., molybdenite dressing 1566 mer ury 768
cobbing hammers at Mill 186 1917	Wells, J. W., molybdenite dressing 1567
pans 1282	Wendt, A. F., Wendt jig 640
Comet brusher 1202	crushing and jigging at Crown Point mines, New York 1174
Colorado Iron Works continuous grinding pans 1282 Comet breaker 41, 46 Danver Engineering Works Company's Blake	New York
breakers, table of . 1204	jig 640, 901
Comet breaker Denver Engineering Works Company's Blake breakers, table of dies in amalgamating pans Ding's magnetic separators Dodge breaker Solution State	Connecting rods on
Ding's magnetic separators	construction of
Dodge breaker 30	
Farrol Blake breakers table of 1900	Wengler & Lowe's classifier . 413, 478 hydraulic classifier . 1367
Ferrure hall mills table of 1200	Wonström magnetic consenter 200
Dodge breaker 30	Wenström magnetic separator 800 data on the
Gates ball mile table of 1301	products of 802
style "K" breakers table of 1908	
Gilpin County humping table 681	Wentworth Company, mill 1181
gravity stamps 218	Goldfields Company, shoe and die used in mill of 181 stamps 227
stamp mortars 164	mill, plates in
hammers for breaking 11	Wessinger, H. J., on breaking . 60
	con hing hometite at Minnesota Ison Minn 60
Humphrey rolls, table of 1235	West Argentine Co., 170n stamp frame Western Chemical Mfg. Co., Denver, Colo., milling at the mill of the R. B. Hosker Chihuahua, milling in 1664 Westehdus jirs, in 644
improved Huntington mills, table of 1312	Western Chemical Mfg Co. Denver Colo milling
	at the mill of the R. B. Hosker 2045
Kennedy gyratory breakers, table of 1214 Kent roller mills 1304 Knowles' New Century magnetic separators,	Chihuahua, milling in 1664
Kent roller mills . 1304	Wheeled Scraper Co., jaw breaker. 25
Knowles' New Century magnetic separators,	Westphaha, jigs in
table of 1542	
Krupp gyratory breakers, table of . 1215	West Rand, slime settling at 478
 La Point flour gold separators, table of . 1510 	West Waverly Gold Mining Company Limited, mill xxviii,
log washer 324	1026
La Point flour gold separators, table of 1510 log washer 324 machines 1096 McCully breaker 44	Yankee concentrator of Detroit Copper Co
McCully breaker 44 gyratory breakers, table of 1212 McLanahan and Stone single roll crushers,	Bryan mills at 1309
gyratory breakers, table of 1212	effort to clarify water at . 1416
McLanahan and Stone single roll crushers,	Wet concentration versus oil process 832
table of	magnetic separator, Conkling
mills 1126	
moving parts of Nordberg steeple-compound	silver mill
moving parts of Nordberg steeple-compound steam stamp at Mill 180 1901 muller and shoes for amalgamating pan 246	
muller and shoes for amalgamating pan 246	versus dry concentration, bibliography for 837
new and old jaw plates for Blake breakers at	Wetherill horizontal magnetic separator 805
Mill 100 1624	inclined magnetic separator 807 J. P., magnetic concentrating plant 1054 cost of screens 361
New Standard concentrators	J. P., magnetic concentrating plant 1054
Nissen stamps at Milli 105 1851 ore for sampling 851, 852 parts of stamp 189 Pilling hoists, table of 1609 roll shells 66	cost of screens 361 magnetic separators 804, 891, 1156 results of tests of 808 Wotherill plant at Franklin, New Jersey 835, 1181
ports of stamp	magnetic separators 804, 891, 1156
Dilling holds table of	results of tests of 808
rining noists, table of	wetneriii piant at Franklin, New Jersey 835, 1181
samples in mechanical sampling	magnet
Samples in mechanical sampling 10/5, 15/6	treatment by the
Samson preakers, table of 1203	magnetic concentrating plant, Sterling Iron and
at Mill 117	treatment by the 2028 magnetic concentrating plant, Sterling Iron and Zinc Company mill
at Will 11/ 1008	mill
at Mill 119 1277	separator 804, 1521, 2025
at 174111 110	separator
samples in mechanical sampling 1575, 1576 Samson breakers, table of 1203 six-pand dies 182, 183, 184 at Mill 117 1668 stamp parts 190 at Mill 118 1677 stem 187 stems at Mill 117 1668 stamps 209, 221	at milis 1525, 1810, 1826, 1862, 1863, 1891,
stamps	
stamps	attendance required

	Waves on slime tables 685 Wear of Alsing cylinder 267 amalgamating pan 249 ball mill 261 belt conveyors 860 Blake breakers 25 breakers 56 Bryan mills 272 buhrstone mill 253 Chili mill 269 centrifugal pumps 870 Cyclone pulverizer 289 Dodge breakers 31 Forster breaker 28 Griffin roller mill 282 grizzlies 340 Heberli mill 259 Huntington mill 280 jigs 604 jig screens 547 log washer 324 pebbles in Alsing cylinder 267
Water on amalgamated plates 773 pipes for gravity stamps 199 jigs 538	Waves on slime tables
pipes for gravity stamps	Wear of Alsing cylinder 267
power	amalgamating pan
effect on cost 1128	helt conveyors 980
effect on cost	Blake breakers 25
pumps 868, 871	belt conveyors 860 Blake breakers 25 breakers 56
quantities of, in rectangular launders . 878	Bryan mills
quantities of, in rectangular launders S78 quantity for film sizing 707 707	buhrstone mill
	Chili mill
recovered by settling 460 recovery, G. E. Binckley 1419 at Goldfield, Nevada 2020	centrifugal pumps 870
recovery. G. E. Binckley 1419 at Goldfield, Nevada . 2020	Cyclone pulverizer
regulators	Dodge breakers
regulators	Forster breaker
Card tables at Mill 144 1777	grizzlies
classifiers at Mill 165 1852	Heberli mill
Evans and Hancock jurs compared 1449	Huntington mill
Ferraris patent tables, table of 1490	jigs
Frue vanners at Mill 100	jig screens
Hancock jigs 1441	log washer 324 pebbles in Alsing cylinder 267 punched steel screens at Mill 144 1365
	pebbles in Alsing cylinder 267
Harz jigs at mills 1692, 1693, 1694, 1772, 1773,	
1774, 1775 Hodge jigs at Mill 180 1902, 1903, 1904, 1905 Hodge jigs at Mill 180 1902, 1903, 1904, 1905	rolls 108 roll shells 66 at mills 1877, 1906 Schranz mill 276 screens 109, 170, 343 at Mill 139 109, 1305 effect of moisture on 344 in trommels 356 shoes and dies 182, 183, 184 in grinding pans 1284 steel ball in hall mills 1303 Sturtevant mill 288 Whelpiey & Storer pulverizer 289 Wearing parts. See also each machine.
Hodge jigs at Mill 180 1902, 1903, 1904, 1905 Huntungton mills at mills 1687, 1706, 1753 individual machines at mills 1698, 1699, 1709, 1780, 1816	roll shells 66
Huntington mills at mills 1087, 1700, 1753	at mills
individual machines at milis . 1096, 1099, 1700,	Schranz mill
jigs at Mill 126 1707, 1708	screens 109, 170, 343
jigs at Mill 126 1707, 1708 Johnston vinners	at Mill 109
Johnston vunners	in transpole 256
log washers at Mill 154 1816	shoe and dies 182 183 184
New Humboldt concentrator 1494	in grinding rans 1284
Nissen slamps at Mill 100 . 1852	steel ball in ball mills
Nordberg steeple compound steam stamp at	Sturtevant mill
Mill 180 . 1901	Whelpley & Storer pulverizer 289
stamps at mills 1621, 1624	Wearing parts. See also each machine. for jaw breakers, Krupp's
suspended frame vanner 1503	
turbo at Mill 154 1816	stamp batteries, materials for 1277
vanners at Mill 144 1778	steam stamps
water jackets of Wilfley roaster at Mill 140 1759	nie or 1222, 1223
Wilfley slimer 1506 tables at mills . 1625, 1694, 1695, 1708, 1776,	materials for
1777 1859 1904	of Allis-Chalmers rolls at Mill 179 1898
Woodbury table 1496 separation. W. J. May 2021 softening of 1027	ball mills at Mill 159
separation. W. J. May . 2021	
softening of 1027	life of 1221
Collett	Bryan mills at Mill 173 1879
spray pipe on Hallett table . 676	Buchanan jaw breakers at Mill 157 . 1818
supply at Mill 158 1827	Butters' centrifugal pumps at Mill 117 1671.
pumps for 871	1672, 1674
table of weights and measurements of . 1187	Byron-Jackson pump at Mill 114 1662
tanks . 1106	centrifugal pumps at mills 1711, 1712, 1856,
tube boilers 1090 used by Brink & Hubner's disintegrator 286	1904, 1905
used by Brink & Hubner's disintegrator 286 Heberh mill 259	drag or disc conveyors 1583 elevators at mills 1707, 1710, 1711, 1818, 1819, 1853, 1854, 1855, 1877, 1880, 1898 Gates breakers of mills 1706, 1718, 1737, 1898
Huntington mill 980	1952 1954 1955 1977 1990 1900
Schranz mill	Gates breakers at mills . 1706, 1716, 1727, 1828,
trommels (360	1853
in Blake breakers, table of 26	Griffin mills at Mill 105
breakers . 49	grinding pans, life of
Bryan mill	
Forster breaker in Mill 67 28	Hodge and Cleaves sand numps at Mill 182
milis. See individual sillis in Chapter AA,	jigs at Mill 180 . 1902, 1903, 1904, 1905
steam stamps 126–129	jigs at Mill 180 . 1902, 1903, 1904, 1905
on amalgamated plates 745 jigs 596, 597	riuntington mills at mills 1317, 1009, 1087, 1711,
slime tables 694	V newles dupley recurre number at Mill 114 1679
steam stamps 129	triplex number at Mill 117 1674
vanners 659, 660	Knowles duplex vacuum pumps at Mill 114 1673 triplex pumps at Mill 117 1674 Krogh pumps at Mill 100 1266 life of 1633
value of miner's inch . 1197	life of 1633
versus air for concentration 825	MCCURY Dreakers at Mili 159 . 1222, 1749
weights and volumes of . 1187	
wheel for arrastra . 238, 239	Nordberg steeple-compound steam stamp at Mill 180 1901, 1902
wheels 1089	at Mill 180 . 1901, 1902
in mills. See Individual Mills in Chapter XX. with classifier pulp	rolls at mills . 1244, 1080, 1080, 1710, 1714, 1771,
with classifier pulp 418	1773, 1774, 1854
waters, I neodore, raison's plant in New Jersey 1183	materials for 1243
	Sherman Huntington mills at Mill 132 . 1728
strength of stone 300 Wauchope, J. A., stage crushing 2015	spindle breakers 46, 47
Wauchope, J. A., stage crushing 2015 Waugh and Bignell, dry concentration process. D. D. Wolff 2026 dry vanner 838 Waverly mill, breaker in 60	SpinGle breakers 40, 47
D. D. Wolff	Waddell Chili mills at Mill 174 1888
D. D. Wolff 2026 dry vanner 838	Wetherill magnetic separators 1525
Waverly mill, breaker in 60	Wilfley roasting furnace 1547
stamps in	tables at Mill 126 1708
Nova Scotia, mill at 1026	Weathering diamond ore
stamps in 228 Nova Scotia, mill at 1026 Waves in film-sizing tests 717	
on amatgamated plates	gurnets at Meronitz
canvas tables	of clay 1075
10	8

Pages 1199-1610, Vol. III.	IND	EX.	Pages 1611-2052, Vo	l. IV.	
Willemite, phosphorescence of	. 1931	Wolverine mine, cost of	f mining and milling	1191	
specific gravity of	1189	Mining Co	mechanical efficiency of san	1181	•
settling slimes	476	wheel .	mechanical einciency of san	d . 1587	
G. W., metallurgy at Broken Hill	459 1568	burned to recover for launders	gold	. 177	
hinged hammer pulverizer . 1281	1, 1322	mill buildings	* * * * * * * * * * * * * * * * * * * *	1088	
Williams, Albert, Jr., bottom discharge tanks for settling slimes on settling tanks G. W., metallurgy at Broken Hill. hinged hammer pulverizer 1281 J. R., burnt lime for settling slimes cost of milling on the Rand definition of slimes slime precipitating agents Patent Crusher Company, hinged hammer pulverizer	. 2049	rimes slime table surfa	gold	. 721	
definition of slimes	1399 1416	stamp guides frames for jigs		. 155	
Patent Crusher Company, hinged hammer pul-	1990	grizzlies .		338	
Patent Crusher Company, hinged hanner pulverizer wilds, b. L., Frisbee Lucop mill Wilson, E. B., stamps for different processes steam stamp steel for shoes and dies Wiltsee, E. A. and J. B. Hobson, arrastra at Smarts- ville and Mooney Fla. Wimmer's jig. Windows	2015	Henry E., amalgan	trap for concentrating table Wethey Wethey A. H. Wethey S. 13 tables aconda concentrator Company Cananca Mexico 1922	s 1516	
Wilson E. B. stamps for different processes	. 294	picked out by hand	1	482	
steam stamp	12, 143	removal of. A. H	. Wethey	. 1106 . 1609	
Wiltsee, E. A. and J. B. Holson, arrastra at Smarts	. 185	from ore	34	. 1607	
wille and Mooney Flat Wimmer's jig Windows Windows Windows Wine Harbor, Whelpley & Storer pulverizer at Wings in amalgamating pans Winnowing ore dry Winslow, W. H., Ryerson pulverizer Winter George W. Peck separator Wire cloth, brass copper galvanized iron Manufacturers' Association standards phenyber branes.	. 290	removed by hand	picking	. 480	
Windows	. 1100	required for drying	A. H. Wetney	. 2031	
Windser cyanide plant, slime settling at Wine Harbor, Whelpley & Storer pulverizer at	. 478 . 289	retorting Sieve frames for iie		. 782	`
Wings in amalgamating pans	245	steam stamp	13	6, 2011	
Winslow, W. H., Ryerson pulverizer	299	Woodbridge, D. E., An	ibles	2040	
Winter, George W., Peck separator	839 1264	Arizona Copper	Company	. 1923	
copper	1364	Concentration at	Cananca, Mexico . 192	1923 3, 2038	
iron	1365 1364	in Arizona La Cananca mir	Cananea, Mexico 192; ning camp ananea on in Arizona s at Mill 177 189;	2038	
Manufacturers' Association standards	1364 1364	ore dressing at C	ananea	1419	
phosphor bronze screens, cost of stationary	1904	Woodbur - Benedict jigs	on in Arizona s at Mill 177 . 1891	1925 2. 1893	
stationary Tyler double crimped	340 370	bull jigs		. 1449	
steel .	1364	clean-up jig		. 1448	
tinned Tyler double-crimped mining wire cloth	1365 1364	concentrators at Mill 117		1669	
versus plate for testing screens punched plate for screens	1138 354	distributor end shake vanner	• • • • • • • • • • • • • • • • • • • •	. 855	
for jig screens	546	Evans and Collom	jigs, capacities compared	701 1448	
gauges S. H. Stupakoff	$\frac{1194}{2019}$	Imperial concentration	or	2023	
in screens, use of bronze	2019	jig systems J. T. Glidden jigs at mills	• •	$\frac{1440}{2022}$	
netting for rifles on dredges picking belt at Mill 137 1438,	1012 , 1740	jigs at mills	1448, 1449, 1450, 1451	1447 1900	
rope elevators ropes	862 1095	differential motio	n for	1457	
Wiscensin, concentration in	1568	middlings jig slime classifiers at Mill 164		1448 1447 1850	
southwest. G. S. Brooks Huff electrostatic separators in	$\frac{2038}{1552}$	system of ore conce	entrution	1450	
Iowa, and Illinois, milling the lead ores of Lead & Zinc Co., separation of blende and pyrite practice at Mill 148	2038 829	table . vanner	67	6, 680	
practice at Mill 148	1792	belt .		647	
zinc milling in	1548 2038	Wooden jigs, life of Woods dry placer much	ine 89	8, 839	
Wiswall pulsatory concentrator. W. S. Zehring	2023 235	Woods dry placer mach Wood's mill bibliography for Woodward, A. E. Woolen blanket tables		235	
pulverizer, bibliography for	296	Woodward, A. E.		296 476	
Witherbee, Sherman and Company mill 1053, 1054, 1117,	1059, 1820	Woolen blanket tables Worcester S A design	of milling plants	703 2049	
products of Wangtröm conventor of	600	Workester, o. A., design	or mining plants		
Witherite, specific gravity of Witkowitz coal washery. II. Fillunger	2052	of Blake and Dodg	7 rolls	312 35	
Witter, magnetic concentration Witwatersrand, cost of producing gold in 1983, 1984,		classifiers, quality	of	461 134	
govern william and the	1986	required for crushir	umyot 🕌	304	
general milling practice in	1043 1257	Voue Own Digging	e mill	308 1021	
mill equipment on the milling on the, II. H. Webb & P. Yeatman practice on the. E. D. Chester	2012	Working of amalgamatu	ng pan pumps at mills 1696, 1745	248	
practice on the. E. D. Chester	2035	pump at Mill 175		020	
at the Espiritu Santo mill at Cana in the	เดข	Wrighteon's coul picking	• talda	1890 2021	
Darien	788 759	Wrought iron, specific g	ravity of	1189	
Darien amalgamated plates concentration in the Kootenay district, B. C.	2034	figures on cost	304-355, 370, 1138 of screens	, 1196 548	
remedy for hard amalgam	2033 2024	Wulfenite, specific gravi	ravity of 354–355, 370, 1138 of screens ty of (tlassifier)	1189	
Wolf breaker Wolff, D. 17, Waugh & Bignell concentrator	56, 58	Wunderlich coal washer trough classifier	(classifier) g in New Mexico xxvii y, mill xxix	477 478	
Wolff, D. D. Waugh & Bignell concentrator Wolframite, independently test on 613	838 3, 617	Wynkoop, N. C., minin, W. Y. O. D. mill	g in New Mexico	2036	
separated from tin ores	829 8 460	Wythe Lead & Zinc Co		809	
specific gravity of	1189	Mine Company		, 1065	
Wolt-tongue classifier	1369 1387		X		
Woltramite, hindered-settling test on scparated from tin ores settling velocity of specific gravity of Wolf-tongue classifier improved classifier Wolhuter mill, details of stamps	• 221	Xenon, atomic weight of	f	1188	
	711				

	Zinc blende and barytes, separation by decrepitation
Y Y	and screening
-	chloride, a heavy solution for testing 1993
Yagle Foundry and Machine Company, Blake rock	cost of producing 1968
breaker 1223	ore, magnetic separation of 809
Yale, C. G., amalgamators 789	mill for 893, 903, 909, 910, 911, 958, 961, 965,
Huntington oscillating stamp mill	1004, 1005
Huntington pan	See also Blende.
Tustin mill	ores, foreign schedules
	immunities effection action of 1000 1000
Yeatman classifier	impurities affecting value of1932, 1933
Pope and H. H. Webb, hand picking on the Rand 492	Joplin zinc ore penalties
milling on the Witwatersrand 2035	ore prices
on mill tests	marketing
stamp mills in South Africa 225	mills for 892, 900, 908, 1060, 1065, 1066
Yellow Aster mill, Randsburg, California 2043	roasted for porosity
Dog mill, Missouri. R. L. Herrick 2042	schedules for calculating value of
ground	separated by roasting and magnetism 814, 815
Yield of small tests	treatment charge on
Ymir stamp mill. S. S. Fowler 2034	value of precious metal values 1939
Yoke for magnets	western zinc ore prices
Young's gold dredge 2043	plant at mills
Yreka, California, dredging at 1007	required in precipitating boxes at mills . 1628, 1632,
Ytterbium, atomic weight of	1641 1673 1678
Yttrium, atomic weight of	specific gravity of
Yuba River, dredging on	sulphate solution
	Zincite, specific gravity of
2	Zircon, specific gravity of
_	Zirconium, atomic weight of
Zacatecas, arrastras at	Zirkler, H xx
Zaratite, specific gravity of	German mill schemes
Zeile Mining Company millxxviii, 1034	gravity stamps
Zenner	rolls in Germany
Zinc amalgam	slime tables in the Harz mountains
for brightening mercury	Zollverein colliery, air blast at
atomic weight of	mine, air blast at
atomic weight of 1100	mine, an phase at



